

H06-3

Work Order on 2018 New Holland T8.390 Tractor

Harder's Iron Horse Garage  
Box 188  
Dundurn SK S0K 1K0  
3069147725  
logan.harder02@gmail.com  
GST/HST Registration No : 793148313RT0001

INVOICE

BILL TO

INVOICE # 1618  
DATE 06/02/2025  
DUE DATE 06/02/2025  
TERMS Due on receipt

ACTIVITY	QTY	TAX	RATE	AMOUNT
<b>Shop Rate</b> T8.390 New Holland replace range and power shift transmissions flushed out lines and transferred all exterior parts to new transmissions disassembled axles to repair and install brakes and axles stub shafts	1	GST	15,000.00	15,000.00
<b>Parts</b> brake plate	8	GST	94.09	752.72
<b>Parts</b> brake friction plate	8	GST	209.94	1,679.52
<b>Parts</b> piston	2	GST	361.37	722.74
<b>Parts</b> oring	8	GST	3.02	24.16
<b>Parts</b> shield	1	GST	64.94	64.94
<b>Parts</b> seal	1	GST	134.20	134.20
<b>Parts</b> gasket	1	GST	84.27	84.27

I _____ certify that the above parts and services are for farm use Land location: _____	<b>SUBTOTAL</b> GST @ 5% <b>TOTAL</b>	18,462.55 923.14 19,385.69
---	---	----------------------------------

All invoices must be paid in full before equipment will be released

Mail Payment to  
Box 188  
Dundurn SK  
S0K 1K0

Or call 1-306-914-7725 to arrange pick up  
Thank you

Signature: \_\_\_\_\_

BALANCE DUE

**\$19,385.69**

# INVOICE

BILL TO



INVOICE # 1595  
 DATE 03/04/2025  
 DUE DATE 03/04/2025  
 TERMS Due on receipt

ACTIVITY	QTY	TAX	RATE	AMOUNT
Parts filter	1	GST	188.27	188.27
Parts filter	1	GST	153.05	153.05
Ehc filter	2	GST	1.25	2.50
Parts gasket	1	GST	26.48	26.48

I, Sheldon Kennedy certify that the above parts and services are for farm use.  
 Land location: NR 15 - 24 - 07 W 2  
 Signature: Sheldon Kennedy

SUBTOTAL 87,617.62  
 GST @ 5% 4,380.88  
 TOTAL 91,998.50  
 BALANCE DUE **\$91,998.50**

ACTIVITY	QTY	TAX	RATE	AMOUNT
Shop Rate New Holland T8.390 low tractor into shop go through complete transmission and rear end systems to diagnose what is causing Transmission low pressure issue found that the park brake clutch pack had failed and is sending fillings and debris throughout the whole transmission and hydraulic system  disassembled and removed range transmission from tractor removed valves and range clutches and gears found filling and contamination in valves removed parkbrake/FWA clutch packs while disassembling i noticed the engineering flaw that caused failure, the glued seal where oil goes from shaft to clutch piston had failed  the new style range transmission has an updated shaft with oring to correct this issue, speed transmission and fwa shaft need to be changed also to match up with new style range transmission this is the best option since we have already seen signs of contamination at the transmission clutch packs	1	GST	10,000.00	10,000.00
Parts updated reman range transmission	1	GST	24,156.25	24,156.25
Parts core for reman range transmission will need find out if its worth shipping back for credit	1	GST	1,438.30	1,438.30
Parts new speed transmission	1	GST	48,683.29	48,683.29
Parts FWA upgrade shaft	1	GST	2,327.74	2,327.74
Parts tube	1	GST	251.70	251.70
Parts green	1	GST	205.68	205.68
Parts switch	1	GST	102.40	102.40
Parts gasket	1	GST	79.96	79.96

Ad RBC NSF  
Repair 2012 NH T.8390 TRACTOR

Harder's Iron Horse Garage  
 Box 188  
 Dundurn SK S0K 1K0  
 3069147725  
 logan.harder02@gmail.com  
 GST/HST Registration No.: 793148313RT0001

## INVOICE

BILL TO

INVOICE # 1632  
 DATE 08/19/2025  
 DUE DATE 08/19/2025  
 TERMS Due on receipt

ACTIVITY	QTY	TAX	RATE	AMOUNT
<b>Shop Rate</b> New Holland T8.350 completed assembly of transmissions reassembled everything that was previously removed from tractor had to clean rust from all the bolts and a lot of time and research was needed to figure out where everything needed to go	1	GST	20,000.00	20,000.00
<b>Hydraulic oil</b> pails	10	GST	110.00	1,100.00
<b>Enviro</b>	10	GST	3.34	33.40
<b>Enviro</b>	9	GST	1.10	9.90
<b>Anti-freeze</b> jugs	9	GST	16.99	152.91
<b>Parts</b> Diesel fuel	1	GST	350.00	350.00
<b>Parts</b> Engine controller, Software and programming	1	GST	6,397.20	6,397.20
<b>Parts</b> exhaust clamp	2	GST	123.56	247.12
<b>Parts</b> gasket	1	GST	19.97	19.97
<b>Parts</b> bolt	10	GST	4.22	42.20

All invoices must be paid in full before equipment will be released

Mail Payment to  
 Box 188  
 Dundurn Sk  
 S0K 1K0

Or call 1-306-914-7725 to arrange pick up  
 Thank you

ACTIVITY	QTY	TAX	RATE	AMOUNT
<b>Parts</b> bolt	6	GST	4.64	29.04
<b>Parts freight</b>	1	GST	50.00	50.00
<b>Parts</b> filter	1	GST	188.27	188.27
<b>Parts</b> filter	1	GST	153.05	153.05
<b>Ehc filter</b>	2	GST	1.10	2.20
<b>Shop supplies</b>	1	GST	250.00	250.00
<b>Parts</b> filter head	1	GST	216.10	216.10
<b>Parts</b> steering sensor	1	GST	1,090.17	1,090.17
<b>Parts</b> snap ring	1	GST	1.83	1.83
<b>Parts</b> used New Holland GPS antenna	1	GST	2,500.00	2,500.00
<b>Shop Rate</b> Diagnose steering sensor issue for auto steer disassemble left front steering knuckle and replace sensor set up and calibrate auto steer	1	GST	1,500.00	1,500.00

ACTIVITY	QTY	TAX	RATE	AMOUNT
<b>Shop Rate</b> Repair issues with tractor after it has been assembled and test driven electric fuel pump not working, removed, and disassembled, it was seized from sitting for so long  Engine controller randomly going offline tested all powers, grounds and communication wires going to a from controller, all tested good replaced controller and reprogramed  front axle suspension not working tested electrical all good found stuck valve in manifold, cleaned and tested  pto not turning on, switch was sticking, cleaned and tested  3 point hitch load cell error turn off the faulty sensor, still have working one on the other side  hydraulic remote valves not working contaminated oil causing valves to stick took apart flushed and cleaned tested  brakes only working on one side pressure tested and found two hoses were hooked up backwards from the factory  replaced hydraulic filters after testing tractor	1	GST	5,000.00	5,000.00
<b>Air conditioning</b> front	1	GST	112.00	112.00

I \_\_\_\_\_ certify that the above parts and services are for farm use.  
 Land location: \_\_\_\_\_  
 Signature: \_\_\_\_\_

SUBTOTAL 39,445.36  
 GST @ 5% 1,972.28  
 TOTAL 41,417.64  
 BALANCE DUE **\$41,417.64**

All invoices must be paid in full before equipment will be released

Mail Payment to  
 Box 188  
 Dundurn St  
 SCK 1K0

Or call 1-306-914-7729 to arrange pick up  
 Thank you