

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 8/29/2023 Serial: 6015
Make: John Deere location: 105
Model: 6175 Hours/Mileage:

Work performrd (print)
Installed new battery and fixed
leak on bailer at farm

Parts/supplies used (print)
A: 1-TY26783B Battery

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 9/7/2023 Serial: 6015
Make: John Deere location: 3514
Model: 6175 Hours/Mileage: 3,838

Work performrd (print)
Replaced Hyd hose on box blade

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/8/2023

Serial: 6015

Make: John Deere

location: 3514

Model: 6175R

Hours/Mileage: 3838

Work performrd (print)

Installed new Hyd hose

Parts/supplies used (print)

A: 1-HHYD2WB06 Hyd hose

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Jared Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 12/28/2023 Serial: 6015
Make: John Deere location: 3514
Model: 6175 R Hours/Mileage: 3,859

Work performrd (print)
Changed out filter housing

Parts/supplies used (print)

A: 1-AL217852 air filter cover

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 2/2/2024 Serial: 6015
Make: John Deere location: 3514
Model: 6175R Hours/Mileage: 3,998

Work performrd (print)

Installed cutting edge's on box blade

Parts/supplies used (print)

A: 2-cutting edge's

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willingham,Danyel Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 4/3/2024 Serial: 6015
Make: John Deere location: 3514
Model: 6175r Hours/Mileage: 4,017

Work performrd (print)
Did 500 hour service

Parts/supplies used (print)

- A: 1-AI215053 air filter
- B: 1-I214634 fuel filter's
- C: 1-RE539279 oil filter
- D: 1-DZ115391 A/C filter
- E: 1-AI220527 cab-n- air filter
- F: 7-rotella T-4 1 gallon engine oil

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin	5/8/2024	Serial:	6015
Make:	John Deere	location:	3514
Model:	6175R	Hours/Mileage:	4,034

Work performrd (print)
Fixed flat tire on box blade

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert willingham

Total Hours spent on Repair: 1 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/10/2024 Serial: 6015
Make: John Deere location: 3514
Model: 6175R Hours/Mileage: 4,039

Work performrd (print)

Tire on box blade flat found bead was
leaking removed tire and took to Monica
Brother's

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain: Pick up tire on Monday

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 5/15/2024

Serial: 6015

Make: John Deere

location: 3514

Model: 6175R

Hours/Mileage: 4,039

Work performrd (print)

installed repaired tire on box

blade

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert willingham

Total Hours spent on Repair: 1 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/7/2024 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,052

Work performrd (print)
Removed tire from box blade
to have repaired

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 1

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/10/2024 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,056

Work performrd (print)

Installed spare tire on box blade
broke tire off rim and cleaned out
mud with pressure washer and installed
back on rim

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 6/20/2024 Serial: 6015
Make: John deere location: 3514
Model: 6175R Hours/Mileage: 4,058

Work performrd (print)

Repaired rear fenders temporary
ordered new rivets

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 1/24/2025

Serial: 6015

Make: John Deere

location: 3514

Model: 6175R

Hours/Mileage: 4203

Work performrd (print)

Removed box blade and moved
machine to R/C and installed
box blade back on

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert ,Danyel Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 2/4/2025 Serial: 6015
Make: John Deere location: R/C
Model: 6175r Hours/Mileage: 4,260

Work performrd (print)

Rebuilt hub on box blade

Parts/supplies used (print)

A:

B: 2- bearing's

C: 1-seal From O'reillys

D: 1- cap

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 2/9/2025 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,276

Work performrd (print)

Box blade hitch was worn out fabricated
new hitch and welded it back on, hooked
up box blade to tractor and brought to shop
and washed

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert ,Danyel Willingham

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 2/10/2025 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,296

Work performrd (print)

Installed cutting edge's and Fabricated 2
side cutting edge's and drilled mounting
holes and fabricated longer hitch pin
on box blade

Parts/supplies used (print)

A: 2-7D-1158 cutting edge
 2-fabricated side cutting edge's
B:
 26-bolt's
C: 26-nut's
 52- washer's From M&D supply
D: 1-bolt
 1-nut
E: 1-washer

F:

Repaired Completed By (Mechanic-Print)
Robert ,Danyel Willingham

Total Hours spent on Repair: 6

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 2/12/2025

Serial: 6015

Make: John Deere

location: R/C

Model: 6175R

Hours/Mileage: 4,301

Work performrd (print)

Installed cutting blade back on
box blade and repaired flat tire

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)

Robert Willinghaqm

Total Hours spent on Repair: 2 1/2

In Service (y/n) yes

Repairs complete (y/n) yes

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 3/14/2025 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,325

Work performrd (print)

was over heating checked with heat
gun across radiator not getting enough
temp ordered part's

Parts/supplies used (print)

A:

B:

C:

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 2

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain:

Kerr Tractor Southwest

Mechanic Equipment Repair Report

Date begin 3/14/2025 Serial: 6015
Make: John Deere location: R/C
Model: 6175R Hours/Mileage: 4,325

Work performrd (print)

Installed pump ran for 10 min and
started throwing code for low coolant
pressure cleared code and ran again same thing
replaced radiator cap and ran still throwing code

Parts/supplies used (print)

A:

B: 1-RE557899 pump

C: 2-DZ127927 thermostat

D:

E:

F:

Repaired Completed By (Mechanic-Print)
Robert Willingham

Total Hours spent on Repair: 3

In Service (y/n) yes

Repairs complete (y/n) no

If No Explain: