

M.F.S. Mobile Fleet Services
P.O. Box 554
907 Centennial Drive North
Martensville, SK S0K 2T0, CA
service@mobilefleet-services.ca
(306) 370-9444



Invoice: INV-50098
Date: 3/12/2021

Bill To

Remit Payment To
Mailing Address:
P.O. Box 554
907 Centennial Drive North
Martensville, SK S0K 2T0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Unit #
SO-3019	COD	3/12/2021	TYRON SIROIS		2005 International SF625

Item	Description	Quantity	Rate	Amount
Complaint: REPLACE ENGINE				
Cause: ENGINE BLOCK CRACKED ON CYLINDER #2				
Labor	Correction:			\$6,600.00
	TRUCK - REPAIRS / Repairs / REMOVE DRIVELINE, PTO AND SHIFT TOWER, PULL TRANSMISSION, REMOVE INPUT SHAFT AND CROSS SHAFTS. REMOVED HOOD AND RADIATOR. REMOVE ENGINE HARNESSSES, COOLANT AND FUEL LINES. REMOVED ENGINE COVER IN CAB. UNBOLT MOTOR MOUNTS AND LIFT ENGINE OUT. INSPECT THE ENGINE HARNESS AND REPAIRED DAMAGED AND FRAYED WIRING AND LOOM. PRESSURE WASHED THE FRAME RAILS AND BOTTOM OF THE CAB. INSTALLED NEW FUEL LINE AS WAS DAMAGED. INSTALL NEW REAR ENGINE MOUNTS.			
	CHANGED PARTS OVER FROM OLD ENGINE TO NEW ENGINE: THE NEW ENGINE DIDNT COME WITH A JAKE BRAKE ASSEMBLY SO WE CHANGED IT OVER FROM THE OLD ENGINE ALONG WITH A NEW INJECTOR HARNESS AND VALVE COVER GASKET/HARNESS. SWAP OVER AIR COMPRESSOR, WATER PORTS, AND HOSES, ENGINE MOUNTS, MULTIPLE FITTINGS, ECM, AND HARNESSSES. INSTALL RESURFACED FLYWHEEL, FAN HUB, AND BELT DRIVE ASSEMBLY, EGR COOLER, AND CROSS OVER TUBE. INSTALLED THE ENGINE INTO TRUCK AND HOOKED UP ALL CONNECTIONS INCLUDING THE RADIATOR AND HOOD. FILLED ENGINE OIL, POWER STEERING FLUID, AND COOLANT. PRESSURIZED THE COOLING SYSTEM TO LOOK FOR LEAKS. FOUND NO LEAKS.			
	INSTALLED NEW INPUT SHAFT INTO THE TRANSMISSION ALONG WITH BEARING, CLUTCH BRAKE, AND CROSS SHAFTS. WASHED THE TRANSMISSION AND INSTALLED. SET THE CLUTCH ADJUSTMENT, INSTALLED DRIVELINE. FILLED THE TRANSMISSION WITH GEAR OIL. RAN ENGINE AND CHECKED FOR LEAKS. FOUND NONE. TEST DROVE UNIT AND FOUND ALL SWITCHES AND CONTROLS WORKING CORRECTLY. TESTED TRAILER WIRING WITH TRAILER. FOUND WORKING CORRECTLY.			
Parts	BRAKE KLEEN - 313			\$7.78
Parts	ENGINE DT466 COMPLETE - 2596573C92			\$26,440.83
Parts	ENGINE MOUNT/INSULATOR - 1664726C4			\$60.11
Parts	CLUTCH 14" - C10723710M0			\$699.00
Parts	CROSS SHAFT, CLUTCH - 309129C1			\$26.81
Parts	CROSS SHAFT CLUTCH - 3532872C1			\$45.88
Parts	INSULATOR - 3549169C2			\$459.75
Parts	INPUT SHAFT - FULS2790			\$431.29
Parts	BEARING, ROLLER - 4308451			\$76.45
Parts	SNAP RING - 4303362			\$2.99
Parts	SNAP RING - 16980			\$1.97
Parts	GASKET FRONT BEARING COVER - 14311			\$1.41
Parts	INSULATOR MOUNT - 1664723C5			\$54.87
Parts	Dirty Core for CLUTCH 14" - CORE DEPOSIT			-\$190.59
Parts	Inherent Core for CLUTCH 14" - CORE DEPOSIT			\$190.59
Parts	TUBE, NYLON BLACK - 3551172C1			\$46.11
Parts	FITTING, FUEL OUTLET - 3533426C3			\$47.29
Parts	FITTING, FUEL OUTLET - 3533425C3			\$42.84
Parts	CONNECTOR FEMALE W/PAC - 762158			\$3.34
Parts	CONNECTOR MALE W/PAC - 762159			\$2.97
Parts	WEATHER PAC SEAL BLUE - 762190			\$1.65
Parts	WEATHER PAC TERMINAL - 762153			\$2.80
Parts	WEATHER PAC TERMINAL - 762154			\$2.80
Parts	Dirty Core for ENGINE DT466 COMPLETE - Core Deposit			-\$5,760.18
Parts	Inherent Core for ENGINE DT466 COMPLETE - Core Deposit			\$5,760.18
Parts	CLAMP 7/16" - 25/32" - 3506			\$4.73

108-1

Item	Description	Quantity	Rate	Amount
Parts	HARNESS - 1846154C95			\$442.30
Parts	LUG COPPER 2/0 X 1/2 - 84-9178			\$3.92
Parts	6PK 3/4" RED SHRINK TUBE - 669986PK			\$1.93
Parts	GASKET KIT - 2596621C91			\$1,166.25
Parts	FLYWHEEL RESURFACE - FW FLAT			\$70.59
Parts	BRAKE KLEEN - 313			\$3.89
Parts	WASHER LOCK 3/8 - 8LWS-038			\$0.80
Parts	GASKET ASSY, VALVE COVER - 18426196C9			\$569.46
Parts	HOSE HEATER 1/2" SILICON - HHS850			\$9.73
Parts	LOOM 1" PER FOOT - 816S-T			\$1.73
Parts	FREIGHT - FREIGHT			\$56.25
Parts	BRAKE KLEEN - 313			\$3.89
Parts	BLOCK HEATER, ELEMENT - 3500054			\$102.48
Parts	CLAMP 13/16" - 1-1/2" - 62016			\$1.90
Parts	STRAP 3/4 - TS16R12			\$1.80
Parts	WASHER FLAT 8MM - ZFWMB-08			\$0.20
Parts	BOLT 8MM X 20MM - ZCSM10BC-08-20			\$0.80
Parts	BOLT 6MM X 20MM - ZCSM10BC-06-20			\$0.20
Parts	NUT 8MM GR10 - ZHNM10BC-08			\$0.18
Parts	WASHER FLAT 8MM - ZFWMB-08			\$0.10
Parts	BOLT 8MM X 20MM - ZCSM10BC-08-20			\$0.40
Parts	ZIP TIE 15-1/4" HD BLACK TIE - 83-6029			\$0.07
Parts	HOSE HEATER 3/4" - HHS1250			\$6.71
Parts	11.1" ZIP TIES - 83-6021			\$25.00
Parts	WASHER FLAT 10MM - ZFWMB-10			\$0.25
Parts	AIR FILTER - RS4636			\$60.99
Parts	AIR FILTER, INNER - RS4637			\$56.96
Parts	RAD CAP - 3589278C3			\$38.00
Parts	CLAMP 9/16" - 1-1/16" - 62010			\$1.93
Parts	ZIP TIE 15-1/4" HD BLACK TIE - 83-6029			\$0.07
Parts	TRANS FLUID ATF - P/S - ATF-DM-QT			\$12.82
Parts	15W40 BULK OIL PETRO CAN - DHP15B20			\$126.72
Parts	NUT 12MM GR10 - ZHNM10BC-12			\$0.68
Parts	WASHER FLAT 12MM - ZFWMB-12			\$0.18
Parts	WASHER FLAT 3/8 - 8WS-038			\$0.80
Parts	BOLT 3/8 X 1-1/2" NC - CS8SC-038-150			\$1.58
Parts	GASKET SHIFT TOWER - 4305294			\$11.89
Parts	NUT NYLOCK 3/8 NC - NN8SC-038			\$0.68
Parts	CLUTCH BRAKE - BK312			\$44.27
Parts	WASHER FENDER 1/4 - 452-013			\$0.75
Parts	BOLT 6MM X 25MM - ZCSM10BC-06-25			\$0.90
Parts	11.1" ZIP TIES - 83-6021			\$25.00
Parts	75W90 GEAR OIL SYN - 550026914			\$198.98
Parts	10 X 3/8NPT FITTING - 1468-10C			\$13.32
Parts	WINDSHIELD WASHER - 49302			\$5.16
Parts	15W40 BULK OIL PETRO CAN - DHP15B20			\$15.21
Parts	1/8NPT COUPLING - 103-A			\$2.13
Parts	GREASE HOSE - 11140			\$8.83
Parts	COOLANT 50/50 DRUM - 74071			\$84.00
Subtotal				\$38,245.35

Complaint: INSTALL ELECTRIC BRAKE CONTROLLER AND 7 PIN BLADE RV PLUG. USE JUNCTION BOX AT REAR OF CAB. JUNCTION BOX MAY NEED TO BE CHANGED OUT.

Cause: Customer request (Inspection)

Item	Description	Quantity	Rate	Amount
Labor	Correction:			\$600.00
	TRUCK - REPAIRS / Repairs / RAN ARCTIC 7 WIRE FROM REAR OF THE TRUCK TO JUNCTION BOX, INSPECT JUNCTION BOX AND FOUND IT TO BE IN FAIR CONDITION, DRILLED HOLE IN THE REAR LIGHT HOLDER TO MOUNT THE 7 BLADE FEMALE CONNECTOR AND WIRE IT APPROPRIATELY. INSTALLED TRAILER BRAKE CONTROLLER AND RAN WIRING. RAN WIRE FROM FUSE PANEL FOR THE 12V SUPPLY, GROUNDED CONTROLLER TO THE FIREWALL, RAN THE TRAILER FEED TO THE JUNCTION BOX, RAN WIRE FROM STOP LIGHT CIRCUIT TO BRAKE CONTROLLER FOR SIGNAL. SECURED ALL WIRING.			
Parts	BRAKE CONTROLLER - 90885			\$218.09
Parts	7 WAY BLADE PLUG - 16714			\$15.73
Parts	COMPRESSION FITTING 1/2 - 50841			\$9.09
Parts	ARCTIC 7 WIRE - 3623			\$93.70
Parts	ZIP TIE8" - 83-6019			\$2.00
Parts	FUSE HOLDER - 82-2166			\$5.34
Parts	30 AMP FUSE - PATC-30			\$1.23
Parts	WIRE 12 GAUGE RED - 87-6000RL			\$1.88
Parts	WIRE 12 GAUGE BLACK - 87-6002RL			\$1.88
Parts	WIRE 12 GAUGE BLUE - 87-6010RL			\$4.80
Parts	WIRE 12 GAUGE WHITE - 87-6007RL			\$1.20
Parts	ZIP TIE 15-1/4" HD BLACK TIE - 83-6029			\$0.14
Parts	FUSE HOLDER - 82-2166			\$2.67
Parts	WIRE 12 GAUGE RED - 87-6000RL			\$6.25
Parts	ZIP TIE 15-1/4" HD BLACK TIE - 83-6029			\$0.07
Parts	GREASE HOSE - 11140			\$8.83
Parts	WIRE 12 GAUGE RED - 87-6000RL			\$9.38
Parts	ZIP TIE8" - 83-6019			\$2.00
Subtotal				\$984.28

Complaint: COOLING SYSTEM PRESSURISING

Cause: ENGINE COUNTERBORE DAMAGED (Inspection)

Labor	Correction:	\$1,440.00
	TRUCK - REPAIRS / Repairs / BROUGHT UNIT INTO SHOP AND REMOVED AIR COMPRESSOR DISCHARGE LINE AND DRAINED AIR TANKS. FOUND NO COOLANT IN AIR TANKS. RAN ENGINE WITH DISCHARGE LINE OFF AND UNIT WAS STILL PRESSURIZING COOLING SYSTEM. REMOVED EGR CROSSOVER PIPE AND FOUND NO SIGNS OF COOLANT COMING FROM EGR VALVE. REMOVED TURBO, EGR COOLER, EXHAUST MANIFOLD, FUEL FILTER HOUSING, VALVE COVER, ENGINE BRAKES, INJECTORS, ROCKER SHAFTS VALVE BRIDGES, CRANKCASE BREATHER AND COOLANT LINES. REMOVED CYLINDER HEAD AND FOUND SIGNS OF HEAD GASKET FAILURE. CLEANED CYLINDER HEAD AND INSPECTED FOR CRACKS. NO VISIBLE SIGNS OF CYLINDER HEAD CRACKS. CLEANED DECK OF BLOCK OFF AND MEASURED LINER HEIGHTS. FOUND #2 CYLINDER LINER NOT SITTING CORRECTLY IN COUNTER BORE. REMOVED OIL PAN AND OIL PUMP. PULLED PISTON AND LINER ON #2 CYLINDER. FOUND THE BLOCK CRACKED BETWEEN PISTONS 1 AND 2. ORDERED NEW LONG BLOCK DT466E. REASSEMBLED ENGINE FOR CORE. PLACED CORE ONTO SHIPPING STAND.	
Subtotal		\$1,440.00

Unit: 2005 International SF625 (21 - TY) VIN: 1HTWGAA06J287480

2005 International SF625

Chassis: 750,056 Kilometers

Labor	\$8,640.00
Parts	\$32,029.63
Shop Supplies	\$300.00
Pre Tax Total	\$40,969.63
GST (5.0000% of \$40,969.63)	\$2,048.48
PST (6.0000% of \$40,969.63)	\$2,458.18
Total	\$45,476.29
Payments & Credits	\$45,476.29
Balance Due	\$0.00

Payment Information

Date Created	Date Applied	Payment #	Method	Reference #	Payout ID	Amount
3/12/2021	3/12/2021	1580422	Cheque	0207		\$39,000.00
3/12/2021	3/12/2021	1580423	MasterCard	7253		\$6,476.29

WE ACKNOWLEDGE INDEMNITIES TO M.J. MOBILE FLEET SERVICES INC. (887 773-20 4334 RT0009) IN THE AMOUNT AS INDICATED. WE HEREBY WAIVE THE RIGHT TO BE NOTIFIED OF ANY FINANCING STATEMENT PURSUANT TO ANY PERSONAL PROPERTY SECURITY ACT, UCC, FUEL SYSTEMS, SUPPLY, AND/OR SERVICE CONTRACTS. WE HEREBY WAIVE THE RIGHT TO WARRANTY. WE HAVE PROMISED PARTS TO BE USED IN THE REPAIR AND/OR MAINTENANCE OF OUR VEHICLE TO BE USED IN ACCORDANCE WITH THE STANDARDS, TOLERANCES, AND CONDITIONS WHICH ARE AVAILABLE BY REQUEST OR ON WWW.MJMOBILEFLEETSERVICES.COM. WE DO NOT AGREE TO MECHANICAL ADVICE PROVIDED BY ANY UNLICENSED PERSON. WE DO NOT AGREE TO THE EMISSIONS SYSTEMS IN ANYWAY AND/OR DO NOT AGREE TO MECHANICAL ADVICE PROVIDED BY ANY UNLICENSED PERSON.

Sign: _____ Plot Name: _____ Date: _____

Saskatchewan Certificate of Registration			
Expiry Date:	Plate No: BNW222		
02Jan2014			
Issue Date:	Customer No: 87852539		
03Jan2013			
Registration Issued To:			
Hundseth Power Line Construction			
Registered Owner's CIVIC (Physical) Address:			
715 47th St W			
Saskatoon, SK S7L 7M1			
Registered Owner's MAILING Address:			
715 47th St W			
Saskatoon, SK S7L 7M1			
1977 TRAILER			
VIN: 2381ET2028			
Body Style: Transport Trailer			
Colour:	Red		
Class:	Fuel:	Seat Cap:	Engine Cap:
TS			

Annual			
Registration	Insurance	Insurance Discount	Total
\$32	\$57	\$0	\$89
Prorated			
Total	Included Variable Term Fee Of:		
\$89	\$0		
Lessed From:			
Lessed From:			
Unit No:	NSC No:	RGVW:	Declared Value:
4914			\$5,000
Primary Use:		Dealer Type:	
Commercial			
Intended Uses/Discounts:			
Automobile Accident Insurance Act coverage Saskatchewan Certificate of Registration Subject to the AAIA and its Regulations Personal Injury: SEE AAIA GUIDE Vehicle Physical Damage: Lesser ACV/Declared Vehicle Deductible: \$600 Liability: \$200,000			

Saskatchewan Certificate of Registration	
Vehicle Identification Number (VIN):	
2381ET2028	
	
Motorcycle Engine/Coach VIN:	
Vehicle Description:	
1977 TRAILER	
VIN Information:	
Transfer of Ownership (Please Print)	
Purchaser:	
Date of Purchase:	Amount Paid:
DD MMM CCYY	\$
Seller Name:	
Seller Signature:	
Printed: 03Jan2013 03:22 PM 217188563 2246	