

Perih Heavy Duty Inc
RR1
Gilbert Plains, MB R0L 0X0, CA
perihhd@gmail.com
204-648-3122



4
Invoice: 238
Date: 6/27/2021

Remit Payment To
Perih Heavy Duty Inc
RR1
Gilbert Plains, MB R0L 0X0, CA

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
1347	COD	6/27/2021	Lowell Penner		Perih, Steven	L788

Item	Description	Quantity	Rate	Amount
Complaint: Diagnose and Repair Check Engine Light				
Cause: Customer request				
Labor	Correction: Engine / Electrical / Check Codes and VVA Pressure. Tested primary engine speed sensor as there were codes for engine speed sensor. Crank shaft sensor connector was damaged. Removed connector and replaced with new. Cleaned connection and re-installed. Ran truck and cleared codes. - 6/27/2021	2.00000	\$100.00	\$200.00
Subtotal				\$200.00

Unit: L788 VIN: 1NKDL40X3CR956925
2012 Kenworth T800
Chassis: 646,810 Miles
Engine: 14,634 Hours

Labor \$200.00
Shop Supplies \$5.00
Pre Tax Total \$205.00
GST (5.0000% of \$205.00) \$10.25
PST (7.0000% of \$205.00) \$14.35
Total \$229.60
Payments & Credits \$0.00
Balance Due \$229.60

GST# 753299528