

# Maintenance History 413

## SER# TWR02799

Work Order ID	Description	Sublet Vendor Labor \$	Part \$	Total \$	Hour Reading
824	-REPLACE STEERING COLUMN TILT LEVER KIT AND SHOCK	\$0.00	\$119.74	\$119.74	6666 on 8/12/2012 10:36:23 AM
1687	-REPLACE STEADY BEARING	\$0.00	\$198.33	\$198.33	7444 on 1/14/2013 2:57:40 PM
3193	-REPLACE STEERING COLUMN TILT LEVER KIT AND SHOCK	\$0.00	\$118.90	\$118.90	8287 on 7/21/2013 8:26:42 AM
4632	REPLACED ENGINE OIL PAN GASKET REPLACED FUEL LIFT PUMP REPLACED GASKETS AND SEALS ON FRONT COVER AND WATER PUMP REPLACED IGNITION SWITCH REPLACED QUICK ATTACH TOGGLE SWITCH REPAIRED OIL LEAKS CHARGED BRAKE ACCUMULATORS ADJUSTED BRAKE LINKAGE	\$0.00	\$953.72	\$953.72	9250 on 4/7/2014 2:34:26 PM
5946	-REPLACE THERMOSTAT	\$0.00	\$152.54	\$152.54	9448 on 10/14/2014 11:04:15 AM

6593	REPLACED ENGINE OIL COOLER LINE REPAIRED STEERING COLUMN REBUILT QUICK ATTACH CYLINDER RESEALED SERVICE BRAKE TREADLE VALVE REPLACE (2) QUICK ATTACH LINES UNDER CAB REPLACED HEATER MOTOR	\$0.00	\$1,021.90	\$1,021.90	9801 on 2/18/2015 11:47:35 AM
6911	-REPLACE LIFT PUMP	\$0.00	\$177.42	\$177.42	9853 on 3/30/2015 10:40:14 AM
8654	-REPLACE BATTERIES (2)	\$0.00	\$666.70	\$666.70	10117 on 9/20/2015 7:46:30 AM
11387	-REPAIR ENGINE, -R&I ENGINE TO REPAIR OIL LEAKS, -REPLACE DAMPER -RESEAL OIL PAN -REPLACE FRONT AND REAR CRANK SEALS -RESEAL VALVE COVER -REPLACE CCB FILTER HOUSING AND HOSES -RESEAL ENGINE OIL FILTER HOUSING -REPLACE STARTER -REPLACE CRANK SPEED SENSOR -REPLACE WATER PUMP  -REPLACE TRANS FLEX COUPLING -REPLACE TORQUE OUTPUT SEAL -REPLACE A/C AND ALT BELTS -REPLACE ENG OIL AND FUEL FILTERS	\$0.00	\$5,128.85	\$5,128.85	10625 on 3/13/2016 7:58:23 AM

14205	-REPAIR ENGINE OIL LEAKS, -REPLACE ENGINE OIL COOLER HOSE -RESEAL ENGINE OIL COOLER -REPLACE REAR DIFF INPUT SEAL & RETAINER	\$0.00	\$1,291.24	\$1,291.24	11100 on 11/2/2016 8:13:15 AM
15494	-T/S COOLANT LEAK, -REPLACE LOWER THERMOSTAT HOUSING -REPLACE UPPER RAD HOSE -REPLACE BATTERIES (2)	\$0.00	\$866.62	\$866.62	12030 on 2/17/2017 7:32:44 AM
15701	-REPLACE ALTERNATOR BRACKET -T/S & REPAIR ELECTRICAL ISSUES	\$0.00	\$616.60	\$616.60	12432 on 3/26/2017 8:46:24 AM
16587	REPLACED TORQUE REPLACED LEFT FRONT CAB WINDOW	\$148.90	\$2,777.09	\$2,925.99	12655 on 6/21/2017 11:33:30 AM
18487	-REPLACE STARTER RELAY	\$0.00	\$110.89	\$110.89	13324 on 12/10/2017 10:59:24 AM
19389	-REPAIR ENGINE OIL LEAKS, -REPLACE ENGINE OIL COOLER HOSES -RESEAL ENGINE OIL COOLER -REPLACE BRAKE PUMP MOUNTING GASKET	\$0.00	\$606.25	\$606.25	13426 on 4/16/2018 9:47:42 AM

20113	REPLACED ENGINE OIL COOLER FLUSHED RAD/ENGINE REPLACED TURBO REPLACED CAC REPAIRED/REPLACED WINDOW LATCHES REPAIRED LIGHTS REPLACED RAD CAP REPLACED BOOTS ON AIR INTAKE	\$0.00	\$6,152.58	\$6,152.58	13630 on 9/5/2018 10:41:38 AM
21265	REPLACED FRONT WINDOW REPLACED LEFT MIRROR REPAIRED CAB LIGHTS CLEANED OUT COOLANT RESERVOIR (RESIDUAL OIL FROM PREVIOUS OIL COOLER FAILURE)	\$132.60	\$240.78	\$373.38	13760 on 1/4/2019 4:31:45 PM
21432	-REPLACE BLOCK HEATER & CORD -REPLACE STEERING COLUMN TILT SHOCK	\$0.00	\$276.68	\$276.68	14386 on 3/9/2019 8:13:24 AM
21814	-REPLACE QUICK ATTACH CYLINDER	\$0.00	\$1,265.70	\$1,265.70	14530 on 5/1/2019 9:19:05 AM
21822	-REPLACE HYD OIL COOLER	\$0.00	\$3,208.83	\$3,208.83	14603 on 5/25/2019 11:15:45 AM
22176	-REPLACE RECIEVER DRYER	\$0.00	\$87.80	\$87.80	14706 on 6/25/2019 12:55:05 PM

22605	-REPAIR COOLING SYSTEM, -REPLACE THERMOSTAT & HOUSING -REPLACE UPPER RAD HOSE -REPLACE LEAKING HEATER HOSE -REPLACE COOLANT TEMP SENSOR	\$0.00	\$645.13	\$645.13	15000 on 9/5/2019 10:16:24 AM
22754	-REPLACE WATER PUMP -REPLACE HEATER HOSE	\$0.00	\$654.15	\$654.15	15103 on 9/17/2019 10:23:27 AM

22956	RESEALED FRONT COVER REPLACED FAN PUMP REPLACED FUEL LIFT PUMP RESEALED ENGINE OIL FILTER HOUSING SET TOP END RESEALED ENGINE OIL PAN REPLACED REAR AXLE TRUNNION/BEARINGS/SEALS (FRONT AND REAR OF AXLE) REPLACED HYDRAULIC HOSES AS REQUIRED REPLACED A/C COMPRESSOR AND CONDENSOR FAN TESTED BATTERIES/REPLACED REPAIRED WIRING HARNESS REPLACED ENGINE BREATHER CANISTER SHIMMED LOADER BOOM, TILT CYLINDER AND QUICK ATTACH REPLACED TRUNIONS, BUSHINGS ANS SEALS ON REAR AXLE REPLACED STEADY BEARING ON FRONT DRIVE SHAFT REPLACED BOTOM SEAT PAN/CUSHION REPAIRED STEERING COLUMN	\$0.00	\$11,276.45	\$11,276.45	15360 on 1/16/2020 2:49:53 PM
24062	-REPAIR ENGINE, -T/S HARD STARTING, -REPLACE INJECTION PUMP -REPLACE INJECTORS -REPLACE LIFT PUMP	\$0.00	\$4,771.82	\$4,771.82	16128 on 6/8/2020 9:45:15 AM
25701	-REPLACE #6 INJECTION LINE	\$0.00	\$70.07	\$70.07	16622 on 3/19/2021 7:13:32 AM
29757	-REPLACE HVAC WATER VALVE & CABLE	\$0.00	\$374.87	\$374.87	17245 on 9/20/2022 1:21:40 PM

30048	-REPLACE CAC OUTLET HOSE	\$0.00	\$194.65	\$194.65	17460 on 12/9/2022 11:26:03 AM
30828	-MISC REPAIRS, -REPLACE LEAKING BLOCK HEATER -REPAIR SEAT, -REPLACE SEAT SUSPENSION -REPLACE PRE-CLEANER DUST BOWL	\$0.00	\$3,157.79	\$3,157.79	17943 on 6/5/2023 1:49:32 PM
31678	REBUILT LIFT CYLINDERS REPLACED LEAKING ENGINE OIL COOLER HOSES REPAIRED LIGHTS RAN NEW SIGNAL WIRE FROM ENGINE OIL PRESSURE SENSOR TO ECM	\$1,326.40	\$15,140.90	\$16,467.30	18815 on 11/30/2023 11:46:34 AM
31903	-REPAIR ENGINE, -REPLACE FUEL PRIMING/X-FER PUMP -REPAIR OIL LEAK (TURBO DRAIN LINE)	\$0.00	\$73.73	\$73.73	18172 on 7/5/2023 1:15:30 PM
31915	-REPLACE LIGHT SWITCH	\$0.00	\$269.41	\$269.41	18530 on 8/15/2023 3:36:45 PM
Totals:		\$1,607.90	\$62,668.13	\$64,276.03	