

Bench test furnace after cleaning,
working as it should.

- Repair leaking black tank flush plumbing
- Repair exterior cracked shower coupling
- Install new bulb seal on rear passenger slide top.
- Install new group 27 battery
- Repair plumbing leak underneath exterior kitchen sink
- New sewer cap installed
- Adjust propane regulator to spec
- Re install fire extinguisher
- Lubricate slide gears

6.90 X \$110.00

Lippert 1P Shower Surround

~~\$898.00~~

New one piece shower surround install



Gold Package

\$1,500.00

Tandem axle bearing & brake service (Parts extra)

A/C inspection & service (clean filter, delta temp inspection, comb out bent fins)

Exterior, interior light inspection

Battery testing

Emergency brake away inspection

Stabilizer jacks/ step inspection & maintenance

Furnace, fridge operation inspection (If furnace needs to be removed for cleaning + \$ 59)

Awning operation inspection

Roof inspection

Interior inspection

Safety inspection (Gas test, smoke & CO alarm)

Check all slide seals

Charging system inspection

Tire pressure test

Water pressure test toilet, sinks, water pump (repairs extra)

Bench test furnace after cleaning,
working as it should.

- Repair leaking black tank flush plumbing
- Repair exterior cracked shower coupling
- Install new bulb seal on rear passenger slide top.
- Install new group 27 battery
- Repair plumbing leak underneath exterior kitchen sink
- New sewer cap installed
- Adjust propane regulator to spec
- Re install fire extinguisher
- Lubricate slide gears

6.90 X \$110.00

**Lippert 1P
Shower
Surround**

~~\$898.00~~

New one piece shower surround install