



Inland Kenworth (US) Inc.

9730 CHERRY AVE
FONTANA, CA 92335
Phone: (909) 823-9955

For current parts specials,
locations, and inventory, visit:
inland-group.com

SERVICE ORDER:
ESTIMATE:

PRE-INVOICE

DATE ARRIVED	DATE INVOICE	ADVISOR	TERMS	CUSTOMER PO#		
4/29/2026		50689	CASH			
YEAR	MAKE	MODEL	VIN	CUSTOMER UNIT #	IN SERVICE	ODOMETER
2022	KENWORTH	T680	1XKYDP9X8NJ156230	K88	2/23/2022	670000

Operations

JOB# 3

WARRANTY

CLAIM NUMBER#

COMPLAINT: A. Recall Campaign: [24KWE] 24KWE: Kongsberg Automotive Right-Hand Shift Stalk (OPEN) Proactive -

CAUSE:

CORRECTION The vehicle was brought in to address a recall campaign related to the 24KWE issue. Upon inspection, the technician
COMPLICATION confirmed that the necessary actions were required under this recall.

CONFIRMATION:

To proceed, the technician documented the current condition of the vehicle by taking detailed photographs and ordered the required parts for the repair.

At this point, there are no complications noted, and we will ensure that the necessary parts are received and installed promptly to complete the recall service. Thank you for your attention to this important safety matter.

24kwea

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD	1	534P/Q21-6124-211	CONTROL-RH STALK SHIFTER, ASSY		
SOLD		LABOR DECISIV	[24KWE] 24KWE: Kongsberg Au		
SOLD	Prepay: 0.00	Parts: 0.00	Labor: 0.00	Misc: 0.00	Sublet: 0.00
					Subtotal: 0.00

Job # 3 Subtotal: 0.00



SERVICE ORDER:

ESTIMATE:

JOB# 7

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: C. RHS FREIGHT-NOT WARRANTY -

CAUSE:

CORRECTION

COMPLICATION

CONFIRMATION:

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD	1	FRT	FREIGHT	130.00	130.00

SOLD Prepay: 0.00 Parts: 0.00 Labor: 0.00 Misc: 130.00 Sublet: 0.00 Subtotal: 130.00

Job # 7 Subtotal: 130.00



SERVICE ORDER:

ESTIMATE:

JOB# 12

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: E. R/R 6- FUEL INJECTORS AND PROGRAM VALVE CLEAN EXHAUST PIPING, BPV AND NOX SENSOR E ADJUSTMENT -

CAUSE:

CORRECTION

COMPLICATION

CONFIRMATION:

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR 045-GEN	E. REMOVE # 6- FUEL INJECTORS AND PROGRAM VALVE CLEAN EXHAUST PIPING, BPV AND NOX SENSOR & ADJUSTMEN		3,900.00
SOLD	6	534P/1313120PE	BOLT-FLANGE M8X55	0.59	3.54
SOLD	1	534P/2105834PE	GASKET, VALVE COVER, MX-13 EPA	69.94	69.94
SOLD	1	534P/2105835PE	GASKET, VALVE TRAIN CASING	108.46	108.46
SOLD	1	534P/1865847PE	O-RING, INJECTOR	7.76	7.76
SOLD	1	534P/1638270PE	O-RING INJECTOR	7.74	7.74
SOLD	1	534P/2127551PE	RING SEAL, INJECTOR	9.32	9.32
SOLD	1	534P/2491047PEX	INJECTOR, MX-13, EPA21/24 (6 P	1,073.51	1,073.51
SOLD	1	534P/2491047PEX-CO RE	INJECTOR, MX-13, EPA21/24 (6 P	1,425.00	1,425.00
SOLD	-1	DISC	GOODWILL DISCOUNT 10%	390.00	-390.00
SOLD	-1	DISC	GOODWILL DISCOUNT 20%	780.00	-780.00

SOLD Prepay: 0.00 Parts: 2,705.27 Labor: 3,900.00 Misc: -1,170.00 Sublet: 0.00 Subtotal: 5,435.27

Job # 12 Subtotal: 5,435.27



SERVICE ORDER: RA534000503

ESTIMATE: 20031317

JOB# 16

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: G. R/R DPF SENSING TUBES AND DPF DIFF SENSOR -

CAUSE:

CORRECTION The customer reported an issue with the DPF sensing tubes and the DPF differential sensor. Upon inspection, the technician identified that the sensing tubes required cleaning and the differential sensor needed replacement.

COMPLICATION

CONFIRMATION: The technician successfully cleaned the sensing tubes and replaced the faulty DPF differential sensor. After completing these tasks, the issue was resolved, and the system is now functioning properly.

We appreciate your trust in our service and are glad to have addressed your concerns effectively.

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR 045-GEN	G. R/R DPF SENSING TUBES AND DPF DIFF SENSOR		390.00
SOLD	1	534P/2200138PE	SENSOR,PRESSURE	161.15	161.15
SOLD	-1	DISC	GOODWILL DISCOUNT 20%	78.00	-78.00
SOLD	3	534D/EC3501	COOLANT-TRP ELC 50/50 JUG	7.99	23.97

SOLD Prepay: 0.00 Parts: 185.12 Labor: 390.00 Misc: -78.00 Sublet: 0.00 Subtotal: 497.12

Job # 16 Subtotal: 497.12

JOB# 17

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: I. PARTS -DPF & DOC

CAUSE:

CORRECTION

COMPLICATION

CONFIRMATION:

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD	1	534P/2274612PE	DPF KIT, W/ CLAMPS, GASKETS, E	3,161.42	3,161.42
SOLD	1	534P/2131526PE	DOC (INLET MODULE)	5,100.84	5,100.84

SOLD Prepay: 0.00 Parts: 8,262.26 Labor: 0.00 Misc: 0.00 Sublet: 0.00 Subtotal: 8,262.26

Job # 17 Subtotal: 8,262.26



SERVICE ORDER: RA534000503

ESTIMATE: 20031317

Job # 20 Subtotal: 2,062.70

JOB# 23

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: L. R/R NOX SENSOR - DOWNSTREAM / OUTLET

CAUSE:

CORRECTION

COMPLICATION

CONFIRMATION:

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR 043-007-096	L. R/R NOX SENSOR - DOWNSTREAM / OUTLET-RECOMMENDED		390.00

SOLD	Prepay: 0.00	Parts: 0.00	Labor: 390.00	Misc: 0.00	Sublet: 0.00	Subtotal: 390.00
------	--------------	-------------	---------------	------------	--------------	------------------

Job # 24 Subtotal: 390.00



SERVICE ORDER: RA534000503

ESTIMATE: 20031317

JOB# 25

CUSTOMER PAY

CLAIM NUMBER#

COMPLAINT: K. RPLACE NOX SENSOR + RUN REGENS

CAUSE:

CORRECTION The technician addressed the customer's concerns regarding a malfunctioning NOx sensor and the need for
COMPLICATION regeneration.

CONFIRMATION: Upon inspection, it was determined that the forward NOx sensor was faulty. The technician faced some challenges, as th
sensor was seized in place. After disconnecting the harness from the sensor, the technician applied a penetrating fluid to
loosen it and, after some time, was able to successfully remove the seized sensor. The insert that holds the sensor was
also taken out but was reinstalled properly before fitting the new forward NOx sensor. The harness was then secured.

After replacing the NOx sensor, the technician attempted to perform a regeneration process. However, this was
complicated by an active fault code (P3753), which prevented the regeneration from being completed. The technician
initiated the regeneration while ensuring the unit was at operating temperature; unfortunately, the process was aborted
due to the active code.

The next steps will involve addressing the fault code to allow for successful regeneration.

STATUS	QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
SOLD		LABOR 043-007-071	K. REPLACE INLET NOX SENSOR + RUN REGENS		650.00
SOLD	1	534P/2347656PE	NOX SENSOR, FORWARD, MX-13 EPA	734.61	734.61
SOLD	Prepay: 0.00	Parts: 734.61	Labor: 650.00	Misc: 0.00	Sublet: 0.00
					Subtotal: 1,384.61

Job # 25 Subtotal: 1,384.61



SERVICE ORDER: RA534000503

ESTIMATE: 20031317

BY SIGNING BELOW, I ACKNOWLEDGE THAT I WAS NOTIFIED BY INLAND OF THE SERVICES AND REPAIRS ITEMIZED IN THIS INVOICE AND AUTHORIZED INLAND TO PERFORM THE SERVICES AND REPAIRS ITEMIZED IN THIS INVOICE. PAYMENT TERMS ARE CASH ON COMPLETION OR ON AN APPROVED INLAND PARTS AND SERVICE ACCOUNT. TERMS ON THE INLAND PARTS AND SERVICE ACCOUNT ARE NET 30 DAYS FROM THE INVOICE DATE. PAST DUE CHARGES ARE CHARGED INTEREST OF 1.5% PER MONTH OR 18% PER ANNUM. I ALSO ACKNOWLEDGE I HAVE READ AND UNDERSTAND THE TERMS AND CONDITIONS LISTED ON THE BACK OF THIS DOCUMENT.

Approved:

Labor:	\$12,740.00
Parts:	\$13,107.04
Misc:	\$-2,640.50
Sublet:	\$0.00
Subtotal:	\$23,206.54
Supplies:	\$499.00
Taxes:	\$0.00
PrePay:	\$-5,000.00
Total:	\$18,705.54

RECEIVED BY: _____

PRINT NAME OF SIGNER: _____

DATE: _____

Please Remit Payment to:

Inland Kenworth (US) Inc.

PO Box 840769

Los Angeles, CA 90084-0769

DISCLAIMER OF WARRANTY: ANY WARRANTIES BY A MANUFACTURER ARE THEIRS, NOT INLAND KENWORTH (US) INC.'S, AND ONLY SUCH MANUFACTURER SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS AND SERVICES ARE PROVIDED BY INLAND KENWORTH (US) INC. AS IS. INLAND KENWORTH (US) INC. EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, IN CONNECTION WITH THE SALE OF PARTS AND ACCESSORIES AND/OR SERVICES AND REPAIRS PERFORMED BY INLAND KENWORTH (US) INC. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM INLAND KENWORTH (US) INC. ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFITS, OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

HAZARDOUS WASTE DISPOSAL COSTS: A CHARGE MAY BE ASSESSED TO COVER COSTS ASSOCIATED WITH THE HANDLING, MANAGEMENT AND DISPOSAL OF TOXIC WASTE OR HAZARDOUS SUBSTANCES UNDER CALIFORNIA AND FEDERAL LAW.

LEAD-ACID BATTERY FEE: THIS DEALER IS REQUIRED BY LAW TO CHARGE A NON-REFUNDABLE \$1 CALIFORNIA BATTERY FEE AND A REFUNDABLE DEPOSIT FOR EACH LEAD-ACID BATTERY PURCHASED. A CREDIT OF THE SAME AMOUNT AS THE REFUNDABLE DEPOSIT WILL BE ISSUED IF A USED LEAD-ACID BATTERY IS RETURNED AT THE TIME OF PURCHASE OR UP TO 45 DAYS LATER ALONG WITH THIS DEALER'S RECEIPT.

TO OUR SERVICE CUSTOMERS

1. Inland Kenworth (US) Inc. is not responsible for claims, costs or damages to the unavailability of parts or delays in parts shipment.
2. All labor and materials will be paid for in cash or approved credit card unless Inland Kenworth (US) Inc. agrees to other payment arrangements in advance.
3. Customer is hereby notified that the vehicle and any of its contents are not insured or protected to the amount of the actual cash value thereof, or otherwise, against loss occasioned by theft, fire or vandalism while the property remains with Inland Kenworth (US) Inc. Customer agrees that Inland Kenworth (US) Inc. or its agents may operate or transport any vehicle left with Inland Kenworth (US) Inc. for repairs for the purpose of testing, inspection, deliver, or service.
4. NOTICE OF ANY AND ALL DISPUTES MUST BE MADE TO INLAND KENWORTH (US) INC. WITHIN TWENTY (20) DAYS OF THE INVOICE DATE. THE NOTICE MUST BE IN WRITING AND STIPULATE THE SPECIFIC DISPUTE.
5. Upon completion of any authorized work or services, Customer agrees to full and immediate payment of any written statement of charges for completed work or services and prompt removal of customer's vehicle from the Inland Kenworth (US) Inc. repair facility upon payment of the repair invoice. In addition to any and all other legal remedies available, ALL REPAIRS ARE SUBJECT TO A MECHANIC'S LIEN. ALL CHARGES FOR REPAIRS, TOWING, AND/OR STORAGE ARE A LIEN ON THIS VEHICLE AND MAY BE SUBJECT TO A LIEN SALE PROCEEDING. THE VEHICLE MAY BE SOLD TO SATISFY THE LIEN IF THE CHARGES ARE NOT PAID. Customer agrees and acknowledges that full payment of all repair invoice(s) is a condition to release of Customer's vehicle to the customer and that beginning 10 days after completion of any authorized work or services, the Customer agrees to pay reasonable per diem storage fees, in addition to the charges on the repair invoice, and that such storage fees may include charges for performance of additional vehicle maintenance as Inland Kenworth (US) Inc. deems necessary in its sole discretion to prevent damage or waste to the Customer's vehicle and/or other vehicles. Customer hereby consents to pay such storage fees and maintenance and expressly waives notice under Vehicle Code 10652.5(a)(2).
6. Where a Customer fails to remove its vehicle from an Inland Kenworth (US) Inc. repair facility within fifteen (15) days of the earlier of: i) completion of any authorized work or services and a written invoice is present to Customer (whether the invoice is paid or not), or, ii) a determination is made by either Inland Kenworth (US) Inc. or Customer not to proceed with any further work or services, Customer acknowledges that Inland Kenworth (US) Inc. may deem such vehicle abandoned, and that Inland Kenworth (US) Inc. is hereby expressly authorized to sell said vehicle at public auction after giving a twenty (20) day written notice by certified mail to the legal owner, registered owner, and Department of Motor Vehicles of intent to do so. On the sale date, the Customer agrees that Inland Kenworth (US) Inc. may sell the abandoned vehicle to the highest cash bidder and the proceeds of sale must be used first to satisfy any applicable lien plus storage fees and costs incident to sale, and net proceeds shall be forwarded to the Lien Sale Unit of the Department of Motor Vehicles in accordance with the provisions of Civil Code § 3073, or other applicable law in effect. Fees and costs incidental to the sale shall also include reasonable attorney's fees and costs, which may be necessarily incurred.
7. If any such charges incurred by Customer to work performed by or storage fees incurred therefrom remain unpaid for thirty (30) days after such request for payment, Inland Kenworth (US) Inc. reserves its rights, without waiving any of its existing rights or remedies, to initiate legal action and Customer will be responsible for all reasonable attorney's fees and costs.
8. The Power-of-Attorney granted on the front of this Repair Order/Invoice shall be irrevocable and shall remain in effect for so long as there is an outstanding amount due under this Repair Order/Invoice. Inland Kenworth (US) Inc. and the customer knowingly, voluntarily and intentionally waive any right they may have to a trial by jury in any litigation based upon or arising out of the repairs and services provided by Inland Kenworth (US) Inc. or any parts or accessories sold by Inland Kenworth (US) Inc. or any course of conduct, dealing, statements (whether oral or written), or any act of Inland Kenworth (US) Inc. or the customer.
9. Inland Kenworth (US) Inc. and the Customer knowingly, voluntarily and intentionally waive any right they may have to a trial by jury in any litigation based upon or arising out of the repairs and services provided by Inland Kenworth (US) Inc. or any parts or accessories sold by Inland Kenworth (US) Inc. or any course of conduct, dealing, statements (whether oral or written), or any act of Inland Kenworth (US) Inc. or the customer.
10. The sole and exclusive venue for any dispute or litigation arising under or concerning this Agreement shall be in the courts located in and for the county in which the repairs were performed and the parts or accessories were sold, and the parties irrevocably consent to the jurisdiction of said courts. The Repair Order/Invoice shall be construed and governed by the laws of the state in which the repairs were performed and the parts or accessories were sold.

WARNING

Motor vehicles contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. These chemicals are contained in many vehicle components and replacement parts, vehicle fluids, and paints and materials used to maintain vehicles, including, but not limited to, fuel, oil, batteries, brakes, and wheel balancing weights. When you service, clean or maintain your car, you will be exposed to listed chemicals contained in used oil, waste and replacement fluids, fumes, grease, grime, touch-up paint, certain replacement parts, and particulates from component wear. When we service your car, we will return used components to you upon request. Used parts and components contain chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.

To minimize your exposure when servicing, maintaining or cleaning your vehicle: 1) work in a well ventilated area; 2) do not smoke, drink or eat while working; 3) wash your hands when finished or when taking a break; and 4) follow all manufacturer instructions pertaining to proper use and maintenance of motor vehicles and vehicle components.

(Posted in accordance with Proposition 65 in Cal. Health & Safety Code §25249.5 *et seq*)