475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 306-721-3993 Fax:

\$33,660

** Reprint **

Invoice:

Date / Hour: 5/5/2015 9:33:07AM

Repair Order: 109244 Customer: 00104

Branch: R

Total Invoice: \$ 1,688.46

Cash

Page 1 of 4

Bill To:

Ship To:

Work:

Customer P/O:

Type: Heavy

Supp.

Add User: fmonkhouse

Open Date: 05/02/2015

Completion Date: 05/04/2015

Salesperson: 000

Unit Number: 8925-08

Model Year: 2008

Make/Model: International 7500 6x4

VIN: 1HTWPAZT08J578925

Meter: 114315 Kilometers

Task: 92-000-03 Saskatchewan Safety Inspection - Tractor

Department: Service

Department: Service

Complaint: SASK SAFETY

Part Supply6(3)

Description / Ref Number Shop Supplies

U/M Task 1 Subtotals Quantity 1.0

Price \$13.20 Parts:

Labor: Miscellaneous:

\$0.00 \$220.00 \$13.20

Extended

\$13.20

Price

Task 1 Subtotals

\$233,20

Engine Warning Light, Diag Task: 12-000-369

Complaint: CHECK REASON YELLOW LIGHT ON IN DASH, ALSO SET SPEED, CRUISE & PEDAL AT 120 KM

Correction: CK CODES, IAT SENSOR UNPLUGGED & INTAKE HOSE TO AIR COMPRESSOR RUBBED THROUGH . PLUG IN SENSOR & REPL HOSE.

SET CRUISE & ROAD SPEED TO 120 KMP. ROAD TEST UNIT & EBP CODE CAME ACTIVE, REPLEXHAUST BACK PRESSURE

SENSOR & REPAIR & REPOUTE WIRING

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	1883423C91	SENSOR, EBP ASSY	ĒĀ	1.0	\$44.08	\$44.08
GY	L2643486	HOSE HEATER 3/4 ID	EA	2.0	\$4.70	\$9.40
	Ez Tech	Ez Tech Computer Fee		1.0	\$50.00	\$50.00
	Supply6(3)	Shop Supplies		1.0	\$20.20	\$20.20
			Task 2 Subtotals	Parts:		\$53.48
				Labor:		\$336.72
				Miscellaneous:		\$70.20
				Task 2 Subtotals	-	\$460.40

Task: 3 17-000-14 Tire Inspection and/or Adjust Pressures

Complaint: CHECK REASON FOR UNEVEN TIRE WEAR ON FRONT

Correction: CK FRT END SUSPENSION, GOOD. UNIT NEEDS ALIGNMENT

Department: Service

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	Supply6(3)	Shop Supplies		1.0	\$3.31	\$3.31
			Task 3 Subtotals	Parts:		\$0.00
				Labor:		\$55.20
				Miscellaneous:		\$3.31
				Task 3 Subtotals		\$58.51

Task: 95-000-11 S&I Convex Mirrors - Per Mirror

Complaint: LEFT CONVEX MIRROR CRACKED Correction: REPL BOTH GLASS PIECES ON LFT SIDE **Department: Service**

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 5/5/2015 9:33:07AM

Repair Order: 109244 Customer: 00104 Branch: R

Total Invoice: \$ 1,688.46

Cash

Page 2 of 4

Bill To:

Ship To:

Office Phone:

	r P/O:		Open [Date: 05/02/2015	Completion Date:	05/04/2015
Add	User: fmonkhouse		Salesper	son: 000	- January Barra	00/0 //2010
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended
NI	2505818C2	GLASS ASSY MIR PRPRTRY FLT H	EA	1.0	\$109.67	\$109.67
NI .	2505820C2	GLASS ASSY MIR PRPRTRY CNVX	EA	1.0	\$107.03	\$107.03
	Supply6(3)	Shop Supplies	月鳳	1.0	\$4.14	\$4.14
	-	Task 4	Subtotals	Parts: Labor: Miscellaneous:		\$216.70 \$69.00 \$4.14
				Task 4 Subtotals		\$289.84
Comple Supp.	int: REPLACE CLUTCH PEDAL GRIF Part	Ssy, Adjust Description / Ref Number	U/M	Quantity	artment: Servio	Extended
NI IV	2505695C1	PAD PEDAL*COVER	EA	1.0	\$26.62	Price \$26.62
	Supply6(3)	Shop Supplies		1.0	*	·
		Chief Cappiles		140	\$0.41	\$0.41
	<i></i>	• • • •	Subtotals	Parts: Labor:	\$0.41	\$0.41 \$26.62 \$6.90
	35pp.y0(0)	• • • •	Subtotals	Parts: Labor: Miscellaneous:	\$0.41	\$26.62
		• • • •	Subtotals	Parts: Labor:	\$0.41	\$26.62 \$6.90
		Task 5 :	Subtotals	Parts: Labor: Miscellaneous: Task 5 Subtotals	artment: Service	\$26.62 \$6.90 \$0.41 \$33.93
Compla Correcti	6 16-000-41 Cab Doo int: LEFT SIDE DOOR PANEL LOOS on: SECURE DOOR PANEL Part	Task 5 :	Subtotals U/M	Parts: Labor: Miscellaneous: Task 5 Subtotals	0	\$26.62 \$6.90 \$0.41 \$33.93
Compla Correcti	6 16-000-41 Cab Doo int: LEFT SIDE DOOR PANEL LOOS on: SECURE DOOR PANEL	r Weather Seal(S), Rep		Parts: Labor: Miscellaneous: Task 5 Subtotals	artment: Servic	\$26.62 \$6.90 \$0.41 \$33.93
Compla Correcti	6 16-000-41 Cab Doo int: LEFT SIDE DOOR PANEL LOOS on: SECURE DOOR PANEL Part	Task 5 : r Weather Seal(S), Rep Description / Ref Number Shop Supplies		Parts: Labor: Miscellaneous: Task 5 Subtotals Deparement	artment: Service	\$26.62 \$6.90 \$0.41 \$33.93
Compla Correcti	6 16-000-41 Cab Doo int: LEFT SIDE DOOR PANEL LOOS on: SECURE DOOR PANEL Part	Task 5 : r Weather Seal(S), Rep Description / Ref Number Shop Supplies	U/M	Parts: Labor: Miscellaneous: Task 5 Subtotals Depart Quantity 1.0 Parts: Labor:	artment: Service	\$26.62 \$6.90 \$0.41 \$33.93 Se Extended Price \$6.87 \$0.00 \$114.54
Compla	6 16-000-41 Cab Doo int: LEFT SIDE DOOR PANEL LOOS on: SECURE DOOR PANEL Part	Task 5 : r Weather Seal(S), Rep Description / Ref Number Shop Supplies	U/M	Parts: Labor: Miscellaneous: Task 5 Subtotals Depart Quantity 1.0 Parts:	artment: Service	\$26.62 \$6.90 \$0.41 \$33.93 Se Extended Price \$6.87 \$0.00

Task: 7 69-000-15 Sun Visors, Rep Complaint: SUN VISOR CLIP

Correction: REPL LT SUN VISOR CLIP

Extended Supp. Description / Ref Number Quantity Price U/M Price 3599154C3 CLIP, SUN VSR ROD LH COOL GR EΑ 1.0 \$14.10 \$14.10 Supply6(3) **Shop Supplies** 1.0 \$1.66 \$1.66 Task 7 Subtotals Parts: \$14.10 Labor: \$27.60 Miscellaneous: \$1.66

Department: Service

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Task 8 Subtotals

Department: Service

Department: Service

\$38.55

Date / Hour: 5/5/2015 9:33:07AM

Repair Order: 109244 Customer: 00104 Branch: R

Page 3 of 4

Bill To:

Ship To.

			Offic	e Phone:			
	Work:						
Custome	Customer P/O:		Open D	Date: 05/02/2015	Completion Date:	ate: 05/04/2015	
Add User: fmonkhouse			Salesper	son: 000	·		
-				Task 7 Subtota	als	\$43.36	
Compla	8 16-000-143 int: FIRE EXTINGUISHER on: INSTALL FIRE EXT B		eplace	De	epartment: Servic	Extended	
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price	
SFC	FX1600	BRACKET, VEHICLE 2 1/2LB	EA	1.0	\$9.29	\$9.29	
	Supply6(3)	Shop Supplies		1.0	\$1.66	\$1.66	
		•	Task 8 Subtotals	Par Lab		\$9.29 \$27.60	
				Miscellaneou	IS:	\$1.66	

Task: 9 14-000-28 Out (Thru) Shaft Bearings, Rep

Complaint: ALIGN THROUGH SHAFT

Correction: REM DRIVELINE & REALIGN. REASSY & GREASE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
CG	SD657018X	BEARING STRAP KIT 1710/1810	EA	1.0	\$10.96	\$10.96
	Supply6(3)	Shop Supplies		1.0	\$4.97	\$4.97
		Task 9	Subtotals	Parts:		\$10.96
				Labor:		\$82.80
				Miscellaneous:		\$4.97
	_			Task 9 Subtotals		\$98.73

Task: 10 04-000-39 Air Tank Mntg Cable Or U-Bolt, Rep

Complaint: REPLACE MISSING BOLT AT AIR BAG & ON BOX CYCLINER

Correction: HEAT & TIGHTEN LOOSE BOLTS ON SPRING, REPL BOLTS ON FRT CYLINDER ON BOX HOIST

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	24841R1	BOLT 3/8 X 1-1/2 PHC TYPE 8	EA	2.0	\$3.63	\$7.26
NI	25709R1	WASHER406X.812X.089HDN	EA	4.0	\$3.81	\$15.24
NI	9413979	NUT HEX LOCK 3/8-16	EA	2.0	\$1.44	\$2.88
	Supply6(3)	Shop Supplies		1.0	\$7.45	\$7.45
		Task 1	I0 Subtotals	Parts:		\$25.38
				Labor:		\$124.20
				Miscellaneous:		\$7.45
				Task 10 Subtotals		\$157.03

GST/HST Number:

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 5/5/2015 9:33:07AM

Repair Order: 109244 Customer: 00104

Branch: R Total Invoice: \$1,688.46

Cash

Page 4 of 4

Bill To:

Ship To:

Office Phone: --

Work:

 Customer P/O:
 Open Date: 05/02/2015
 Completion Date: 05/04/2015

Add User: fmonkhouse Salesperson: 000

 Detail Tax Info:
 Total Parts:

 GST 89362 3934 RT
 \$76.75
 Total Labor:

 SK PST
 \$76.75
 Total Miscellaneous:

Total:

Invoice Subtotal:

Total Invoice:

ee Subtotal: \$1,534.96
Total Tax: \$153.50

\$356.53

\$113.87

\$1,064.56

\$1,688.46

Terms Due Date
00 DUE UPON RECEIPT OF 5/5/2015

\$153.50

Cash 00 DUE

INVOICE

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

Paid With:

Payment Method

Remit To-

Cash

Amount Due: \$1,688.46

Amount Received:\$1,688.46

Chg Due: \$0.00

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Hénderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 306-721-3993 Fax:

** Reprint **

Date / Hour: 6/5/2015 4:54:31PM

Repair Order: 109699 Customer: 00104 Branch: R

Total Invoice: \$ 975.50

Cash

Page 1 of 2

Bill To:

Ship To:

Office Phone

Work:

Customer P/O:

Type: Heavy

VIN: 1HTWPAZT08J578925

Open Date: 06/04/2015

Completion Date: 06/05/2015

Salesperson: 000

Add User: emclaughlin Unit Number: 8925-08

Model Year: 2008

Make/Model: International 7500 6x4

Meter: 119687 Kilometers

ECM Reading: 3805

Task: 1 Crank (Start) Relay, Rep 08-000-49

Complaint: TURNS OVER WON'T START, WARNING LIGHTS ON.

Department: Service

Correction: CK CODES & TRY STARTING TRUCK, FOUND NO FUEL PRESSURE, PRIME FUEL SYSTEM WITH HAND PUMP, WON'T PRESSURE UP. REM FUEL LINE TO HAND PUMP & BLOW THROUGH LINE, GOOD. REM LINE AFTER FUEL LIFT PUMP, NO FUEL WHEN CRANKING. REPL FUEL LIFT PUMP & BLEED AIR OUT OF SYSTEM. R&I AIR FILTER HOUSING TO REPL LIFT PUMP & LT SPLASH SHIELD. PUT

FUEL GAUGE ON & CK PRESSURES, GOOD. UPDATE ECM & CLEAR CODES.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
N1	2511369C91	KIT, LOW PRESSURE FUEL PUMP	EA	1.0	\$292.99	\$292.99
N1	2511369C91-C1	CORE, LP FUEL PUMP	EA	1.0	\$94.50	\$94.50
LO	330	VALVE	EA	1.0	\$8.71	\$8.71
N1	2511369C91-C1	CORE, LP FUEL PUMP	EA	-1.0	\$94.50	\$(94.50)
	Supply6(3)	Shop Supplies		1.0	\$33.12	\$33.12

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$44.34 \$44.34 Total: \$88.68

Total Parts: \$301.70 **Total Core Charge:** \$94.50 **Total Core Ret:** \$(94.50) **Total Labor:** \$552.00 **Total Miscellaneous:** \$33.12 **Invoice Subtotal:** \$886.82 **Total Tax:** \$88.68 Total Invoice: \$975.50

Payment Method

Terms

Due Date

Cash

00 DUE UPON RECEIPT OF 6/5/2015

INVOICE

-Remit To -

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

Paid With:

Cash

Amount Due: \$975.50

Amount Received:\$975.50

Chg Due: \$0.00

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 6/5/2015 4:54:31PM

Repair Order: 109699 Customer: 00104 Branch: R

Total Invoice: \$ 975.50

Page 2 of 2

Bill To:

Ship To:

Work: 306-536-5055

Customer P/O:

Add User: emclaughlin

Open Date: 06/04/2015

Completion Date: 06/05/2015

Salesperson: 000



I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 N08-I

** Reprint **

Invoice:

Date / Hour: 5/26/2016 2:31:53PM

Repair Order: 114281 Customer: 00104 Branch: R

Total Invoice: \$ 2,937.34

Cash

Open Date: 05/18/2016

Page 1 of 3

Bill To:

1

Ship To:

Salesperson: 000

Add User: fmonkhouse
Unit Number: 8925

Model Year: 2008

Make/Model: International 7500 6x4

Type: Gravel

Customer P/O:

Supp.

VIN: 1HTWPAZTO8J578925

Meter: 145410 Kilometers

ECM Reading: 4455

Quantity

1.0

Task: 1 92-000-03

Saskatchewan Safety Inspection - Tractor

Shop Supplies

Department: Service

Completion Date: 05/26/2016

Complaint: GOVT SAFETY

Part

Supply6(3)

Description / Ref Number

U/M ___

Task 1 Subtotals

Task 2 Subtotals

Price \$13.20 Parts:

Miscellaneous: Task 1 Subtotals

Labor:

\$13.20 \$233.20

Extended

\$13.20

\$0.00

\$220.00

Price

Department: Service

Task: 2 12-000-167 Engine - Diagnose For No Start Or Hard Starting

Complaint: CK FOR HARD STARTING

Cause: PERFORM DIAG & CK FOR CODES

FND ICP CODES ACTIVE

Correction: REM INTAKE PIPES, UNBOLT & REM VALVE COVER AND REPL ICP SENSOR

CLEAN COVER & REASSY

TRUCK STARTS NO ACTIVE CODES

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	1875784C93	SENSOR ASSEMBLY ICP/BCP	ËA	1.0	\$465.81	\$465.81
	ETC<	Electronic Tool Charge (Diagnostic/Calibration)		1.0	\$75.00	\$75.00
	Freight	Parts Freight		1.0	\$48.00	\$48.00
	Supply6(3)	Shop Supplies		1.0	\$28.98	\$28.98

Labor: Miscellaneous: \$465.81 \$483.00 \$151.98

Task 2 Subtotals

Task 3 Subtotals

Parts:

\$1,100.79

\$24.87

Task: 3 16-000-94 Hood Mtd Mirror, Rep Complaint: MIRRORS LOOSE

Task:

4

Correction: TIGHTEN ALL MIRROR BOLTS

65-000-09

Extended Supp. Quantity Price Description / Ref Number U/M Price Supply6(3) Shop Supplies 1.0 \$1.41 \$1.41 **Task 3 Subtotals** Parts: \$0.00 Labor: \$23,46 Miscellaneous: \$1.41

Clearance Lights, Rep

Department: Service

Department: Service

** See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 5/26/2016 2:31:53PM

Repair Order: 114281 Customer: 00104 Branch: R

Total Invoice: \$ 2,937.34

Cash

Page 2 of 3

Bill To:

LAU

2591779C92

FINAL CHARGE NOAT 50/50 PRE-MIX RED

995526L19

TS17R-10

Ship To:

Customer	P/0:		Open [Date: 05/18/2016	Completion Date	: 05/26/2016
	Jser: fmonkhouse		Salesper	son: 000		
	nt: REPAIR BOX LIGH					
Correction	on: REPL 2 BURNT OL	JT BOX LIGHTS				
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extende Price
BF	1462-4	UNION COUPLING,1/4T	EA	1.0	\$1.73	\$1.73
GL	45832-3	LAMP,2 1/2'ROUND RED	EA	1.0	\$1.71	\$1.71
GL	45833-3	LAMP,2 1/2 ROUND AMBER	EA	1.0	\$1.71	\$1.71
	Supply6(3)	Shop Supplies		1.0	\$1.90	\$1.90
			Task 4 Subtotals	Parts:	· ·	\$5.15
				Labor:		\$31.74
				Miscellaneous:		\$1.90
				Task 4 Subtotals		\$38.79
	5 08-000-183	Service Batteries & Cables		Depa	artment: Servi	ce
Complai	nt: SERVICE BATTER	IES AND CABLES		·		
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended
очрр.	Supply6(3)	Shop Supplies	U/M	1.0	\$4.97	Price \$4.97
			Task 5 Subtotals	Parts:	Ψ1.37	
			1451. 5 545151415	Labor:		\$0.00 \$82.80
				Miscellaneous:		\$4.97
				Task 5 Subtotals		\$87.77
Task:	6 09-000-24	Fan Drive Belt - Replace		Den	artment: Servi	
Complai	nt: REPL FAN BELT			506	artificiti. Oct vi	
Supp.	Part	Description / Ref Number	11/04	Quantity	Price	Extended
NI	1879853C1	BELT FAN 10PK 2475MM	U/M EA	1.0	\$86.82	Price \$86.82
	Freight	Parts Freight		1.0	\$9.00	\$9.00
	Supply6(3)	Shop Supplies		1.0	\$6.62	\$6.62
		Shop dappinds	Task 6 Subtotals	Parts:	Ψ0.02	·
			radit o oabtotais	Labor:		\$86.82 \$110.40
				Miscellaneous:		\$15.62
				Task 6 Subtotals		\$212.84
	7 09-000-16	Fan Drive Shroud - Repair/Replace		Depa	artment: Servi	ce
	nt: REPLACE FAN SH		00140114000	•		
Correction	on: HH GHILL, AC CO	NDENSOR, SURGE TANK, OVERFLOW TANK AND) SPLASH APRON- RI	EPL WITH NEW SHRO	ŲD	E 4
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	2591779C92	SHROUD FAN	FΔ		98 091/2	1 1100

SHROUD FAN

A/FREEZE 50/50 RED 3.78L

RUBBER TUBE CLAMP,5/8

\$460.86

\$9.49

\$0.31

\$460.86

\$9.49

\$0.31

1.0

1.0

1.0

EΑ

EΑ

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 5/26/2016 2:31:53PM

\$2,937.34

\$256.44

Repair Order: 114281 Customer: 00104 Branch: R

Total Invoice: \$ 2,937.34

Cash

Page 3 of 3

Bill To:

Ship To:

Customer P/O:		Open D	ate: 05/18/2016	Completion Date: 05/26/20	
Add User: fmonkhouse		Salesperson: 000			
Supply6(3)	Shop Supplies	<u></u>	1.0	\$28.98 \$28.	
		Task 7 Subtotals	Parts:	\$470.66	
			Labor:	\$483.00	
			Miscellaneous:	\$28.98	
GST/HST Number:	REP	RIN	Task 7 Subtotals	\$982.64	
Detail Tax Info:			Total Parts:	\$1,028.44	
GST 89362 3934 RT	\$134.05		Total Labor:	\$1,434.4(
SK PST	\$122.39	Tota	Miscellaneous:	\$218.06	
	Total: \$256.44		-	Ψ210.00	
			nvoice Subtotal:	\$2,680.90	

Payment Method ****Cash***

Terms

Due Date

00 DUE UPON RECEIPT OF 5/26/2016

INVOICE

-Remit To -

Maxim Truck & Trailer

475 Henderson Drive

Regina, SK S4P 3C2

Paid With:

Cash

Amount Due: \$2,937.34

Amount Received:\$2,937.34

Chg Due: \$0.00

Total Tax:

Total Invoice:

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993

** Reprint **

Invoice:

Date / Hour: 12/4/2020 1:29:53PM

Repair Order: 4525 Customer: 00104

Branch: R Total Invoice: \$ 2,038.33

***9 - Visa - __

Page 1 of 2

Bill To:

Ship To:

Customer P/O:

Type: Gravel

Add User: emclaughlin

VIN: 1HTWPAZTO8J578925

Completion Date: 12/04/2020

Open Date: 12/03/2020 Salesperson: PartsDefault

Unit Number: 8925

Model Year: 2008

Make/Model: International 7500 6x4

Meter: 216538 Kilometers

ECM Reading: 6340

Diagnose/Inspect - Truck/Bus Engine System* 12-000-001

Complaint: LONG CRANK TIME TO START ENG WARM OR COLD

Cause: CK FOR CODES. FOUND ICP ONLY BUILDING TO 200 PSI.

Correction: REM FENDER, INTAKE PIPE AND FILTER & HIGH PRESSURE LINE. HOOK UP PRESSURE TESTER, FOUND LEAK UNDER VALVE

COVER. REM BRACKETS & VALVE COVER, PRESSURE UP & FOUND LEAKING AT #1 CYLINDER. REM OIL RAIL & FOUND O-RINGS

TORN. REPL O-RINGS, REASSY & PRESSURE TEST, GOOD. ROAD TEST UNIT & CLEAR CODES

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	1842626C96	KIT, HP OIL RAIL SEALS	EA	1.0	\$156.01	\$156.01
	ETC<	Electronic Tool Charge		1.0	\$95.00	\$95.00
	SS-10	Shop Supplies		1.0	\$58.80	\$58.80
			Task 1 Subtotals	Parts:		\$156.01
				Labor:		\$588.00
				Miscellaneous:		\$153.80
				Task 1 Subtotals		\$897.81

Task: 2 Saskatchewan Safety Inspection - Tractor* 92-000-003

Correction: PERFORM SGI SAFETY INSPECTION AND SUPPLY PARTS

Department: Service

Department: Service

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	3549169C2	INSULATOR ENG REAR MTG	EA	2.0	\$287.46	\$574.92
CR	43761XT	SEAL FRT AXLE SCOTSEAL EXTR	EA	1.0	\$57.37	\$57.37
GROTE	45833-3	LAMP,2 1/2ROUND AMBER	EA	1.0	\$2.00	\$2.00
WISDOM	4715Q23KKIT	4715Q,23K BRAKE SHOE KIT	EA	1.0	\$95.86	\$95.86
	DotFee	DOT Decal Fee		1.0	\$20.00	\$20.00
	SS-10	Shop Supplies		1.0	\$22.00	\$22.00
		Task 2	Subtotals	Parts:		\$730.15
				Labor:		\$220.00
				Miscellaneous:		\$42.00
				Task 2 Subtotals		\$992.15

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$53.87 \$148.37 Total:

\$94.50

Total Parts: Total Labor: \$886.16 \$808.00 \$195.80

Total Miscellaneous:

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice

Date / Hour: 12/4/2020 1:29:53PM

Repair Order: 4525 Customer: 00104 Branch: R

Total Invoice: \$ 2,038.33

Page 2 of 2

Bill To:

Ship To:

Customer P/O: Open Date; 12/03/2020 Completion Date: 12/04/2020 Add User: emclaughlin Salesperson: PartsDefault **Invoice Subtotal:** \$1,889.96 **Total Tax:** \$148.37 Total Invoice: \$2,038.33 Payment Method <u>Terms</u> **Due Date** ***9 - Visa -01 COD 12/5/2020

Remit To-

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 306-721-3993

** Reprint **

Invoice:

Date / Hour: 12/15/2020 4:07:29PM

Repair Order: 4649 Customer: 00104 Branch: R

Total Invoice: \$917.38

***9 - Visa - _

Page 1 of 2

Bill To:

Ship To:

Customer P/O:

Open Date: 12/15/2020 Salesperson: PartsDefault Completion Date: 12/15/2020

Add User: emclaughlin

Model Year: 2008

Make/Model: International 7500 6x4

Type: Gravel

Unit Number: 8925

VIN: 1HTWPAZTO8J578925

Meter: 216736 Kilometers

Task: 1 02-000-006 Truck/Bus (S/A) Wheel Seal - R/R*

Complaint: RT STEER AXK LE WHEEL SEAL LEAKING

Correction: LIFT AXLE, REM WHEEL & BRAKES. REM HUB & CLEAN ALL COMPONENTS. REPL WHEEL SEAL & BRAKE SHOES (SUPPLIED).

REASSY, SET BRAKES & TORQUE WHEEL TO SPEC.

Supp.	Part	Description / Ref Number	D JU/M	Quantity	Price	Extended Price
KLNFLO	313	BRAKE CLEAN NON-CHL 390GF	EA	1.0	\$3.00	\$3.00
PRMTX	51550	ANAROBIC FLANGE SEALANT 5	OML EA	1.0	\$24.31	\$24.31
	SS-10	Shop Supplies		1.0	\$36.75	\$36.75
		Та	sk 1 Subtotals	Parts:		\$27.31
				Labor:		\$367.50
				Miscellaneous:		\$36.75
				Task 1 Subtotals		\$431.56

Task: 2 16-000-056 Truck/Bus Cab Rear Mount Insulator/Cushion - R/R

Department: Service

Department: Service

Complaint: REPLACE BOTH REAR

Correction: REM FENDERS & UNBOLT MOUNT, LIFT ENGINE & REPL MOUNTS, REINSTALL FENDERS

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SS-10	Shop Supplies	· · · · · ·	1.0	\$26.46	\$26.46
			Task 2 Subtotals	Parts:		\$0.00
				Labor:		\$264.60
				Miscellaneous:		\$26.46
				Task 2 Subtotals		\$291.06

19-000-098 Truck HVAC Cabin/Fresh Air Filter - R/R

Correction: REPL CABIN AIR FILTER & VACUUM OUT EXCESSIVE DUST

•		
		Extend
	Price	D-1

Department: Service

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
MICRON	IN0201P	CAB FLTR 03-05 42/43/76/8600	EA	1.0	\$23.00	\$23.00
	SS-10	Shop Supplies		1.0	\$7.35	\$7.35
		٦	ask 3 Subtotals	Parts:		\$23.00
				Labor:		\$73.50
				Miscellaneous:		\$7.35
				Task 3 Subtotals	·	\$103.85

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$41.32 \$49.59 Total: \$90.91

Total Parts: \$50.31 **Total Labor:** \$705.60 **Total Miscellaneous:** \$70.56

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700

Fax: 306-721-3993

** Reprint **

Invoice: 1

Date / Hour: 12/15/2020 4:07:29PM

Repair Order: 4649 Customer: 00104 Branch: R

Total Invoice: \$ 917.38

Page 2 of 2

Bill To:

Ship To:

Customer P/O: Open Date: 12/15/2020 Completion Date: 12/15/2020 Add User: emclaughlin Salesperson: PartsDefault **Invoice Subtotal:** \$826.47 **Total Tax:** \$90.91 **Total Invoice:** \$917.38 Payment Method <u>Terms</u> **Due Date** 01 COD ***9 - Visa -12/16/2020

-Remit To-

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 306-721-3993

** Reprint **

Invoice:

Date / Hour: 11/10/2021 11:47:29AM

Repair Order: 8155 Customer: 00104 Branch: R

Total Invoice: \$ 1,255.69

2 - Cash

Page 1 of 1

Bill To:

Ship To:

Office Phone:

Work:

Customer P/O:

Type: Gravel

Model Year: 2008

Open Date: 11/08/2021

Completion Date: 11/10/2021

Department: Service

Salesperson: PartsDefault

Unit Number: 8925

Add User: fmonkhouse

Make/Model: International 7500 6x4

VIN: 1HTWPAZTO8J578925 Meter: 149298 Kilometers

Task: 12-000-001 Diagnose/Inspect - Truck/Bus Engine System* Complaint: TOWED IN WITH COMPLAINT OF NO START - TOW TRUCK DRIVER SAID UNIT STARTED

Cause: UNIT STARTED THEN DIED

CHECK FOR FAULT CODES ICP NOT BUILDING

REM INTAKE ASSY AND FND CONNECTOR TERMINAL SPREAD

Correction: REM AND REPL WITH NEW CONNECTOR

RECHECK OPERATION-OK

REINSTALL INTAKE, FENDER AND CLEARED CODE

ROAD TEST

CRANK DAMPNER COMING APART AND CODE FOR EOT SENSOR ACTIVE

ADV CUSTOMER

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	2501107C1	CONNECTOR INJ CTRL REG & SEN	EA	1.0	\$56.10	\$56.10
GROTE	83-2150-1	SHRINKABLE BUTT CON,(EACH)	EA	2.0	\$0.75	\$1.50
	ETC<	Electronic Tool Charge		1.0	\$95.00	\$95.00
	SS-10	Shop Supplies		1.0	\$49.50	\$49.50
	Sub	TOWING		1.0	\$434.15	\$434.15

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$67.88 \$124.44 Total:

Total Parts: \$57.60 **Total Labor:** \$495.00 **Total Miscellaneous:** \$578.65

Invoice Subtotal: \$1,131.25 **Total Tax:** \$124.44

Total Invoice: \$1,255.69

Payment Method ***2 - Cash***

Terms 01 COD **Due Date** 11/11/2021

\$56.56

-Remit To -

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Flenderson Drive

Regina, SK S4P 3C2

Phone: 306-721-9700

306-721-3993

** Reprint ** Invoice

Date / Hour: 2/2/2022 10:49:56AM

Repair Order: 8932 Customer: 00104

Branch: R

Total Invoice: \$ 5,246.54

***7 - Mastercard - ____

Page 1 of 3

	_
Bill	To:

Fax:

Ship To: U.L.

Customer P/O:

Type: Gravel

Unit Number: 8925

Add User: fmonkhouse

Open Date: 01/17/2022

Completion Date: 01/31/2022

\$260.00

Department: Service

Department: Service

Salesperson: PartsDefault

Model Year: 2008

VIN: 1HTWPAZTO8J578925

Make/Model: International 7500 6x4

Meter: 242547 Kilometers

Task 1 Subtotals

ECM Reading: 7029

12-000-001 Diagnose/Inspect - Truck/Bus Engine System*

Complaint: ADVISE CAUSE ROUGH RUNNING

Cause: PERFORM DIAG AND CK FOR FAULT CODES

PERFORM CYL CUT OUT TEST AND

RELATIVE COMPRESSION TEST FND #6 -2- & 3 LOW

VALVE COVER WILL HAVE TO COME OFF

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	ETC<	Electronic Tool Charge	404 404 405	1.0	\$95.00	\$95.00
	SS-10	Shop Supplies		1.0	\$15.00	\$15.00
			Task 1 Subtotals	Parts:		\$0.00
				Labor:		\$150.00
				Miscollaneous:		\$110.00

Truck/Bus Engine Valve Cover/Gasket - R/R* 12-000-171

Complaint: R AND R VALVE COVER TO ASSESS CAUSE OF LOW COMPRESSION

Cause: INJECTOR PLUGGED

THEN FOUND DIRT IN PIPING-TURBO DAMAGED

Correction: 1/26/2022 8:39:28 AM 1501 suspected carn failure-remove splash gaurd, intake piping and filter, blow by tube, valve cover,

remove oil rail, rocker arms and push tubes, inspect all, no damage found, drain oil and remove pan, cam looks to be in good shape, call customer and previous shop and try to figure out recent history, cut open filter and look for filings, none, clean up and reinstall pan, inststall rocker arms and see if any are loose or tight all seem ok, crank engine and make sure all moving as should, do overhead set, reassemble, run truck, ran good till warm, then had noise, unplug each injector and run truck, noise goise away when #3 injector unplugged, order injector, has closed crankcase system, go to make open and find elbow broken, dirt in piping and turbo damaged

1/31/2022 2:25:56 PM 1501 get go ahead for injector, order, reassemble and take out, bring back in remove intake piping, valve

cover, oil rail, replace injector, reassemble, check and replace air filter, road test, noise gone,

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	1836197C1	GASKET OIL PAN	EA	1.0	\$343.64	\$343.64
NI	1842626C96	KIT, HP OIL RAIL SEALS	EA	1.0	\$162.04	\$162.04
NI	3532801C1	ELEMENT AIR CLEANER PRIMARY	EA	1.0	\$171.64	\$171.64
GROTE	85-6021	11 1/2WRAP TIE BLACK (PKG)	EA	2.0	\$3,31	\$6.62
IRVBLK	F0114360	10W30 IDO PREM + SYN BLEND OIL (TOTE	CK² EA	32.0	\$4,39	\$140.48
	OIL-BULK	EHC Oil - 1 Litre Bulk		1.0	\$1.60	\$1.60
FG	LF9025	FILTER-LUBE OIL	EA	1.0	\$88.73	\$88.73
	FILTER>8"	EHC Filter - Greater Than 8"		1.0	\$1.00	\$1.00
	Freight	Parts Freight		1.0	\$0.00	\$-

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 2/2/2022 10:49:56AM

Repair Order: 8932 Customer: 00104 Branch: R

Total Invoice: \$ 5,246.54

ard -

Page 2 of 3

Bill To:

Ship To:

ustomer P/O:		Open Date: 0	1/17/2022	Completion Date:	01/31/2022
Add User: fmonkhouse		Salesperson: P	artsDefault		
Freight	Parts Freight		1.0	\$106.97	\$106.97
SS-10	Shop Supplies		1.0	\$243.00	\$243.00
		Task 2 Subtotals	Parts:		\$913.15
			EHC:		2.60
	The same of the sa		Labor:		\$2,430.00
			Miscellaneous:		\$349.97
			ask 2 Subtotals		3,695.72

Task: 3 12-000-243 Truck/Bus Engine Open Breather Conversion - R/R

Department: Service

Department: Service

Complaint: INSTALL NEW TURBO ELBOW AND MODIFY TO OPEN CC BREATHER KIT.

CLEAN OUT INTAKE PIPING OF FOREIGN DEBRIS

Correction: 1/31/2022 2:29:03 PM 1501 wash out intake piping, replace elbow at turbo and block off brether elbow, remove pipe at breather and turn down,

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
BF	109-D	PLUG SQ.HEAD 1/2P	EA	1.0	\$1.64	\$1.64
BF	110-ED	BUSHING,3/4P-1/2P	EA	1.0	\$2.15	\$2.15
BF	HC6-16	STANDARD GEAR CLAMP	EA	2.0	\$0.72	\$1.44
	SS-10	Shop Supplies		1.0	\$28.50	\$28.50
			Task 3 Subtotals	Parts:		\$5.23
				Labor:		\$285.00
				Miscellaneous:		\$28.50
				Task 3 Subtotals		\$318.73

Task: 4 16-000-137 Truck Cab Windshield Glass - R/R*

Complaint: REPLACE WINDSHIELD

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	Shop	URETHANE		2.0	\$15.00	\$30.00
	SS-10	Shop Supplies		1.0	\$16.00	\$16.00
	Sub	WINDSHIELD		1.0	\$246.30	\$246.30
			Task 4 Subtotals	Parts:		\$0.00
				Labor:		\$160.00
				Miscellaneous:		\$292.30
				Task 4 Subtotals		\$452.30

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$283.45 Total: \$519.79

\$236.34

Total Parts:	\$918.38
Total EHC:	\$2.60
Total Labor:	\$3,025.00
Total Miscellaneous:	\$780.77

475'Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice: Date / Hour: 2/2/2022 10:49:56AM

Repair Order: 8932 Customer: 00104 Branch: R

Total Invoice: \$5,246.54

ard -

Page 3 of 3

Bill To:

Ship To.

Customer P/O:

Add User: fmonkhouse

Open Date: 01/17/2022

Completion Date: 01/31/2022

Salesperson: PartsDefault

Invoice Subtotal:

\$4,726.75

Total Invoice:

\$519.79 \$5,246.54

Payment Method

***7 - Mastercard -

Terms 01 COD Due Date 2/3/2022

-Remit To -

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

Herriic 10

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 NO8-I

** Reprint **

Invoice:

Date / Hour: 8/18/2022 10:28:34AM

Repair Order: 11116 Customer: 00104 Branch: R

Total Invoice: \$ 1,458.68

***7 - Mastercard - _____

Page 1 of 2

Bill To:

Ship To:

Office Phone:

Work: !

Customer P/O:

Type: Gravel

Open Date: 08/15/2022

Completion Date: 08/18/2022

\$497.12

Add User: fmonkhouse Salesperson: PartsDefault

Unit Number: 8925

Model Year: 2008

Make/Model: International 7500 6x4

VIN: 1HTWPAZTO8J578925

Meter: 250318 Kilometers

ECM Reading: 7209

Task: 1 12-000-124 Truck/Bus Engine Oil Dipstick Tube/Gasket - R/R

Department: Service

Complaint: Reinstall dipstick tube

Correction: BRING TRUCK INTO SHOP

REM SPLASH GUARD, INTAKE & INTAKE BOX. REM OLD DIPSTICK AND FND IT WAS BROKEN - ORDER PARTS

REASSY & TAKE TRUCK OUT

BRING TRUCK BACK IN AND INSTALL NEW DIPSTICK TUBE AND SEAL

ADDED OIL

WASHED TRUCK TOP UP COOLANT

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
NI	1812559C1	SEAL, OIL DIPSTICK TUBE	EA	1.0	\$20.36	\$20.36
NI	3613268C2	TUBE, ENGINE OIL FILL	EA	1.0	\$320.79	\$320.79
NEMCO	5147-004	ANTIFREEZE HD ESI (N)OAT NITRITE RED 4L JG	50 EA	1.0	\$12.10	\$12.10
	AF-PRE-JUG	EHC Anti-Freeze Premix - 4 Litre		1.0	\$0.96	\$0.96
NI	690835C1	CLAMP, OIL FILLER TUBE	EA	1.0	\$20.86	\$20.86
MICRON	IN0201P	FILTER, CAB 03-05 42/43/76/8600	EA	1.0	\$20.95	\$20.95
CHVNBK	ZJB257000990	10W30 SYNBLND CK4 BULK	EA	18.0	\$5.67	\$102.06
	OIL-BULK	EHC Oil - 1 Litre Bulk		1.0	\$0.90	\$0.90
	Freight	Parts Freight		1.0	\$48.00	\$48.00
	SS-10	Shop Supplies		1.0	\$69.75	\$69.75

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$78.74 Total: \$144.45

Total Latter	¥ 14111
Total EHC:	\$1.86
Total Labor:	\$697.50
Total Miscellaneous:	\$117.75
Invoice Subtotal:	\$1,314.23
Total Tax:	\$144.45
Total Invoice:	\$1,458.68

Total Parts:

Payment Method

***7 - Mastercard -

Terms 01 COD Due Date 8/19/2022

\$65.71

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 8/18/2022 10:28:34AM

Repair Order: 11116 Customer: 00104 Branch: R

Total Invoice: \$ 1,458.68

ard - _

Page 2 of 2

Bill To:

Ship To:

Office Phone:

Work:

Customer P/O:

Add User: fmonkhouse

Open Date: 08/15/2022

Completion Date: 08/18/2022

Salesperson: PartsDefault

-Remit To-

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993

** Reprint **

Invoice:

Date / Hour: 5/7/2024 12:05:16PM

Repair Order: 16718 Customer: 00104

Branch: R

Total Invoice: \$ 1,663.46

2 - Cash

Page 1 of 1

Bill To:

Ship To:

Office Phone

Work:

Customer P/O:

Add User: jrathgaber1

Unit Number: 8925

Type: Gravel

Model Year: 2008

VIN: 1HTWPAZTO8J578925

Open Date: 05/03/2024

Completion Date: 05/07/2024

Price

\$736.36

\$52.50

Salesperson: PartsDefault

Make/Model: International 7500 6x4

Meter: 167864 Kilometers

Task: 12-000-001 Diagnose/Inspect - Truck/Bus Engine System*

Complaint: TOWED IN, ENGIDIES AFTER RUNNING FOR A FEW MINUTES - ADVISE ON REPAIR

Correction: GET ENGINE RUNNING-FOUND IPR IS CUTTING OUT

REPLACE IPR AND PIGTAIL

ROAD TEST ALL OK

1878629C95

2501107C1

83-3150-1

ETC<

SS-10

Part

Electronic Tool Charge

\$74.93

Shop Supplies

Description / Ref Number
KIT, IPR VALVE W/CONN SEAL
CONNECTOR, IPR VALVE PIGTAIL

Hs Butt, Poly, 22-18 Ga, PER PIECE

U/M	Quantity
EA	1.0
EA	1.0

EΑ

\$88.55	\$88.55	1.0
\$1.20	\$0.60	2.0
\$95.00	\$95.00	1.0

Department: Service

GST/HST Number:

Detail Tax Info:

Supp.

GROTE

NI

NI

GST 89362 3934 RT SK PST

\$89.92 \$164.85 Total:

Total Parts: Total Labor: Total Miscellaneous:

\$826.11 \$525.00 \$147.50

Extended

\$736.36

\$52.50

Price Price

Invoice Subtotal: Total Tax:

1.0

\$1,498.61 \$164.85

Total Invoice:

\$1,663.46

Payment Method ***2 - Cash***

<u>Terms</u> 01 COD **Due Date** 5/8/2024

Remit To -

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993

** Reprint **

Invoice:

Date / Hour: 2/20/2025 4:18:03PM

Repair Order: 18818 Customer: 00104 Branch: R

Total Invoice: \$ 1,815.67

***7 - Mastercard - _____

Page 1 of 4

Bill To:

Ship To:

Customer P/O:

Add User: tbeedle

Salesperson: PartsDefault

Open Date: 01/31/2025

Completion Date: 02/05/2025

Evtended

Unit Number: 8925

Model Year: 2008

VIN: 1HTWPAZTO8J578925

Make/Model: International 7500 6x4

Department: Service

Type: Gravel

Meter: 281958 Kilometers

ECM Reading: 7942

Task: 1 12-000-001 Diagnose/Inspect - Truck/Bus Engine System*

Complaint: ADVISE CAUSE UNIT RUNS FINE COLD, ROUGH WHEN HOT

Correction: CK CODES, REPL CONNECTOR ON OIL TEMP SENSOR, CLEAR CODES

Supp.	Part	Description / Ref Number U/M Quantity	Price	Extended Price
GROTE	83-3150-1	Hs Butt, Poly, 22-18 Ga, PER PIECE EA 2.0	\$0.60	\$1.20
	ETC<	Electronic Tool Charge	\$95.00	\$95.00
	Shop	TXT126870106 1.0	\$7.94	\$7.94
	Shop	TXT126870125 2.0	\$4.52	\$9.04
	SS-10	Shop Supplies 1.0	\$43.75	\$43.75
		Task 1 Subtotals Parts: Labor: Miscellaneous:		\$1.20 \$437.50 \$155.73
		Task 1 Subtotals		\$594.43

Conkatahawan Cafatu Inangation Task: 2 92-000-003

Complaint: SAFETY

Correction: Perform Sask safety inspection

Saskatchewan Safety Inspection - Fractor	Department: Service

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
	DotFee	DOT Decal Fee		1.0	\$20.00	\$20.00
	SS-10	Shop Supplies		1.0	\$24.40	\$24.40
			Task 2 Subtotals	Parts: Labor; Miscellaneous:		\$0.00 \$244.00 \$44.40
				Task 2 Subtotals		\$288.40

17-000-007 Truck/Bus Wheel Torque Indicator - R/R

Complaint: RETORQUE RIGHT FRONT

Correction: TORQUE RT FRT WHEEL

Supp.	Part	Description / Ref Number	U/M_	Quantity	Price	Extended Price
	SS-10	Shop Supplies		1.0	\$3.50	\$3.50
			Task 3 Subtotals	Parts:		\$0.00
				Labor:		\$35.00
				Miscellaneous:		\$3.50
				Task 3 Subtotals		\$38.50

16-000-153 Truck/Bus Cab Sunvisor Check Or Clip - R/R

Complaint: RIGHT SUN VISOR CLIP MISSING

Department: Service

Department: Service

** See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice.

Date / Hour: 2/20/2025 4:18:03PM

Repair Order: 18818 Customer: 00104 Branch: R

Total Invoice: \$ 1,815.67

ard - ___

Page 2 of 4

Department: Service

Department: Service

Department: Service

Bill To:

Ship To:

Customer P/O: Add User: tbeedle			Open Date: 01/31/2025 Salesperson: PartsDefault		Completion Date: 02/05/2025	
Correcti Supp.	on: INSTALL MISSING I	NSERT & INSTALL RT VISOR Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	4058906C1	FASTENER, M6 SPEED	EA	2.0	\$4.86	\$9.72
	SS-10	Shop Supplies		1.0	\$8.75	\$8.75
		REPI	Task 4 Subtotals	Parts: Labor: Miscellaneous: Task 4 Subtotals		\$9.72 \$87.50 \$8.75 \$105.97

Task: 5 19-000-141 Truck/Bus Windshield Wiper Blade(s) - R/R

Complaint: WIPER BLADES WORN

Correction: REPL BOTH WIPER BLADES

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended
FLTWB	FLTS22	STANDARD 22IN WIPER BLADE	EA	2.0	\$5.59	\$11.18
	SS-10	Shop Supplies		1.0	\$5.25	\$5.25
		Task 5	Subtotals	Parts:		\$11.18
				Labor:		\$52.50
				Miscellaneous:		\$5.25
				Task 5 Subtotals	·- ·	\$68.93

Task: 6 04-000-003 Truck/Bus Brake Minor Maintenance - RTR*

Complaint: DASH VALVE LOOSE

Correction: TIGHTEN LOOSE SCREWS

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	SS-10	Shop Supplies		1.0	\$5.25	\$5.25
			Task 6 Subtotals	Parts:		\$0.00
				Labor:		\$52.50
				Miscellaneous:		\$5.25
				Task 6 Subtotals	•	\$57.75

Task: 7 08-000-043 Truck/Bus Clearance/Marker Light - R/R*

Complaint: REAR BOX LIGHT OUT

Correction: REPL LIGHT, PIGTAIL & REPAIR CORRODED WIRING

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
GROTE	45832-3	LAMP,2 1/2ROUND RED, W/REFL	ECTOR EA	1.0	\$3.36	\$3.36
GROTE	67050-3	PIGTAIL, SEALED MARKER	EA	1.0	\$1.65	\$1.65
GROTE	83-3350-1	Hs Butt, Poly 16-14 GA ea.	EA	2.0	\$0.61	\$1.22
	SS-10	Shop Supplies		1.0	\$14.00	\$14.00
		Ta	sk 7 Subtotals	Parts:		\$6.23
				Labor:		\$140.00
				Miscellaneous:		\$14.00

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

** Reprint **

Invoice

Date / Hour: 2/20/2025 4:18:03PM

Repair Order: 18818 Customer: 00104 Branch: R

Total Invoice: \$ 1,815.67

ard - ___

Page 3 of 4

Bill To:

Ship To

Add User: tbeedle				n Date: 01/31/2025	Completion Date	
	Add User: tbeedle		Salesp	erson: PartsDefault		
				Task 7 Subtota	ls	\$160.23
Task: 8 05-000-0 Complaint: LEAK AT P/S F Correction: REPL GASKET	RES	s Power Steering Reservo	ir - R/R	De	partment: Servi	ce
Supp. Part		Description / Ref Number		Quantity	Price	Extende Prio
NI 2507061C1	111	GASKET, RESERVOIR CAP	CANISTER EA	1.0	\$32.78	\$32.78
SS-10	100	Shop Supplies	ALL DE DE	1.0	\$5.25	\$5.25
			Task 8 Subtotals	Part Labo		\$32.78 \$52.50
				Miscellaneou	s:	\$5.25
				Task 8 Subtota	ls	\$90.53
Task: 9 03-000-0	06 Truck/Bu	s (S/S) Aux Air Spring Dun	np Valve - R/R	De	partment: Servi	ce
		NG AND HAS CODE FOR DUMP S IS TIME	SOLENOID			
Correction: CUST DECLIN		S TIME Description / Ref Number	U/M	Quantity	Price	Pric
Correction: CUST DECLIN		IS TIME	U/M	1.0	\$21.00	Pric \$21.00
Correction: CUST DECLIN		S TIME Description / Ref Number			\$21.00 s:	\$21.00 \$0.00
Correction: CUST DECLIN		S TIME Description / Ref Number	U/M	1.0 Part	\$21.00 s: or:	Pric \$21.00
Correction: CUST DECLIN Supp. Part		S TIME Description / Ref Number	U/M	1.0 Part Labo	\$21.00 s: or: s:	\$21.00 \$0.00 \$210.00
Correction: CUST DECLIN Supp. Part		S TIME Description / Ref Number	U/M	1.0 Part Labo Miscellaneou	\$21.00 s: or: s:	\$21.00 \$0.00 \$210.00 \$210.00
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info:		S TIME Description / Ref Number	U/M	1.0 Part Labo Miscellaneou Task 9 Subtotal	\$21.00 s: or: s:	\$210.00 \$21.00 \$231.00
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info: GST 89362 3934 RT		Description / Ref Number Shop Supplies	U/M	1.0 Part Labo Miscellaneou	\$21.00 s: or: s:	\$21.00 \$0.00 \$210.00 \$210.00 \$231.00 \$61.11
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info:	ED REPAIR AT TH	Description / Ref Number Shop Supplies \$81.79 \$98.14	U/M Task 9 Subtotals	1.0 Part Labo Miscellaneou Task 9 Subtotal	\$21.00 s: or: s: s:	\$21.00 \$0.00 \$210.00 \$210.00 \$231.00
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info: GST 89362 3934 RT		Description / Ref Number Shop Supplies \$81.79 \$98.14	U/M Task 9 Subtotals	1.0 Part Labo Miscellaneou Task 9 Subtotal Total Parts Total Labor stal Miscellaneous Invoice Subtotal	\$21.00 s: or: s: s: s: \$	\$21.00 \$0.00 \$210.00 \$210.00 \$231.00 \$61.11 1,311.50 \$263.13
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info: GST 89362 3934 RT	ED REPAIR AT TH	Description / Ref Number Shop Supplies \$81.79 \$98.14	U/M Task 9 Subtotals	1.0 Part Labo Miscellaneous Task 9 Subtotal Total Parts Total Labor stal Miscellaneous Invoice Subtotal	\$21.00 s: or: s: ds	\$21.00 \$21.00 \$210.00 \$210.00 \$231.00 \$231.00 \$61.11 1,311.50 \$263.13 1,635.74 \$179.93
Correction: CUST DECLIN Supp. Part SS-10 GST/HST Number: Detail Tax Info: GST 89362 3934 RT	ED REPAIR AT TH	Description / Ref Number Shop Supplies \$81.79 \$98.14	U/M Task 9 Subtotals	1.0 Part Labo Miscellaneou Task 9 Subtotal Total Parts Total Labor stal Miscellaneous Invoice Subtotal	\$21.00 s: or: s: ds	\$21.00 \$0.00 \$210.00 \$210.00 \$231.00 \$61.11 1,311.50 \$263.13

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice

Date / Hour: 2/20/2025 4:18:03PM

Repair Order: 18818 Customer: 00104 Branch: R

Total Invoice: \$ 1,815.67

ard - _

Page 4 of 4

Bill To:

Ship To:

Customer P/O:

Add User: tbeedle

Open Date: 01/31/2025

Completion Date: 02/05/2025

Salesperson: PartsDefault



I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 N08-1

** Reprint **

Invoice:

Date / Hour: 3/11/2025 3:36:20PM

Repair Order: 19197 Customer: 00104 Branch: R

Total Invoice: \$802.67

2 - Cash

Page 1 of 1

Bill To:

Ship To:

Open Date: 03/11/2025

Salesperson: PartsDefault

Customer P/O:

Type: Gravel

Unit Number: 8925

Add User: emclaughlin

Completion Date: 03/11/2025

Department: Service

mclaughlin

Model Year: 2008

Make/Model: International 7500 6x4

VIN: 1HTWPAZTO8J578925

Meter: 175250 Kilometers

Task: 1 03-000-003 Truck/Bus (S/S) Minor Maintenance - RTR*

Complaint: REAR AIR SUSP CONTINUALLY DUMPING SEE BOYD

Cause: CK CODES. FOUND SUSPENSION DUMP SOLENOID A OPEN

Correction: REPL SOLENOID, FOUND SWITCH NOT WORKING. MOVE SWITCH TO AN OPEN SPOT. PROGRAM & CK OPERATION, GOOD.

Supp.	Part		Price	Extended Price
NI	2506712C91	KIT, AIR BRAKE SOLENOID (NO) EA 1.0 \$16	4.87	\$164.87
	SS-10	Shop Supplies 1.0 \$5	0.75	\$50.75

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST

\$43.39 Total: \$79.55 Total Parts: \$164.87
Total Labor: \$507.50
Total Miscellaneous: \$50.75
Invoice Subtotal: \$723.12
Total Tax: \$79.55
Total Invoice: \$802.67

Payment Method
2 - Cash

Terms 01 COD <u>Due Date</u> 3/12/2025

\$36.16

-Remit To-

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 NO8-7

** Reprint **

Invoice:

Date / Hour: 6/27/2025 9:27:29AM

Repair Order: 20066 Customer: 00104

Branch: R Total Invoice: \$7,446.09

***7 - Mastercard - ___

Page 1 of 2

Bill To:

Ship To:

Customer P/O:

Type: Gravel

Add User: plaiwani

Open Date: 06/13/2025

Completion Date: 06/27/2025

Salesperson: PartsDefault

Unit Number: 8925

Model Year: 2008

Make/Model: International 7500 6x4

Meter: 284590 Kilometers

ECM Reading: 8048

Task: 1 12-000-001 Diagnose/Inspect - Truck/Bus Engine System*

Department: Service

Complaint: Towed in was running rough now not at all, LP fuel pump replaced core on pass seat to be returned to Marcel

Correction: 6/27/2025 8:27:03 AM 1548 Removed valve cover and removed wiper cowl, Removed high pressure oil rail and changed out o rings. Changed out injector 4 beacuse of engine miss and reasmbled. Ran truck outside and got hot. Truck doesnt start hot. Removed valve cover again and install pressure test tool. Found all injectors leaking so customer only wanted to change the two worst ones. Changed out injectors 2,5 and reinstalled rail again and wiper cowl and brackets on valve cover. Tied up wires. Ran truck. Had to bleed fuel system as was losing prime. Found damaged fuel filter in fuel filter housing. Ran truck again and test drove. Truck cranks for a few seconds but then starts.

VIN: 1HTWPAZTO8J578925

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	1812348C1	SLEEVE, 3/8 TUBE -FLEX	EA	3.0	\$9.50	\$28.50
NI	1842626C96	KIT, HP OIL RAIL SEALS	EA	1.0	\$238.62	\$238.62
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EA	-1.0	\$395.93	\$(395.93)
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EΑ	-2.0	\$403.18	\$(806.36)
N1	5010823R91	KIT, FUEL INJECTOR (DT570)	EA	1.0	\$881.33	\$881.33
N1	5010823R91	KIT, FUEL INJECTOR (DT570)	EA	2.0	\$881.00	\$1,762.00
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EA	1.0	\$395.93	\$395.93
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EA	2.0	\$403.18	\$806.36
FG	FS19947	FILTER-FUEL/WATER SEPARATOR	EA	1.0	\$150.02	\$150.02
	FILTER<8"	EHC Filter - Less Than 8"		1.0	\$0.55	\$0.55
	ETC<	Electronic Tool Charge		1.0	\$95.00	\$95.00
	Freight	Parts Freight		1.0	\$140.00	\$140.00
	SS-10	Shop Supplies		1.0	\$310.20	\$310.20

GST/HST Number:

Detail Tax Info:

GST 89362 3934 RT SK PST \$335.41 \$402.46 Total: \$737.87

Total Parts: \$3,060.47 **Total Core Charge:** \$1,202.29 **Total Core Ret:** \$(1,202.29) **Total EHC:** \$0.55 Total Labor: \$3,102.00 **Total Miscellaneous:** \$545.20 Invoice Subtotal: \$6,708.22 **Total Tax:** \$737.87 **Total Invoice:** \$7,446.09

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700

Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 6/27/2025 9:27:29AM

Repair Order: 20066 Customer: 00104 Branch: R

Total Invoice: \$7,446.09

ard - _

Page 2 of 2

Bill To:

Ship To:

Customer P/O: Open Date: 06/13/2025 Completion Date: 06/27/2025 Add User: plalwani Salesperson: PartsDefault Payment Method Terms Due Date ***7 - Mastercard -01 COD 6/28/2025 Remit To-Maxim Truck & Trailer 475 Henderson Drive Regina, SK S4P 3C2

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 306-721-3993 Fax:

** Reprint **

Invoice:

Date / Hour: 7/22/2025 12:41:00PM

Repair Order: 20289 Customer: 00104

Branch: R

Total Invoice: \$ 4,716.09

2 - Cash

Page 1 of 3

Bill To:

Ship To:

Customer P/O:

Type: Gravel

Open Date: 07/11/2025

Completion Date: 07/18/2025

Salesperson: PartsDefault

Add User: rstaub Unit Number: 8925

Model Year: 2008

Make/Model: International 7500 6x4

VIN: 1HTWPAZTO8J578925

Meter: 286086 Kilometers

ECM Reading: 8085

Task: 12-000-084 Truck/Bus Engine Fuel Injector (Electronic) - R/R*

Department: Service

Complaint: REPLACE 3 INJECTORS NO. 1,3 AND 6

Correction: 7/18/2025 1:31:11 PM 1548 Removed high pressure oil line and hooked up pressure test tool. Removed wiper cowl and moved wiring harness off to the side, removed air intake pipe and filter housing. Removed valve cover and removed injector harness off to the side. Found injectors leaking. Removed high pressure oil rail and changed o rings. Changed out 3 injectors and torqed. Torqed rail back into place. Torqed valve cover and reinstalled wiper cowl and installed high pressure oil line back onto head. Washed

engine and cleared codes. Test drove. Truck now starts hot.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EA	-2.0	\$403.17	\$(806.34)
N1	5010823R91	KIT, FUEL INJECTOR (DT570)	EA	2.0	\$881.00	\$1,762.00
N1	5010823R91-C	CORE, INJECTOR ASSY REMAN	EA	2.0	\$403.17	\$806,34
	SS-10	Shop Supplies		1.0	\$51.15	\$51.15
		Task	k 1 Subtotals	Parts:		\$1,762.00
				Core Chg:		\$806.34
				Core Ret:		(\$806.34)
				Labor:		\$511.50
				Miscellaneous:		\$51.15
				Task 1 Subtotals		\$2,324.65

Task: 2 Heat, A/C, Wipers & Seats Minor Maintenance - RTR* 19-000-003

Department: Service

Complaint: HEATER FAN NOT WORKING

Correction: REPLACE BLOWER MOTOR, REP POWER & GROUND TO BLOWER MOTOR, REPLACE FUSE TERMINAL

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
FLTMS	FLTBM3542611	MOTOR, HEATER BLOWER	EA	1.0	\$195.29	\$195.29
	SS-10	Shop Supplies		1.0	\$16.92	\$16.92
			Task 2 Subtotals	Parts:		\$195.29
				Labor:		\$169.20
				Miscellaneous:		\$16.92
				Task 2 Subtotals		\$381.41

Task: 3 04-000-003 Truck/Bus Brake Minor Maintenance - RTR*

Department: Service

Complaint: LOW AIR ALARM GOING OFF

Correction: FIND & TEST BOTH SENSORS SWITCH SENSORS, INSTALL NEW PINS AT BODY CONTROLLER, INSTALL & PROGRAME TEST BODY CONTROL GAUGE WORKS, REINSTALL OLD BODY CONTROL GAUGE NOT WORKING

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
NI	3522073C1	TERMINAL, CABLE FEMALE	EA	2.0	\$5.45	\$10.90
	SS-10	Shop Supplies		1.0	\$58.28	\$58.28

^{**} See Last Page for Invoice Total **

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 7/22/2025 12:41:00PM

Repair Order: 20289 Customer: 00104 Branch: R

Total Invoice: \$ 4,716.09

2 - Cash

Page 2 of 3

Bill To:

Ship To: _...

Customer P/O:	Open Date:	Open Date: 07/11/2025		
Add User: rstaub	Salesperson:	Salesperson: PartsDefault		
	Task 3 Subtotals	Parts:	\$10.90	
		Labor:	\$582.80	
		Miscellaneous:	\$58.28	
		Task 3 Subtotals	\$651.98	

Task: 4 12-000-163 Truck/Bus Engine Water Pump Housing/Gasket - R/R*
Complaint: WATER PUMP LEAKING

Department: Service

Correction: FOUND WATER PUMP LEAKING AT WHEEP HOLE, DRAINED COOLANT AND REMOVED FAN BELT, REMOVED WATER PUMP, CLEANED MOUNTING SURFACE CHANGED OVER PULLEY, INSTALLED FAN BELT, FILLED COOLANT AND WASHED OFF ENGINE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
BF	241-B	DRAIN COCK,1/4P	EA	1.0	\$11.31	\$11.31
NEMCO	5147-004	AF HD ESI (N)OAT NITRITE 50/50 R	ED 4 JUG	1.0	\$12.26	\$12.26
	AF-PRE-JUG	EHC Anti-Freeze Premix - 4 Litre		1.0	\$1.04	\$1.04
PREST	74055	PRESTONE HD ELC 50/50 3.78L	EA	2.0	\$21.96	\$43.92
	AF-PRE-JUG	EHC Anti-Freeze Premix - 4 Litre		1.0	\$2.08	\$2.08
FLTWP	FLT1842665	WATER PUMP	EA	1.0	\$282.56	\$282.56
	SS-10	Shop Supplies		1.0	\$48.88	\$48.88
		Task	4 Subtotals	Parts:		\$350.05
				EHC:		3.12
				Labor:		\$488.80
				Miscellaneous:		\$48.88
				Task 4 Subtotals	 -	\$890.85

GST/HST Number:

GST 89362 3934 RT \$212.45 SK PST \$254.75 Total: \$467.20

Total Parts:	\$2,318.24
Total Core Charge:	\$806.34
Total Core Ret:	\$(806.34)
Total EHC:	\$3.12
Total Labor:	\$1,752.30
Total Miscellaneous:	\$175.23
Invoice Subtotal:	\$4,248.89
Total Tax:	\$467.20
Total Invoice:	\$4,716,09

Payment Method	
2 - Cash	

Terms 01 COD <u>Due Date</u> 7/23/2025

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 ** Reprint **

Invoice:

Date / Hour: 7/22/2025 12:41:00PM

Repair Order: 20289 Customer: 00104 Branch: R

Total Invoice: \$ 4,716.09 ***2 - Cash***

Page 3 of 3

Bill To:

Ship To.

Customer P/O:

Add User: rstaub

Open Date: 07/11/2025

Completion Date: 07/18/2025

Salesperson: PartsDefault

-Remit To-

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

REPRINT

I understand that all charges for parts and service work are due 30 days from the invoice date.

475 Henderson Drive Regina, SK S4P 3C2 Phone: 306-721-9700 Fax: 306-721-3993 NO8-I

** Reprint **

Invoice:

Date / Hour: 7/31/2025 2:59:37PM

Repair Order: 20366 Customer: 90098 Branch: R

Total Invoice: \$ 1,479.49

Navistar Warranty

Invoice Subtotal:

Total Invoice:

Total Tax:

\$1,409.04

\$1,479.49

\$70.45

Page 1 of 1

Bill To:

Payment Method

-Remit To -

Navistar Warranty

Maxim Truck & Trailer 475 Henderson Drive

Regina, SK S4P 3C2

Ship To:

Customer P/O:					pen Date: 07/22/202	5 Compl	etion Date	o: 07/18/2025	
Add	User: plalwani			Salesperson: Consignment Accounts					
Unit Number: 8925 Model Year: 2008				Make/Model: International 7500 6x					
Type:	Gravel		VIN: 1HTWPAZTO8J57892	.5	Meter: 286086	Kilometers			
					ECM Reading:	8085			
Task: Comple Correct	tion: REPLACED WIT SRT: SRT:	D TO START HOT, L H NEW M12-1563K A12-2158K	Engine Fuel Injector (Electro OW ICP, DIAG FIND NO 4 INJECT		THROUGH SPILL F Hours: Hours:	1.80 0.60	nt: Servi PLACED	ice	
Supp.	Part 1842626C96	A12-2802A	Description / Ref Number KIT, HP OIL RAIL SEALS	U/NEA	Hours: Quantity	0.10	Price \$170.41	Extended Price \$170.41	
N1	5010823R91-C		CORE, INJECTOR ASSY REMAN	EA	-1.0		\$287.16	\$(287.16)	
N1	5010823R91		KIT, FUEL INJECTOR (DT570)	EA	1.0		\$801.13	\$801.13	
N1	5010823R91-C		CORE, INJECTOR ASSY REMAN	EA	1.0		\$287.16	\$287.16	
Detail Tax	9362 3934 RT	Total:	\$70.45 \$0.00 \$70.45	2.50	Total F Total Core Ch Total Core Total L	arge: Ret:		\$971.54 \$287.16 \$(287.16) \$437.50	

I understand that all charges for parts and service work are due 30 days from the invoice date.

<u>Terms</u>

00 NET 30 DAYS

If not paid within 30 days, account privileges may be withdrawn, and interest charged on the past due balance at the rate of 2.33% per month and 28% per annum will be charged to my account.

Due Date

8/30/2025

Tarpco Mfg Ltd

Box 360 Avonlea SK S0H 0C0 3064364449

tarpco@sasktel.net

GST/HST Registration No.: 871355327

Business Number 871355327

INVOICE

BILL TO

INVOICE#

DATE 10/04/2025
DUE DATE 10/04/2025
TERMS Due on receipt

WORK ORDER #

14599

DATE	ACTIVITY	DESCRIPTION	N	QTY	RATE	AMOUNT		
	Services	complete 15 installed	x 96 electric Dura	1	3,620.00	3,620.00		
	Services	Less wire		1	-150.00	-150.00		
	Services	shop supplie	1	60.00	60.00			
E-transfer tarpco@sasktel.net		SUBTOTAL			3,530.00			
2% per month on all invoices over 30 days			oices over 30 days GST @ 5%			176.50		
			PST (SK) @ 6%			211.80		
TARPCO CARRIES GRAIN BAGS		3S	TOTAL			3,918.30		
			BALANCE DUE		A	,918.30		