



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Internal Used Stock No. 146334	Invoice Number: 719921
Bus Phone:	Invoice Date: 3/26/2024
Prv Phone:	Location:
	Work Order Number:
	Payment Type:
	Page: 1 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/SPRAYEROPR4045 F Internal

COMPLAINT:

01 RECONDITIONING INSPECTION SPRAYER

CORRECTION:

Engine hours: 2030
 Spray hours: 867

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,643.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$1,739.50		

/GLOPCLEANR4045 F Internal

COMPLAINT:

02 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	69.60	69.60	\$69.60	N
Labor: \$1,160.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$69.60	Sub-Total: \$1,229.60		

/120168R4045 F Internal

COMPLAINT:

03 WET SYSTEMS, INSPECT AND WINTERIZE

CORRECTION:



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Invoice Number: [REDACTED]	Invoice Date: 3/26/2024	Location: [REDACTED]	Work Order Number: [REDACTED]
Bus Phone:	Bus Phone:	Payment Type: [REDACTED]	Page: 2 of 15
Prv Phone:	Prv Phone:		

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/120168R4045 F Internal

Add John Deere Winterizer Fluid along with
 Run sprayer wet system until winterization fluid is running
 NOTE: Sprayer wet system must be completely cleaned and flushed
 IF SPRAYER HAS BOTH CARBON FIBRE AND EXACTAPPLY OPTIONS, AT END OF WINTERIZATION PROCESS ENSURE
 NOZZLE POSITIONS A AND B ARE COVERED BY NOZZLE OR A CAP FOR ALL BODIES THAT FACE UPRIGHT IN
 TRANSPORT/STORAGE POSITION. NEVER LEAVE BODY POSITION A AND B OPEN TO ELEMENTS FOR A SPRAYER THAT
 HAS BOTH OF THESE OPTIONS.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
Z0010-20L	18.9L Standard SCE Winterizer(-50 Degee)	6.00	38.95	38.95	\$233.70	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	25.95	25.95	\$25.95	N
Labor: \$432.50	Parts: \$233.70	OL&M: \$0.00	Misc: \$25.95	Sub-Total: \$692.15		

Gen4- Internal

COMPLAINT:
 04 DIAGNOSE BOOMTRAC NOT WORKING
 - INNER TWO BOOMTRAC SENSORS ARE NO GOOD

CORRECTION:
 Replaced 2 inner boom height sensors. Set sensor serial numbers in display. Tested boomtrac.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AN304552	BoomTrac Height Sensor	2.00	2,744.07	2,744.07	\$5,488.14	N
Miscellaneous	DESCRIPTION	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	25.95	25.95	\$25.95	N
Labor: \$432.50	Parts: \$5,488.14	OL&M: \$0.00	Misc: \$25.95	Sub-Total: \$5,946.59		

Gen5- Internal

COMPLAINT:
 05 REPLACE BROKEN BOOM FOLD POTENTIONMETER LINKAGE



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 3 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

Gen5- Internal

CORRECTION:

Removed broken link and installed new one. Checked boom fold calibration. Calibrated and tested boom fold.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
24M7518	Washer	2.00	0.73	0.73	\$1.46	N
AKK20497	Tie Rod Assembly	1.00	125.76	125.76	\$125.76	N
N318933	Lock Nut 1/4"	2.00	1.38	1.38	\$2.76	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.38	10.38	\$10.38	N
Labor: \$173.00		Parts: \$129.98		OL&M: \$0.00		Misc: \$10.38
						Sub-Total: \$313.36

/170639R4045 Internal

COMPLAINT:

06 REPLACE BOOM BREAKAWAY BOOMS - REMOVE BOOMS, SEND TO WELDING SHOP FOR REPAIR

CORRECTION:

Loosen breakaway tension and disconnect chain. Disconnect all hoses and electrical connectors at the breakaway. Disconnect cable. Support breakaway with forklift. Remove snap ring and breakaway pivot pin. Remove breakaway. Reassemble in reverse order.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	51.90	51.90	\$51.90	N

OL&M Charges:

<u>Description</u>	<u>Value</u>
OUTSIDE LABOUR AND MATERIAL	\$373.57
Labor: \$865.00	
Parts: \$0.00	
OL&M: \$373.57	
Misc: \$51.90	
Sub-Total: \$1,290.47	



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 4 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

GEN7- Internal

COMPLAINT:

07 BRING ENGINE EMISSION SYSTEM BACK TO OEM - NEEDS NEW DEF PUMP

CORRECTION:

The previous customer deleted the DEF system due to the DEF pump module failed. Will need to replace the DEF pump and reprogram ECU with OEM software.

Removed and replaced DEF pump. Tried to reprogram ECU but it kept failing to reprogram and saying the payload had expired. Tried using a different computer and had the same result. Used CAN wizard to make sure the ECU was communicating and it was. Tried updating the CAB and CCU controllers first and they both reprogrammed fine but ECU still failed. Looked through DTAC and couldn't find anything. Made a DTAC case and they sent an interactive solution to test the ECU. That led to needing to replace the ECU due to tampering from the delete. Removed and replaced the ECU installed software onto the new ECU. Performed lost ECU data reset. Had to remove all the exhaust shields to find the SCR part number and serial number. Cleared and checked for codes. Performed service regen and DPF differential pressure reset.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ121770	DEF Dosing Unit Pump	1.00	1,784.46	1,784.46	\$1,784.46	N
DZ121770-CR	CORE for:DEF Dosing Unit Pump	1.00	139.00	139.00	\$139.00	N
RM100131	Engine Controller Reman	1.00	3,792.44	3,792.44	\$3,792.44	N
RM100131-CR	CORE for:Engine Controller Reman	-1.00	277.00	277.00	(\$277.00)	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
FREIGHT	FREIGHT	1.00	20.00	20.00	\$20.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,866.67		Parts: \$5,438.90		OL&M: \$0.00		Misc: \$116.00
						Sub-Total: \$7,421.57

GEN8- Internal

COMPLAINT:

08 REPLACE BROKEN SHIELD UNDER THE SPRAYER

CORRECTION:



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 5 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

GEN8- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
KK21893	SHIELD	1.00	651.32	651.32	\$651.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	10.38	10.38	\$10.38	N
Labor: \$173.00		Parts: \$651.32		OL&M: \$0.00		Misc: \$10.38
						Sub-Total: \$834.70

/120076R4045 Internal

COMPLAINT:
 09 REPLACE SOLUTION TANK SIGHT TUBE

CORRECTION:
 Removed hose clamps and p-clamps. Removed sight tube and installed new one in reverse order.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
PMK010-1216	3/4" Clear PVC Bulk Hose (Per FT)	5.00	3.38	3.38	\$16.90	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.19	5.19	\$5.19	N
Labor: \$86.50		Parts: \$16.90		OL&M: \$0.00		Misc: \$5.19
						Sub-Total: \$108.59

GEN12- Internal

COMPLAINT:
 12 DIAGNOSE WINDSHIELD WASHER SYSTEM NOT WORKING

CAUSE:
 High resistance in the power wire caused the motor to burn out.

CORRECTION:
 Replaced motor and ran new power wire. Filled washer fluid and tested.



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 6 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

GEN12- Internal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
57M10217	Elec. Connector Terminal	1.00	3.72	3.72	\$3.72	N
57M11973	Elec. Connector Seal	1.00	4.32	4.32	\$4.32	N
AL228317	Pump	1.00	89.84	89.84	\$89.84	N
U46662	Electrical Connector Terminal	1.00	2.39	2.39	\$2.39	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	54.18	54.18	\$54.18	N
Labor: \$903.06		Parts: \$100.27		OL&M: \$0.00		Misc: \$54.18
						Sub-Total: \$1,057.51

/110059R4045 F Internal

COMPLAINT:
 13 CLEAN BOOM, MAIN, INLET & FOAM STRAINERS, CLEAN FLOWMETER

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	20.76	20.76	\$20.76	N
Labor: \$346.00		Parts: \$0.00		OL&M: \$0.00		Misc: \$20.76
						Sub-Total: \$366.76

/10030110R4045 F Internal

COMPLAINT:
 14 FUEL FILTER - R&R
 - WATER SEPARATOR BOWL IS FULL OF WATER

CORRECTION:

Drained fuel filter. Removed separator bowl from filter. Removed filters. Cleaned separator bowl. Installed new filters and installed separator bowl.



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 7 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/10030110R4045 F Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
DZ112918	Secondary Engine Fuel Filter (Long)	1.00	211.38	211.38	\$211.38	N
RE539465	Primary Engine Fuel Filter	1.00	168.18	168.18	\$168.18	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	2.00	1.00	1.00	\$2.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	6.53	6.53	\$6.53	N
Labor: \$108.99		Parts: \$379.56	OL&M: \$0.00	Misc: \$8.53	Sub-Total: \$497.08	

/170786R4045 Internal

COMPLAINT:
 16 R&R CENTER BOOM SECTION SHUT OFF VALVE

CORRECTION:
 Drained solution from center boom section. Cleaned dirt off of valve area. Removed valve actuator. Removed hose from valve. Removed mounting hardware and valve. Installed new valve in reverse order.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN403958	VALVE	1.00	185.84	185.84	\$185.84	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.19	5.19	\$5.19	N
Labor: \$86.50		Parts: \$185.84	OL&M: \$0.00	Misc: \$5.19	Sub-Total: \$277.53	

GEN18- Internal

COMPLAINT:
 18 DIAGNOSE HORN NOT WORKING

CAUSE:
 Horn needed to be replaced.



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 8 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

GEN18- Internal

CORRECTION:

Checked connections and they seemed good. Checked power and ground to horn and they were good (11.5V) so horn needs to be replaced. Removed and replaced horn. Tested and horn worked properly.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AL203265	Horn Assembly 113 db	1.00	90.45	90.45	\$90.45	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	20.76	20.76	\$20.76	N
Labor: \$346.00	Parts: \$90.45	OL&M: \$0.00	Misc: \$20.76	Sub-Total: \$457.21		

GEN19- Internal

COMPLAINT:

19 REPLACE MISSING LIGHT BLOCK OUT COVER IN OUTER CAB ROOF

CORRECTION:

REMOVE BIRDS NEST AND INSTALL COVER

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
L176879	Shield	1.00	25.81	25.81	\$25.81	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.19	5.19	\$5.19	N
Labor: \$86.50	Parts: \$25.81	OL&M: \$0.00	Misc: \$5.19	Sub-Total: \$117.50		

/140370R4045 F Internal

COMPLAINT:

20 CHANGE HYDRO/HYDRAULIC OIL AND FILTERS

CORRECTION:

Drained hydraulic oil. Removed filters. Cleaned sealing surfaces and installed new filters. Filled hydraulic oil.



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 9 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/140370R4045 F Internal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AN203010	Hydraulic Oil Filter	2.00	105.38	105.38	\$210.76	N
AT318160	Hydraulic Oil Filter	1.00	215.82	215.82	\$215.82	N
TY26797	18.9LT 10W30 TORQ-GARD.	5.00	155.81	155.81	\$779.05	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	5.00	3.00	3.00	\$15.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	20.76	20.76	\$20.76	N
Labor: \$346.00		Parts: \$1,205.63		OL&M: \$0.00		Misc: \$37.26
						Sub-Total: \$1,588.89

/140161R4045 F Internal

COMPLAINT:
 21 CHANGE PLANETARY HUB OILS (250HR SERVICE)

CORRECTION:

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
TY26372	946ML 80W140 GL-5 SYNTHETIC	12.00	48.38	48.38	\$580.56	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
EF100	ENVIRO FEE	12.00	1.00	1.00	\$12.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	20.76	20.76	\$20.76	N
Labor: \$346.00		Parts: \$580.56		OL&M: \$0.00		Misc: \$32.76
						Sub-Total: \$959.32

/150371R4045 Internal

COMPLAINT:



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 10 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/150371R4045 Internal
 22 REPLACE HYDRAULIC TANK FILL CAP

CORRECTION:
 Removed filler cap. Removed chain from retaining ring. Installed new chain onto retaining ring and installed new cap.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK25690	Filler Cap	1.00	77.74	77.74	\$77.74	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.07	2.07	\$2.07	N
Labor: \$34.60		Parts: \$77.74	OL&M: \$0.00	Misc: \$2.07	Sub-Total: \$114.41	

/120169R4045 F Internal
 COMPLAINT:
 23 CHANGE ENGINE OIL AND FILTER

CORRECTION:
 Drained engine oil. Replaced filter and o-ring. Filled engine oil.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
RE509672	Engine Oil Filter Cartridge	1.00	43.80	43.80	\$43.80	N
TY26673	3.78L 15W40 PLUS 50 II	1.00	35.43	35.43	\$35.43	N
TY26675	9.46L 15W40 PLUS 50 II	1.00	87.44	87.44	\$87.44	N
TY26679	18.9L 15W40 PLUS 50 II	1.00	166.52	166.52	\$166.52	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	1.00	\$1.00	N
EF300	ENVIRO FEE	1.00	3.00	3.00	\$3.00	N
EF50	ENVIRO FEE	2.00	0.50	0.50	\$1.00	N



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 11 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/120169R4045 F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	7.78	7.78	\$7.78	N	
Labor: \$129.75		Parts: \$333.19		OL&M: \$0.00		Misc: \$12.78	
				Sub-Total: \$475.72			

/110018R4045 F Internal
 COMPLAINT:
 24 REPLACE ENGINE AIR FILTERS

CORRECTION:
 Removed filters. Cleaned housing and installed new filters.



Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind	
AN403918	Primary Air Filter	1.00	276.26	276.26	\$276.26	N	
AN403919	Secondary Air Filter	1.00	240.23	240.23	\$240.23	N	
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind	
SERVACCESS	SERVICE ACCESSORIES	1.00	5.19	5.19	\$5.19	N	
Labor: \$86.50		Parts: \$516.49		OL&M: \$0.00		Misc: \$5.19	
				Sub-Total: \$608.18			

/15146R4045 F Internal
 COMPLAINT:
 25 REPLACE AIR DRYER FILTER

CORRECTION:
 Released all air pressure. Removed filter and o-ring. Cleaned sealing surfaces. Installed new o-ring and installed new filter.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AKK11031	Filter, Air Drier	1.00	286.33	286.33	\$286.33	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 12 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/15146R4045 F Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	4.15	4.15	\$4.15	N	
Labor: \$69.20		Parts: \$286.33		OL&M: \$0.00		Misc: \$4.15	
						Sub-Total: \$359.68	

/140159R4045 F Internal
 COMPLAINT:
 26 REPLACE CAB AIR FILTERS

CORRECTION:
 Left filters in the cab.



<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
RE333567	Cab Fresh Air - Activated Carbon Filter	1.00	664.60	664.60	\$664.60	N	
RE333569	Air Filter	1.00	546.95	546.95	\$546.95	N	
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
SERVACCESS	SERVICE ACCESSORIES	1.00	3.63	3.63	\$3.63	N	
Labor: \$60.55		Parts: \$1,211.55		OL&M: \$0.00		Misc: \$3.63	
						Sub-Total: \$1,275.73	

/140163R4045 F Internal
 COMPLAINT:
 27 GREASE UNIT COMPLETE INCLUDING DRIVELINE

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY6341	SD POLYUREA GREASE	1.00	10.31	10.31	\$10.31	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: [REDACTED] Invoice Date: 3/26/2024 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: [REDACTED] Page: 13 of 15
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/140163R4045 F Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	15.57	15.57	\$15.57	N
Labor: \$259.50		Parts: \$10.31	OL&M: \$0.00	Misc: \$15.57	Sub-Total: \$285.38	

GEN28- Internal
 COMPLAINT:
 28 FILL AND DIAGNOSE HYDRAULIC OIL LEAK

CAUSE:
 Rear LH wheel motor case drain line was cracked.

CORRECTION:
 Removed zip ties and hose clamps. Removed hose and installed new one. Installed all hose clamps and zip ties.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AKK34317	Hydraulic Hose	1.00	349.97	349.97	\$349.97	N
TY26797	18.9LT 10W30 TORQ-GARD.	2.00	155.81	155.81	\$311.62	N
Miscellaneous						
EF300	ENVIRO FEE	2.00	3.00	3.00	\$6.00	N
EF50	ENVIRO FEE	1.00	0.50	0.50	\$0.50	N
SERVACCESS	SERVICE ACCESSORIES	1.00	38.71	38.71	\$38.71	N
Labor: \$645.29		Parts: \$661.59	OL&M: \$0.00	Misc: \$45.21	Sub-Total: \$1,352.09	

/150336R4045 Internal
 COMPLAINT:
 29 REPLACE HYDRO MOTOR SHAFT SEAL

CAUSE:
 Wheel motor shaft seal was wore out and leaking hydraulic oil into the planetary hub.



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	Invoice Number: Invoice Date: 3/26/2024 Location: Work Order Number: Payment Type: Page: 14 of 15
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/150336R4045 Internal

CORRECTION:

Cleaned pails and drained the hydraulic oil. Drained the planetary hub. Cleaned all dirt off of wheel motor. Removed and capped all hoses on the wheel motor. Disconnected all electrical. Removed mounting bolts and wheel motor. Removed snap ring and seal spacer ring. Removed shaft seal. Cleaned up sealing surface. Installed new seal, spacer and snap ring. Cleaned up sealing surface on planetary hub. Reinstalled motor in reverse order. Cleaned up all oil.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KK13045	Seal Kit	1.00	317.44	317.44	\$317.44	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	83.04	83.04	\$83.04	N
Labor: \$1,384.00		Parts: \$317.44		OL&M: \$0.00		Misc: \$83.04
						Sub-Total: \$1,784.48

/4GMTGUPGRADER4045 Internal

COMPLAINT:

30 REMOVE 2G/3G MTG AND INSTALL NEW 4G MTG

CORRECTION:

OLD/REMOVED MTG SN# PCMAMGE800830
 NEW/INSTALLED MTG SN# PCMA4RA651753

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
021TPC	JDLink R Modem 4G	1.00	311.00	311.00	\$311.00	N
PFP16073	JD Ethernet Cable	1.00	99.00	99.00	\$99.00	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



Box 400
 Highway 6
 Raymore, SK S0A 3J0
 Phone: 306-746-2110
 www.southcountry.ca

Moose Jaw, SK 306-692-2371
 Mossbank, SK 306-354-2411
 Assiniboia, SK 306-642-3366
 Emerald Park, SK 306-721-5050
 Weyburn, SK 306-842-4686
 Southey, SK 306-726-2155
 Raymore, SK 306-746-2110
 Montmartre, SK 306-424-2212



JOHN DEERE

SERVICE INVOICE

Invoice To Account No: 0

Deliver To:

Bus Phone:
 Prv Phone:

Bus Phone:
 Prv Phone:

Invoice Number:
 Invoice Date: 3/26/2024
 Location:
 Work Order Number:
 Payment Type:
 Page: 15 of 15

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2017 JD R4045 120' HIGH CLEAR	2030	1N04045RPG0176186	1N04045RPG0176186	

/4GMTGUPGRADER4045 Internal						
SERVACCESS	SERVICE ACCESSORIES	1.00	10.00	10.00	\$10.00	N
Labor: \$178.00	Parts: \$410.00	OL&M: \$0.00	Misc: \$10.00	Sub-Total: \$598.00		

Customer PO No:
 Tax Exempt No:
 Advisor:

Labor:	\$12,249.11
Parts:	\$18,351.70
OL&M:	\$373.57
Misc:	\$777.62
Grand Total:	\$31,752.00

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00 00	160	1	146334			USED AG EQUIPMENT
07 40	382	1	8228			INTERNAL LABOR-AG
00 00	178	17	8228			WORK IN PROCESS PARTS -MJ
07 40	394	0	8228			OUTSIDE LABOR & MATERIAL
00 00	249	6	385891			PFW CLEARING ACCOUNT
07 40	482	1	8228			COS INTERNAL LABOR-AG
07 40	494	0	8228			OUTSIDE LABOR&MATERIAL
07 40	544	1	8228			SUPPLIES EXPENSE
07 30	372	2	8228			OTHER MFR PARTS-CNTR
00 00	172	7	8228			OTHER PARTS-MOOSE JAW
07 30	366	2	8228			JD PARTS-COUNTER
00 00	166	7	8228			JD PARTS-MOOSE JAW
07 30	375	1	8228			PARTS SPECIAL HANDLING
07 30	375	3	8228			PARTS SPECIAL HANDLING
07 30	472	2	8228			OTHER MFR PARTS-CNTR
07 30	466	2	8228			JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: