



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 1 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/SPX9 1000 Internal**  
 COMPLAINT:  
 01 GREENLIGHT SERVICE INSPECTION COMBINE

CORRECTION:

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY27786	WINTER FUEL CONDITIONER 946ML	2.00	32.00	32.00	\$64.00	N
<b>Labor: \$2,599.00</b>		<b>Parts: \$64.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$0.00</b>	<b>Sub-Total: \$2,663.00</b>	

**Gen2- Internal**  
 COMPLAINT:  
 02 LUBE ALL GULLWING LATCHES

CORRECTION:  
 lubed all gullwing latches

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	4.46	4.46	\$4.46	N
<b>Labor: \$74.40</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$4.46</b>	<b>Sub-Total: \$78.86</b>	

**/150428X9 1000 Internal**  
 COMPLAINT:  
 03 RE-INSTALL FIRE EXTINGUISHER

CORRECTION:  
 fire extinguisher is on combine, emptied out water

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 2 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>/150428X9 1000 Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N
<b>Labor: \$18.60</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$1.12</b>	<b>Sub-Total: \$19.72</b>	

**Gen4- Internal**  
 COMPLAINT:  
 04 REMOVE ALL NUMBER DECALS

CORRECTION:

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**/120471X9 1000 Internal**  
 COMPLAINT:  
 05 ADJUST ALL BELTS

CORRECTION:  
 adjusted all belt tensions



Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$197.16</b>	

**Gen6- Internal**  
 COMPLAINT:  
 06 REPAIR BOTTOM STEP OF CAB LADDER - BENT

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 8/11/2025 Location: Work Order Number: Payment Type:  Page: 3 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**Gen6- Internal**

whole bottom that folds up was bent. all arms, brackets and steps, replaced badly bent parts and straightened out the rest, installed all to proper locations. had to take the ladder apart to repair and replace needed parts

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE11045	Ladder Kit	1.00	735.65	735.65	\$735.65	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
FREIGHT	FREIGHT	1.00	20.00	20.00	\$20.00	N
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>		<b>Parts: \$735.65</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$31.16</b>	<b>Sub-Total: \$952.81</b>	

**/170222X9 1000 Internal**

COMPLAINT:  
 07 TOP UP WASHER FLUID

CORRECTION:  
 topped up windshield washer fluid

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
WASHER	W/W Fluid 4 lt Jug	1.00	6.99	6.99	\$6.99	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
<b>Labor: \$46.50</b>		<b>Parts: \$6.99</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.79</b>	<b>Sub-Total: \$56.28</b>	

**GEN8- Internal**

COMPLAINT:  
 08 REPAIR CAB DOOR CINCH - NOT WORKING

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 4 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**GEN8- Internal**

removed covers to get access to door motor etc, followed diagnostic procedure, found no wiring issues. problem is in the latch mechanism itself and has to be replaced. removed entire faulty latch assembly, installed new latch assembly. connected wiring - works as should

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE88627	Latch	1.00	3,747.06	3,747.06	\$3,747.06	N
HXE132357	Plastic Expanding Rivet M6.5 X 14.5	1.00	0.98	0.98	\$0.98	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>		<b>Parts: \$3,748.04</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$3,945.20</b>	

**GEN9- Internal**

COMPLAINT:  
 09 REPAIR FRONT WASHER NOZZLES - PLUGGED & RH WASHER - SPRAYING EVERYWHERE

CORRECTION:  
 front nozzles were plugged - cleaned out and works as should  
 rh side nozzle damaged and spraying everywhere had to be replaced

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AL210369	Nozzle	1.00	62.48	62.48	\$62.48	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$62.48</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$210.35</b>	

**/110302X9 1000 Internal**

COMPLAINT:  
 10 REMOVE 2 WAY RADIO AND ANTENNA

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 5 of 37
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**/110302X9 1000 Internal**

removed antenna, removed 2-way and mike, removed panel in cab, removed aux strip to remove power cable for 2-way, installed panel and antenna cap

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.95	13.95	\$13.95	N
<b>Labor: \$232.50</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$13.95</b>	<b>Sub-Total: \$246.45</b>	

**GEN11- Internal**

COMPLAINT:  
 11 REMOVE ALL PERSONAL ITEMS FROM CAB AND TOOLBOX

CORRECTION:  
 removed all items from cab and toolbox and placed in new combine

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.12	3.12	\$3.12	N
<b>Labor: \$52.08</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.12</b>	<b>Sub-Total: \$55.20</b>	

**/110176X9 1000 Internal**

COMPLAINT:  
 12 CHECK OUT ALL CODES FOUND ON GREENLIGHT

HAD 517486.08, 522468.16  
 VTI 524055.16

CORRECTION:  
 VTI 524055.16 - less than 5% storage on display, all data exported on to a usb and data deleted off of display. Code not appearing anymore

both HAD codes cleared and tested, knife bank works from cab as should and unloading auger moved in and out and code not appearing





1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 6 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/110176X9 1000 Internal**

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$197.16</b>	

**/140968AX9 1000 Internal**

COMPLAINT:  
 13 UPDATE ALL MACHINE CONTROLLERS SOFTWARE

CORRECTION:  
 updated all required software with edl, usb device and service advisor

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	27.90	27.90	\$27.90	N
<b>Labor: \$465.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$27.90</b>	<b>Sub-Total: \$492.90</b>	

**GEN14- Internal**

COMPLAINT:  
 14 REPAIR FRONT TOP BUBBLE SHIELDS FRONT SEALS - PULLING DOWN & TIGHTEN HARDWARE - LOOSE

CORRECTION:  
 removed front side deflector, upper deflector, removed damaged seals, insalled new seals, installed deflectors

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE138024	Seal	2.00	51.16	51.16	\$102.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
<b>Labor: \$55.80</b>		<b>Parts: \$102.32</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$161.47</b>	



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 7 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/1018012002X9 1000 Internal**

**COMPLAINT:**

15 REPLACE FEED ACCELERATOR SUPPORT RIGHT AND LEFT (OFFSETS), 4 BENT

**CORRECTION:**

Remove: Upper shields Attaching hardware Offsets Replace or remove paddles from old offset and install on new Install in reverse order to specification. Test run.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
19M9370	Flange Head Cap Screw M10 X 30 GR10.9	3.00	3.34	3.34	\$10.02	N
HXE174444	Feed Accelerator Beater Wing Strip	2.00	439.29	439.29	\$878.58	N
HXE177730	Feed Accelerator Beater Wing Strip	2.00	612.53	612.53	\$1,225.06	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N
<b>Labor: \$558.00</b>		<b>Parts: \$2,113.66</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$33.48</b>
						<b>Sub-Total: \$2,705.14</b>

**GEN16- Internal**

**COMPLAINT:**

16 CLEAN OUT FEED ACCELERATOR

**CORRECTION:**

cleaned out all debris from feed accelerator

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.58</b>
						<b>Sub-Total: \$98.58</b>

**/110014X9 1000 Internal**

**COMPLAINT:**

17 ADJUST FEEDERHOUSE DRIVE CHAIN & LUBE



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 8 of 37
--------------------------	--------------------------	---

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/110014X9 1000 Internal**

**CORRECTION:**

lubed and adjusted feederhouse drive chain

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26350	CHAIN LUBE	1.00	14.71	14.71	\$14.71	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>		<b>Parts: \$14.71</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.23</b>	<b>Sub-Total: \$54.14</b>	

**GEN18- Internal**

**COMPLAINT:**

18 REMOVE FEEDERHOUSE SLIP CLUTCH AND CHECK SPLINES

**CORRECTION:**

removed chain, removed slip clutch and inspected splines, added anti seize, installed and torqued slip clutch

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**/11550X9 1000 Internal**

**COMPLAINT:**

19 ADJUST FEEDERHOUSE CONVEYOR CHAIN TENSION

**CORRECTION:**

adjusted feederhouse conveyor chain tension

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 9 of 37
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

/11550X9 1000 Internal						
SERVACCESS	SERVICE ACCESSORIES	Quantity	List Price	Net Price	Extended Price	Taxed Ind
		1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**GEN20- Internal**  
 COMPLAINT:  
 20 WELD DRIVESHAFT SHIELD MOUNTING TAB - BROKEN OFF

CORRECTION:  
 removed broken driveshaft cover, welded broken tab, painted and installed cover

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$147.87</b>	

**GEN21- Internal**  
 COMPLAINT:  
 21 REPLACE 8 UPPER AND LOWER STRIPS AT FEEDER HOUSE CONVEYOR CHAIN - WORN PAST SLANTS

CORRECTION:  
 loosened off conveyor chain tension, removed 8 wear slats and installed 8 new wear slats, tightened up conveyor chain

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE144929	Strip	8.00	74.22	74.22	\$593.76	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	35.71	35.71	\$35.71	N
<b>Labor: \$595.20</b>		<b>Parts: \$593.76</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$35.71</b>	<b>Sub-Total: \$1,224.67</b>	

**/101711009X9 1000 Internal**  
 COMPLAINT:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 10 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/101711009X9 1000 Internal**  
 22 R&R FEEDER HOUSE DRUM - NUMEROUS DENTS WHERE CHAIN RIDES

**CORRECTION:**

Remove and install conveyor shield, chain, arm, bearings and housings. Loosen drum chain tension. Remove: Master links Drum (One additional person required to remove drum, 0.1 hours) Install drum and drive chain. (One additional person required to install drive chain, 0.2) Adjust conveyor chain tension, as needed. (See Job No. 11005D.) Install shield. Remove from both sides: Pins and arms Collars Flange bearings Separate bearing from housings. Clean, inspect and repair or replace worn or defective parts Reinstall to specifications.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE88163	Wide Feeder House Drum	1.00	2,564.07	2,564.07	\$2,564.07	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	27.90	27.90	\$27.90	N
<b>Labor: \$465.00</b>		<b>Parts: \$2,564.07</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$27.90</b>
				<b>Sub-Total: \$3,056.97</b>		

**GEN23- Internal**

COMPLAINT:  
 23 TIGHTEN SHEAR BOLT AT HEADER LOCKING PINS

**CORRECTION:**

tightened shear bolt at locking pins

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N
<b>Labor: \$18.60</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$1.12</b>
				<b>Sub-Total: \$19.72</b>		

**GEN24- Internal**

COMPLAINT:  
 24 REMOVE CROSS AUGER PULLEY BUFF AND PAINT - CONTACTING SIDES

**CORRECTION:**



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 11 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**GEN24- Internal**

removed pulley, buffed and painted

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY25624	Paint Ag/CCE Green Spray Bomb	1.00	20.07	20.07	\$20.07	N
TY26268	BUFF PRIMER SPRAY	1.00	15.84	15.84	\$15.84	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF25	ENVIRO FEE	2.00	0.25	0.23	\$0.46	N
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$35.91</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$6.04</b>	<b>Sub-Total: \$134.95</b>	

**/150290X9 1000 Internal**

COMPLAINT:  
 25 CLEAN UNLOADING AUGER SUMP OF DEBRIS

CORRECTION:  
 cleaned out debris from unloading auger sump

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**GEN26- Internal**

COMPLAINT:  
 26 REPAIR FRONT COVER SEAL AT SEPARATING COVERS - PULLING OFF

CORRECTION:  
 installed seal correctly

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 12 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>GEN26- Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.23</b>	<b>Sub-Total: \$39.43</b>	

**GEN27- Internal**  
 COMPLAINT:  
 27 CLEAN OUT FRONT SHAKER FAN

CORRECTION:  
 cleaned out debris from front shaker pan

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$147.87</b>	

**GEN28- Internal**  
 COMPLAINT:  
 28 SET MECHANICAL ADJUST OF LOUVERS TO 1" AND INSTALL HOLDER PART NUMBER X9BOLT

CORRECTION:  
 set louvers to 1inch and installed missing X9 bolt

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
19M7818	Flange Head Cap Screw M12 X 80 GR10.9	1.00	8.09	8.09	\$8.09	N
X9BOLT	X9 FRONT CHAFFER BOLT RETAINER.	1.00	69.95	69.95	\$69.95	N
<b>Labor: \$46.50</b>		<b>Parts: \$78.04</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.79</b>	<b>Sub-Total: \$127.33</b>	



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 13 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/10180250AX9 1000 Internal**

COMPLAINT:

29 CONCAVE LEVEL, ADJUST, AND CALIBRATE (WITH ACI), REPEAT PROCEDURE ON OPPOSITE SIDE

CORRECTION:

concave leveling done with ACI procedure

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	50.22	50.22	\$50.22	N
<b>Labor: \$837.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$50.22</b>	<b>Sub-Total: \$887.22</b>		

**GEN30- Internal**

COMPLAINT:

30 REALIGN FRONT END DRIVE BELT AND PULLEY

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$197.16</b>		

**GEN31- Internal**

COMPLAINT:

31 REPLACE 1 GRATE FINGER ON THE INSIDE IN ROW 1 - BROKEN

CORRECTION:

removed damaged separator grate and installed new grate

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE108431	Separator Grate	1.00	379.09	379.09	\$379.09	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 14 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>GEN31- Internal</b>								
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N		
<b>Labor: \$55.80</b>	<b>Parts: \$379.09</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$438.24</b>				

**/10180120X91000 Internal**  
 COMPLAINT:  
 32 REPLACE 2 BROKEN SEPARATOR TINES - 1 ON RH SIDE 1 ON LH SIDE

\*\* found 2 more tines broken - 4 replaced in total \*\*

CORRECTION:  
 Remove separator grate covers as necessary to access tines. 4 tines in different groups broken, replaced 4 groups of 2 tines each, hardware torqued.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
KXE10959	TINE KIT.	4.00	322.15	322.15	\$1,288.60	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	37.05	37.05	\$37.05	N
<b>Labor: \$617.52</b>	<b>Parts: \$1,288.60</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$37.05</b>	<b>Sub-Total: \$1,943.17</b>		

**GEN33- Internal**  
 COMPLAINT:  
 33 CLEAN OUT TAILINGS AUGER TROUGH UNDERNEATH COMBINE

CORRECTION:  
 cleaned out debris from tailings auger underneath

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 15 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>GEN33- Internal</b>						
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
<b>Labor: \$55.80</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$59.15</b>	

**/110016X9 1000 Internal**  
 COMPLAINT:  
 34 ADJUST TAILINGS PADDLE CHAIN

CORRECTION:  
 adjusted tailings paddle chain tension

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.23</b>	<b>Sub-Total: \$39.43</b>	

**GEN35- Internal**  
 COMPLAINT:  
 35 REPAIR FOR TAILINGS TENSIONER NUT SEIZED ON ROD

CORRECTION:  
 removed tailings elevator belt tensioner, threads were packed with debris and rust. cleaned off debris and rust, lubed and installed tensioner with new nuts, adjusts easy now

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7275	Hex Nut M12	2.00	1.72	1.72	\$3.44	N
<b>Labor: \$139.50</b>		<b>Parts: \$3.44</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$151.31</b>	



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 16 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/170531X9 1000 Internal**

COMPLAINT:

36 CLEAN ACTIVE VISION CAMERA LENSES

CORRECTION:

cleaned debris from active vision camera lenses

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$147.87</b>	

**GEN37- Internal**

COMPLAINT:

37 CLEAN OFF CAKED ON DEBRIS ON ACTIVE WEAR STRIPS

CORRECTION:

removed drive belt, cleaned debris off of active wear strips

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**/10180010X9 1000 Internal**

COMPLAINT:

38 R&R ROTOR DRIVE BELT - CRACKING OUT BETWEEN LUGS

CORRECTION:

removed top end feederhouse drive belt tensioner and belt, loosened off rotor adjusting bracket bolts, tension rod nuts seized could not move it had to cut off and replace, removed damaged rotor belt. installed new belt and tensioner rod, adjusted bracket and tightened bolts, installed top end drive belt and tensioner

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> <b>Work Order Number:</b> <b>Payment Type:</b>  <b>Page:</b> 17 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**/10180010X9 1000 Internal**

14M7291	Flange Nut M16	2.00	4.80	4.80	\$9.60	N
H152450	EYEBOLT	1.00	84.75	84.75	\$84.75	N
HXE107859	X9 Rotor Belt	1.00	1,596.54	1,596.54	\$1,596.54	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	30.69	30.69	\$30.69	N

**Labor: \$511.50      Parts: \$1,690.89      OL&M: \$0.00      Misc: \$30.69      Sub-Total: \$2,233.08**

**GEN39- Internal**

COMPLAINT:  
 39 REPLACE EITHER HOSE OR FITTING ORINGS ON MAIN HYDRAULIC PUMP

HOSE NUMBER AXE68942-C

CORRECTION:  
 removed hydraulic hose, o-ring at pump fitting was in pieces, removed pump fitting and replaced o-rings, installed hose. ran and checked for leak

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
51M7048	O-RING	1.00	7.52	7.52	\$7.52	N
T76938	#16 Flat Face O-Ring	3.00	4.86	4.86	\$14.58	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	22.32	22.32	\$22.32	N

**Labor: \$372.00      Parts: \$22.10      OL&M: \$0.00      Misc: \$22.32      Sub-Total: \$416.42**

**GEN40- Internal**

COMPLAINT:  
 40 REPAIR BLACK CANISTER ON LH SIDE - LEAKING, CLAMPS ?

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 18 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**GEN40- Internal**

top 2 clamps were very loose, tightened up clamps

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
<b>Labor: \$46.50</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$2.79</b>
<b>Sub-Total: \$49.29</b>						

**GEN41- Internal**

COMPLAINT:  
 41 REPAIR STEERING STOP - INCORRECT FOR AXLE SETTING

CORRECTION:  
 removed still installed steering axle stops, should be removed with PDI

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$5.58</b>
<b>Sub-Total: \$98.58</b>						

**/10172010X9 1000 Internal**

COMPLAINT:  
 42 R&R STRAW CHOPPER HAMMERS - ALL VERY WORN

CORRECTION:  
 removed all knives, bolts, bushings and nuts, installed new knives, bushings, bolts and nuts. hardware torqued

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE118760	Lock Nut M10	34.00	2.63	2.63	\$89.42	N
HXE132357	Plastic Expanding Rivet M6.5 X 14.5	2.00	0.98	0.98	\$1.96	N
KXE11195	Knife Kit - 8 Blades per Kit	8.00	429.92	429.92	\$3,439.36	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 19 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

/10172010X9 1000 Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N		
<b>Labor: \$558.00</b>	<b>Parts: \$3,530.74</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$33.48</b>	<b>Sub-Total: \$4,122.22</b>				

**GEN43- Internal**  
 COMPLAINT:  
 43 REPLACE NUTS AT TOP OF SPREADER BELT ON LH SIDE - MISSING

CORRECTION:  
 installed new nuts at belt mounting plate that was missing.

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind		
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N		
<b>Labor: \$37.20</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.23</b>	<b>Sub-Total: \$39.43</b>				

**/110305X9 1000 Internal**  
 COMPLAINT:  
 44 CLEAN OUT SIEVE & CHAFFER SO CAN ADJUST

CORRECTION:  
 cleaned out sieve and chaffer so can adjust

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind		
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N		
<b>Labor: \$93.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>				

**/110081X9 1000 Internal**  
 COMPLAINT:  
 45 R&R SIEVE & CHAFFER TO CHECK FOR CRACKS



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

[Redacted]  Bus Phone: Prv Phone:	[Redacted]  Bus Phone: Prv Phone:	<b>Invoice Number:</b> [Redacted] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [Redacted] <b>Work Order Number:</b> [Redacted] <b>Payment Type:</b> [Redacted]  <b>Page:</b> 20 of 37
--	--	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[Redacted]

**/110081X9 1000 Internal**  
 CORRECTION:  
 removed and inspected sieve and chaffer elements, installed sieve and chaffer elements

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N
<b>Labor: \$558.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$33.48</b>	<b>Sub-Total: \$591.48</b>	

**/180015X9 1000 Internal**  
 COMPLAINT:  
 46 PREFORM INSTALL CALIBRATION OF SIEVE & CHAFFER  
  
 CORRECTION:  
 performed sieve and chaffer element calibrations

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$197.16</b>	

**GEN47- Internal**  
 COMPLAINT:  
 47 CLEAN OUT RETURN PAN  
  
 CORRECTION:  
 cleaned out debris from return pan

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 21 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**GEN48- Internal**

COMPLAINT:

48 REPLACE 1 DISCHARGE GRATE VANE ON RH SIDE - BENT

CORRECTION:

removed return pan rear hardware and lowered down, removed bent grate vane and installed new vane, raised and installed new hardware in rear of return pan, hardware torqued while locked in mid stroke

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7358	Carriage Bolt M16 X 140	2.00	22.65	22.65	\$45.30	N
14M7291	Flange Nut M16	2.00	4.80	4.80	\$9.60	N
HXE172396	VANE	1.00	110.84	110.84	\$110.84	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N

**Labor: \$186.00    Parts: \$165.74    OL&M: \$0.00    Misc: \$11.16    Sub-Total: \$362.90**

**/1200250X9 1000 Internal**

COMPLAINT:

49 CLEAN OUT PRECLEANER ELEMENT

CORRECTION:

cleaned out debris from pre cleaner element



Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N

**Labor: \$93.00    Parts: \$0.00    OL&M: \$0.00    Misc: \$5.58    Sub-Total: \$98.58**

**/160023X9 1000 Internal**

COMPLAINT:

50 REPLACE VACUUM FAN ROUND SEAL



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 22 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/160023X9 1000 Internal**

**CORRECTION:**

removed damaged seal, installed new seal

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE38720	Weatherstrip	1.00	93.32	93.32	\$93.32	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N
<b>Labor: \$46.50</b>		<b>Parts: \$93.32</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.79</b>	<b>Sub-Total: \$142.61</b>	

**GEN51- Internal**

**COMPLAINT:**

51 REPAIR POSITIVE BATTERY CABLE - LOOSE ON SHUT OFF

**CORRECTION:**

tightened positive cable

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
<b>Labor: \$55.80</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$59.15</b>	

**GEN52- Internal**

**COMPLAINT:**

52 CLEAN OUT CLEAN GRAIN AUGER TROUGH UNDERNEATH COMBINE

**CORRECTION:**

cleaned out debris from clean grain auger underneath

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 23 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

GEN52- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N	
<b>Labor: \$55.80</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$59.15</b>			

**/110015X9 1000 Internal**  
 COMPLAINT:  
 53 ADJUST CLEAN GRAIN PADDLE CHAIN

CORRECTION:  
 adjusted clean grain paddle chain tension

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$2.23</b>	<b>Sub-Total: \$39.43</b>		

**GEN54- Internal**  
 COMPLAINT:  
 54 CLEAN CLEAN GRAIN CAMERA LENSES

CORRECTION:  
 cleaned debris from clean grain camera lens

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
<b>Labor: \$55.80</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total: \$59.15</b>		

**GEN55- Internal**  
 COMPLAINT:  
 55 REPLACE RH REAR COVER SEAL AT SEPARATING COVERS - RIPPED



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 8/11/2025 Location: Work Order Number: Payment Type:  Page: 24 of 37
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**GEN55- Internal**

CORRECTION:

removed damaged seal, installed new seal

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE141829	Seal	1.00	61.02	61.02	\$61.02	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>		<b>Parts: \$61.02</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$2.23</b>
						<b>Sub-Total: \$100.45</b>

**GEN56- Internal**

COMPLAINT:

56 REPLACE KNOB AND SHORT PLATE AT FRONT SEPARATOR COVER

CORRECTION:

installed missing nob and plate

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE157294	Plate	1.00	30.82	30.82	\$30.82	N
HXE167838	Knob	1.00	15.57	15.57	\$15.57	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N
<b>Labor: \$18.60</b>		<b>Parts: \$46.39</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$1.12</b>
						<b>Sub-Total: \$66.11</b>

**/10680190AX9 1000 Internal**

COMPLAINT:

57 REPLACE 2 SEPARATOR GRATES - HAVE BROKEN FINGERS

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 8/11/2025 Location: Work Order Number: Payment Type:  Page: 25 of 37
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**/10680190AX9 1000 Internal**

Perform procedure as instructed in InstallationInstruction.NOTE: Recommended for harvesting small grains to reduce cleaning shoe loads.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H135891	Flange Lock Nut M10	1.00	2.24	2.24	\$2.24	N
HXE108431	Separator Grate	1.00	379.09	379.09	\$379.09	N
HXE132083	Separator Grate	1.00	592.39	592.39	\$592.39	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	13.39	13.39	\$13.39	N
<b>Labor: \$223.20</b>		<b>Parts: \$973.72</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$13.39</b>
						<b>Sub-Total: \$1,210.31</b>

**GEN58- Internal**

COMPLAINT:  
 58 REPAIR OR REPLACE CLEAN GRAIN ELEVATOR DOOR UBOLT - BENT OUTWARDS

CORRECTION:  
 removed and replaced bent u bolt

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
H128877	U-BOLT	1.00	19.84	19.84	\$19.84	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.23	2.23	\$2.23	N
<b>Labor: \$37.20</b>		<b>Parts: \$19.84</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$2.23</b>
						<b>Sub-Total: \$59.27</b>

**/101802500X9 1000 Internal**

COMPLAINT:  
 59 CONCAVE, R&R - RH SIDE # 1 & #5 FOR REPAIRS - BROKEN / BENT BARS

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

Invoice To Account No: 0

Deliver To:

**SERVICE INVOICE**

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 26 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/101802500X9 1000 Internal**

Remove side covers.Lower concave.Remove retainers, hardware and concaves.Reassemble.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
03M7199	Carriage Bolt M12 X 35	1.00	2.40	2.40	\$2.40	N
14M7299	Flange Nut M12	1.00	2.78	2.78	\$2.78	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	41.96	41.96	\$41.96	N

**Labor: \$699.36      Parts: \$5.18      OL&M: \$0.00      Misc: \$41.96      Sub-Total: \$746.50**

**/110259X9 1000 Internal**

COMPLAINT:

60 WELD AND REPAIR CONCAVE AS NEEDED (WHEN OUT) - RH SIDE # 1 & #5 FOR REPAIRS - BROKEN / BENT BARS

CORRECTION:

4,5,6 RH side concaves had several badly bent bars. Had to cut, straighten and weld te repair badly damaged concaves.  
 1# concave was damaged to much and has to be replaced

[REDACTED] concaves were bent, 7 concaves had several bent bars

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N

**Labor: \$558.00      Parts: \$0.00      OL&M: \$0.00      Misc: \$33.48      Sub-Total: \$591.48**

**/10180140X9 1000 Internal**

COMPLAINT:

61 REPLACE THRESHING SEPARATOR ELEMENTS (2 MATCHED SET OF 3 ) DOES NOT INCLUDE CONCAVE R&R - BROKEN RH SIDE

CORRECTION:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> Invoice Date: 8/11/2025 Location: Work Order Number: Payment Type:  Page: 27 of 37
--------------------------	--------------------------	---

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

**/10180140X9 1000 Internal**

Remove separator grate covers as necessary to accelement, removed 2 sets of 3 element and installed new elements, hardware torqued

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
KXE10756	RH Side Grain Threshing Element Kit	2.00	1,317.81	1,317.81	\$2,635.62	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	27.90	27.90	\$27.90	N

**Labor: \$465.00    Parts: \$2,635.62    OL&M: \$0.00    Misc: \$27.90    Sub-Total: \$3,128.52**

**/10171030X9 1000 Internal**

COMPLAINT:  
 62 R&R FEED ACCELERATOR BELT - BURNT

CORRECTION:  
 Release tension.Remove all belts.Replace feed accelerator belt.Reinstall all belts.Reset tension.Test run.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
HXE171261	X9 Feed Accelerator Drive Belt Fast Spee	1.00	290.45	290.45	\$290.45	N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	13.95	13.95	\$13.95	N

**Labor: \$232.50    Parts: \$290.45    OL&M: \$0.00    Misc: \$13.95    Sub-Total: \$536.90**

**GEN63- Internal**

COMPLAINT:  
 63 REMOVE FEED ACCELERATOR PULLEY BUFF AND PAINT - BURNT

CORRECTION:  
 removed pulley, buffed and painted

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
---------------	-------------	----------	------------	-----------	----------------	-----------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 28 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**GEN63- Internal**

SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N
<b>Labor: \$186.00</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$11.16</b>	<b>Sub-Total: \$197.16</b>		

**GEN64- Internal**  
 COMPLAINT:  
 64 REPAIR LADDER GULLWING FIBERGLASS HITS BACK PANEL FIBERGLASS

CORRECTION:  
 adjusted ladder fiberglass panel location so that it does not catch rear panel

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>	<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$147.87</b>		

**GEN65- Internal**  
 COMPLAINT:  
 65 REPAIR ENGINE DECK LATCHES - VERY STIFF

CORRECTION:  
 removed and replaced push pull cable and adjusted the latch bracket

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE82464	Push Pull Cable	1.00	243.87	243.87	\$243.87	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>	<b>Parts: \$243.87</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$342.45</b>		

**/10030020X9 1000 Internal**  
 COMPLAINT:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 29 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/10030020X9 1000 Internal**  
 66 ROTARY SCREEN DRIVE BELT, REMOVE AND REPLACE - CRACKING OUT

CORRECTION:  
 removed and replaced damaged v-belt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE184110	Rotary Screen Drive Belt (Eng Side)	1.00	113.09	113.09	\$113.09	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$113.09</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$260.96</b>	

**GEN67- Internal**  
 COMPLAINT:  
 67 REPLACE BIG ROTARY SCREEN BELT - FRAYING

CORRECTION:  
 removed and replaced rotary screen belt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE168680	Rotary Screen Driven Belt	1.00	94.94	94.94	\$94.94	N
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$94.94</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$193.52</b>	

**/170208X9 1000 Internal**  
 COMPLAINT:  
 68 TOP UP COOLANT

CORRECTION:  
 topped up coolant to correct level



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 30 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/170208X9 1000 Internal**

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
TY26576	9.46L COOL-GARD PREMIX	1.00	61.58	61.58	\$61.58	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF240	ENVIRO FEE	1.00	2.40	2.16	\$2.16	N
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N

**Labor: \$18.60      Parts: \$61.58      OL&M: \$0.00      Misc: \$3.28      Sub-Total: \$83.46**

**GEN69- Internal**

COMPLAINT:  
69 TIGHTEN ALL HOSE CLAMPS

CAUSE:  
tightened up hose clamps

CORRECTION:

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	11.16	11.16	\$11.16	N

**Labor: \$186.00      Parts: \$0.00      OL&M: \$0.00      Misc: \$11.16      Sub-Total: \$197.16**

**GEN70- Internal**

COMPLAINT:  
70 REPLACE HYDRAULIC BREATHER

CORRECTION:  
removed and replaced hydraulic tank breather

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 8/11/2025	<b>Location:</b> [REDACTED]	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> [REDACTED]	<b>Page:</b> 31 of 37
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**GEN70- Internal**

AXE82230	Hydraulic Reservoir Breather	1.00	135.61	135.61	\$135.61	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	2.79	2.79	\$2.79	N

**Labor: \$46.50      Parts: \$135.61      OL&M: \$0.00      Misc: \$2.79      Sub-Total: \$184.90**

**GEN71- Internal**

COMPLAINT:  
 71 REPLACE FUEL TANK FILL SCREEN - MISSING

CORRECTION:  
 installed missing fuel tank screen

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
R183142	SCREEN	1.00	201.41	201.41	\$201.41	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	1.12	1.12	\$1.12	N

**Labor: \$18.60      Parts: \$201.41      OL&M: \$0.00      Misc: \$1.12      Sub-Total: \$221.13**

**/120018X91100 Internal**

COMPLAINT:  
 72 REPLACE SMALL FUEL FILTER, AND CLEAN FUEL PRE-SCREEN

CORRECTION:  
 replaced small fuel filter and cleaned fuel prescreen

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
DZ124786	Fuel Filter, Secondary 2 Micron.	1.00	158.96	158.96	\$158.96	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
EF100	ENVIRO FEE	1.00	1.00	0.90	\$0.90	N



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 32 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>/120018X91100 Internal</b>							
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N	
<b>Labor: \$139.50</b>		<b>Parts: \$158.96</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$9.27</b>	
					<b>Sub-Total: \$307.73</b>		

**/110040X9 1000 Internal**  
 COMPLAINT:  
 73 TOP UP OIL IN ENGINE/ SEPARATOR GEARCASE

CORRECTION:  
 topped up oil in separator gearcase

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
TY6354	3.78L HYGARD HYD/TRANS OIL J20C	3.00	35.61	35.61	\$106.83	N	
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>	
EF50	ENVIRO FEE	2.00	0.50	0.45	\$0.90	N	
SERVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N	
<b>Labor: \$55.80</b>		<b>Parts: \$106.83</b>		<b>OL&amp;M: \$0.00</b>		<b>Misc: \$4.25</b>	
					<b>Sub-Total: \$166.88</b>		

**GEN74- Internal**  
 COMPLAINT:  
 74 WASH AND CHECK FOR LEAKS ALL AROUND FUEL INJECTION PUMP - REAR OF ENGINE INSIDE COVERED IN OILY CHAFF

CORRECTION:  
 cleaned off debris from fuel injection pump, ran and inspected for leaks. one fuel line was a little loose and had a slow leak. tightened up and not leaking anymore

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

Invoice To Account No: 0

Deliver To:

**SERVICE INVOICE**

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 33 of 37
--------------------------	--------------------------	--

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>GEN74- Internal</b>							
SERVACCESS	SERVICE ACCESSORIES	1.00	16.74	16.74	\$16.74	N	
<b>Labor: \$279.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$16.74</b>	<b>Sub-Total: \$295.74</b>		

**GEN75- Internal**  
 COMPLAINT:  
 75 REPAIR TORQUE SENSING DRIVEN SHEAVE HUB SEAL - LEAKING

CORRECTION:  
 removed step to get access to driveshaft, removed driveshaft and yoke, removed leaking seal, installed new seal, installed driveshaft, installed step

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>	
DE31858	Seal	1.00	80.68	80.68	\$80.68	N	
<b>Miscellaneous</b>	<b>DESCRIPTION</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>	
SERVACCESS	SERVICE ACCESSORIES	1.00	33.48	33.48	\$33.48	N	
<b>Labor: \$558.00</b>		<b>Parts: \$80.68</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$33.48</b>	<b>Sub-Total: \$672.16</b>		

**GEN76- Internal**  
 COMPLAINT:  
 76 REPLACE HINGE BOLT AT GRAIN TANK FRONT COVER - MISSING & SITS ON ANGLE

CORRECTION:  
 lifted and installed missing hinge bolt

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
14M7298	Flange Nut M8	1.00	1.47	1.47	\$1.47	N
19M7817	Flange Head Cap Screw M12 X 70 GR10.9	1.00	7.42	7.42	\$7.42	N
19M8039	Flange Head Cap Screw M8 X 80 GR10.9	1.00	5.00	5.00	\$5.00	N
<b>Miscellaneous</b>	<b>Description</b>	<b>Quantity</b>	<b>List Price</b>	<b>Net Price</b>	<b>Extended Price</b>	<b>Taxed Ind</b>



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

<b>Invoice Number:</b> [REDACTED]	<b>Invoice Date:</b> 8/11/2025	<b>Location:</b> [REDACTED]	<b>Work Order Number:</b> [REDACTED]
<b>Bus Phone:</b>	<b>Bus Phone:</b>	<b>Payment Type:</b> [REDACTED]	<b>Page:</b> 34 of 37
<b>Prv Phone:</b>	<b>Prv Phone:</b>		

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

<b>GEN76- Internal</b>	<b>SERVACCESS</b>	<b>SERVICE ACCESSORIES</b>	<b>1.00</b>	<b>8.37</b>	<b>8.37</b>	<b>\$8.37</b>	<b>N</b>
<b>Labor: \$139.50</b>		<b>Parts: \$13.89</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$161.76</b>		

**/10230100AX9 1000 Internal**  
 COMPLAINT:  
 77 R&R CLEAN GRAIN LOADING AUGER - PRETTY SHARP AT TOP

CORRECTION:  
 Fold down loading auger housing.Remove end bearing support.Remove auger.Reassemble.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
AXE89023	Auger	1.00	3,954.39	3,954.39	\$3,954.39	N
<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	8.37	8.37	\$8.37	N
<b>Labor: \$139.50</b>		<b>Parts: \$3,954.39</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$8.37</b>	<b>Sub-Total: \$4,102.26</b>	

**GEN78- Internal**  
 COMPLAINT:  
 78 CLEAN OUT LOADING AUGER TUBE OF DEBRIS

CORRECTION:  
 cleaned out debris from auger tube

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.58	5.58	\$5.58	N
<b>Labor: \$93.00</b>		<b>Parts: \$0.00</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$5.58</b>	<b>Sub-Total: \$98.58</b>	

**/GLOPCLEANX9 1000 Internal**  
 COMPLAINT:



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 35 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**/GLOPCLEANX9 1000 Internal**  
 80 GREENLIGHT CLEANING CHECKLIST  
 MOVED TO SEPARATE WORK ORDER

CORRECTION:

<b>Labor:</b> \$0.00	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$0.00	<b>Sub-Total:</b> \$0.00
----------------------	----------------------	-------------------------	---------------------	--------------------------

**GEN81- Internal**  
 COMPLAINT:  
 81 CALIBRATE TCM

CORRECTION:  
 calibrated the tcm using procedure steps



<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	7.03	7.03	\$7.03	N

<b>Labor:</b> \$117.18	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$7.03	<b>Sub-Total:</b> \$124.21
------------------------	----------------------	-------------------------	---------------------	----------------------------

**GEN82- Internal**  
 COMPLAINT:  
 82 FINAL RUN AND CHECKOVER

CORRECTION:  
 ran and checked over combine with [REDACTED] after repair work

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
SERVACCESS	SERVICE ACCESSORIES	1.00	5.91	5.91	\$5.91	N

<b>Labor:</b> \$98.58	<b>Parts:</b> \$0.00	<b>OL&amp;M:</b> \$0.00	<b>Misc:</b> \$5.91	<b>Sub-Total:</b> \$104.49
-----------------------	----------------------	-------------------------	---------------------	----------------------------



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
[www.southcountry.ca](http://www.southcountry.ca)

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone: Prv Phone:	Bus Phone: Prv Phone:	<b>Invoice Number:</b> [REDACTED] <b>Invoice Date:</b> 8/11/2025 <b>Location:</b> [REDACTED] <b>Work Order Number:</b> [REDACTED] <b>Payment Type:</b> [REDACTED]  <b>Page:</b> 36 of 37
--------------------------	--------------------------	--

<b>Make/Model:</b>	<b>Meter:</b>	<b>Serial Number:</b>	<b>Eq ID:</b>	<b>Fleet No:</b>
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	[REDACTED]

**GEN83- Internal**

**COMPLAINT:**

83 REPLACE SEPARATOR COVER KNOB - SEIZED

**CORRECTION:**

cut off seized knob and extracted bolt, lubed and installed new knob

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
HXE167838	Knob	1.00	15.57	15.57	\$15.57	N

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------



**SOUTH COUNTRY**  
 E Q U I P M E N T



1731 Main Street N.  
 Moose Jaw, SK S6J 1L6  
 Phone: 306-692-2371  
 www.southcountry.ca

Moose Jaw, SK 306-692-2371  
 Mossbank, SK 306-354-2411  
 Assiniboia, SK 306-642-3366  
 Emerald Park, SK 306-721-5050  
 Weyburn, SK 306-842-4686  
 Southey, SK 306-726-2155  
 Raymore, SK 306-746-2110  
 Montmartre, SK 306-424-2212



**JOHN DEERE**

**SERVICE INVOICE**

Invoice To Account No: 0

Deliver To:

Bus Phone:  
Prv Phone:

Bus Phone:  
Prv Phone:

Invoice Number:  
 Invoice Date: 8/11/2025  
 Location:  
 Work Order Number:  
 Payment Type:  
 Page: 37 of 37

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2022 JD X9 1000 COMBINE	1080	1H0X910XEN0820052	1H0X910XEN0820052	

GEN83- Internal	SEVACCESS	SERVICE ACCESSORIES	1.00	3.35	3.35	\$3.35	N
<b>Labor:</b>	<b>\$55.80</b>	<b>Parts: \$15.57</b>	<b>OL&amp;M: \$0.00</b>	<b>Misc: \$3.35</b>	<b>Sub-Total:</b>	<b>\$74.72</b>	

INVOICE CONTAINS \$0.48 DISCOUNT

Customer PO No:  
 Tax Exempt No:  
 Advisor:

<b>Labor:</b>	\$17,129.32
<b>Parts:</b>	\$26,506.59
<b>OL&amp;M:</b>	\$0.00
<b>Misc:</b>	\$896.24
<b>Grand Total:</b>	<b>\$44,532.15</b>

\*\*\* DOCUMENT COPY \*\*\*

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
00	00	160	1		149377	USED AG EQUIPMENT
01	40	382	1		7194	INTERNAL LABOR-AG
00	00	178	11		7194	WORK IN PROCESS PARTS -MJ
01	40	482	1		7194	COS INTERNAL LABOR-AG
01	30	366	2		7194	JD PARTS-COUNTER
00	00	166	1		7194	JD PARTS-MOOSE JAW
01	40	544	1		7194	SUPPLIES EXPENSE
01	30	375	1		7194	PARTS SPECIAL HANDLING
01	30	372	2		7194	OTHER MFR PARTS-CNTR
00	00	172	1		7194	OTHER PARTS-MOOSE JAW
01	30	375	3		7194	PARTS SPECIAL HANDLING
01	30	466	2		7194	JD PARTS-COUNTER
01	30	472	2		7194	OTHER MFR PARTS-CNTR

**TERMS AND CONDITIONS**

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by: .....Date: .....