



GOOSE
 5809 54th Ave
 Bonnyville, AB T9N 0C4
 (780) 201-4476
 service@goosemaintenance.com
 https://www.goosemaintenance.ca

Invoice for RO #15119
 Service Advisor: Lisa Sargent
 Posted Date: 03/25/22 at 11:56 AM MDT
 Client:
 Vehicle: 2015 GMC Sierra 3500 HD SLT

POST

	2015 GMC Sierra 3500 HD SLT 6.6L 8Cyl DIESEL LML Turbocharged VIN: 1GT423C84FF619656 License: 485-MKU Color: Black Odometer In: 208601 / Out: 208641	RO #15119
--	---	-----------

1 - Diagnose Front chattering First main issue		
	Diagnose Front chattering Road tested with customer, can hear loud growling noise from under drivers feet Also has a vibration at different speeds but not at the same time as the growl noise Two issues may not be related Checked entire driveline, nothing loose There is evidence of the front diff hitting the front crossmember on the drivers side, possible this is the vibration Pried up and slide in piece of matting to cushion where diff was hitting Lowered torsion keys 1 inch to see if it is a diff or driveline issue, didn't change There is some play in the stub shaft on the drivers front so the needle bearings inside may be grinding at certain levels of torque	
<i>Labor:</i>		\$284.00
✓ Approved on 01/24/22 at 12:30 PM MST		Subtotal \$284.00 + est. Tax \$14.20 \$298.20

2 - GM Duramax 6.6L 11-15 Change head gaskets #1																																																																																								
	Drain fluids Remove front bumper, Remove cab Remove cylinder heads and accessories Check block for cracks and with straight edge Send heads away to get checked for warpage and cracks Replace head gaskets, installed ARP head studs, replaced thermostats Installed LB7 up-pipe, and perform updates Replaced air filter, cleaned MAF and MAP sensors Replaced glow plugs as tips were looking worn out, put truck back together.																																																																																							
<i>Labor:</i>		\$3,692.00																																																																																						
<i>Parts:</i>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%;">Right head gasket</td> <td style="width: 5%; text-align: center;">1</td> <td style="width: 10%; text-align: right;">\$167.62</td> <td style="width: 5%;"></td> <td style="width: 10%; text-align: right;">\$167.62</td> </tr> <tr> <td>Left head gasket</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$167.62</td> <td></td> <td style="text-align: right;">\$167.62</td> </tr> <tr> <td>HD ANTIFREEZE ALLMKS 50/50 3.78L</td> <td style="text-align: center;">5</td> <td style="text-align: right;">\$19.71</td> <td></td> <td style="text-align: right;">\$98.55</td> </tr> <tr> <td>2011-2016 Duramax LML 9th Injector</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$43.07</td> <td></td> <td style="text-align: right;">\$43.07</td> </tr> <tr> <td>UP PIPE PASSENGER SIDE 01-17 DURAMAX</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$287.27</td> <td></td> <td style="text-align: right;">\$287.27</td> </tr> <tr> <td>Machining, Pressure test,</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$991.93</td> <td></td> <td style="text-align: right;">\$991.93</td> </tr> <tr> <td>Power Steering fluid</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$18.28</td> <td></td> <td style="text-align: right;">\$18.28</td> </tr> <tr> <td>Dexron VI 1L</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$10.70</td> <td></td> <td style="text-align: right;">\$10.70</td> </tr> <tr> <td>CAC RH lower seal</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$68.61</td> <td></td> <td style="text-align: right;">\$68.61</td> </tr> <tr> <td>Turbo intake o ring</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$24.93</td> <td></td> <td style="text-align: right;">\$24.93</td> </tr> <tr> <td>Up Pipe hardware</td> <td style="text-align: center;">12</td> <td style="text-align: right;">\$22.77</td> <td></td> <td style="text-align: right;">\$273.24</td> </tr> <tr> <td>Fuel filter Duramax 6.6L 01-16</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$68.87</td> <td></td> <td style="text-align: right;">\$68.87</td> </tr> <tr> <td>Headgasket kit</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$486.00</td> <td></td> <td style="text-align: right;">\$486.00</td> </tr> <tr> <td>Head studs</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$1,200.14</td> <td></td> <td style="text-align: right;">\$1,200.14</td> </tr> <tr> <td>Diesel Glow Plug</td> <td style="text-align: center;">8</td> <td style="text-align: right;">\$45.05</td> <td></td> <td style="text-align: right;">\$360.40</td> </tr> <tr> <td>Downpipe plug kit</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$77.87</td> <td></td> <td style="text-align: right;">\$77.87</td> </tr> <tr> <td>RAD HOSE O-RING</td> <td style="text-align: center;">1</td> <td style="text-align: right;">\$32.11</td> <td></td> <td style="text-align: right;">\$32.11</td> </tr> </table>	Right head gasket	1	\$167.62		\$167.62	Left head gasket	1	\$167.62		\$167.62	HD ANTIFREEZE ALLMKS 50/50 3.78L	5	\$19.71		\$98.55	2011-2016 Duramax LML 9th Injector	1	\$43.07		\$43.07	UP PIPE PASSENGER SIDE 01-17 DURAMAX	1	\$287.27		\$287.27	Machining, Pressure test,	1	\$991.93		\$991.93	Power Steering fluid	1	\$18.28		\$18.28	Dexron VI 1L	1	\$10.70		\$10.70	CAC RH lower seal	1	\$68.61		\$68.61	Turbo intake o ring	1	\$24.93		\$24.93	Up Pipe hardware	12	\$22.77		\$273.24	Fuel filter Duramax 6.6L 01-16	1	\$68.87		\$68.87	Headgasket kit	1	\$486.00		\$486.00	Head studs	1	\$1,200.14		\$1,200.14	Diesel Glow Plug	8	\$45.05		\$360.40	Downpipe plug kit	1	\$77.87		\$77.87	RAD HOSE O-RING	1	\$32.11		\$32.11		
Right head gasket	1	\$167.62		\$167.62																																																																																				
Left head gasket	1	\$167.62		\$167.62																																																																																				
HD ANTIFREEZE ALLMKS 50/50 3.78L	5	\$19.71		\$98.55																																																																																				
2011-2016 Duramax LML 9th Injector	1	\$43.07		\$43.07																																																																																				
UP PIPE PASSENGER SIDE 01-17 DURAMAX	1	\$287.27		\$287.27																																																																																				
Machining, Pressure test,	1	\$991.93		\$991.93																																																																																				
Power Steering fluid	1	\$18.28		\$18.28																																																																																				
Dexron VI 1L	1	\$10.70		\$10.70																																																																																				
CAC RH lower seal	1	\$68.61		\$68.61																																																																																				
Turbo intake o ring	1	\$24.93		\$24.93																																																																																				
Up Pipe hardware	12	\$22.77		\$273.24																																																																																				
Fuel filter Duramax 6.6L 01-16	1	\$68.87		\$68.87																																																																																				
Headgasket kit	1	\$486.00		\$486.00																																																																																				
Head studs	1	\$1,200.14		\$1,200.14																																																																																				
Diesel Glow Plug	8	\$45.05		\$360.40																																																																																				
Downpipe plug kit	1	\$77.87		\$77.87																																																																																				
RAD HOSE O-RING	1	\$32.11		\$32.11																																																																																				
<i>Fee:</i>	Freight on special order parts			\$46.00																																																																																				
✓ Approved on 02/07/22 at 01:45 PM MST		Subtotal \$8,115.21 + est. Tax \$405.76		\$8,520.97																																																																																				

3 - Front differential			
	Left hand axle seal/ needle bearing into diff		
Labor:	Unit has differential drop spacers, spacers are 1" thick, suggest cutting in half and reinstalling to give clearance to cross member. Got spacer blocks cut down and reinstalled. Vibration is much better.		\$284.00
✓ Approved on 02/07/22 at 01:45 PM MST		Subtotal \$284.00 + est. Tax \$14.20	\$298.20

4 - GM Duramax 6.6L 11-15 Extras for headgasket job			
Labor:	Remove and replace Water Pump while cab is off Installed smooth idler, replaced transmission cooler line and replaced thermostats		\$71.00
Parts:	2011-2016 Duramax LML Fleece Plug, Rear Engine Cover Coolant Return Plug	1	\$59.03 \$59.03
	Engine Water Pump	1	\$379.22 \$379.22
	Accessory Drive Belt Tensioner Assembly	1	\$210.77 \$210.77
	Accessory Drive Belt Idler Pulley	1	\$62.19 \$62.19
	Serpentine Belt	1	\$144.80 \$144.80
	IDLER PULLEY	1	\$62.19 \$62.19
	Engine Coolant Thermostat	1	\$78.54 \$78.54
	Engine Coolant Thermostat	1	\$75.74 \$75.74
✓ Approved on 03/07/22 at 09:38 AM MST		Subtotal \$1,143.48 + est. Tax \$57.17	\$1,200.65

5 - Install Cp3 conversion kit			
Labor:	Install CP3 Conversion Kit with pump, While Head Gaskets are getting done Installed cp3 conversion kit. modified fuel line		\$497.00
Part:	Fleece CP3 Conversion Kit	1	\$2,340.00 \$2,340.00
Fee:	Shipping		\$15.00
✓ Approved on 03/07/22 at 09:38 AM MST		Subtotal \$2,852.00 + est. Tax \$142.60	\$2,994.60

6 - Fleece Turbo			
Labor:	Replace turbo, with cab off and heads off Removed old turbo, cleaned all gasket surfaces, installed turbo, pre-lubed and installed new banjo washers.		\$177.50
Part:	Fleece Turbo 63mm	1	\$3,500.00 \$3,500.00
✓ Approved on 03/07/22 at 09:38 AM MST		Subtotal \$3,677.50 + est. Tax \$183.88	\$3,861.38

7 - Extras when torn down, Quick connect for air bag line, stock air intake has failed stuck pieces into turbo, diamond plate gasket			
Labor:	Replace rear diamond plate gasket Replace transmission line		\$71.00 \$106.50
Parts:	Diamond Plate Gasket	1	\$16.60 \$16.60
	Glow plug nuts	1	\$6.30 \$6.30
	1/4" union quick connect	1	\$19.14 \$19.14
	S&B Air Intake	1	\$599.19 \$599.19
	Transmission cooler line	1	\$56.00 \$56.00
	Barb Fitting	2	\$4.50 \$9.00
	90 Deg Elbow	2	\$8.26 \$16.52
	Pipe Coupling	1	\$5.31 \$5.31
✓ Approved on 03/09/22 at 01:30 PM MST		Subtotal \$905.56 + est. Tax \$45.28	\$950.84

8 - Tank Lift Pump			
Labor:	Install lift pump Installed lift pump and bled fuel system.		\$426.00
Part:	Lift Pump	1	\$1,313.09 \$1,313.09
✓ Approved on 03/23/22 at 06:52 AM MDT		Subtotal \$1,739.09 + est. Tax \$86.95	\$1,826.04

9 - GM Duramax 6.6L 01-18 Synthetic oil change			
Labor:	Synthetic oil change		\$71.00
Parts:	Oil filter Duramax 6.L 01-16	1	\$10.87 \$10.87
	Winter Windshield Washer Fluid	1	\$5.87 \$5.87
	5W40 Synthetic	10	\$8.90 \$89.00
	Standard Mini bulb	1	\$1.93 \$1.93
✓ Approved on 03/23/22 at 09:33 AM MDT			Subtotal \$178.67 + est. Tax \$8.93
			\$187.60

10 - Relocate air bag compressor			
Labor:	- Relocated air bag compressor as the air box bracket that it was mounted to was removed for the s and b intake air system. Relocated the air compressor to the inner left hand frame rail ahead of the fuel tank.		\$248.50
✓ Approved on 03/23/22 at 05:20 PM MDT			Subtotal \$248.50 + est. Tax \$12.43
			\$260.93

11 - Vibration-			
Labor:	Diagnose vibration Found vibration to be the hot cac tube hitting on the frame as the positive air shut down spread the pipe too much. Cut down tube from either side of the metal pipe and reinstalled positive air shut down. Took for test drive and no more clunks or vibrations felt. Does have a tire vibration around 105 and up.		\$284.00
✓ Approved on 03/25/22 at 09:05 AM MDT			Subtotal \$284.00 + est. Tax \$14.20
			\$298.20

RO Fees			
Fee:	Shop Supplies/Enviro		\$71.62
			Subtotal
			\$71.62

GST: 843630633 RC0001

Warning: wheel nuts require retorquing after 50 kilometers. Wheel nuts should be torqued to the manufacturer's specifications when tires have been removed for repair or replacement.

We offer a 2 year 50,000 km limited warranty on workmanship and parts. Vehicle must be brought back to the shop to honor warranty.

(Turbochargers come with 1yr Warranty for Parts & Labour)

****No warranty on customer supplied parts****

Storage fees are 35\$ per day after vehicle has not been picked up within 1 week of repair.

* If the vehicle invoice is not paid for after 90 days we have the right to sell the vehicle for the invoice amount.

Total Repair Order & Signature:

Total Jobs: \$19,651.01
Total Fees: \$132.62
Subtotal: \$19,783.63
Taxes: \$989.18
Grand Total: \$20,772.81
BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions		
03/29/22	\$11,487.21	Check Payment
03/09/22	\$3,000.00	Other Payment
03/09/22	.	.
03/09/22	\$3,000.00	Other Payment
03/09/22	\$3,000.00	Other Payment
02/03/22	\$285.60	Credit Card Payment



GOOSE
 5809 54th Ave
 Bonnyville, AB T9N 0C4
 (780) 201-4476
 service@goosemaintenance.com
 https://www.goosemaintenance.ca

Invoice for RO #16401
 Service Advisor: Lisa Sargent
 Posted Date: 09/16/22 at 01:40 PM MDT
 Client:
 Vehicle: 2015 GMC Sierra 3500 HD SLT

	2015 GMC Sierra 3500 HD SLT 6.6L 8Cyl DIESEL LML Turbocharged VIN: 1GT423C84FF619656 License: 485-MKU Color: Black Odometer In: N/A / Out: N/A	RO #16401
--	---	-----------

1 - Over the counter			
Labor:	2 Center caps-		\$0.00
Part:	D581	2	\$69.44 \$138.88
Fee:	freight		\$30.00
✓ Approved on 09/16/22 at 01:38 PM MDT			Subtotal \$168.88 + est. Tax \$8.44 \$177.32

RO Fees			
Fee:	Shop Supplies/Enviro		\$0.00
			Subtotal \$0.00

GST: 843630633 RC0001

Warning: wheel nuts require retorquing after 50 kilometers. Wheel nuts should be torqued to the manufacturer's specifications when tires have been removed for repair or replacement.

We offer a 2 year 50,000 km limited warranty on workmanship and parts. Vehicle must be brought back to the shop to honor warranty.

(Turbochargers come with 1yr Warranty for Parts & Labour)

****No warranty on customer supplied parts****

Storage fees are 35\$ per day after vehicle has not been picked up within 1 week of repair.

* If the vehicle invoice is not paid for after 90 days we have the right to sell the vehicle for the invoice amount.

Total Repair Order & Signature:

Total Jobs: \$138.88
 Total Fees: \$30.00
 Subtotal: \$168.88
 Taxes: \$8.44
 Grand Total: \$177.32
BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions		
09/16/22	\$177.32	Credit Card Payment



GOOSE
 5809 54th Ave
 Bonnyville, AB T9N 0C4
 (780) 201-4476
 service@goosemaintenance.com
 https://www.goosemaintenance.ca

Invoice for RO #18765
 Service Advisor: Gerald Malo
 Posted Date: 05/02/23 at 06:28 PM MDT
 Client:
 Vehicle: 2015 GMC Sierra 3500 HD SLT

Phone:	2015 GMC Sierra 3500 HD SLT 6.6L 8Cyl DIESEL LML Turbocharged VIN: 1GT423C84FF619656 License: 485-MKU Color: Black Odometer In: N/A / Out: N/A	RO #18765
--------	---	-----------

1 - Replacement Air bags				
Part:	Air Bags	2	\$295.00	\$590.00
Fee:	Freight			\$40.00
✓ Approved on 05/02/23 at 10:26 AM MDT			Subtotal \$630.00 + est. Tax \$31.50	\$661.50

RO Fees				
Fee:	Shop Supplies/Enviro			\$0.00
			Subtotal	\$0.00

GST: 843630633 RC0001

Warning: wheel nuts require retorquing after 50 kilometers. Wheel nuts should be torqued to the manufacturer's specifications when tires have been removed for repair or replacement.

We offer a 2 year 50,000 km limited warranty on workmanship and parts. Vehicle must be brought back to the shop to honor warranty.

(Turbochargers come with 1yr Warranty for Parts & Labour)

****No warranty on customer supplied parts****

Storage fees are 35\$ per day after vehicle has not been picked up within 1 week of repair.

* If the vehicle invoice is not paid for after 90 days we have the right to sell the vehicle for the invoice amount.

Total Repair Order & Signature:

Total Jobs: \$590.00
 Total Fees: \$40.00
 Subtotal: \$630.00
 Taxes: \$31.50
 Grand Total: \$661.50
BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions		
05/02/23	\$661.50	Credit Card Payment



GOOSE
 5809 54th Ave
 Bonnyville, AB T9N 0C4
 (780) 201-4476
 service@goosemaintenance.com
 https://www.goosemaintenance.ca

Invoice for RO #21094
 Service Advisor: Timothy Huxley
 Posted Date: 12/08/23 at 09:50 AM MST
 Client:
 Vehicle: 2015 GMC Sierra 3500 HD SLT

	2015 GMC Sierra 3500 HD SLT 6.6L 8Cyl DIESEL LML Turbocharged VIN: 1GT423C84FF619656 License: 485-MKU Color: Black Odometer In: 253667 / Out: 253701	RO #21094
--	---	-----------

1 - Goose		
✓ Approved on 12/04/23 at 06:46 AM MST	0	0

2 - Driver Window Issue		
<i>Labor:</i>	Driver window would not roll down and driver door ajar message was always on dash Removed for panel Removed and replaced customer supplied door harness Re Installed door panel and verified operation Dash message is now gone and Window now works.	\$292.00
✓ Approved on 11/30/23 at 01:56 PM MST	Subtotal \$292.00 + est. Tax \$14.60	\$306.60

3 - Surging - on a heavy acceleration		
<i>Labor:</i>	Check for surge when taking off, when you lay into it surges. We installed CP3 conversion kit on this one. Road tested multiple times and could not get truck to surge Watched desired and actual rail pressure all was good Found air filter was very plugged and needs to be cleaned. Also found that fuel filters could be getting plugged due to fuel filter life being at 1% Suggest changing fuel filter and cleaning air filter to verify if unit still surging	\$146.00
✓ Approved on 11/30/23 at 01:56 PM MST	Subtotal \$146.00 + est. Tax \$7.30	\$153.30

4 - Stabiltrak light and abs light		
<i>Labor:</i>	Diagnose stabiltrak light and abs light on dash. When unit came in no dash lights were on Scanned unit fan found codes for front left and left rear wheel speed sensor circuit erratic Road tested and watched wheel speed sensor data and all sensors were reading the same Will need to test when dash lights are on to verify issue	\$146.00
✓ Approved on 11/30/23 at 01:56 PM MST	Subtotal \$146.00 + est. Tax \$7.30	\$153.30

5 - GM Duramax 6.6L 01-18 Synthetic oil change		
<i>Labor:</i>	Synthetic oil change	\$73.00
	Performed Oil Change	
<i>Parts:</i>	Oil filter Duramax 6.6L 01-16	1 \$16.85 \$16.85
	Winter Windshield Washer Fluid	1 \$5.87 \$5.87
	5w40 Synthetic	10 \$11.48 \$114.80
✓ Approved on 11/30/23 at 01:56 PM MST	Subtotal \$210.52 + est. Tax \$10.53	\$221.05

6 - Spare S&B filter requested.			
	Change air filter		
Labor:	Removed dirty air filter Installed new air filter Cleaned old air filter and gave back to customer as a spare		\$14.60
Part:	Air filter for intake kits 75-5075 Oiled cotton cleanable	1	\$108.87 \$108.87
✓ Approved on 11/30/23 at 01:56 PM MST		Subtotal \$123.47 + est. Tax \$6.17	\$129.64

7 - CTS3-Quote and Install			
Labor:	Install CTS3 Monitor		\$146.00
Part:	Edge CTS3 Monitor	1	\$769.21 \$769.21
✓ Approved on 12/06/23 at 04:18 PM MST		Subtotal \$915.21 + est. Tax \$45.76	\$960.97

8 - Lower Balljoints/Front wheel stud			
	Remove and replace lower balljoints		
Labor:	Lower ball joints has major play Removed wheels Removed brakes Removed knuckles Removed and replaced ball joints Re installed knuckles Re installed brakes Re installed wheels Road tested and retorqued		\$584.00
Part:	STUD KIT,FRONT LOWER CONTROL ARM BALL	2	\$135.95 \$271.90
✓ Approved on 12/06/23 at 04:18 PM MST		Subtotal \$855.90 + est. Tax \$42.80	\$898.70

9 - License lights			
	Remove and replace license plate lights		
Labor:	Removed and replaced plate lights Both lights work good		\$36.50
Part:	194 BULB	2	\$1.27 \$2.54
✓ Approved on 12/06/23 at 04:18 PM MST		Subtotal \$39.04 + est. Tax \$1.95	\$40.99

10 - GM Duramax 6.6L 01 - 16 Fuel Filter Replacement			
	Change fuel filter		
Labor:	Removed and replaced fuel filter Primed system and started truck Verified no leaks and reset fuel filter life		\$109.50
Part:	Fuel filter Duramax 6.6L 01-16	1	\$80.86 \$80.86
✓ Approved on 12/06/23 at 04:18 PM MST		Subtotal \$190.36 + est. Tax \$9.52	\$199.88

11 - Rear axle seal- left rear. & Rear differential service			
Labor:	Remove and replace left rear axle seal.-Blow out differential vent and ensure its clear. Perform rear differential service		\$401.50
	Left rear axle seal was leaking and rear diff was black Removed wheels Removed calliper Removed diff cover Removed axle nut and wheel hub Removed and replaced axle seal Re installed hub and axle nut Filled diff Re installed calliper Re installed wheels Torqued rear tires		\$109.50
	When torquing front wheels found broken wheel studs on both front wheels		
Parts:	Rear Axle Seal	1	\$104.65 \$104.65
	Rear axle flange gasket	1	\$48.34 \$48.34
	Lucas 75w90 Gear Oil	4	\$26.78 \$107.12
	LOCKREAR WHEEL BEARING ADJUST NUT	1	\$38.94 \$38.94
✓ Approved on 12/06/23 at 04:18 PM MST		Subtotal \$810.05 + est. Tax \$40.50	
		\$850.55	

12 - MAJOR - Front Wheel Studs (breaking when installing lug nuts)			
Labor:	Remove and Replace Front Wheel Studs		\$182.50
	Removed and replaced wheel studs on hub adapters on both front comers		
Part:	Front Wheel Stud	16	\$25.07 \$401.12
✓ Approved on 12/08/23 at 10:07 AM MST		Subtotal \$583.62 + est. Tax \$29.18	
		\$612.80	

13 - Battery			
Labor:	Remove and replace driverside battery		\$73.00
Part:	Battery - Gold 42 Month Warranty	1	\$283.13 \$283.13
✓ Approved on 12/11/23 at 07:37 AM MST		Subtotal \$356.13 + est. Tax \$17.81	
		\$373.94	

RO Fees			
Fee:	Shop Supplies/Enviro		\$63.28
		Subtotal	
		\$63.28	

GST: 843630633 RC0001

Warning: wheel nuts require retorquing after 50 kilometers. Wheel nuts should be torqued to the manufacturer's specifications when tires have been removed for repair or replacement.

We offer a 2 year 50,000 km limited warranty on workmanship and parts. Vehicle must be brought back to the shop to honor warranty.
(Turbochargers come with 1yr Warranty for Parts & Labour)

****No warranty on customer supplied parts****

Storage fees are 35\$ per day after vehicle has not been picked up within 1 week of repair.

* If the vehicle invoice is not paid for after 90 days we have the right to sell the vehicle for the invoice amount.

Total Repair Order & Signature:

Total Jobs: \$4,668.30
Total Fees: \$63.28
Subtotal: \$4,731.58
Taxes: \$236.58
Grand Total: \$4,968.16
BALANCE DUE: \$0.00

X

✓ PAID

Completed Transactions		
12/11/23	\$4,968.16	Credit Card Payment