

Experian AutoCheck Report

Report run: 09/10/2026 10:58:31 EDT

2021 Ram 1500 Tradesman

Extended Cab 4D (3.6L V6 SMPI Gas/Electric Mild Hybrid)


VIN:	1C6RRFCGXMN738199
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	5 year(s)
Estimated In Service:	08/16/2021
Last Reported Odometer:	86,914 (03/14/2024)

One Owner

AutoCheck

Vehicle Usage

Personal



Vehicle History at a Glance

State Title Brand CLEAN	Auction Brand / Issues NO ISSUE	Accident / Damage No Accidents or Damage Reported NO ISSUE
Open Recall Check 1 OPEN RECALL(S)	Insurance Loss / Transfer NO ISSUE	Odometer Check Last reported odometer: 86,914 (03/14/2024) NO ISSUE
Certified Pre-Owned NO CPO INFO AVAILABLE	Service / Repair 1 Service Record(s) Reported NO ISSUE	Additional History NO ISSUES REPORTED



This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

Learn More

Your Vehicle Checks Out There were no accidents or damage events disclosed to Experian AutoCheck for this vehicle. Since not all damage-related events are reported to Experian AutoCheck, an inspection may provide added confidence in the vehicle's condition before purchase.



Airbag Deployed



Structural Damage



Overturned



No Damage



Open Recall Check



Information Reported: AutoCheck found 1 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 08/06/2026

Recall Type - Safety

NHTSA / OEM Recall No. - 26V-495 / 67D

Campaign Description - Safety Recall: 2019-2026 MY RAM 1500 (DT) REAR SEAT BUCKLE ASSEMB
Status: Remedy Unknown

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ram Dealer](#) to schedule repair.



Service History

Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.



Regular Oil Changes

- 1 oil services reported
- Last oil service reported 05/11/2023



Fluids Maintained

Information not available.



Brakes Maintained

Information not available.



Tires Maintained

Information not available.



A/C & Climate Control

Information not available.



Other Services

Information not available.

OEM Recommended Services



84000 Mile Service

- Change engine oil and engine oil filter
- Inspect brake hoses and lines
- Inspect brake linings, replace if necessary



90000 Mile Service Not Yet Due

- Adjust parking brake on vehicles equipped with 4 wheel disc brakes
- Change engine oil and engine oil filter
- Change transfer case fluid



Odometer Check



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported



Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2021 Ram 1500 Tradesman (1C6RRFCGXMN738199) Report Run Date: 09/10/2026 10:58:31 EDT

2021

Vehicle Prep and Other Pre-Titling Events

Location: LA

Preparation Date: 08/2021

Event Date	Location	Odometer	Data Source	Details
08/16/2021	LA	16	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection

2021

Owner 1

Location: TX

Owned From: 09/2021

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/23/2021	BATON ROUGE, LA		Motor Vehicle Dept.	Title
09/23/2021	GONZALES, LA		Motor Vehicle Dept.	Title(Title #:F2461315)
09/23/2021	BATON ROUGE, LA		Motor Vehicle Dept.	Registration Event/Renewal
08/29/2022	LA	42,954	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
05/11/2023	LA	59,196	Service Record	Vehicle Inspected Vehicle Recall Service Performed Recommended Maintenance Performed Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
03/14/2024	LA	86,914	Motor Vehicle Dept.	Passed Emission Inspection Passed Safety Inspection
06/30/2025	GONZALES, LA		Motor Vehicle Dept.	Registration Event/Renewal
08/06/2026			Manufacturer	Manufacturer Recall NHTSA Recall 26V-495 / Mfr. Recall 67D Safety Recall: 2019-2026 MY RAM 1500 (DT) REAR SEAT BUCKLE ASSEMB LOCATE YOUR NEAREST AUTHORIZED RAM DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](#) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1C6RRFCGXMN738199) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpterm](#)s or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service

1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.