

2020 Kenworth T-800

This is a Owner/ Operator truck ordered in fall of 2018 and taken delivery Spring 2019 from Kenworth Sales in Utah... It was in service over 6 years before being replaced. This truck has had 1 driver that owned it and he has over 25 years experience.

The truck is owned by Tamarack Trucking from Salina, UT. It was specks super lite weight but durable.

This truck is all factory settings and the exhaust is not modified. It's been a good truck and never given me problems.

This truck has never grossed over 80,000 pounds, never hauled heavy or pulled doubles.

All maintenance and repairs were done at Kenworth Sales in Utah

Oil changes and service every 30,000 miles... All maintenance done on Paccar recommended intervals by a Paccar shop

Unit was replaced in July 2025 and has been parked since. Unit was taken out of service due to age, the fleet is a Haz Mat carrier and does not keep equipment over 5 model years old.

It is a great truck and its name is Lucrum; Latin for profit...

Owner has all the receipts for all items listed and can email a 56 Mb PDF to you if contacted me at tamaracktruck.com I will happily send it to you.

This will make someone a great emission compliant used truck.

New ECM at 13,800 hours May 2024, all hours showing now were since May 2024...

Clutch was replaced & transmission was inspected Oct 2024

Maintenance records Jan 2023 to current show:

Service 497,000 miles

New NOX sensors 526,000 miles

New DPF filter 536,000 miles

New fan hub 536,000 miles

New belt, pullies and tensioner 558,009 miles

Service 558,000 miles

New fuel pumps 574,000 miles

Service at 594,000 miles

New rear airbags October 2023

Replace Bugle Line 613,000

Rebuild 5th wheel jaws 621,000

Service 626,000 miles, exhaust leak fixed

Fuel tank strap & headlights. replaced 641,000 miles

Rear mudflaps and brackets replaced 647,000 miles

Replace rear air lines and electrical lines 647,000

Replace all coolant hoses, thermostats and hose clamps 655,000 miles

Service 679,000 miles

4 - new batteries 679,000

New clutch 704,000 miles

Replace load pressure sensor 704,000 mile

Service Power Steering 704,000

Replace defrost blower motor December 2024

Service Espar heater and inspect battery cables 724,000 miles

Service 729,000 miles

Alignment January 2025

Replace turbo actuator April 2025

Rebuild air dryer May 2025

Service 762,000 miles

Replace radiator 762,000 miles

Replace 4 batteries June 2024

Replaced AC compressor and charged A/C 770,000 miles