

EM Work Order History By Equipment / Cost Code

Equipment: 1011 - 1011

Cost Codes: 11. 1 - 31. 5

All Categories

WO	Item	Date Comp	Hour Meter
Equipment: 1011	2014 Gradall XL4300		05/14/26
	Serial #: 4300000095		7,883
Cost Code: 11. 1 Tires & Undercarriage - Sched.			
37959 Auto-Init WO - November 17, 2014	Complete Tire Eval Sheet	10/14/14	687
41342 Auto-Init WO - December 4, 2015	Complete Tire Eval Sheet	12/03/16	2,405
42733 check top roller on arm that goes in & out	replace all 8 tires--10.00 x 20 lugger	02/21/17	2,644
48113 Auto-Init WO - November 17, 2017	Complete Tire Eval Sheet	10/28/17	3,362
68718 right front outside tire needs switched--tread depth off	match right front outside tire & check RR duals pressure	02/02/23	6,563
72394 right rear outer tire is flat	repair/replace right rear outer tire--INSIDE TIRE	02/19/24	7,093
78434 driverside rear outside tire is flat	repair/replace driverside rear outside tire 10.00 x 20	09/12/25	7,754
Cost Code: 11. 2 Tires & Undercarriage - Unsch.			
37177 rightside rear tire flat 10.00 x 20 lugger	fix or replace tire	09/08/14	500
38807 rear inside tire flat	fix flat tire 10.00 x 20 lugger	03/09/15	864
38874 left inside tire flat	fix or replace tire 10.00 x 20	03/16/15	864
62401 right front outer tire blew	replace right front outer tire 10.00 x 20	07/16/21	5,590
68812 needs pins & bushing in front of bucket	tire repair	07/05/24	7,093
74883 back right outside tire if blade is in front of you	repair/replace back right outside tire	09/30/24	7,429
77771 driverside left rear outside tire only has 40 lbs in it	repair driverside left rear outside tire 10.00 x 20	07/17/25	7,596
78479 passengerside front tire & rear back tire flat	repair/replace PS front tire & rear tire 10.00 x 20	09/18/25	7,766
Cost Code: 13. 1 Special Wear Items - Sched.			
42457 replace cutting edge on 5' bucket	replace cutting edge	04/26/16	1,878
42532 hooked unto a piece of concrete & bent cutting edge	remove & replace edge	01/31/20	4,502
42913 Auto-Init WO - June 16, 2016 - R6	replace tooth that is missing	07/12/16	2,125
43152 won't start	remove & replace welded cutting edge on 10' blade	07/12/16	2,125
44695 several hydraulic leaks at fittings???	boom rollers are shot	03/01/17	2,646
46201 bottom of joystick is falling off	install cutting edge	07/05/18	3,622
68812 needs pins & bushing in front of bucket	adjust rollers	07/05/24	7,093
Cost Code: 13. 2 Special Wear Items - Unsch.			
39549 hydraulic leak from main controls in center of machine	flip cutting edge	02/15/16	1,763
42532 hooked unto a piece of concrete & bent cutting edge	straighten edge	04/28/16	1,878
Cost Code: 14. 1 Engine - Scheduled			

37787 tail pipe broke off @ mounting clamp	replace hose clamps for coolant	11/11/14	687
44695 several hydraulic leaks at fittings???	exhaust rattle	02/28/17	2,646
46201 bottom of joystick is falling off	belt squeals at times when throttled up	10/18/17	3,288
	AC doesn't always work	05/01/18	3,586
47729 change coolant	change coolant	10/16/17	3,288
50682 oil leak underneath	fix oil leak	08/21/18	3,748
56377 check rollers on boom	crack in muffler needs welded	01/08/20	4,494
	replace AC compressor	01/08/20	4,494
58885 Auto-Init WO - August 25, 2020 - SF1	small fuel filter cap is broken	02/02/23	6,563
61983 AC don't work	fix AC	01/31/23	6,563
	AC/heater hose currently using hose clamp-valve?	01/31/23	6,563
62132 Auto-Init WO - June 24, 2021 - SF1	cap for coolant/reservoir	01/30/23	6,563
62449 change coolant	replace basket inside fuel filter housing	07/13/21	5,549
65602 switch valves from heat to AC	change coolant	02/07/23	6,563
67858 Auto-Init WO - October 26, 2022 - SF	switch valves from heat to AC	04/15/22	5,961
	replace fan drive belt	01/31/23	6,563
Equipment: 1011 2014 Gradall XL4300	Serial #: 4300000095		05/14/26

- Continued

66380 right rear roller is not working & making noises	housing oil leak (add oil)?	01/27/23	6,563
78751 oil leak from transfer case	muffler bracket broke & muffler welds broken		
80366 bring back to sell	check noise issue		7,883

Cost Code: 14. 2 Engine - Unscheduled

37787 tail pipe broke off @ mounting clamp	replace tail pipe--warranty	11/11/14	687
39554 won't start	bled air out of lines	05/22/15	1,161
40793 test ports for taking hydraulic pressures are leaking	replace cap on overflow tank	10/08/15	1,746
50825 oil leak coming from steel line over near fuel tank	fix oil leak at steel line	09/06/18	3,804
	fix oil leak where locking pin locks housing from spinning	11/26/18	4,097
60794 check heat issue	replace thermostats	01/28/21	5,484
61396 won't start	loss of power	04/15/21	5,230
62132 Auto-Init WO - June 24, 2021 - SF1	won't start	07/08/21	5,544
65987 Auto-Init WO - May 16, 2022 - B2	won't start	06/02/22	6,124
72186 bolts sheared off on back inside (gear that rotates boom)	check AC	07/05/24	7,095
77814 hydraulic leak	charge AC	07/22/25	7,521

Cost Code: 15. 1 Transmission - Scheduled

78751 oil leak from transfer case	fix leak at transfer case	11/04/25	7,856
-----------------------------------	---------------------------	----------	-------

Cost Code: 17. 1 Hydraulic - Scheduled

39549 hydraulic leak from main controls in center of machine	fix hyd leak in front of swing drive & big hose in back	02/15/16	1,763
40793 test ports for taking hydraulic pressures are leaking	replace o-rings in test ports	02/04/16	1,762

42373	o-ring on black pipe at the valve bank leaking	replace o-ring	04/13/16	1,788
42457	replace cutting edge on 5' bucket	hydraulic leak	04/19/16	1,814
44695	several hydraulic leaks at fittings???	main hose from tank to pump leaking/ leaks around pump	03/02/17	2,646
		fix hydraulic leaks	12/27/16	2,646
46201	bottom of joystick is falling off	lock pin for travel leaking hydraulic	11/26/18	4,097
49899	left work lights under boom & worklight on bottom of cab out	small unknown leak	05/01/18	3,586
54476	bucket has a bow in it	needs UTF hydraulic oil	06/13/18	3,578
		check coupler	01/25/20	4,502
		guards were removed & cylinders got damaged	01/25/20	4,502
56377	check rollers on boom	hydraulic leak	01/10/20	4,494
59458	hydraulic hose leaking	remove & replace hydraulic hose	10/20/20	4,730
65753	hydraulic leak on axle where rotates on boom	repair hydraulic leak	04/28/22	6,021
68380	right rear roller is not working & making noises	check for leaks above locking pin under rear of the cab	01/31/23	6,563
68851	hydraulic oil leak by block	repair hydraulic oil leak	01/29/24	7,088
		remove main hydraulic pump	01/25/24	7,088
		hydraulic leak by left side radiator	02/02/24	7,088
		hydraulic leak under machine	01/30/24	7,088
71693	hydraulic leak on the main line into the hydraulic cooler	fix hydraulic leak on the main line into the hyd. cooler	11/29/23	7,004
72141	Auto-Init WO - January 9, 2024 - A3	changed hydraulic oil & filters	02/08/24	7,093
78751	oil leak from transfer case	weld steel hydraulic line	10/27/25	7,733
Cost Code: 17. 2 Hydraulic - Unscheduled				
37193	hydraulic leak off pump back of motor	fix hydraulic leak	09/17/14	652
39511	grease tube fitting in boom needs replaced	oil leak at drive gear	05/20/15	1,101
42373	o-ring on black pipe at the valve bank leaking	blew hydraulic line	04/13/16	1,788
44695	several hydraulic leaks at fittings???	hydraulic leak in boom	03/02/17	2,646
Equipment: 1011 2014 Gradall XL4300		Serial #: 4300000095		05/14/26
- Continued				
44695	several hydraulic leaks at fittings???	install hose guard @ steel hydraulic line	02/23/17	2,646
		repair hydraulic hose clamp in cradle	02/23/17	2,646
48553	hydraulic leak	fix hydraulic leak	01/10/18	3,571
49219	hydraulic leak	repair hydraulic leak	04/10/18	3,479
49386	hydraulic motor that turns the boom leaking	tilt gear box & auto idle not working	05/08/18	3,521
50706	oil leak underneath	fix oil leak	08/24/18	3,764
53630	big lines on boom for drive lines have leak-possible o-ring	replace o-rings	05/21/19	4,150
54479	fitting beginning to leak--steel line	remove & replace fitting	08/28/19	4,251
58440	gearbox & hyd. motor that rotates the boom is coming apart	remove & replace gearbox & hyd. motor that rotates boom	07/31/20	4,580
65602	switch valves from heat to AC	fix hydraulic leak	04/15/22	5,961
67784	Hyd tube leaking	Diagnose and repair hyd leak	10/21/22	6,356

74687 Blown Hyd hose	Locate and replace blown hyd hose	09/13/24	7,235
77814 hydraulic leak	fix hydraulic leak	07/22/25	7,521
77921 hydraulic leak	tighten bolts for rotation motor	07/22/25	7,521
	fix hydraulic leak	08/25/25	7,693
	added oil	08/07/25	7,680

Cost Code: 18. 1 Electrical - Scheduled

40662 install telematics	install telematics	09/23/15	1,506
49899 left work lights under boom & worklight on bottom of cab out	replace bulbs or lights	06/19/18	3,586
58885 Auto-Init WO - August 25, 2020 - SF1	left tail light broke	01/23/23	6,563
61581 need new door handle	replace right & left joysticks	05/06/21	5,338
62449 change coolant	won't start	02/06/23	6,563
67632 won't start--Batteries replaced in November 2021	check no start issue	10/10/22	6,324
67858 Auto-Init WO - October 26, 2022 - SF	issue with not starting all the time--replace 2 sensors	10/28/22	6,454
68380 right rear roller is not working & making noises	strobe light on roof	01/25/24	7,088
	replace ignition	01/27/23	6,563
	remove starter & install after replacement	02/02/24	7,088
76356 check if starts	get started	02/27/25	7,476

Cost Code: 18. 2 Electrical - Unscheduled

39697 rotation on bucket don't work	check issue with rotation on bucket	06/10/15	1,161
42913 Auto-Init WO - June 16, 2016 - B6	replace cab mirror	07/08/16	2,101
43152 won't start	get running	07/20/16	2,162
48576 Multiple Electric Issues with Lock Out & Hydraulic	Diagnosis Electrical	01/15/18	3,390
53610 won't start	get started--batteries	05/14/19	4,227
54432 won't start	get started	07/25/19	4,207
61396 won't start	get started	04/15/21	5,230
61431 shut off again & won't start no clicking, etc	check issue why shuts off & will not start back up right awa	04/21/21	5,440
61983 AC don't work	fix radio	06/18/21	6,563
63712 won't start	get started	11/03/21	5,704
64013 won't start just clicks	get started	12/01/21	5,783
67858 Auto-Init WO - October 26, 2022 - SF	several of the swing flashers are not working	01/23/23	6,563
70072 Auto-Init WO - June 29, 2023 - SF2	cranks over hard like a low battery issue	10/28/22	6,563
75740 won't start	tested batteries	07/06/23	6,781
	get started--check batteries--replace starter	12/30/24	7,468

Cost Code: 19. 1 Chassis - Scheduled

36564 Auto-Init WO - July 14, 2014 - A1	install numbers & decals	07/31/14	306
Equipment: 1011 2014 Gradall XL4300	Serial #: 4300000095	05/14/26	7,883
- Continued			

42532 hooked unto a piece of concrete & bent cutting edge	repair bent bucket	01/31/20	4,502
---	--------------------	----------	-------

42733	check top roller on arm that goes in & out	check top roller on arm that goes in & out	05/24/16	1,989
46201	bottom of joystick is falling off	fix or replace bottom of joystick	05/01/18	3,586
		key ignition loose	05/01/18	3,586
49899	left work lights under boom & worklight on bottom of cab out	plastic belly pan under motor needs fixed	06/13/18	3,578
54476	bucket has a bow in it	fix bucket	01/25/20	4,502
56377	check rollers on boom	go over machine--grease & check fluids	01/13/20	4,494
		replace blade guard on top of cylinders	01/13/20	4,494
61581	need new door handle	check rollers on boom & replace if necessary	12/30/19	4,473
61983	AC don't work	replace door handle	05/06/21	5,338
62862	safety handle broke	fix door lock	06/14/21	6,563
63345	right side mirror broke off	fix safety handle	08/26/21	5,596
68380	right rear roller is not working & making noises	replace broken mirror	10/11/21	5,628
		check issue with roller not working	01/25/23	6,563
68812	needs pins & bushing in front of bucket	check door latch on side of cab	01/24/23	6,563
68851	hydraulic oil leak by block	left side windshield handle latch missing	01/27/23	6,563
71888	one of the 6 counterweight bolts broke off	replace pins & bushings in front end of bucket	02/09/24	7,088
72186	bolts sheared off on back inside (gear that rotates boom)	remove counterweight	01/24/24	7,088
75017	bracket for mirror broke plastic piece off	remove broken bolt & replace all 6	02/02/24	7,088
77921	hydraulic leak	remove/ replace sheared off bolts	07/05/24	7,095
80366	bring back to sell	right side roller main boom outside bearing out of it	12/10/24	7,467
		replace step	09/02/25	7,717
		bring back to sell		
		blow off all the grease & decals		

Cost Code: 19. 2 Chassis - Unscheduled

36564	Auto-Init WO - July 14, 2014 - A1	make grease hoses for greasing machine inside boom	07/22/14	268
38894	hit dumpster when spinning around damaged tail light	replace tail light	03/26/15	864
39511	grease tube fitting in boom needs replaced	replace grease fitting	05/20/15	1,101
42913	Auto-Init WO - June 16, 2016 - B6	replae broken mirror	06/24/16	2,071
44695	several hydraulic leaks at fittings???	replace gas strut on right side compartment door	02/28/17	2,646
47474	couple of grease fittings need replaced	replace grease fittings	09/25/17	3,222
62116	roller on side of boom not spinning	check if roller is spinning	06/22/21	5,618
65743	bracket for mirror on passengerside broken	replace door compartment key & ignition key	06/02/22	6,083
67858	Auto-Init WO - October 26, 2022 - SF	repair or replace broken bracket for mirror on passengerside	06/02/22	6,083
68812	needs pins & bushing in front of bucket	handle for the hyd. activation on the left arm rest is broke	01/23/23	6,563
		replace rubber support left bottom step	02/05/24	7,088
		fill hydraulics	07/05/24	7,093
75017	bracket for mirror broke plastic piece off	replace plastic piece on bracket for mirror	11/24/24	7,454

Cost Code: 20. 1 PM/Grease/Oil/Filter - Sched.

36564	Auto-Init WO - July 14, 2014 - A1	Perform A. Service Check List	07/31/14	306
-------	-----------------------------------	-------------------------------	----------	-----

37715 Auto-Init WO - October 23, 2014 - B2	Perform A Service Check List	10/31/14	676
	Perform B Service Check List	10/31/14	676
39255 Auto-Init WO - April 29, 2015 - A3	Perform A Service Check List	05/22/15	1,101
40539 Auto-Init WO - September 9, 2015 - C Service	Perform A Service Check List	09/20/15	1,431
	Perform B Service Check List	09/20/15	1,431
	Perform C Service Check List	09/20/15	1,431

Equipment: 1011 2014 Gradall XL4300 Serial #: 4300000095

- Continued

41698 Auto-Init WO - January 15, 2016 - A5	Perform A Service Check List	02/04/16	1,762
42913 Auto-Init WO - June 16, 2016 - B6	Perform B Service Check List	07/11/16	2,125
	Perform A Service Check List	07/11/16	2,125
44690 Auto-Init WO - December 20, 2016 - A7	Perform A Service Check List	01/09/17	2,533
46176 Auto-Init WO - June 12, 2017 - D Service	Perform A Service Check List	06/28/17	2,870
	Perform B Service Check List	06/28/17	2,870
	Perform C Service Check List	06/28/17	2,870
	Perform D Service Check List	06/28/17	2,870
47468 Auto-Init WO - September 22, 2017 - A1	Perform A Service Check List	10/05/17	3,272
49537 Auto-Init WO - May 8, 2018 - B2	Perform A Service Check List	06/07/18	3,568
	Perform B Service Check List	06/07/18	3,568
51032 Auto-Init WO - September 25, 2018 - A3	Perform A Service Check List	10/02/18	3,865
53991 Auto-Init WO - June 18, 2019 - C4	Perform C Service Check List	10/18/19	4,379
	Perform B Service Check List	10/18/19	4,379
	Perform A Service Check List	10/18/19	4,379
58885 Auto-Init WO - August 25, 2020 - SF1	needs cab air filter		
60068 Auto-Init WO - November 23, 2020 - SF2	Complete Sample Filter Check List	02/02/23	6,563
61394 Auto-Init WO - April 15, 2021 - A1	Complete Sample Filter Check List	09/15/20	4,612
	Complete Sample Filter Check List	12/07/20	4,931
62132 Auto-Init WO - June 24, 2021 - SF1	Perform A Service Check List	04/27/21	5,271
64079 Auto-Init WO - December 2, 2021 - SF2	Complete Sample Filter Check List	04/27/21	5,271
65987 Auto-Init WO - May 16, 2022 - B2	Complete Sample Filter Check List	07/08/21	5,526
	Perform B Service Check List	12/21/21	5,805
67858 Auto-Init WO - October 26, 2022 - SF	Perform A Service Check List	06/01/22	6,083
70072 Auto-Init WO - June 29, 2023 - SF2	Perform A Service Check List	06/01/22	6,083
72141 Auto-Init WO - January 9, 2024 - A3	Complete Sample Filter Check List	01/24/23	6,563
	Complete Sample Filter Check List	07/06/23	6,776
	Perform A Service Check List	02/08/24	7,093
	Complete Sample Filter Check List	02/08/24	7,093
	Complete Sample Filter Check List	05/27/25	7,508

Cost Code: 20. 2 PM/Grease/Oil/Filter - Unsched

44695 several hydraulic leaks at fittings???

Cost Code: 22. 2 Brakes - Unscheduled

47748 when shut off brake pedal comes up, when on brake pedal do

greased machine, replaced 2 grease fittings

03/06/17

2,646

Cost Code: 24. 1 Final Drives/Diff. - Scheduled

44695 several hydraulic leaks at fittings???

leak around swing pump

03/06/17

2,646

49280 swind drive oil needs changed

change swing drive oil

04/18/18

3,487

Cost Code: 24. 2 Final Drives/Diff.-Unscheduled

78479 passengerside front tire & rear back tire flat

check rear axle housing-leaked oil when changing tires

09/22/25

7,781