

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
16/04/2019 R01055062		
101	74VO	CARRY OUT ROAD WORTHY INSPECTION
102	74	CARRY OUT ROAD WORTHY INSPECTION
103	STAR	*****
104	N	- MIRROR LIGHTS ON PASSENGER SIDE BUT NOT DRIVER SIDE, UNSYMETRICAL
105	N	LIGHTING
106	N	- FIRE EXTINGUISHER EXPIRED IN CAB
107	N	- DRIVER DOOR MIRROR ADJUSTER MODULE INOP
108	N	- SUNROOF SWITCH INOP
109	N	- AIR LEAK CONTROL BOX BEHIND DRIVER SIDE STEER GUARD
110	N	- DRIVER SIDE WINDOW SCRATCHED AND FROSTED
111	N	- BULLBAR PLACARDS DAMAGED/UNSECURED
112	N	- CHASSIS FIRE EXTINGUISHER EXPIRED
113	N	- HOOKUP LIGHT INOP
114	N	- PASSENGER SIDE 1ST AXLE STEER GUARD DAMAGED
115	N	- OUTER FOG LIGHTS INOP, FAULT ON DASH
116	N	- LHS 2ND STEER GUARD RUBBING ON TANK
117	N	- 1ST DRIVE MUD FLAPS TORN
118	N	- BATTERY BOX COVER MISSING FASTENER
119	N	- BULLBAR INDICATORS CRACKED/WATER INGRESS
120	N	- 1ST STEER DRIVER SIDE LOWER SHOCK MOUNT LOOSE
121	N	- FRONT ENGINE MOUNT WORN/CRACKED
122	N	- STEER FLUID LEAK AROUND RESERVOIR AND HOSES
123	N	- OIL LEAK AROUND CRANK CASE VENT FILTER HOUSING
124	N	- UNSECURED WIRES NEAR MAIN DRIVESHAFT
125	N	- 1ST DRIVE DROP LINKS WORN/TORN BOOTS
126	N	- 1ST DRIVE LHR AIRBAG CRACKED
127	N	- 2ND DRIVE LHF AIRBAG CRACKED
128	N	- 2ND DRIVE REAR AIRBAGS CRACKED
129	N	- REVERSE BUZZER INOP/EXPOSED WIRING
130	N	- SUZI COILS DAMAGED/WORN
131	N	- 1ST STEER SHACKLE PINS WORN
132	N	- SANDWICH PLATE MINOR OIL WEEPING (WASH N INSPECT, RECOMMEND REPAIR)
133	N	- CAB TILT FLIUD LEAKING RHS
134	N	- TRANS COOLER HOSES (X2) UNSECURED AND LEAKING
135	N	- 1ST DRIVE SIGNIFICANT OUTPUT YOKE MOVEMENT
701	63VO	REPAIR MIRROR LIGHTS AS REQUIRED
702	63	REPAIR MIRROR LIGHTS AS REQUIRED
703	VT20746401	COVER MIRROR FM-FH LH-RH CH 123488-
704	STAR	*****
705	N	removed the l/h clearance lights and fitted a new back cover as both
706	N	lights need to be symmetrical remounted the top work light on the r/h
707	N	mirror as it was just hanging there had to drill out the rivets on
708	N	the l/h mirror and completely disassemble it to tape off the positive
709	N	and negative wires for clearance lights.
1001	62VO	REPAIR RH MIRROR ADJUSTER N/W
1002	62	REPAIR RH MIRROR ADJUSTER N/W
1003	VT22566508	SWITCH PANEL
1004	STAR	*****
1005	N	repair mirror adjuster not working
1006	N	switch block faulty
1007	N	: tested the adjuster it adjusted in all directions except to the
1008	N	right swapped over with another one was working ordered new switch
1009	N	block installed it working good.
1301	62VO	REPAIR SUNROOF SWITCH INOP
1302	62	REPAIR SUNROOF SWITCH INOP
1303	STAR	*****
1304	n	checked the switches both were working correctly and had power and
1305	n	ground to them removed the lining around the sunroof underneath it

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
1306	n	tested the control unit it was working found it had power and ground
1307	n	and both signals were there the power and ground were good at the
1308	n	motor removed control unit and disassembled checked position sensor
1309	n	wheel wasn't stuck all good checked over the rails found the sliding
1310	n	mechanism wasn't clean and some dirt had gotten in cleaned it out and
1311	n	manually wound the motor back and forth then the roof hatch was
1312	n	working as it should.
1601	62VO	REPAIR AIR LEAK FROM CONTROL BOX
1602	STAR	*****
1901	62VO	REPLACE BOTH FIRE EXTINGUISHERS
1902	62	REPLACE BOTH FIRE EXTINGUISHERS
1903	VT22556828	FIRE EXTINGUISHER 2.3KG AND BRACKET FIRX925A
1904	STAR	*****
1905	n	replace both fire extinguishers as required
2201	63VO	REPAIR HOOKUP LIGHT INOP
2202	63	REPAIR HOOKUP LIGHT INOP
2203	SPACX3064	TERMINAL JOINER RED STD & HEAT SHRINKABL
2204	AMNARV56600	HEATSHRINK PACK 3.2mm - 6.4mm DIA
2205	AMNARV72430	9-80V LED WORK LAMP FLOOD BEAM
2206	STAR	*****
2207	N	REPLACE HOOK UP LIGHT AND REPAIR WIRING
2501	41VO	REPAIR PASSENGER SIDE 1ST AXLE STEER GUARD DAMAGED
2502	41	REPAIR PASSENGER SIDE 1ST AXLE STEER GUARD DAMAGED
2503	STAR	*****
2504	n	replace damaged 1st steer mudgaurd
2801	63VO	REPAIR OUTER FOG LIGHTS INOP, FAULT ON DASH
2802	63	REPAIR OUTER FOG LIGHTS INOP, FAULT ON DASH
2803	AMNARV48700	GLOBE H3 24V 70W
2804	AMNARV56310	CABLE TIE LARGE 1=10PACK BLACK NARVA
2805	STAR	*****
2806	N	REPLACE FOG LIGHT GLOBES ABD REPAIR WIRING
3101	41VO	REPAIR LHS 2ND STEER GUARD RUBBING ON TANK
3102	41	REPAIR LHS 2ND STEER GUARD RUBBING ON TANK
3103	STAR	*****
3104	n	reposition l/h 2nd steer gaurd
3401	31VO	REPAIR 1ST STEER RHS LOWER SHOCK MOUNT LOOSE
3402	STAR	*****
3701	11VO	REPLACE FRONT ENGINE MOUNT
3702	11	REPLACE FRONT ENGINE MOUNT
3703	VT20503551	MOUNT ENGINE FRONT FH NH D12A D12C-D
3704	VT990996	BOLT FLANGED 16MM X 150MM LONG
3705	VT990944	NUT FLANGED 16MM 8 GRADE
3706	VT20538904	WASHER
3707	VT21078879	HOSE CLAMP
3708	VT991074	NIPPLE PLASTIC 8MMX1.0MM REGULAR
3709	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
3710	VT3090957	RUBBER BUSHING
3711	VT20538906	WASHER
3712	VT20538171	SLEEVE
3713	VT20537955	WASHER
3714	VT20538166	BOLT MOUNT ENGINE FRONT FH-FM
3715	VT21104781	LINK ARM FRONT ENGINE MOUNT FH16 D16E
3716	VT21104784	BRACKET
3717	STAR	*****
3718	N	replace front engine mount and bolts as required
4001	32VO	REPAIR STEER FLUID LEAK AROUND RESERVOIR AND HOSES
4002	32L	REPAIR STEER FLUID LEAK AROUND RESERVOIR AND HOSES
4003	VTWUR053800816	HOSE CLAMP 9MM
4004	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
4005	VT991075	NIPPLE PLASTIC 12MMX1.5MM REGULAR

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
4006	VT25339078	NUT TAILSHAFT FE-LATE FH-M LATE MODELS
4007	STAR	*****
4008	n	repair power steering oil leak
4301	11VO	REPAIR OIL LEAK @ CRANK CASE VENT FILTER HOUSING
4302	11	REPAIR OIL LEAK @ CRANK CASE VENT FILTER HOUSING
4303	VT20532891	GASKET SEPERATOR BREATHER FM
4304	STAR	*****
4305	n	attend to oil leak at ccv.Replace mounting gasket and clean
4601	61VO	SECURE UNSECURED WIRES NEAR MAIN DRIVESHAFT
4602	61	SECURE UNSECURED WIRES NEAR MAIN DRIVESHAFT
4603	STAR	*****
4604	n	secure loos wiring as required
4901	33VO	REPLACE 1ST DRIVE DROP LINKS WORN/TORN BOOTS
4902	33	REPLACE 1ST DRIVE DROP LINKS WORN/TORN BOOTS
4903	VT21287061	ROD LINK STAB ANTI ROLL BAR REAR
4904	STAR	*****
4905	n	replace 1st drive axle drop links
5201	33VO	REPLACE CRACKED AIR BAGS
5202	33	REPLACE CRACKED AIR BAGS
5203	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
5204	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
5205	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
5206	VT992021	NIPPLE X
5207	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
5208	cc	CONSUMABLES
5209	VT991083	FITTING BRASS SWIVEL REGULAR M16X1.5
5210	VT992021	NIPPLE X
5211	AMFTM1862X8	JOINER 8mm PUSH IN
5212	VT980832	AIRLINE PLASTIC PIPE 8MM OD
5213	VT984859	BOLT FLANGED 14MM X 70MM LONG 10.9 GRADE
5214	VT992328	NUT FLANGED 14MM DEEP HEAD 8.8 GRADE
5215	star	*****
5216	n	replace 4 drive axle air bags
5501	63VO	REPAIR REVERSE BUZZER INOP/EXPOSED WIRING
5502	63	REPAIR REVERSE BUZZER INOP/EXPOSED WIRING
5503	STAR	*****
5504	n	repair reverse buzzer andsecure wiring
5801	34VO	REPLACE SUZI COILS DAMAGED/WORN
5802	34	REPLACE SUZI COILS DAMAGED/WORN
5803	AMABC78060	SUZI COIL AIR LONG TAIL
5804	AMABCABF108	COUPLING MALE WITH 1/2 FEMALE THREAD
5805	AMABCABF218	COUPLING, FEMALE 1
5806	star	*****
5807	n	replace suzi coils
6101	31VO	REPLACE 1ST STEER SHACKLE PINS WORN
6102	31	REPLACE 1ST STEER SHACKLE PINS WORN
6103	VT21630737	BOLT PIN SHACKLE SPRING FM-FH D123488-
6104	VT20533294	BUSH SPRING FRONT EYE FM-H D13 V2
6105	STAR	*****
6106	n	replace 1st steer shackle pins and bushes
6401	41VO	REPAIR CAB TILT FLIUD LEAKING RHS
6402	41	REPAIR CAB TILT FLIUD LEAKING RHS
6403	VT85123544	KIT HOSE CAB TILT RAM-RAM FH-M
6404	VT1161935	OIL HYDRAULIC CAB PUMP 1 LITRE
6405	VT85110123	NUT
6406	STAR	*****
6407	n	replace cab tilt hose and bleed system
6701	24VO	REPAIR TRANS COOLER HOSES (X2) UNSECURED & LEAKING
6702	24L	REPAIR TRANS COOLER HOSES (X2) UNSECURED & LEAKING
6703	VT21339891	HOSE WATER 13MM ID AIR COMP-WATER-OILCOL

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
6704	VT21052612	CONNECTOR PLASTIC 90 DEGREE
6705	VT21380391	CONNECTOR PLASTIC 45 DEGREE
6706	VT21380391	CONNECTOR PLASTIC 45 DEGREE
6707	VT21158071	CLAMP ATTACHMENT
6708	VT21279613	CONNECTOR
6709	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
6710	star	*****
6711	n	replace trans cooler hoses and secure
7001	33VO	REPAIR 1ST DRIVE SIGNIFICANT OUTPUT YOKE MOVEMENT
7002	33	REPAIR 1ST DRIVE SIGNIFICANT OUTPUT YOKE MOVEMENT
7003	VT1673393	NUT DIFF REAR THRU SHAFT RTS2370A
7004	VT1524838	SEALING RING
7005	VT1524838	SEALING RING
7006	VT994102	BOLT TAILSHAFT FE-LATE FH-M LATE48MMXM14
7007	star	*****
7008	n	remove jack shaft and replace out put flange retaining nut
7301	41VO	SUBLET TO REMOVE / REPLACE RH WINDOW TINT APPROX
7302	SC	REMOVE AND REPLACE RH WINDOW TINT
7303	STAR	*****
7304	n	sublet repair to remove and retint window
7601	41VO	REPAIR BATTERY BOX COVER LOOSE
7602	41	REPAIR BATTERY BOX COVER LOOSE
7603	VT192591	WING NUT BATTERY BOX
7604	VT960143	WASHER
7605	VT192591	WING NUT BATTERY BOX
7606	star	*****
7607	n	secure battery box cover

29/04/2019 R01055620

101	11VO	repair damage to truck - rework
102	11	repair damage to truck - rework
104	VT1676400	EXPANSION TANK WATER FL-FH12 D12A-CD B12
105	VT21312236	HOSE INTERCOOLER TOP D9A D12D 123488-
106	VT21312237	HOSE INTERCOOLER BOTTOM FH-M D12-D13
107	VTCAL8394800	COOLANT VCS PREMIX YELLOW 20LTR DRUM
108	VT990941	NUT FLANGED 10MM
109	VT21255304	OIL FILLER PIPE
110	VT20592783	CLAMP INTERCOOLER PIPE FH-NH-MP10
111	VT20740344	HOSE RADIATOR BOTTOM FH-M D13A D127846-
112	VT995680	HOSE CLAMP
113	VT20968388	HOSE HEATER FM-FH12 D12C
114	VT992084	HOSE CLAMP 23 - 35 SIZE
115	STAR	*****

29/04/2019 R01055622

101	41VO	REMOVE BULL BAR, REAR GAURDS, PTO, HYD TANK AND BRACKETS
102	41	REMOVE BULL BAR, REAR GAURDS, PTO, HYD TANK AND BRACKETS
103	VT21448610	PANEL GRILLE FRONT FH16 123488-
104	VT82065120	TRIM MOULDING
105	VT20529740	BUMPER BAR CENTRE FM-FH D123488-PLASTIC
106	VT82073938	COVER
107	VT984838	BOLT FLANGED 16MM X 90MM LONG 10.9 GRADE
108	VT82073948	COVER
109	VT21500484	CLAMPING PLATE
110	VT8154564	KIT FITTING CATWALK-LADDER FH FM NH
111	VT990962	LOCK NUT M16 STAB BAR & CAB FL C0589
112	VT1628670	BRACKET SUZI COIL & FUEL TANK
113	VT1669376	COVER PLATE PTO SR1700 SR1900
114	VT21425186	PLUG COVER GRILLE FRONT FM FH 12348-
115	VT992023	TEST NIPPLE FH-M VER-4
116	VT949647	O RING PTO COVER SR1900 I-SHIFT M-DRIVE
117	VT990951	LOCK NUT 10MM

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
118	VT1628671	PLATE RUBBER FUEL TANK & SUZI COIL
119	VT21425186	PLUG COVER GRILLE FRONT FM FH 12348-
120	VT994795	SCREW SIX POINT M6X16MM
121	VT991062	PLUG BRASS M16X1.5
122	VT984739	BOLT FLANGED 8MM X 50MM LONG 8.8 GRADE
123	VT984753	BOLT FLANGED 10MM X 25MM LONG 8.8 GRADE
124	VT996110	PLUG BLANK OFF 12MM
125	C	CONSUMABLES;CLEANING;EPA
126	STAR	*****
127	N	C: REMOVE BULL BAR, PTO, BRACKETS, GUARDS, HYDRAULIC TANK
128	N	C: REQUESTED
129	N	C: DRAINED HYDRAULIC TANK HAD ABOUT 140L AND DISPOSED OF OIL ALSO HAD
130	N	TO DRAIN SOME DIESEL FROM THE OTHER HALF OF THE TANK, REMOVED HOSES,
131	N	REMOVED TANK STRAPS, REMOVED TANK FROM VEHICLE. REMOVED BOLTS ON REAR
132	N	WHEEL GUARDS REMOVED GUARDS AND BRACKETS. REMOVED PTO CONTROL BOX AND
133	N	REMOVED WIRING TO BATTERY. REMOVED BRACKETS IN THE WAY OF HYDRAULIC
134	N	TANK FRAME. REMOVED BOLTS AND LIFTED TANK FRAME OUT WITH CRANE.
135	N	REMOVED FUEL LINE HOSE.REMOVED T-PIECE TO REMOVE ONE OF THE FITTINGS
136	N	AS IT WAS SEIZED ON BAD. ORDERED BLANK FOR FITTING. HAS ARRIVED READY
137	N	TO INSTALL. ORDERED BRACKETS FOR SUZI COIL MOUNTING POINT. WAITING ON
138	N	PARTS. INSTALLED BRACKETS FOR SUZI COIL CONNECTIONS. INSTALLED BLANK
139	N	IN FUEL LINE AND REFITTED. DRAINED GEARBOX OIL, REMOVED PTO INSTALLED
140	N	BLANKING PLATE ON GEARBOX WHERE PTO WAS. REFILLED GEARBOX OIL REMOVED
141	N	THE BULL BAR THEN TRIED REMOVING BULLBAR MOUNT FRAME ONE OF THE BOTLS
142	N	SEIZED ON SPENT SOME TIME ON THAT FINALLY REMOVED IT REMOVED THE
143	N	MOUNTING FRAME THEN REMOVED GRILLE CUT BACK SPOTLIGHT WIRES AND TAPED
144	N	THEM OFF ORDERED THE GRILLE PIECES AND ONCE THEY CAME IT FITTED THE
145	N	NEW CHASSIS GRILLE SECTIONS
401	11VO	FIT SUPPLIED GUARDS
402	11	FIT SUPPLIED GUARDS
403	STAR	*****
404	N	C- FIT SUPPLIED STAINLESS MUD GUARDS
405	N	C- REQUESTED
406	N	C- FITTED SUPPLIED POLES AND MESURED UP STAINLESS MUD GUARDS TO FIT
407	N	ON TRUCK WITH ENOUGH CLEARANCE ON SECOND STEER. CHECKED CLEARANCES,
408	N	REMOVED P/S REAR MUDFLAP TO USE FORK LIFT TO BENT STEEL LIGHT BAR
409	N	OUT, TO ALLOW ENOUGH CLEARANCE TO FIT GUARD. TIGHTED ALL GRUB SCREWS
410	N	AND CHASSIS POLE BOLTS.
1001	74VO	CARRY OUT SECOND RWC INSPECTION
1002	01	SERVICE LABOUR
1003	STAR	*****
1004	N	C: RWC 2ND INSPECTION
1005	N	C: FOLLOW UP FROM 1ST INSPECTION
1006	N	C: CONDUCTED 2ND INSPECTION. NOTED CABLES NEAR DRIVESHAFT LOOSE.
1007	N	SECURED CABLES AS NECESSARY. ALSO FOUND LHR GUARD LOOSE. TIGHTENED
1008	N	GUARD AND CHECKED OVER ALL OTHER GUARDS. INSPECTION PASSES. RWC
1009	N	ISSUED.
1301	33VO	check and repair rear suspension fault
1302	33	check and repair rear suspension fault
1303	VT22194741	SENSOR LEVEL VALVE FH-M GRAS D129093-
1304	VT20803650	SENSOR PRESSURE AIRBAG
1305	STAR	*****
1306	N	C: CHECK REPAIR REAR SUSPENSION FAULT
1307	N	C: AIR LEAKS AT SUSPENSION FITTINGS, FAULTY REAR PRESSURE SENSORS AND
1308	N	RH REAR LEVEL SENSOR OPEN CIRCUIT
1309	N	C: RIDE HEIGHT FAULT ON DASH. CHECKED CODES, ACTIVE CODE FOR RH LEVEL
1310	N	SENSOR. CHECKED WIRES AND CONNECTORS TO BOTH LEVEL SENSOR, ALL OK.
1311	N	CHECKED SENSOR RESISTANCE, FOUND RH SENSOR OPEN CIRCUIT. ORDERED AND
1312	N	FITTED NEW SENSOR. CHECKED SENSOR OPERATION. RECHECKED CODES, LEVEL
1313	N	SENSOR FAULT NOW INACTIVE. CHECKED RIDE HEIGHT OPERATION WITH HAND

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
1314	N	CONTROLLER, STILL NOT OPERATING CORRECTLY, NOT RETURNING TO RIDE
1315	N	HEIGHT. CONDUCTED PRESSURE SENSOR VALUE CHECK. FOUND NEGATIVE ERRATIC
1316	N	PRESSURE SENSOR READINGS. REPLACED SENSORS. RECHECKED PRESSURE SENSOR
1317	N	READING, ALL OK. CONDUCTED RIDE HEIGHT CALIBRATION AND OPERATION
1318	N	CHECK, ALL OK. DURING REPAIRS AIR LEAKS WERE DETECTED AT RHR
1319	N	SUSPENSION FITTINGS. REPLACED LEAKING FITTINGS. RECHECKED FOR AIR
1320	N	LEAKS, ALL OK.
1321	N	.
1322	N	NOTE: TURNTABLE CHANGE OVER PENDING !
1601	41VO	CHANGE TURN TABLE TO PEDESTAL TYPE - K HITCH
1602	SC	CHANGE OVER TURNTABLE TO PEDESTAL, P0151857 K HITCH
1603	STAR	*****

20/06/2019 **R01058204**

101	33VO	RECTIFY LEAKING AIR BAG??? QUOTE PRIOR TO REPAIR
102	33	RECTIFY LEAKING AIR BAG??? QUOTE PRIOR TO REPAIR
103	c	CONSUMABLES;CLEANING;EPA
104	STAR	*****
105	VT992023	TEST NIPPLE FH-M VER-4
106	VT991980	T NIPPLE
107	VT991074	NIPPLE PLASTIC 8MMX1.0MM REGULAR
108	VT992021	NIPPLE X
109	VT992247	FITTING BRASS SWIVEL M16X1.5
110	VT991075	NIPPLE PLASTIC 12MMX1.5MM REGULAR
111	VT991083	FITTING BRASS SWIVEL REGULAR M16X1.5
112	VT991074	NIPPLE PLASTIC 8MMX1.0MM REGULAR
113	VT991075	NIPPLE PLASTIC 12MMX1.5MM REGULAR
114	n	C RECTIFY LEAKING AIR BAG
115	n	C BELLOWS WERE DROPPING
116	n	C ALL BELLOWS WERE CHECKED FOR LEAKAGE NO LEAKAGE FOUND ON BELLOWS
117	n	FOLLOWING WERE REASONS:-
118	n	TOO MUCH OIL AND WATER IN RESERVIOR TANK ALL TANKS DRAINS
119	n	TEE CONECTOR ON TOP BELLOW ON LH SIDE WAS LEAKING BADLY REPLACE

04/07/2019 **R01059018**

101	32VO	CHECK/QUOTE PWR STEERING LEAK
102	STAR	*****
103	n	C: Check/quote power steering leak
104	n	C: Requested
105	n	C: Visual inspection and washed the engine. Took for test drive,
106	n	brought back and check the power steering leak and was coming from
107	n	the bottom rubber power steering line which is connected to the power
108	n	steering box, quoted all the parts. Customer declined and will
109	n	collect truck.
1001	02CAMP	CAMPAIGN CHECK
1002	N	*****
1003	N	NO CAMPAIGNS OUTSTANDING
1004	N	CHECK BY EN
1005	N	DATE 3.7.19
1006	N	*****

07/10/2019 **R01063420**

101	74VO	Carry out roadworthy inspection
102	74	INSPECTIONS LABOUR
103	STAR	*****
104	n	- Mirror lights on passenger side but not driver side,
105	n	Unsymmetrical
106	n	Lighting
107	n	- fire extinguisher expired in cab
108	n	- driver door mirror adjuster module inop
109	n	- sunroof switch inop
110	n	- air leak control box behind driver side steer guard

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
111	n	- driver side window scratched and frosted
112	n	- bullbar placards damaged/unsecured
113	n	- chassis fire extinguisher expired
114	n	- hookup light inop
115	n	- passenger side 1st axle steer guard damaged
116	n	- outer fog lights inop, fault on dash
117	n	- lhs 2nd steer guard rubbing on tank
118	n	- 1st drive mud flaps torn
119	n	- battery box cover missing fastener
120	n	- bullbar indicators cracked/water ingress
121	n	- 1st steer driver side lower shock mount loose
122	n	- front engine mount worn/cracked
123	n	- steer fluid leak around reservoir and hoses
124	n	- oil leak around crank case vent filter housing
125	n	- unsecured wires near main driveshaft
126	n	- 1st drive drop links worn/torn boots
127	n	- 1st drive lhr airbag cracked
128	n	- 2nd drive lhf airbag cracked
129	n	- 2nd drive rear airbags cracked
130	n	- reverse buzzer inop/exposed wiring
131	n	- suzi coils damaged/worn
132	n	- 1st steer shackle pins worn
133	n	- sandwich plate minor oil weeping (wash n inspect,
134	n	Recommend repair)
135	n	- cab tilt fluid leaking rhs
136	n	- trans cooler hoses (x2) unsecured and leaking
137	n	- 1st drive significant output yoke movement

07/10/2019 **R01063421**

101	63VO	Repair mirror lights as required
102	63	LIGHTS LABOUR
103	VT20746401	COVER MIRROR FM-FH LH-RH CH 123488-
104	STAR	*****
105	N	Removed the l/h clearance lights and fitted a new back cover as both
106	N	lights need to be symmetrical remounted the top work light on the r/h
107	N	mirror as it was just hanging there had to drill out the rivets on
108	N	the l/h mirror and completely disassemble it to tape off the positive
109	N	and negative wires for clearance lights.
401	63VO	Repair RH Mirror Adjuster N/W
402	63	LIGHTS LABOUR
403	VT22566508	SWITCH PANEL R/H WINDOWS & MIRROR
404	STAR	*****
405	n	C: Repair mirror adjuster not working
406	n	C: Switch block faulty
407	n	C: Tested the adjuster it adjusted in all directions except to the
408	n	right swapped over with another one was working ordered new switch
409	n	block installed it working good.
701	62VO	Repair sunroof switch inop
702	62	INSTRUMENTS LABOUR
703	STAR	*****
704	n	Checked the switches both were working correctly and had power and
705	n	ground to them, removed the lining around the sunroof underneath it,
706	n	tested the control unit it was working found it had power and ground
707	n	and both signals were there the power and ground were good at the
708	n	motor removed control unit and disassembled checked position sensor
709	n	wheel wasn't stuck all good checked over the rails found the sliding
710	n	mechanism wasn't clean and some dirt had gotten in cleaned it out and
711	n	manually wound the motor back and forth then the roof hatch was
712	n	working as it should.
1001	62VO	Replace both fire extinguishers
1002	62	INSTRUMENTS LABOUR

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
1003	VT22556828	FIRE EXTINGUISHER 2.3KG AND BRACKET FIRX925A
1004	STAR	*****
1005	n	Replace both fire extinguishers as required
1301	63VO	Repair hookup light inop
1302	63	LIGHTS LABOUR
1303	SPACX3064	TERMINAL JOINER RED STD & HEAT SHRINKABL
1304	AMNARV56600	HEATSHRINK PACK 3.2mm - 6.4mm DIA
1305	AMNARV72430	9-80V LED WORK LAMP FLOOD BEAM
1306	STAR	*****
1307	n	Replaced hook up light and repair wiring
1601	41VO	Repair passenger side 1st axle steer guard damaged
1602	41	BODY PANELS LABOUR
1603	STAR	*****
1604	n	Replaced damaged 1st steer mudguard
1901	63VO	Repair outer fog lights inop, fault on dash
1902	63	LIGHTS LABOUR
1903	n	Replace fog light globes and repair wiring
1904	STAR	*****
1905	AMNARV48700	GLOBE H3 24V 70W
1906	AMNARV56310	CABLE TIE LARGE 1=10PACK BLACK NARVA
2201	41VO	Repair LHS 2nd steer guard rubbing on tank
2202	41	BODY PANELS LABOUR
2203	STAR	*****
2204	n	Reposition l/h 2nd steer gaurd
2501	11VO	Replace front engine mount
2502	11	ENGINE MECHANICAL LABOUR
2503	VT20503551	MOUNT ENGINE FRONT FH NH D12A D12C-D
2504	VT990996	BOLT FLANGED 16MM X 150MM LONG
2505	VT990944	NUT FLANGED 16MM 8 GRADE
2506	VT20538904	WASHER
2507	VT21078879	HOSE CLAMP
2508	VT991074	NIPPLE PLASTIC 8MMX1.0MM REGULAR
2509	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
2510	VT3090957	RUBBER BUSHING
2511	VT20538906	WASHER
2512	VT20538171	SLEEVE
2513	VT20537955	WASHER
2514	VT20538166	BOLT MOUNT ENGINE FRONT FH-FM
2515	VT21104781	LINK ARM FRONT ENGINE MOUNT FH16 D16E
2516	VT21104784	BRACKET
2517	STAR	*****
2518	n	Replace front engine mount and bolts as required
2801	32VO	Repair steer fluid leak around reservoir and hoses
2802	32L	STEERING LABOUR
2803	VTWUR053800816	HOSE CLAMP 9MM
2804	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
2805	VT991075	NIPPLE PLASTIC 12MMX1.5MM REGULAR
2806	VT25339078	NUT TAILSHAFT FE-LATE FH-M LATE MODELS
2807	STAR	*****
2808	n	Repair power steering oil leak
3101	11VO	Repair oil leak at crank case vent filter housing
3102	11	ENGINE MECHANICAL LABOUR
3103	VT20532891	GASKET SEPERATOR BREATHER FM
3104	STAR	*****
3105	n	Attend to oil leak at ccv, replaced mounting gasket and cleaned.
3401	61VO	Secure unsecured wires near main driveshaft
3402	61	CHASSIS ELECTRICAL LABOUR
3403	STAR	*****
3404	N	Secure loose wiring as required.
3701	33VO	Replaced cracked air bags

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
3702	33	REAR AXLE LABOUR
3703	c	CONSUMABLES;CLEANING;EPA
3704	n	- Replaced 4 drive axle air bags
3705	STAR	*****
3714	VT980832	AIRLINE PLASTIC PIPE 8MM OD
3715	VT984859	BOLT FLANGED 14MM X 70MM LONG 10.9 GRADE
3716	VT992328	NUT FLANGED 14MM DEEP HEAD 8.8 GRADE
4001	63VO	Repair reverse buzzer inop/exposed wiring
4002	63	LIGHTS LABOUR
4003	STAR	*****
4004	n	Repair reverse buzzer and secured wiring
4301	34VO	Replaced suzi coils damaged/worn
4302	34	BRAKES LABOUR
4303	AMABC78060	SUZI COIL AIR LONG TAIL
4304	AMABCABF108	COUPLING MALE WITH 1/2 FEMALE THREAD
4305	AMABCABF218	COUPLING, FEMALE 1
4306	STAR	*****
4307	n	Replaced suzi coils
4601	31VO	Replace 1st steer shackle pins worn
4602	31	FRONT AXLE LABOUR
4603	VT21630737	BOLT PIN SHACKLE SPRING FM-FH D123488-
4604	VT20533294	BUSH SPRING FRONT EYE FM-H D13 V2
4605	STAR	*****
4606	n	Replaced 1st steer shackle pins and bushes
4901	41VO	Repair cab tilt fluid leaking R/H/S
4902	41	BODY PANELS LABOUR
4903	VT85123544	KIT HOSE CAB TILT RAM-RAM FH-M
4904	VT1161935	OIL HYDRAULIC CAB PUMP 1 LITRE
4905	VT85110123	NUT
4906	STAR	*****
4907	n	Replace cab tilt hose and bleed system
5201	24VO	Repair trans cooler hoses (x2) unsecured and leaking
5202	24L	AUTO TRANSMISSION LABOUR
5203	STAR	*****
5204	VT21339891	HOSE WATER 13MM ID AIR COMP-WATER-OILCOL
5205	VT21052612	CONNECTOR PLASTIC 90 DEGREE
5206	VT21380391	CONNECTOR PLASTIC 45 DEGREE
5207	VT21380391	CONNECTOR PLASTIC 45 DEGREE
5208	VT21158071	CLAMP ATTACHMENT
5209	VT21279613	CONNECTOR
5210	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
5211	star	*****
5212	n	Replaced trans cooler hoses and secured
5501	33VO	Repair 1st Drive significant output yoke movement
5502	33	REAR AXLE LABOUR
5503	STAR	*****
5504	VT1673393	NUT DIFF REAR THRU SHAFT RTS2370A
5505	VT1524838	SEALING RING
5506	VT1524838	SEALING RING
5507	VT994102	BOLT TAILSHAFT FE-LATE FH-M LATE48MMXM14
5508	star	*****
5509	n	- Removed jack shaft and replace out put flange retaining nut.
5801	11VO	Sublet to remove /replace r/h window tint
5802	s	PO - 156132 - Cooler Glass Tint
6101	41VO	Repair battery box cover loose
6102	41	BODY PANELS LABOUR
6103	VT192591	WING NUT BATTERY BOX
6104	VT960143	WASHER
6105	VT192591	WING NUT BATTERY BOX
6106	STAR	*****

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
6107	n	Secure battery box cover
6401	33VO	Replace 1st Drive drop links worn/torn boots
6402	33	REAR AXLE LABOUR
6403	VT21287061	ROD LINK STAB ANTI ROLL BAR REAR
6404	N	Replaced 1st drive axle drop links
6405	STAR	*****
8706	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
8707	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
8708	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
8709	VT992021	NIPPLE X
8710	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
8711	VT991083	FITTING BRASS SWIVEL REGULAR M16X1.5
8712	VT992021	NIPPLE X
8713	AMFTM1862X8	JOINER 8MM PUSH-IN STRAIGHT

22/11/2019 R01065585

101	33VO	Check & Rectify Airbag Level Valve Operation
102	33	Check & Rectify Airbag Level Valve Operation
103	VT21083660	VALVE CONTROL SUSPENSION LHS FM-H
104	VT21083657	VALVE CONTROL SUSPENSION RHS FM-H
105	VT991083	FITTING BRASS SWIVEL REGULAR M16X1.5
106	VT994000	ELBOW NIPPLE 12MM PUSH IN TYPE
107	VT20738621	SEAL PLUG HOUSING SUIT 984849
108	VT984846	CABLE TERMINAL
109	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
110	C	CONSUMABLES;CLEANING;EPA
111	STAR	*****
112	n	Billy mentioned air bag leveling valve not operating and leveling out
113	n	airbags.
114	N	C: Check and rectify airbag level valve operation
115	N	C: Sticking solenoid valves
116	N	C: Carried out all tests, found the solenoid valves were sticking
117	N	causing suspension to get stuck up. Quoted parts. Removed and
118	N	replaced solenoid valves as required, had to replace fittings as u/s.
119	N	Fitted & checked over, no leaks. Also re-pin valve electrical plug as
120	N	one terminal had slight corrosion. Road tested all ok.
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECK BY ...Beck.....
405	N	DATE .21/11/19...
406	N	*****

04/01/2020 R01067382

101	11VO	CHECK/QUOTE ENGINE FAN ON CONSTANTLY - no show
102	STAR	*****
103	N	CUSTOMER HAS REPLACED FAN, BELT & TENSIONER RECENTLY
104	STAR	*****

19/08/2020 R01076861

101	12VO	Check Engine Light On Dash - High Emissions
102	12	Check Engine Light On Dash - High Emissions
103	VT22827995	SENSOR NOX EXHAUST SCR B7R FH-M VER 4
104	VT21738132	VALVE DOSAGE UREA FH-M 13-16 EAS-SCR ENG
105	VT990413	HEX. SOCKET SCREW
106	C	CONSUMABLES;CLEANING;EPA
107	STAR	*****
108	N	C: CHECK HIGH EMISSION ON DASH
109	N	C: FOUND NOX SENSOR AT FAULT AND DOSAGE VALVE LEAKING. ALSO FOUND ABS
110	N	LIGHT ON DASH WHICH WAS A 20% DIFFERENCE ON TE BRAKE PADS ON AXLE 3.
111	N	ALSO FOUND FAULT ON INDICATOR WILL QUOTE GLOBE BUT WILL NEED MORE
112	N	TIME IF IT IS A WIRING FAULT AND NOT JUST GLOBE.

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
113	N	C: PLUGGED IN TECHTOOL AND CHECKED FAULTS, FOUND A COUPLE ACTIVE.
114	N	DIAGNOSED AND FOUND FAULT IN NOX SENSOR, ADBLUE DOSAGE VALVE LEAKING
115	N	AND NEEDS REPLACING. DIFFERENCE WEAR IN AXLE 3 BRAKE PADS. RIGHT HAND
116	N	SIDE INDICATOR NOT WOKRING. ALL PARTS QUOTED PARTS APPROVED. REPLACED
117	N	ONLY THE DOSAGE VALVE AND NOX AS CUSTOMER REQUEST. DID A DOSAGE TEST,
118	N	ALL OK. ROAD TEST AND ENGINE LIGHT GONE - TRUCK ALL OK.
401	COVIDSAN	SANITISE TRUCK
402	74SAN	WIPE DOWN BEFORE / AFTER ENTERING VEHICLE
403	STAR	*****
404	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
405	N	THE START & COMPLETITION OF WORKS
701	02CAMP	CAMPAIGN CHECK
702	N	*****
703	N	NO CAMPAIGNS OUTSTANDING
704	N	CHECKED BYBeck.....
705	N	DATE .14/08/20....
706	N	*****
27/11/2020 R01080484		
101	11VO	CHECK & QUOTE ENGINE DERATE WARNING ON DASH
102	11	CHECK & QUOTE ENGINE DERATE WARNING ON DASH 8
103	VT21333097	FILTER KIT AD-BLUE PUMP FM/FH VER2
104	VT20877939	FILTER CAP AD BLUE
105	VT20748166	CONNECTOR ELBOW 45 AD-BLUE SAE 3/8
106	VT20744599	CONNECTOR ELBOW 45 AD-BLUE SAE 5/16
107	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
108	VT21032572	HOSE CLAMP AD-BLUE
109	C	CONSUMABLES;CLEANING;EPA
110	STAR	*****
111	N	P) CHECK & QUOTE ENGINE DERATE WARNING ON DASH.
112	N	C) DIRT IN ADBLUE TANK, PUMP AND BLOCKED FILTER.
113	N	R) FITTED THE PICKUP BACK IN TANK, THEN REMOUNTED THE AIR TANK TO ITS
114	N	BRACKET AND SECURED. HAD TO REPLACE ONE OF THE ADBLUE PICKUP FITTINGS
115	N	AS FOUND IT BROKEN, THEN FLUSHED THE PUMP AND THE LINES OUT WITH WARM
116	N	WATER. ONCE THEY WERE CLEAN, FITTED THE LINES BACK TO THE PICKUP AND
117	N	SECURED. FITTED BACK THE FILLER NECK AND THE TANK DRAIN PLUG THEN
118	N	FILLED 50L OF ADBLUE INTO THE TANK. CLEARED ALL FAULT CODES AND ROAD
119	N	TESTED THE VEHICLE, FOUND THERE TO BE NO FAULT WITH THE SYSTEM.
401	02CAMP	CAMPAIGN CHECK
402	N	*****
403	N	NO CAMPAIGNS OUTSTANDING
404	N	CHECKED BYMATT H.....
405	N	DATE25/11/20....
406	N	*****
701	COVIDSAN	SANITISE TRUCK
702	STAR	*****
703	N	REMINDER - WIPE DOWN HIGH TOUCH AREAS AT
704	N	THE START & COMPLETION OF WORKS
1001	01TP	****TIME PERMITTING ONLY - BELOW THIS LINE**** _____
1002	N	*TIME PERMITTING ONLY - BELOW THIS LINE*
1003	star	*****
1301	17VO	CHECK & REPORT ENGINE FAN NOT CUTTING OFF SOMETIMES
1302	17	CHECK & REPORT ENGINE FAN NOT CUTTING OFF SOMETIMES 5
1303	VT85000818	EXC THERMO FAN D13C D16C FH
1304	VT990950	NUT FLANGED LOCK NUT 8MM 8 GRADE
1305	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
1306	STAR	*****
1307	N	P) CHECK & REPORT ENGINE FAN NOT CUTTING OFF.
1308	N	C) FAILED FAN.
1309	N	R) INSPECTED THE WIRING HARNESS AND THEN TESTED THE FAN, FOUND THE
1310	N	FAN TO HAVE AN INTERNAL FAULT. QUOTED FAN AS REQUIRED. ONCE APPROVED,

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
1311	N	REMOVED AND REPLACED FAN AS REQUIRED. TESTED AND ALL OPERATING AS IT
1312	N	SHOULD.
1601	33VO	CHECK & REPORT DIFF LOCK WARNING FLASHING CONSTANTLY
1602	33	CHECK & REPORT DIFF LOCK WARNING FLASHING CONSTANTLY 1.5
1603	VT3197873	SWITCH DIFF LOCK CLOSED FH FM VERSION1&2
1604	STAR	*****
1605	N	P) CHECK & REPORT DIFF LOCK WARNING FLASHING CONSTANTLY.
1606	N	C) REAR MOST DIFF LOCK POSITION SENSOR.
1607	N	R) CHECKED THE OPERATION OF THE DIFF LOCK AND IT IS OPERATING, BUT
1608	N	THE LIGHT REMAINS ON AND FLASHING ALL OF THE TIME. REMOVED THE SWITCH
1609	N	IN THE DASH AND ENSURED IT WAS CORRECTLY FITTED AND IT WAS. REMOVED
1610	N	THE PLUG OFF THE DIFF LOCK POSITION SENSORS ONE AT A TIME AND CHECKED
1611	N	THE DASH, FOUND THAT THE REAR MOST SENSOR WAS AT FAULT SENDING AN
1612	N	INCORRECT SIGNAL. QUOTED REQUIRED PARTS AS REQUESTED. REMOVED AND
1613	N	REPLACED SENSOR AND TESTED, LIGHT IS NOW OFF AS IT SHOULD BE AND ON
1614	N	WHEN ACTIVATION OF THE DIFF LOCK.
1901	17VO	CHECK & REPORT SUSPECTED COOLANT LEAK
1902	17	CHECK & REPORT SUSPECTED COOLANT LEAK 1
1903	STAR	*****
1904	N	The driver said he saw a pool of water
1905	N	on the ground under the engine this morning.
1906	star	*****
1907	N	P) CHECK & REPORT SUSPECTED COOLANT LEAK.
1908	N	C) CUSTOMER REQUESTED.
1909	N	R) INSPECTED AND COULD NOT FIND ANY LEAKS, THEN PRESSURE TESTED THE
1910	N	COOLING SYSTEM FOR HALF AN HOUR AND IT MAINTAINED PRESSURE.
1911	N	REINSPECTED AND THERE WERE NO LEAKS.

01/08/2025 **R01126143**

101	01VOBD	ATTEND VOLVO BREAKDOWN 3 HRS MINIMUM
102	01	BREAKDOWN LABOUR INCLUDING TRAVEL - 3 HR MIN.
103	kt	KM TRAVEL CHARGE
104	VT20731521	PIPE AIR DRIER COOLING COIL D13A
105	VT969289	VIPS JOINER 8MM TUBE
106	VT969290	VIPS JOINER 12MM TUBE FEMALE
107	VT976446	VIPS JOINER 12MM TUBE MALE
108	VT976445	VIPS JOINER 8MM TUBE
109	AM97445526062400	SILICONE HOSE 5/8 (SOLD PER FOOT)
110	VT21380391	CONNECTOR PLASTIC 45 DEGREE
111	VT20915849	HOSE CLAMP 27MM ID
112	VTAMP24754661	COOLANT VCS PREMIX VOLVO 5LTR CONTAINER
113	VTAMP24754665	COOLANT VCS PREMIX VOLVO 20LTR DRUM
114	STAR	*****
115	n	ADDRESS:32 lillie crescent tuallamarne vic 3043
116	N	DRIVER PH#0411708458
117	N	CALLER PH# charles bunker smith
118	N	.
119	N	C: AIR LEAK
120	N	C: COOLING COIL PIPE HAD PIN HOLE LEAK DUE TO CORROSION, TRANS COOLER
121	N	HOSE SPLIT AND COMPRESSOR PRESSURIZING HEADER TANK
122	N	C: CALLED CLIENT BEFORE LEAVING WORKSHOP AS THEY KNEW EXACT PART
123	N	REQUIRED CAUSING AIR LEAK, REPLACED PART AND STARTED TRUCK
124	N	-FOUND TRUCK TOOK A LONG TIME TO BUILD UP BUT BUILT UP TO 11BAR +,
125	N	RELEASED BRAKES = OK
126	N	-CUSTOMER ASKED TO BORROW THE WATERING CAN TO TOP UP TRUCK, NOTICED
127	N	EXCESSIVE LEAK ON RHS
128	N	-FOUND TRANS COOLER HOSE SPLIT, AS I REMOVED THE HOSE, THE BRITTLE
129	N	PLASTIC FITTINGS BROKE AWAY
130	N	-DID NOT HAVE SAME HOSE ON BOARD, BUT MADE A SUITABLE REPLACEMENT
131	N	-FILLED TRUCK WITH COOLANT AND FOUND THAT THE COMPRESSOR WAS
132	N	PRESSURIZING HEADER TANK AND EXPELLING ALL THE COOLANT

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
133	N	-ADVISED CUSTOMER THAT A COMPRESSOR REPLACEMENT IS REQUIRED
701	11VO	please call billy before you go to tell you what part is required
702	STAR	*****
31/05/2019 R99002890		
101	CMVREG	3 Months Registration
102	REG001	CMV Administration Fee
401	CMVONROAD	On Roads:
402	REG003	Stamp Duty @ 4.2%
403	REG004	Registration
404	REG005	Plates
405	REG006	TAC Fee
406	REG007	Stamp Duty on TAC Fee
407	REG008	Vic Roads Admin Fee
408	REG009	Vic Roads Inspection Fee
26/05/2020 RE0014546		
401	32VO	Check Hard Steering - Hard to turn
402	n	CUSTOMER SUSPECTS COULD BE LOW ON POWER STEERING FLUID
403	11	JUMP START VEHICLE
404	S	MAKE FITTING TO SAMPLE
405	STAR	*****
406	N	Temp repair done due no part, charged customer on LE0022612.
701	01VOBSR	RETAIL BASIC SERVICE
702	01	RETAIL BASIC SERVICE
703	34	Carry out Brake Roller Test 3 Axle
704	VT85136742	KIT FILTER BASIC D9-11-13-16 EURO4-5 B9
705	VTWUR0892333	WINDSCREEN WASHER ADDITIVE ONE SHOT
706	SPDW4	WATER DISTILLED 4LTR BOTTLE
707	SPDW1	WATER DISTILLED 1LTR BOTTLE
708	VDS4	VGA CAL85121795 ENGINE OIL
709	VC	V.C.A.D.'s CONNECTION FEE
710	GR	GREASE
711	STAR	*****
712	N	Carried out Basic service as per service check list.
713	N	Replace engine oil & filters, fuel filter.
714	N	Checked and level all other fluid levels, including battery water.
715	N	Checked lights,
716	N	Checked for any oil leaks and reported,
717	N	Checked for air leaks,
718	N	Checked all engine mounts and brackets,
719	N	Checked over truck for oil leaks and reported any faults found,
720	N	Checked all suspension components,
721	N	Washed down engine and Road tested, all ok.
722	N	Brake %
723	N	Steer
724	N	R/H =56 % L/H =64.0 %
725	N	2steer-29.6 =16.8
726	N	1St Drive
727	N	R/H = 46.8 % L/H =64.0 %
728	N	2nd Drive
729	N	R/H =78.0% L/H =81.6 %
1001	01VO	INSPECT ALL OILS AND REPORT
1002	star	*****
1301	02CAMP	CAMPAIGN CHECK
1302	N	*****
1303	N	NO CAMPAIGNS OUTSTANDING
1304	N	CHECK BY MADDY
1305	N	DATE 21/05/2020
1306	N	*****
1601	11VO	REPAIR POWER STEERING PUMP LEAKING
1602	11	LABOUR

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
1603	VT22213665	SERVO PIPE
1604	VT1161995	OIL ATF DEXRON 3 5LT VOLVO
1605	VT25559715	SEALING RING POWER STEERING PUMP D132---
1606	VT23296894	NIPPLE PWR STEERING PIPE FM
1607	STAR	*****
1608	N	C: Repair power steering pump leaking.
1609	N	C: Cracked/leaking high pressure pipe.
1610	N	C: Removed and replaced
1611	N	power steering hose to pump, replace washer and top up oil & bled
1612	N	system.
1901	11VO	REPAIR AIR COMPRESSOR HEAD LEAKING
1902	11	REPAIR AIR COMPRESSOR HEAD LEAKING
1903	VT22203109	REPAIR KIT COMPRESSOR HEAD
1904	VT471708	O RING OIL COOLER AND COMPRESSOR HEAD
1905	c	CONSUMABLES;CLEANING;EPA
1906	STAR	*****
1907	n	C-Repair air compressor leaking
1908	n	C-Leaking from air comp head
1909	n	C-Remove and replace air compressor cylinder head as per proce-dure.
2201	34VO	REPLACE 2ND AXLE BRAKE PADS - LOW
2202	34	REPLACE 2ND AXLE BRAKE PADS - LOW
2203	VT23149532	KIT BRAKE PAD FH-M D128250-FE(3)-MACK DISC NB
2204	STAR	*****
2205	n	C: Replace 2nd axle brake pads
2206	n	C: Worn out brake pads
2207	n	C: Carried out brake test, found brake pad come wear limit.
2208	n	Removed wheels and replaced brake pads on 2nd axles.
2209	n	Refitted wheels & torqued all to spec.
2501	11VO	REPLACE INNER & OUTER AIR FILTER & AIR DRIER FILTER
2502	11	REPLACE INNER & OUTER AIR FILTER & AIR DRIER FILTER
2503	VT21716424	FILTER AIR OUTER FH16 D16C-E
2504	VT20411816	FILTER AIR INNER FH16 D16C-E
2505	STAR	*****
2506	N	C: Replace air filter
2507	N	C: Blocked / dirty
2509	N	C: Removed and replaced air filter as req.
2801	11VO	DIAGNOSE & QUOTE CAB TILT LEAK
2802	N	C-Check and quote cab tilt leak
2803	N	C-Requested
2804	N	C-Inspect and found cab tilt rams very slightly leaking. Also found
2805	N	cab tilt pump very slightly leaking. Would recommend wash and
2806	N	monitor, but have quoted anyway
3101	01VO	WASH ALL CAB TILT COMPONENTS AS REQUESTED BY CUSTOMER
3102	01	WASH ALL CAB TILT COMPONENTS AS REQUESTED BY CUSTOMER
3401	11VO	REPLACE AIR DRIER FILTER
3402	11	ENGINE MECHANICAL LABOUR
3403	VT21620181	FILTER AIRDRYER BUS MK3-4-FH-NH-FM-B8R
3404	STAR	*****
3405	N	C: Replace air drier filter - APM
3406	N	C: Blocked / consumed
3407	N	C: Removed and replaced air drier filter and carried out reset.
3701	11VO	JUMP START VEHICLE
3702	STAR	*****
3703	N	VEHICLE WOULD NOT START WHEN PICKED UP BY CUSTOMER

07/12/2020 **RE0020159**

101	41VO	PUT GREASE ON TURNTABLE AS PER DRIVER'S REQUEST
102	41	PUT GREASE ON TURNTABLE AS PER DRIVER'S REQUEST
103	STAR	*****

07/10/2019 **S01004820**

102	74	CARRY OUT ROAD WORTHY INSPECTION
-----	----	----------------------------------

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
702	63	REPAIR MIRROR LIGHTS AS REQUIRED
703	VT20746401	COVER MIRROR FM-FH LH-RH CH 123488-
1002	62	REPAIR RH MIRROR ADJUSTER N/W
1003	VT22566508	SWITCH PANEL
1302	62	REPAIR SUNROOF SWITCH INOP
1902	62	REPLACE BOTH FIRE EXTINGUISHERS
1903	VT22556828	FIRE EXTINGUISHER 2.3KG AND BRACKET FIRX925A
2202	63	REPAIR HOOKUP LIGHT INOP
2203	SPACX3064	TERMINAL JOINER RED STD & HEAT SHRINKABL
2204	AMNARV56600	HEATSHRINK PACK 3.2mm - 6.4mm DIA
2205	AMNARV72430	9-80V LED WORK LAMP FLOOD BEAM
2502	41	REPAIR PASSENGER SIDE 1ST AXLE STEER GUARD DAMAGED
2802	63	REPAIR OUTER FOG LIGHTS INOP, FAULT ON DASH
2803	AMNARV48700	GLOBE H3 24V 70W
2804	AMNARV56310	CABLE TIE LARGE 1=10PACK BLACK NARVA
3102	41	REPAIR LHS 2ND STEER GUARD RUBBING ON TANK
3702	11	REPLACE FRONT ENGINE MOUNT
3703	VT20503551	MOUNT ENGINE FRONT FH NH D12A D12C-D
3704	VT990996	BOLT FLANGED 16MM X 150MM LONG
3705	VT990944	NUT FLANGED 16MM 8 GRADE
3707	VT21078879	HOSE CLAMP
3708	VT991074	NIPPLE PLASTIC 8MMX1.0MM REGULAR
3709	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
3710	VT3090957	RUBBER BUSHING
3711	VT20538906	WASHER
3712	VT20538171	SLEEVE
3713	VT20537955	WASHER
3714	VT20538166	BOLT MOUNT ENGINE FRONT FH-FM
3715	VT21104781	LINK ARM FRONT ENGINE MOUNT FH16 D16E
3716	VT21104784	BRACKET
4002	32L	REPAIR STEER FLUID LEAK AROUND RESERVOIR AND HOSES
4003	VTWUR053800816	HOSE CLAMP 9MM
4004	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
4005	VT991075	NIPPLE PLASTIC 12MMX1.5MM REGULAR
4006	VT25339078	NUT TAILSHAFT FE-LATE FH-M LATE MODELS
4302	11	REPAIR OIL LEAK @ CRANK CASE VENT FILTER HOUSING
4303	VT20532891	GASKET SEPERATOR BREATHER FM
4602	61	SECURE UNSECURED WIRES NEAR MAIN DRIVESHAFT
4902	33	REPLACE 1ST DRIVE DROP LINKS WORN/TORN BOOTS
4903	VT21287061	ROD LINK STAB ANTI ROLL BAR REAR
5202	33	REPLACE CRACKED AIR BAGS
5203	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
5204	VT21961456	AIR BAG GRAS FR OF FR RE OF REAR VER2
5205	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
5206	VT992021	NIPPLE X
5207	VT991971	NIPPLE PLASTIC 8MMX1.0MM SMALL
5208	cc	CONSUMABLES
5209	VT991083	FITTING BRASS SWIVEL REGULAR M16X1.5
5210	VT992021	NIPPLE X
5211	AMFTM1862X8	JOINER 8mm PUSH IN
5212	VT980832	AIRLINE PLASTIC PIPE 8MM OD
5213	VT984859	BOLT FLANGED 14MM X 70MM LONG 10.9 GRADE
5214	VT992328	NUT FLANGED 14MM DEEP HEAD 8.8 GRADE
5502	63	REPAIR REVERSE BUZZER INOP/EXPOSED WIRING
5802	34	REPLACE SUZI COILS DAMAGED/WORN
5803	AMABC78060	SUZI COIL AIR LONG TAIL
5804	AMABCABF108	COUPLING MALE WITH 1/2 FEMALE THREAD
5805	AMABCABF218	COUPLING, FEMALE 1
6102	31	REPLACE 1ST STEER SHACKLE PINS WORN
6103	VT21630737	BOLT PIN SHACKLE SPRING FM-FH D123488-

Repair Order History

Stock#: 137526 **Rego:** AZU291 **VIN:** YV5AP80G4DD137526
Model: FH600 **Body:** P/MVR **Color:** Color

RO Date **RO#**

Line#	Product	Description
6104	VT20533294	BUSH SPRING FRONT EYE FM-H D13 V2
6402	41	REPAIR CAB TILT FLIUD LEAKING RHS
6403	VT85123544	KIT HOSE CAB TILT RAM-RAM FH-M
6404	VT1161935	OIL HYDRAULIC CAB PUMP 1 LITRE
6405	VT85110123	NUT
6702	24L	REPAIR TRANS COOLER HOSES (X2) UNSECURED & LEAKING
6703	VT21339891	HOSE WATER 13MM ID AIR COMP-WATER-OILCOL
6704	VT21052612	CONNECTOR PLASTIC 90 DEGREE
6705	VT21380391	CONNECTOR PLASTIC 45 DEGREE
6706	VT21380391	CONNECTOR PLASTIC 45 DEGREE
6707	VT21158071	CLAMP ATTACHMENT
6708	VT21279613	CONNECTOR
6709	AMNARV56308	CABLE TIE MEDIUM 1=25PACK BLACK NARVA
7002	33	REPAIR 1ST DRIVE SIGNIFICANT OUTPUT YOKE MOVEMENT
7003	VT1673393	NUT DIFF REAR THRU SHAFT RTS2370A
7004	VT1524838	SEALING RING
7005	VT1524838	SEALING RING
7006	VT994102	BOLT TAILSHAFT FE-LATE FH-M LATE48MMXM14
7302	SC	REMOVE AND REPLACE RH WINDOW TINT
7602	41	REPAIR BATTERY BOX COVER LOOSE
7603	VT192591	WING NUT BATTERY BOX
7604	VT960143	WASHER
7605	VT192591	WING NUT BATTERY BOX
7609	N	Credit L01071715/R01055062
7610	N	Authorised by Adam S.
7611	N	Recharged on 2 new invoices
7612	N	Job Card R01063420/R01063421
07/10/2019	S01004821	
3706	VT20538904	WASHER
7609	N	Credit L01071715/R01055062
7610	N	Recharged on R01063421
7611	N	Omitted washer on Replace front engine mount job.