

Description	Part #	Price/Rate	Quantity/Hours	Tax	Amount
KIT OVERHAUL	E0007070111	107.00	1		107.00

Description	Part #	Price/Rate	Quantity/Hours	Tax	Amount
-------------	--------	------------	----------------	-----	--------

OIL	5680039KXCUM	\$ 748.09	1.00	✓	\$748.09
PUMP, WATER	5719759CUM	\$389.22	1.00	✓	\$389.22
GASKET,ACC DRIVE SUPPORT	5440813CUM	\$15.66	1.00	✓	\$15.66
SEAL,RECTANGULAR STRIP	3687007CUM	\$41.96	1.00	✓	\$41.96
GASKET,FUEL PUMP	5414049CUM	\$26.36	1.00	✓	\$26.36
SEAL,OIL	3685173CUM	\$67.44	1.00	✓	\$67.44
SEAL,O RING	3684384CUM	\$11.56	1.00	✓	\$11.56
SEAL, RECTANGULAR RING	5658175CUM	\$19.80	1.00	✓	\$19.80
SEAL,O RING	4299124CUM	\$11.89	1.00	✓	\$11.89
BEARING,THRUST	3685915CUM	\$47.32	1.00	✓	\$47.32
GASKET,ADAPTER	3685556CUM	\$12.44	1.00	✓	\$12.44
SCREW,CAPTIVE WASHER CAP	3680882CUM	\$6.58	13.00	✓	\$85.54

Disclaimer:

I hereby authorize the above repair work be done along with necessary materials. Lopez Brothers employees may operate on the above vehicle for the purpose of repairing, testing, inspecting or delivery at my own risk. An express lien is acknowledge on the above vehicle to secure the amount of the repairs. I understand that Lopez Brothers will not be responsible for loss or damages to the vehicle or articles left in the vehicle in case of fire, theft, accident or any other cause beyond control. I understand that Lopez Brothers will not be held responsible for any towing services after all repairs have been completed and vehicle has left property. I understand that the company warranty is only valid within Lopez Brothers shop.

***There is no warranty on customer supplied parts and used parts ***

Balance is to be paid in full upon job completion


SHAFT, IDLER	3680260CUM	\$102.80	1.00	✓	\$102.80
SCREW, HEX FLANGE HEAD CAP	3681174CUM	\$8.04	8.00	✓	\$64.32
BEARING, THRUST	3681149CUM	\$59.55	1.00	✓	\$59.55
PAINT, CUMMINS APEX RED	3163075	\$26.02	8.00	✓	\$208.16
KIT-SEAL AND SPACER FF FRONT	CM10081518	\$80.06	1.00	✓	\$80.06
ISOLATOR, VIBRATION	3104388CUM	\$11.74	4.00	✓	\$46.96
SCREW, CAPTIVE WASHER CAP	3689758CUM	\$4.21	4.00	✓	\$16.84
ISOLATOR, VIBRATION	3104388CUM	\$11.74	3.00	✓	\$35.22
SCREW, BANJO CONNECTOR	3903035CUM	\$12.22	1.00	✓	\$12.22
WASHER, SEALING	3963990CUM	\$3.67	2.00	✓	\$7.34
RING RETAINING	3411881CUM	\$5.94	1.00	✓	\$5.94
SEAL GROMMET	3682826CUM	\$3.20	2.00	✓	\$6.40

Disclaimer:

I hereby authorize the above repair work be done along with necessary materials. Lopez Brothers employees may operate on the above vehicle for the purpose of repairing, testing, inspecting or delivery at my own risk. An express lien is acknowledge on the above vehicle to secure the amount of the repairs. I understand that Lopez Brothers will not be responsible for loss or damages to the vehicle or articles left in the vehicle in case of fire, theft, accident or any other cause beyond control. I understand that Lopez Brothers will not be held responsible for any towing services after all repairs have been completed and vehicle has left property. I understand that the company warranty is only valid within Lopez Brothers shop.

***There is no warranty on customer supplied parts and used parts ***

Balance is to be paid in full upon job completion





Description	Part #	Price/Rate	Quantity/Hours	Tax	Amount
RADIATOR	AD000004	2050.00	1.00		2050.00

Description

Part #

Price/Rate

Quantity/Hours

Tax

Amount

PERSONNEL, BELT	3690097CUM	\$316.96	1.00	✓	\$316.96
PULLEY, IDLER	3689465CUM	\$122.37	1.00	✓	\$122.37
GASKET, GEAR HOUSING	4393089CUM	\$75.71	1.00	✓	\$75.71
SCREW, TWELVE POINT CAP	4374074CUM	\$2.15	4.00	✓	\$8.60
BEARING, THRUST	3685915CUM	\$47.32	1.00	✓	\$47.32
GEAR, IDLER	3689611CUM	\$254.14	1.00	✓	\$254.14
GEAR, IDLER	3693161CUM	\$904.31	1.00	✓	\$904.31
GASKET, ADAPTER	3685556CUM	\$12.44	1.00	✓	\$12.44
OIL		\$17.00	12.00	✓	\$204.00
COOLANT		\$12.00	14.00	✓	\$168.00
COUNTERBOARD		\$2,600.00	1.00		\$2,600.00
LABOR		\$7,500.00	1.00		\$7,500.00

Disclaimer:

I hereby authorize the above repair work be done along with necessary materials. Lopez Brothers employees may operate on the above vehicle for the purpose of repairing, testing, inspecting or delivery at my own risk. An express lien is acknowledge on the above vehicle to secure the amount of the repairs. I understand that Lopez Brothers will not be responsible for loss or damages to the vehicle or articles left in the vehicle in case of fire, theft, accident or any other cause beyond control. I understand that Lopez Brothers will not be held responsible for any towing services after all repairs have been completed and vehicle has left property. I understand that the company warranty is only valid within Lopez Brothers shop.

***There is no warranty on customer supplied parts and used parts ***

Balance is to be paid in full upon job completion

NOTES:
OVERHAUL

Amount Paid

\$0.00

Disclaimer:

I hereby authorize the above repair work be done along with necessary materials. Lopez Brothers employees may operate on the above vehicle for the purpose of repairing, testing, inspecting or delivery at my own risk. An express lien is acknowledge on the above vehicle to secure the amount of the repairs. I understand that Lopez Brothers will not be responsible for loss or damages to the vehicle or articles left in the vehicle in case of fire, theft, accident or any other cause beyond control. I understand that Lopez Brothers will not be held responsible for any towing services after all repairs have been completed and vehicle has left property. I understand that the company warranty is only valid within Lopez Brothers shop.

***There is no warranty on customer supplied parts and used parts ***

Balance is to be paid in full upon job completion

Subtotal

\$22,522.85

Sales Tax 8.38% on \$12,422.

\$1,040.41

Total

\$23,563.26

Amount Due

\$23,563.26

—  **Engine #1**

Total Vehicle Distance

663147.841 mi

Total Vehicle Distance

663147.841 mi

Total Vehicle Distance (High Resolution)

663147.860 mi

Engine Total Fuel Used

159118.488 gal

Total Vehicle Distance (High Resolution)

663147.860 mi

Total Power Takeoff Hours

706.500 h

Engine Total Hours of Operation

23995.900 h

Engine Total Revolutions

508028000.000 r