

BW Parts Group LLC

2910 W. Cheery Lynn Rd.
AZ 85017

Estimate

Date	Estimate #
10/3/2023	94

Name / Address
DALE JONES

Ship To

Model / Serial	Engine Code	Terms	P.O. No.	Rep
VANTAGE 600SD	TD2.9 L04			
Item	Description	Qty	Rate	Total
	CODE: 11981, SERIAL: U1180207311			
9SL10501-33	ROTOR ASSEMBLY	1	3,796.87	3,796.87T
BW1524	LINCOLN OEM TOLERANCE RING	1	15.99	15.99T
BW330	BRUSH AND HOLDER ASSEMBLY	1	94.00	94.00T
9SS13490-171A	CAPACITOR	1	195.99	195.99T
BW855	DIODE BRIDGE RECTIFIER 35A 800V - FS	1	26.99	26.99T
9SG7362	OEM COOLANT HOSE	1	97.79	97.79T
9SG7363	OEM COOLANT HOSE	1	123.15	123.15T
1184002	BELT, FAN, TD 2.9 L4	1	118.20	118.20T
6489	AIR FILTER	1	39.99	39.99T
B228	OIL FILTER, SPIN ON	1	16.95	16.95T
4137456	FUEL FILTER	1	110.43	110.43T
WF10175	FUEL FILTER	1	67.52	67.52T
OIL 4	15W40 OIL GAL	2.5	28.052	70.13T
	Subtotal			4,774.00
SHOP SUPPLIES	SHOP SUPPLIES		6.50	6.50T
		Subtotal		
		Sales Tax (8.6%)		
		Total		

Phone Number
602-850-7399

Visit us at bwparts.com /
bwrepair.com

BW Parts Group LLC

2910 W. Cheery Lynn Rd.
AZ 85017

Estimate

Date	Estimate #
10/3/2023	94

Name / Address
DALE JONES

Ship To

Model / Serial	Engine Code	Terms	P.O. No.	Rep
VANTAGE 600SD	TD2.9 L04			
Item	Description	Qty	Rate	Total
LABOR - ENGIN...	LABOR, REGULAR HOURLY RATE INSPECT UNIT FOR NO OUTPUT, CHECK FOR CIRCUIT FLASHING, NOTHING, OPEN SIDE PANEL, INNER SLIP RING IS BLUED, CHECK ROTOR FOR WINDING INSULATION, INSULATION IS BROKEN OUT ON ENGINE SIDE, RECOMMEND REPLACING; TOLERANCE RING, BRUSHES, CAPACITOR AND RECTIFIER	1	129.00	129.00
LABOR - ENGIN...	LABOR, REGULAR HOURLY RATE DE-SHELL, DRAIN COOLANT, REMOVE RADIATOR ASSEMBLY, DRAIN FUEL AND REMOVE TANK, REMOVE ENGINE WITH ROTOR ATTACHED, REPLACE ROTOR, INSTALL NEW BEARING, REPLACE TOLERANCE RING, INSTALL ENGINE WITH ROTOR, REPLACE FAN BELT, REPLACE BOTH RADIATOR HOSES, INSTALL RADIATOR ASSEMBLY, INSTALL FUEL TANK, FILL TANK, FILL RADIATOR, REPLACE CAP AND RECTIFIER, REPLACE BRUSHES	12.75	129.00	1,644.75
			Subtotal	

Sales Tax (8.6%)

Total

Phone Number
602-850-7399

Visit us at bwparts.com /
bwrepair.com

BW Parts Group LLC

2910 W. Cheery Lynn Rd.
AZ 85017

Estimate

Date	Estimate #
10/3/2023	94

Name / Address
DALE JONES

Ship To

Model / Serial	Engine Code	Terms	P.O. No.	Rep
VANTAGE 600SD	TD2.9 L04			
Item	Description	Qty	Rate	Total
LABOR - ENGIN...	LABOR, REGULAR HOURLY RATE SERVICE ENGINE; CHANGE OIL AND OIL FILTER, REPLACE AIR AND BOTH FUEL FILTERS, BLEED AIR FROM FUEL SYSTEM, TEST RUN, LOAD BANK WASH UNIT	1.5	145.00	217.50
			Subtotal	\$6,771.75

Note: This estimate is an approximation, based on our initial diagnosis. Additional repair may be required. Actual cost for parts and labor are subject to change.

30 day warranty on labor. 90 day warranty on parts. From the date of the invoice.

Sales Tax (8.6%) \$411.12

Total \$7,182.87

Phone Number
602-850-7399

Visit us at bwparts.com /
bwrepair.com