

From: egreene@QuinnCompany.com

Cc: Chad.Vejar@QuinnCompany.com, Dermot.Coll@QuinnCompany.com, dveenendaal@QuinnCompany.com,

Subject: Challenger MT 955E New Quote

Date: Wed, Sep 30, 2020 2:59 pm

Attachments:

Attached is the quote for new MT 955E Articulated Tractor. As we discussed last week, no changes have been made to the specifications or components of this machine from your current machine.

Thanks,

Eric Greene

Valley Region Manager

Quinn Company

Mobile: (559) 351-7664

Office: (559) 891-5408

egreene@quinncompany.com

www.quinncompany.com



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

Attention: Account Payable
 1075 N. WEST ST.

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3933.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16746

Invoice No. WO740021411

Invoice Date: 10/21/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
		RUSTY DENNIS			
		TRAVEL TO/FROM MACHINE			
		26301 ROAD 52 TULARE, CA			
		REPAIR PROCESS COMMENTS:			
		10/07/2025 (1193)			
		TRAVEL TO AND FROM MACHINE, TRAVELED 36 MILES.			
		10/08/2025 (1193)			
		TRAVEL TO AND FROM MACHINE, TRAVELED 36 MILES.			
			F/R ALL	579.00 *	
		SEGMENT 01 TOTAL			579.00 T

TROUBLESHOOT FUEL SYSTEM

CUSTOMER COMPLAINT:

ACTIVE 520359 FMI 31

CAUSE OF FAILURE:

PCV V837079834

REPAIR PROCESS COMMENTS:

10/07/2025 (1193)

ARRIVED AT MACHINE, CUSTOMER STATED MACHINE HAS AN ACTIVE FAULT CODE, STARTED UP MACHINE, FOUND MACHINE HAD ACTIVE FAULT CODE OF SPN 520359 FMI 31 PCV OPEN LOAD PRESSURE HIGH, ATTEMPTED TO RESET THE PCV BUT CODE CAME BACK, DRAINED 5 GALLONS OF COOLANT, REMOVED COOLANT TANK OFF MACHINE, REMOVED THE EEM4 AND THE EEM4 BRACKET, REMOVED THE FUEL BASES OFF MACHINE, REMOVED TURBO INLET PRESSURE TUBES, REMOVED COOLANT LINES, REMOVED FUEL LINES AND VALVE COVER HARNESSSES TO GAIN ACCESS TO THE PCV, MEASURED THE OHMS OF THE VALVE AND IT WAS READING 9.2 OHMS, REMOVED PCV OFF MACHINE.

10/08/2205 (1193)

ARRIVED AT MACHINE, INSTALLED NEW PCV, INSTALLED VALVE COVER HARNESS, FUEL LINES, COOLANT LINES AND TURBO INLET TUBE BACK ONTO THE MACHINE, INSTALLED FUEL FILTER BASES, EEM4 BRACKET AND EEM4, ZIP TIED ALL WIRE HARNESS, INSTALLED COOLANT TANK BACK ONTO MACHINE, FILLED MACHINE WITH 5 GALLONS OF COOLANT, RAN MACHINE, PERFORMED FUEL PRESSURE TEST, ALL TEST PASSED, FOUND NO LEAKS, NO FAULT CODES WERE PRESENT, RETURN UNIT TO SERVICE.

1	V615870812	WASHER	S	1.95	1.95
5	V615881420	GASKET	S	2.81	14.05
1	V837079834	PRESSURE VALVE	S	565.33	565.33
		TOTAL PARTS	SEG. 02		581.33 *
		LESS 100%-PARTS			581.33-*



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

Make: AGCO CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 3410.0

Quinn Store Location: CORCORAN AG SERVICE, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16441

Invoice No. WO740020903

Invoice Date: 05/12/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

RUSTY DENNIS

TRAVEL TO/FROM MACHINE

HAMPSTRA DAIRY AVE 260 EAST OF RD 68 TULARE, CA

REPAIR PROCESS COMMENTS:

05/08/2025 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 40 MILES.

F/R ALL 254.00 *

SEGMENT 01 TOTAL 254.00 T

 TROUBLESHOOT TRANS

CUSTOMER COMPLAINT:

OIL LEAKING ON GROUND

CAUSE OF FAILURE:

508972D1

RESULTANT DAMAGE:

OIL LEAKING ON GROUND

REPAIR PROCESS COMMENTS:

05/08/2025 (1193)

ARRIVED AT MACHINE, FOUND HOSE 508972D1 WAS LEAKING OIL. THE BELLY PANS WERE BENT AND PUSHED UP ONTO THE HOSE AND CUT THE HOSE. REMOVED BELLY PANS OFF MACHINE. REMOVED AND REPLACED HYD HOSE. HAD TO ADD OIL TO THE MACHINE TO TOP IT OFF. HAD TO HEAT UP BELLY PANS AND STRAIGHTEN THEM, THEN CUT A BIGGER NOTCH INTO THE BELLY PAN NEAR THE HYD HOSE TO PREVENT THIS FROM HAPPENING AGAIN. TEST DROVE MACHINE, FOUND NO OTHER OIL LEAKS, PERFORMED INSPECTION, RETURN UNIT TO SERVICE.

1	508972D1	HOSE/AXLE	S	197.34	197.34
2	79037109B	OIL-821XL 5G	S	135.18	270.36
		TOTAL PARTS			467.70 *
			SEG. 02		870.00 *
			F/R LBR		1337.70 T

2 79037109B OIL-821XL 5G S 135.18 270.36

TOTAL PARTS 467.70 *

SEG. 02 870.00 *

F/R LBR 1337.70 T

SEGMENT 02 TOTAL 1337.70 T

 TOTAL PARTS DISCOUNT .00

ENV/RECYCLE FEE 75.00 T

MISC. SUPPLIES 23.39 T

TAX EXEMPTION LICENSE FARM 09/01/15

STATE SLS TX-AG2.25% 12.74 T

INVOICE TOTAL 1,702.83

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,



10006 Rose Hills Road
 City of Industry, CA 90601
 (62) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

PHONE OR FAX 909-274-3348

Make: AGCO CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 3540.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16516

Invoice No. WO740021053

Invoice Date: 07/15/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

RUSTY DENNIS

TRAVEL TO/FROM MACHINE

D G SHOP

REPAIR PROCESS COMMENTS:

07/01/2025 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 43 MILES.

07/02/2025 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 43 MILES.

F/R ALL

520.00 *

SEGMENT 01 TOTAL

520.00 T

 TROUBLESHOOT HYDRAULIC SYSTEM

LINE(S)

CUSTOMER COMPLAINT:

HOSE IS RUBBING DUE TO P CLIPS MISSING

CAUSE OF FAILURE:

524832D1 HOSE

RESULTANT DAMAGE:

N/A

REPAIR PROCESS COMMENTS:

07/01/2025 (1193)

ARRIVED AT MACHINE, CUSTOMER STATED THEY WANTED
 HYD HOSE 524832D1 REPLACED DUE TO IT WAS RUBBING
 FROM P CLIPS THAT WERE MISSING FROM A REPAIR THEY
 HAD DONE AT NIGHT DURING THE SEASON. REMOVED HYD
 HOSE FROM MACHINE, HYD HOSE CAME FROM THE
 ELECTRONIC STEERING VALVE AND WENT THROUGH THE
 CENTER OF THE MACHINE TO THE HYD REAR VALVE
 STACK. HAD HOSE MADE.

07/02/2025 (1193)

ARRIVED AT MACHINE, INSTALLED HYD HOSE. TESTED
 MACHINE FOR LEAKS, FOUND NONE. WRAP HOSES IN
 CENTER OF MACHINE. RETURN UNIT TO SERVICE.

2	5K-9090	ORFS ORING -16	S	1.71	3.42
399	456-8470	XT3 ES HOSE -16	S	.59	235.41
1	499-1149	COUPLING AS	S	63.06	63.06
1	499-1152	COUPLING AS	S	65.78	65.78

TOTAL PARTS

SEG. 02

367.67 *

F/R LBR

957.00 *

1.00

HOSE ASSY CHG

55.00

TOTAL MISC CHGS

SEG. 02

55.00 *

SEGMENT 02 TOTAL

1379.67 T

 TOTAL PARTS DISCOUNT .00

ENV/RECYCLE FEE

75.00 T

MISC. SUPPLIES

18.38 T

TAX EXEMPTION LICENSE FARM 09/01/15



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3550.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16584

Invoice No. WO740021158

Invoice Date: 08/07/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

RUSTY DENNIS

TRAVEL TO/FROM MACHINE

AVE 240 T'S INTO RD 48 WEST LITTLE DAIRY

REPAIR PROCESS COMMENTS:

2755 7/24/2025

TRAVELED TO AND FROM MACHINE, 40 MILES.

F/R ALL 254.00 *

SEGMENT 01 TOTAL 254.00 T

 TROUBLESHOOT BRAKING SYSTEM

CUSTOMER COMPLAINT:

BRAKES DO NOT WORK.

CAUSE OF FAILURE:

THE PEDESTAL IT PART OF THE 559900D1 CABIN FRAME AND NO PART NUMBER TO REPLACE. WE REPAIRED THE PEDESTAL.**THIS IS NOT A WARRANTABLE REPAIR**

RESULTANT DAMAGE:

THE TAB THAT OLDS THE BRAKE CABLE BROKE OFF THE PEDESTAL FOR THE CAB FRAME.

REPAIR PROCESS COMMENTS:

2755 7/24/2025

ARRIVED AT MACHINE, TESTED BRAKES AND THERE WAS NOTHING. CONNECTED EDT AND CHECKED FOR ANY BRAKE FAULT CODES. PRESSED ON PEDAL AND IT DID NOT FEEL RIGHT. REMOVED DASH PANELS AND FOUND TAB THAT HOLDS CABLE IN PLACE BROKE OFF THE PEDESTAL FOR THE A/C VENTS THAT IS PART OF THE CABIN FRAME. REMOVED CABLE END AND EYELET. REMOVED HVAC DUCTING FROM STEERING COLUMN. CLEANED PAINT AWAY FROM FRAME AND EYELET. COVERED CAB FLOOR AND AREA. WELDED TAB BACK INTO PLACE ONE THE PEDESTAL FOR THE A/C DUCKS AND STEERING COLUMN. INSTALL CABLE AND TESTED. BRAKES NOW WORKED. ASSEMBLED STEERING COLUMN. TESTED ONCE MORE. NOTIFIED CUSTOMER AND RETURNED MACHINE TO SERVICE.

F/R LBR 1044.00 *

SEGMENT 02 TOTAL 1044.00 T

 TOTAL PARTS DISCOUNT .00

ENV/RECYCLE FEE 75.00 T

TAX EXEMPTION LICENSE FARM 09/01/15

STATE SLS TX-AG2.25% 1.69 T

INVOICE TOTAL 1,374.69



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

TOLBARE CA 92714 0078

Make: AGCO CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 3723.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16609

Invoice No. WO740021182

Invoice Date: 08/19/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
FILLED THE ENGINE WITH NEW COOLANT. OPERATED THE MACHINE AND THERE WAS NO LEAKS					
1	V837091633	KIT,WATER PUMP	N	1247.05	1247.05
13	79038100B	OIL-COOLANT-SI-OATS		31.40	408.20
1	1U-5516	SANDING DISC 2IN	S	1.96	1.96
1	A000031292	CRC BRAKE CLEANER	S	7.77	7.77
		TOTAL PARTS	SEG. 02		1664.98 *
		LESS 100%-PARTS			1664.98-*
		TOTAL LABOR	SEG. 02		1552.95 *
		LESS 100%-LABOR			1552.95-*
		SEGMENT 02 TOTAL			.00 T

TROUBLESHOOT AIR CONDITIONER

CUSTOMER COMPLAINT:

WHEN WORKING ON THE WATER PUMP FAILURE, FOUND THE A/C COMPRESSOR BEARING WAS STARTING TO FAIL.

CAUSE OF FAILURE:

COMPRESSOR 563419D2 PULLEY BEARING WAS HARD TO TURN.

RESULTANT DAMAGE:

THE BEARING WAS ABOUT TO FAIL AND WOULD RIP THE FAN BELT.

REPAIR PROCESS COMMENTS:

8-08-2025 1065

WHEN DISASSEMBLING THE WATER PUMP, FOUND THE A/C COMPRESSOR PULLEY BEARING WAS HARD TO TURN AND WAS ABOUT TO LOCK UP. A NEW COMPRESSOR WAS NOT IN STOCK. HAD TO ORDER A COMPRESSOR FROM THE AGCO WAREHOUSE.

8-09-2025 1065

PICKED UP NEW COMPRESSOR FROM THE WAREHOUSE. EVACUATE THE REFRIGERANT AND REMOVED THE COMPRESSOR FROM THE MACHINE. INSTALLED THE NEW COMPRESSOR (563419D2). CHARGED THE SYSTEM BACK UP AND OPERATED THE MACHINE. THE A/C WAS WORKING, RETURNED THE MACHINE TO WORK.

8-10-2025 1065

CUSTOMER CALLED BACK SAYING THE MACHINE A/C WOULD SOME TIMES GET WARM. CONNECTED GAUGES TO THE MACHINE AND MONITORED THE SYSTEM WHEN RUNNING. THE SYSTEM, PRESSURE APPEARED TO BE A LITTLE LOW. CHARGED THE SYSTEM WITH ANOTHER CAN AND OPERATED THE MACHINE. THE A/C WAS BLOW COLD AT 60 DEGREES AT THE VENTS. HAD THE DRIVER OPERATE THE MACHINE, THEY APPROVE THE A/C WOULD STAY WORKING COLD.

1	563419D2	A/C COMPRESSOR	N	623.34	623.34
1	565810D1	BELT TENSIONER	S	270.21	270.21
1	578628D1	FAN BELT-1747MM 12S		178.12	178.12



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable
 1875 ALWEST CT

Make: AGCO CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 3723.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16609

Invoice No. WO740021182

Invoice Date: 08/19/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

MARVIN DAVIS

TRAVEL TO/FROM MACHINE

REPAIR PROCESS COMMENTS:

8-08-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

8-09-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

8-10-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

F/R ALL

484.00 *

 SEGMENT 01 TOTAL

484.00 T

 TROUBLESHOOT ENGINE COOLING SYSTEM

LEAK(S)

CUSTOMER COMPLAINT:

CUSTOMER SAID THE WATER PUMP FAILED AND LOST COOLANT.

CAUSE OF FAILURE:

THE WATER PUMP BEARING V837079934 HAS FAILED.

RESULTANT DAMAGE:

THE WATER PUMP LOCKED UP AND LEAKED COOLANT OUT OF THE ENGINE.

REPAIR PROCESS COMMENTS:

8-08-2025 1065

CONNECTED EDT TO THE MACHINE AND DOWNLOADED MACHINE LOGGED CODES. INSPECTED THE MACHINE AND FOUND THE WATER PUMP BEARING HAS FAILED AND THE COOLANT IS LEAKING OUT OF THE WATER PUMP HOUSING BETWEEN THE SHAFT AND THE HOUSING. THERE WAS NO WATER PUMP IN STOCK. A NEW PUMP HAD TO BE ORDERED FROM THE WAREHOUSE OVER THE WEEKEND.

8-09-2025 1065

PICKED UP NEW PARTS FROM THE AGCO WAREHOUSE. DRAINED THE REMAINING COOLANT FROM THE ENGINE. DISSEMBLED THE FRONT FAN DRIVE PULLEY BRACKETS. REMOVED THE DAMAGED WATER PUMP (V837079934). THE DAMAGED WATER PUMP IMPELLER HAD MADE CONTACT TO THE HOUSING (V837081768) AND WEAR IT DOWN A LITTLE. INSTALLED THE NEW WATER PUMP ASSEMBLY. ASSEMBLED THE PULLEY BRACKET. REPLACED THE BELT TENSIONER (565810D1), WHEN THE DAMAGED WATER PUMP FAILED, THE SHAFT DROPPED AND MADE CONTACT TO THE TENSIONER HOUSING WHEN RUNNING. REPLACED THE FAN BELT (578628D1),



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

[Redacted]
 Attention: Account Payable
 [Redacted]

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3673.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickereil Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16602

Invoice No. WO740021166

Invoice Date: 08/11/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
RUSTY DENNIS					
TRAVEL TO/FROM MACHINE					
DDW DAIRY RD 36 AND AVE 248 TULARE CA					
REPAIR PROCESS COMMENTS:					
08/05/2025 (1193)					
TRAVEL TO AND FROM MACHINE, TRAVELED 32 MILES.					
			F/R ALL		151.00 *
		SEGMENT 01 TOTAL			151.00 T

TROUBLESHOOT STARTING SYSTEM					
CUSTOMER COMPLAINT:					
MACHINE WONT START					
CAUSE OF FAILURE:					
STARTER 571229D1					
RESULTANT DAMAGE:					
N/A					
REPAIR PROCESS COMMENTS:					
08/05/2025 (1193)					
ARRIVED AT MACHINE, CUSTOMER STATES THE STARTERS					
JUST CLICK AND THE MACHINE WONT START, TESTED THE					
STARTING SYSTEM AND FOUND MACHINE WOULD NOT					
START, STARTERS HAD 12 VOLTS AND JUST SPIN BUT					
WOULD NOT ENGAGE. REMOVED AND REPLACED BOTH TOP					
AND BOTTOM STARTERS, MACHINE NOW STARTED WITH NO					
ISSUES, RETURN UNIT TO SERVICE .					
2	571229D1	STARTER	S	766.05	1532.10
		TOTAL PARTS	SEG. 02		1532.10 *
		LESS 100%-PARTS			1532.10-*
		TOTAL LABOR	SEG. 02		839.14 *
		LESS 100%-LABOR			839.14-*
1.00		PART FREIGHT IN			28.00
		TOTAL MISC CHGS	SEG. 02		28.00 *
		LESS 100%-MISC			28.00-*
		SEGMENT 02 TOTAL			.00 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			75.00 T
		AGCO-PARTS WARRANTY			
		COVERED REPAIRS		2399.24	
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			1.69 T
		INVOICE TOTAL			227.69

THANK YOU FOR YOUR BUSINESS.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

██████████
 Attention: Accounts Payable
 1075 N. WEST ST
 ██████████ 8

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3539.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickereil Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16473

Invoice No. WO740020968

Invoice Date: 06/11/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
TROUBLESHOOT HYDRAULIC SYSTEM					
LINE(S)					
REPAIR PROCESS COMMENTS:					
05/30/2025 (1193)					
ARRIVED AT MACHINE, CUSTOMER STATED THE FRONT BELLY PANS WAS SMASHED UP AGAINST THE AXLE HOSE AND IT NEEDED TO BE FIXED. REMOVED BELLY PANS OFF MACHINE, CUT A NOTCH OUT IN THE BELLY PAN, ADD A PIECE OF METAL TO THE BELLY TO HELP STRENGTHEN IT AND WELD IT ONTO THE BELLY PAN. PUT BELLY PAN INTO THE PRESS AND STRAIGHTEN IT AS WELL. ALSO INSTALLED NEW HOSE GUARDS TO THE ARTICULATION HOSES DUE TO GUARD BEING TORN. CUSTOMER PROVIDE THE PARTS AND METAL FOR THESE JOBS.					
1	15608	BRAKE/PARTSCLEANERS		7.69	7.69
20	6K-0806	STRAP-CABLE	S	.47	9.40
20	7K-1181	STRAP CABLE	S	.50	10.00
2	174-8903	CUTOFF WHEEL	S	2.20	4.40
1	653-9562	WIPER	S	13.48	13.48
		TOTAL PARTS	SEG. 04		44.97 *
			F/R LBR		1218.00 *
		SEGMENT 04 TOTAL			1262.97 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			75.00 T
		MISC. SUPPLIES			41.06 T
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			21.09 T

INVOICE TOTAL 3,230.43

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,
 PLEASE LET US KNOW AS SOON AS POSSIBLE!
 SHOULD YOU HAVE ANY QUESTIONS REGARDING THIS INVOICE, PLEASE CONTACT
 LARRY PAREDES, CORCORAN STORE MANAGER, AT (559) 992-2193.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO: [REDACTED]
 Attention: Account Payable
 [REDACTED]

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3539.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16473

Invoice No. WO740020868

Invoice Date: 06/11/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
RUSTY DENNIS					
TRAVEL TO/FROM MACHINE					
D G SHOP					
REPAIR PROCESS COMMENTS:					
05/29/2025 (1193)					
TRAVEL TO AND FROM MACHINE, TRAVELED 46 MILES.					
05/30/2025 (1193)					
TRAVEL TO AND FROM MACHINE, TRAVELED 46 MILES.					
			F/R ALL		532.00 *
		SEGMENT 01 TOTAL			532.00 T

TROUBLESHOOT INCHING PEDAL					
REPAIR PROCESS COMMENTS:					
05/29/2025 (11930)					
ARRIVED AT MACHINE, CUSTOMER STATED THE INCHING PEDAL FUSE KEPT BLOWING THROUGH TOUT THE SEASON. MEASURED RESISTANCE IN THE HARNESS AND COULD NOT FIND A BAD SPOT. ORDER A NEW INCHING PEDAL SWITCH AND POSITION SENSOR.					
05/30/2025 (1193)					
INSTALLED NEW POSITION SWITCH ALONG WITH NEW POSITION SENSOR, RAN A NEW POWER WIRE FROM FUSE BLOCK TO THE SENSOR. TESTED THE INCHING PEDAL, FOUND NO OTHER ISSUES. RETURN UNIT TO SERVICE.					
1	536818D1	SENSOR	S	361.27	361.27
1	544077D1	SWITCH	S	45.22	45.22
		TOTAL PARTS	SEG. 02		406.49 *
			F/R LBR		174.00 *
		SEGMENT 02 TOTAL			580.49 T

TROUBLESHOOT HYDRAULIC SYSTEM					
REMOTE					
REPAIR PROCESS COMMENTS:					
05/29/2025 (1193)					
ARRIVED AT MACHINE, CUSTOMER STATED THE HYD VALVE NUMBER 1 DOES NOT WORK. CONNECTED EDT. FOUND MACHINE HAD ACTIVE ERROR CODE FOR JOYSTICK SENSOR ON VALVE NUMBER 1. ORDER A NEW FINGERTIP SENSOR.					
05/30/2025 (1193)					
ARRIVED AT MACHINE, REMOVED ARM REST OUT OF MACHINE, REMOVED AND REPLACED FINGER TIP NUMBER 1, VALVE NUMBER 1 WAS NOW WORKING CORRECTLY.					
1	4289763M2	JOYSTICK	S	369.82	369.82
		TOTAL PARTS	SEG. 03		369.82 *
			F/R LBR		348.00 *
		SEGMENT 03 TOTAL			717.82 T



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

[REDACTED]
 Attention: Account Payable
 1875 NINEAST ST
 [REDACTED]

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3410.0

Quinn Store Location: CORCORAN AG SERVICE, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16441

Invoice No. WO740020903

Invoice Date: 05/12/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
<p>RUSTY DENNIS TRAVEL TO/FROM MACHINE HAMPSIRA DAIRY AVE 260 EAST OF RD 68 TULARE, CA REPAIR PROCESS COMMENTS: 05/08/2025 (1193) TRAVEL TO AND FROM MACHINE, TRAVELED 40 MILES.</p>					
			F/R ALL	254.00 *	
		SEGMENT 01 TOTAL			254.00 T

<p>TROUBLESHOOT TRANS CUSTOMER COMPLAINT: OIL LEAKING ON GROUND CAUSE OF FAILURE: 508972D1 RESULTANT DAMAGE: OIL LEAKING ON GROUND REPAIR PROCESS COMMENTS: 05/08/2025 (1193) ARRIVED AT MACHINE, FOUND HOSE 508972D1 WAS LEAKING OIL. THE BELLY PANS WERE BENT AND PUSHED UP ONTO THE HOSE AND CUT THE HOSE. REMOVED BELLY PANS OFF MACHINE. REMOVED AND REPLACED HYD HOSE. HAD TO ADD OIL TO THE MACHINE TO TOP IT OFF. HAD TO HEAT UP BELLY PANS AND STRAIGHTEN THEM, THEN CUT A BIGGER NOTCH INTO THE BELLY PAN NEAR THE HYD HOSE TO PREVENT THIS FROM HAPPENING AGAIN. TEST DROVE MACHINE, FOUND NO OTHER OIL LEAKS, PERFORMED INSPECTION, RETURN UNIT TO SERVICE.</p>					
1	508972D1	HOSE/AXLE	S	197.34	197.34
2	79037109B	OIL-821XL 5G	S	135.18	270.36
		TOTAL PARTS	SEG. 02		467.70 *
			F/R LBR		870.00 *
		SEGMENT 02 TOTAL			1337.70 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			75.00 T
		MISC. SUPPLIES			23.39 T
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			12.74 T
		INVOICE TOTAL			1,702.83

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:
 [REDACTED]
 Attention: Account Payable
 [REDACTED]
 TULARE CA 93274-3648

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3338.0

Quinn Store Location: CORCORAN PARTS, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16430

Invoice No. WO740020883

Invoice Date: 05/05/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
<p>RUSTY DENNIS TRAVEL TO/FROM MACHINE OAKDALE AVE AND COLPIEN RD TULARE CA REPAIR PROCESS COMMENTS: 05/02/2025 (1193) TRAVEL TO AND FROM MACHINE, TRAVELED 36 MILES.</p>					
			F/R ALL	246.00 *	
		SEGMENT 01 TOTAL			246.00 T
<p>-----</p> <p>TROUBLESHOOT CLUTCH CUSTOMER COMPLAINT: MACHINE HAS ACTIVE FAULT CODE CAUSE OF FAILURE: FUSE 10AMP RESULTANT DAMAGE: N/A REPAIR PROCESS COMMENTS: 05/02/2025 (1193) ARRIVED AT MACHINE, CUSTOMER STATED MACHINE HAS AN ACTIVE ERROR CODE OF SPN 684, FMI 0 INCHING PEDAL SENSOR CURRENT BELOW NORMAL. REMOVED DASH CONSOLE TO GAIN ACCESS TO THE INCHING PEDAL SENSOR. REMOVED CONNECTOR. MEASURED VOLTAGE BETWEEN PIN A AND PIN C AND HAD ZERO VOLTS. TRACED WIRE 147 PIN A BACK TO FUSE BLOCK 2 FUSE 2 AND FOUND THE 10 AMP FUSE BLOWN. MEASURED RESISTANCE BETWEEN FUSE BLOCK FUSE 2 AND PIN A ON THE CONNECTOR AND HAD 0.6 OHMS. FOUND NO ISSUES WITH THE SENSOR. SENSOR TESTED GOOD. CUSTOMER STATED HE NEEDED TO USE MACHINE, INSTALLED 10AMP FUSE AND TOLD CUSTOMER TO CALL US IF IT POPS AGAIN.</p>					
			F/R LBR	522.00 *	
		SEGMENT 02 TOTAL			522.00 T
<p>-----</p>					
		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			75.00 T
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			1.69 T
		INVOICE TOTAL			844.69

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,
 PLEASE LET US KNOW AS SOON AS POSSIBLE!



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

[REDACTED]
 Attention: Accounts Payable
 1275 N. WEST ST
 [REDACTED]

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3723.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16809

Invoice No. WO740021182

Invoice Date: 08/19/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
FILLED THE ENGINE WITH NEW COOLANT. OPERATED THE MACHINE AND THERE WAS NO LEAKS					
1	V837091633	KIT,WATER PUMP	N	1247.05	1247.05
13	79038100B	OIL-COOLANT-SI-OATS		31.40	408.20
1	1U-5516	SANDING DISC 2IN	S	1.96	1.96
1	A000031292	CRC BRAKE CLEANER	S	7.77	7.77
		TOTAL PARTS	SEG. 02		1664.98 *
		LESS 100%-PARTS			1664.98-*
		TOTAL LABOR	SEG. 02		1552.95 *
		LESS 100%-LABOR			1552.95-*
		SEGMENT 02 TOTAL			.00 T

TROUBLESHOOT AIR CONDITIONER

CUSTOMER COMPLAINT:

WHEN WORKING ON THE WATER PUMP FAILURE, FOUND THE A/C COMPRESSOR BEARING WAS STARTING TO FAIL.

CAUSE OF FAILURE:

COMPRESSOR 563419D2 PULLEY BEARING WAS HARD TO TURN.

RESULTANT DAMAGE:

THE BEARING WAS ABOUT TO FAIL AND WOULD RIP THE FAN BELT.

REPAIR PROCESS COMMENTS:

8-08-2025 1065

WHEN DISASSEMBLING THE WATER PUMP, FOUND THE A/C COMPRESSOR PULLEY BEARING WAS HARD TO TURN AND WAS ABOUT TO LOCK UP. A NEW COMPRESSOR WAS NOT IN STOCK. HAD TO ORDER A COMPRESSOR FROM THE AGCO WAREHOUSE.

8-09-2025 1065

PICKED UP NEW COMPRESSOR FROM THE WAREHOUSE. EVACUATE THE REFRIGERANT AND REMOVED THE COMPRESSOR FROM THE MACHINE. INSTALLED THE NEW COMPRESSOR (563419D2). CHARGED THE SYSTEM BACK UP AND OPERATED THE MACHINE. THE A/C WAS WORKING, RETURNED THE MACHINE TO WORK.

8-10-2025 1065

CUSTOMER CALLED BACK SAYING THE MACHINE A/C WOULD SOME TIMES GET WARM. CONNECTED GAUGES TO THE MACHINE AND MONITORED THE SYSTEM WHEN RUNNING. THE SYSTEM, PRESSURE APPEARED TO BE A LITTLE LOW. CHARGED THE SYSTEM WITH ANOTHER CAN AND OPERATED THE MACHINE. THE A/C WAS BLOW COLD AT 60 DEGREES AT THE VENTS. HAD THE DRIVER OPERATE THE MACHINE, THEY APPROVE THE A/C WOULD STAY WORKING COLD.

1	563419D2	A/C COMPRESSOR	N	623.34	623.34
1	565810D1	BELT TENSIONER	S	270.21	270.21
1	578628D1	FAN BELT-1747MM 12S		178.12	178.12



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

[REDACTED]
 Attention: Account Payable
 [REDACTED]

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3723.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16609

Invoice No. WO740021182

Invoice Date: 08/19/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

MARVIN DAVIS

TRAVEL TO/FROM MACHINE

REPAIR PROCESS COMMENTS:

8-08-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

8-09-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

8-10-2025 1065

TRAVEL TO AND FROM THE MACHINE. PACHECOS. 34 MILES.

F/R ALL

484.00 *

SEGMENT 01 TOTAL

484.00 T

 TROUBLESHOOT ENGINE COOLING SYSTEM

LEAK(S)

CUSTOMER COMPLAINT:

CUSTOMER SAID THE WATER PUMP FAILED AND LOST COOLANT.

CAUSE OF FAILURE:

THE WATER PUMP BEARING V837079934 HAS FAILED.

RESULTANT DAMAGE:

THE WATER PUMP LOCKED UP AND LEAKED COOLANT OUT OF THE ENGINE.

REPAIR PROCESS COMMENTS:

8-08-2025 1065

CONNECTED EDT TO THE MACHINE AND DOWNLOADED MACHINE LOGGED CODES. INSPECTED THE MACHINE AND FOUND THE WATER PUMP BEARING HAS FAILED AND THE COOLANT IS LEAKING OUT OF THE WATER PUMP HOUSING BETWEEN THE SHAFT AND THE HOUSING. THERE WAS NO WATER PUMP IN STOCK. A NEW PUMP HAD TO BE ORDERED FROM THE WAREHOUSE OVER THE WEEKEND.

8-09-2025 1065

PICKED UP NEW PARTS FROM THE AGCO WAREHOUSE. DRAINED THE REMAINING COOLANT FROM THE ENGINE. DISSEMBLED THE FRONT FAN DRIVE PULLEY BRACKETS. REMOVED THE DAMAGED WATER PUMP (V837079934). THE DAMAGED WATER PUMP IMPELLER HAD MADE CONTACT TO THE HOUSING (V837081768) AND WEAR IT DOWN A LITTLE. INSTALLED THE NEW WATER PUMP ASSEMBLY. ASSEMBLED THE PULLEY BRACKET. REPLACED THE BELT TENSIONER (565810D1), WHEN THE DAMAGED WATER PUMP FAILED, THE SHAFT DROPPED AND MADE CONTACT TO THE TENSIONER HOUSING WHEN RUNNING. REPLACED THE FAN BELT (578628D1),



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3673.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16602

Invoice No. WO740021166

Invoice Date: 08/11/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

RUSTY DENNIS

TRAVEL TO/FROM MACHINE

DDW DAIRY RD 36 AND AVE 248 TULARE CA

REPAIR PROCESS COMMENTS:

08/05/2025 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 32 MILES.

F/R ALL

151.00 *

SEGMENT 01 TOTAL

151.00 T

 TROUBLESHOOT STARTING SYSTEM

CUSTOMER COMPLAINT:

MACHINE WONT START

CAUSE OF FAILURE:

STARTER 571229D1

RESULTANT DAMAGE:

N/A

REPAIR PROCESS COMMENTS:

08/05/2025 (1193)

ARRIVED AT MACHINE, CUSTOMER STATES THE STARTERS JUST CLICK AND THE MACHINE WONT START, TESTED THE STARTING SYSTEM AND FOUND MACHINE WOULD NOT START, STARTERS HAD 12 VOLTS AND JUST SPIN BUT WOULD NOT ENGAGE. REMOVED AND REPLACED BOTH TOP AND BOTTOM STARTERS, MACHINE NOW STARTED WITH NO ISSUES, RETURN UNIT TO SERVICE .

2	571229D1	STARTER	S	766.05	1532.10
		TOTAL PARTS	SEG. 02		1532.10 *
		LESS 100%-PARTS			1532.10-*
		TOTAL LABOR	SEG. 02		839.14 *
		LESS 100%-LABOR			839.14-*
1.00		PART FREIGHT IN			28.00
		TOTAL MISC CHGS	SEG. 02		28.00 *
		LESS 100%-MISC			28.00-*
		SEGMENT 02 TOTAL			.00 T

 TOTAL PARTS DISCOUNT .00

ENV/RECYCLE FEE 75.00 T

AGCO-PARTS WARRANTY

COVERED REPAIRS 2399.24

TAX EXEMPTION LICENSE FARM 09/01/15

STATE SLS TX-AG2.25% 1.69 T

INVOICE TOTAL

227.69

THANK YOU FOR YOUR BUSINESS.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

██████████
 Attention: Account Payable
 ██████████

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3550.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC18584

Invoice No. WO740021158

Invoice Date: 08/07/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

RUSTY DENNIS
 TRAVEL TO/FROM MACHINE
 AVE 240 T'S INTO RD 48 GO WEST LITTLE DAIRY
 REPAIR PROCESS COMMENTS:
 2755 7/24/2025
 TRAVELED TO AND FROM MACHINE, 40 MILES.

F/R ALL	254.00 *
SEGMENT 01 TOTAL	254.00 T

TROUBLESHOOT BRAKING SYSTEM

CUSTOMER COMPLAINT:
 BRAKES DO NOT WORK.
 CAUSE OF FAILURE:
 THE PEDESTAL IT PART OF THE 559900D1 CABIN FRAME
 AND NO PART NUMBER TO REPLACE. WE REPAIRED THE
 PEDESTAL.**THIS IS NOT A WARRANTABLE REPAIR**
 RESULTANT DAMAGE:
 THE TAB THAT OLDS THE BRAKE CABLE BROKE OFF THE
 PEDESTAL FOR THE CAB FRAME.
 REPAIR PROCESS COMMENTS:
 2755 7/24/2025
 ARRIVED AT MACHINE, TESTED BRAKES AND THERE WAS
 NOTHING. CONNECTED EDT AND CHECKED FOR ANY BRAKE
 FAULT CODES. PRESSED ON PEDAL AND IT DID NOT FEEL
 RIGHT. REMOVED DASH PANELS AND FOUND TAB THAT
 HOLDS CABLE IN PLACE BROKE OFF THE PEDESTAL FOR
 THE A/C VENTS THAT IS PART OF THE CABIN FRAME.
 REMOVED CABLE END AND EYELET. REMOVED HVAC
 DUCTING FROM STEERING COLUMN. CLEANED PAINT AWAY
 FROM FRAME AND EYELET. COVERED CAB FLOOR AND
 AREA. WELDED TAB BACK INTO PLACE ONE THE PEDESTAL
 FOR THE A/C DUCKS AND STEERING COLUMN. INSTALL
 CABLE AND TESTED. BRAKES NOW WORKED. ASSEMBLED
 STEERING COLUMN. TESTED ONCE MORE. NOTIFIED
 CUSTOMER AND RETURNED MACHINE TO SERVICE.

F/R LBR	1044.00 *
SEGMENT 02 TOTAL	1044.00 T

TOTAL PARTS DISCOUNT	.00	
ENV/RECYCLE FEE		75.00 T
TAX EXEMPTION LICENSE FARM 09/01/15		
STATE SLS TX-AG2.25%		1.69 T

INVOICE TOTAL 1,374.69



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO: [REDACTED]
 Attention: Account Payable
 [REDACTED]

SHIP TO:

Make: AGCO CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 3540.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212. (559) 992-2193

INVOICE DETAIL

Work Order No. ZC16516

Invoice No. WO740021059

Invoice Date: 07/15/2025

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
RUSTY DENNIS					
TRAVEL TO/FROM MACHINE					
D G SHOP					
REPAIR PROCESS COMMENTS:					
07/01/2025 (1193)					
TRAVEL TO AND FROM MACHINE, TRAVELED 43 MILES.					
07/02/2025 (1193)					
TRAVEL TO AND FROM MACHINE, TRAVELED 43 MILES.					
			F/R ALL		520.00 *
		SEGMENT 01 TOTAL			520.00 T

TROUBLESHOOT HYDRAULIC SYSTEM					
LINE(S)					
CUSTOMER COMPLAINT:					
HOSE IS RUBBING DUE TO P CLIPS MISSING					
CAUSE OF FAILURE:					
524832D1 HOSE					
RESULTANT DAMAGE:					
N/A					
REPAIR PROCESS COMMENTS:					
07/01/2025 (1193)					
ARRIVED AT MACHINE, CUSTOMER STATED THEY WANTED					
HYD HOSE 524832D1 REPLACED DUE TO IT WAS RUBBING					
FROM P CLIPS THAT WERE MISSING FROM A REPAIR THEY					
HAD DONE AT NIGHT DURING THE SEASON. REMOVED HYD					
HOSE FROM MACHINE, HYD HOSE CAME FROM THE					
ELECTRONIC STEERING VALVE AND WENT THROUGH THE					
CENTER OF THE MACHINE TO THE HYD REAR VALVE					
STACK. HAD HOSE MADE.					
07/02/2025 (1193)					
ARRIVED AT MACHINE, INSTALLED HYD HOSE. TESTED					
MACHINE FOR LEAKS, FOUND NONE. WRAP HOSES IN					
CENTER OF MACHINE. RETURN UNIT TO SERVICE.					
2	5K-9090	ORFS ORING -16	S	1.71	3.42
399	456-8470	XT3 ES HOSE -16	S	.59	235.41
1	499-1149	COUPLING AS	S	63.06	63.06
1	499-1152	COUPLING AS	S	65.78	65.78
		TOTAL PARTS	SEG. 02		367.67 *
			F/R LBR		957.00 *
1.00		HOSE ASSY CHG			55.00
		TOTAL MISC CHGS	SEG. 02		55.00 *
		SEGMENT 02 TOTAL			1379.67 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			75.00 T
		MISC. SUPPLIES			18.38 T
TAX EXEMPTION LICENSE FARM 09/01/15					



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable
 1075 N WEST ST
 8

Make: CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No: AG0002159
 Machine ID No: AG0002159
 Meter Reading: 733.0

Quinn Store Location: CORCORAN PARTS, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC13678

Invoice No. WO740017077

Invoice Date: 12/16/2021

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
<p>CODE CAME UP, IT WAS CODE 127 - 01 TRANSMISSION PRESSURE. ONLINE ON AGCO CONNECT WEB SITE LOGGED THE CODE 3.127.1 CODE FOR THE LOW PRESSURE EVENT. REMOVED THE TRANSMISSION OIL FILTER AND AXLE LUBE FILTERS AND PUMP SUCTION SCREEN. CUT FILTERS OPEN AND DID NOT SEE ANY PROBLEMS IN THE FILTERS. THE SUCTION SCREEN WAS CLEAN. REPLACED THE FILTERS WITH NEW FILTERS AND TOPPED OFF THE OIL LEVEL. REPLACED THE TRANSMISSION OIL PRESSURE SENSOR (CH161-9932). CLEANED ALL LOGGED CODES AND OPERATED THE MACHINE. THE SYSTEM PRESSURE WAS IN SPEC STILL. RETURNED THE MACHINE TO WORK. 12-10-2021 1065 THE CUSTOMER HAD USED THE MACHINE FOR A FEW WEEKS AND IT HAS NOT HAD A PROBLEM AGAIN. CH161-9932 WAS PART CAUSING FAILURE.</p>					
1	AG609431	FILTER GATOR GOLD, S		67.68	67.68
1	CH161-9932	SENSOR/GP - PRESSUS		138.20	138.20
1	534039D1	ELEMENT, FILTER S		79.99	79.99
1	79036407	LUBRICANT-PERMATRAS		146.86	146.86
1	15608	BRAKE/PARTSCLEANERS		6.41	6.41
4	QLAB 02	SOS PROBE SAMPLE S		18.50	74.00
1	258-8738	SEAL O-RING N		10.08	10.08
1	605-2194	WIPER S		9.27	9.27
		TOTAL PARTS	SEG. 02		532.49 *
		LESS 100%-PARTS			532.49-*
		TOTAL LABOR	SEG. 02		1784.18 *
		LESS 100%-LABOR			1784.18-*
2.00		PART FREIGHT IN			36.00
		TOTAL MISC CHGS	SEG. 02		36.00 *
		LESS 100%-MISC			36.00-*
		SEGMENT 02 TOTAL			.00 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			24.00 T
		AGCO STD-24MO/2000HR			
		COVERED REPAIRS		2352.67	
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			.54 T
INVOICE TOTAL					309.54

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,
 PLEASE LET US KNOW AS SOON AS POSSIBLE!



10006 Rose Hills Road
 City of Industry, CA 90801
 (62) 483-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 733.0

Quinn Store Location: CORCORAN PARTS, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC13678

Invoice No. WO740017077

Invoice Date: 12/16/2021

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

TRAVEL TO/FROM MACHINE

REPAIR PROCESS COMMENTS:

11-15-2021 1065

TRAVEL TO AND FROM THE MACHINE. 38 MILES.

11-23-2021 1065

TRAVEL TO AND FROM THE MACHINE. 36 MILES.

F/R ALL

285.00 *

SEGMENT 01 TOTAL

285.00 T

TROUBLESHOOT FAULT CODE

CUSTOMER COMPLAINT:

CUSTOMER SAID THEY WERE DRIVING THE MACHINE TRANSPORTING IT FROM ONE JOB SITE TO ANOTHER. DURING DRIVING THE MACHINE A TRANSMISSION CODE CAME ACTIVE AND THE MACHINE STOPPED MOVING. THEY HAD TO CYCLE THE KEY SWITCH AND RESTART THE MACHINE TO GET THE MACHINE MOVING AGAIN.

REPAIR PROCESS COMMENTS:

11-15-2021 1065

CONNECTED EDT AND ET TO THE MACHINE AND DOWNLOADED MACHINE LOGGED CODES. THERE WAS NO ACTIVE CODES AND NO RECENT LOGGED CODES. COME ONLINE ON AGCO CONNECT. COM IT LOGGED TWICE ON THE ROUT THE MACHINE WAS DRIVING ON A CODE 3.127.1

TRANSMISSION HYDRAULIC OIL PRESSURE IS BELOW NORMAL. OPERATED THE MACHINE AND THE TRANSMISSION CHARGE PRESSURE WAS ABOUT 290 PSI AT LOW IDLE AND 315 PSI AT HIGH IDLE WITH THE TRANSMISSION OIL TEMP OF 100 DEGREES. WITH THE ONLINE DATA LOG ON WHEN THE EVENT WAS LOGGED THE TRANSMISSION OIL TEMP WAS AT 150 DEGREES AND THE MACHINE WAS STOP AND LOW IDLE. CURRENTLY I COULD NOT GET THE 3.127.1 CODE TO COME ACTIVE. TOOK OIL SAMPLES FROM THE MACHINE AND CLEARED ALL LOGGED CODES. RETURNED THE MACHINE TO WORK.

11-19-2021 1065

HAVE BEEN MONITORING THE MACHINE FROM ONLINE AND THE MACHINE DID NOT LOG THE 3.127.1 CODE AGAIN AND CONTACTED THE CUSTOMER AND THEY SAID THE MACHINE HAS BEEN OPERATING FINE AND DID NOT HAVE THE EVENT AGAIN.

11-23-2021 1065

THE CUSTOMER REPORTED THE MACHINE HAS LOGGED THE SAME CODE AGAIN. RETURNED TO THE MACHINE AND DOWNLOADED MACHINE LOGGED CODES. THERE WAS NO LOGGED LOW PRESSURE CODE ON THE MACHINE ECM'S, THE CUSTOMER TOOK A PHOTO OF THE MONITOR WHEN THE



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

PO BOX 9274 9048

Make: CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 2140.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC15135

Invoice No. W0740018850

Invoice Date: 09/28/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

TRAVEL TO/FROM MACHINE
 PACHECO DAIRY

REPAIR PROCESS COMMENTS:

09/25/2023 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 33 MILES.

09/26/2023 (1193)

TRAVEL TO AND FROM MACHINE, TRAVELED 42 MILES.

F/R ALL

462.00 *

SEGMENT 01 TOTAL

462.00 T

TROUBLESHOOT TRANSMISSION

CUSTOMER COMPLAINT:

TRANSMISSION OIL LEVEL LOW, CUSTOMER ADDED TRANS OIL TO MACHINE.

CAUSE OF FAILURE:

HYD LEVEL SWITCH 539112D2

RESULTANT DAMAGE:

ACTIVE FAULT CODE ON C1000

REPAIR PROCESS COMMENTS:

09/25/2023 (1193)

ARRIVED AT MACHINE, CUSTOMER STATED THE TRANSMISSION HAD A FAULT CODE FOR LOW OIL LEVEL, CUSTOMER ADDED 3 GALLONS OF OIL AND CODE IS STILL ACTIVE ON THE MACHINE, CONNECTED EDT, OBTAINED A ENGINE LOG, INFORMED CUSTOMER THE ACTIVE FAULT CODE WAS A 2602=2 HYD OIL LEVEL LOW, BELOW NORMAL OPERATION RANGE WHICH LOGS THROUGH THE TRANSMISSION ECM. INSPECTED THE OIL LEVEL IN THE HYD TANK, OIL LEVEL WAS FULL. TESTED WIRING BETWEEN THE HYD LEVEL SWITCH AND THE TRANSMISSION ECM. WIRING TESTED GOOD. INFORMED CUSTOMER THE HYD OIL LEVEL SWITCH HAD FAILED. ORDER NEW SWITCH 539112D2. INFORMED CUSTOMER TO KEEP AN EYE AT ALL TIMES ON THE HYD OIL LEVEL BUT HE CAN CONTINUE TO USE THE MACHINE.

09/26/2023 (1193)

ARRIVED AT MACHINE, REMOVED THE DRIVER SIDE STEP ASSEMBLY OFF MACHINE TO GAIN ACCESS TO HYD LEVEL SWITCH. REMOVED AND REPLACED SWITCH 539112D2. FAULT CODE WAS NO LONGER ACTIVE, CLEARED ALL LOGGED CODES OFF MACHINE, INSTALLED STEP ASSEMBLY. CUSTOMER ALSO STATED IF WE COULD FIX A OIL LEAK ON THE LEFT SIDE OF THE ENGINE FOR THE TURBO DRAIN PIPES. TIGHTEN UP DRAIN PIPE. LET MACHINE RUN FOR 1 HOUR, LEAK WAS NO LONGER PRESENT AT THE TIME, FOUND NO OTHER LEAKS OR FAULT CODES, CALLED AND INFORMED CUSTOMER MACHINE



10006 Rose Hills Road
 City of Industry, CA 90801
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 2172.0

Quinn Store Location: CORCORAN PARTS, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC15161

Invoice No. WO740018926

Invoice Date: 10/11/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
TRAVEL TO/FROM MACHINE					
HAMPSTRA DAIRY AVE 260 EAST OF RD 68 TULARE, CA					
REPAIR PROCESS COMMENTS:					
2755 10/6/2023					
TRAVELED TO AND FROM MACHINE 50 MILES.					
			F/R ALL		256.00 *
		SEGMENT 01 TOTAL			256.00 T

TROUBLESHOOT HYDRAULIC SYSTEM					
REPAIR PROCESS COMMENTS:					
2755 10/6/2023					
ARRIVED AT MACHINE, CONNECTED EDT AND FOUND ACTIVE					
FAULT CODE FOR DIRECTIONAL SOLENOID #1. REMOVED					
REAR COVER AND INSPECTED WIRING. REMOVED BOTH					
PROPORTIONAL AND DIRECTIONAL SOLENOID. INSPECTED					
FOR DEBRIS. INSTALLED NEW SET OF SOLENOIDS AND					
TESTED. FAULT CODE WAS NO LONGER ACTIVE AND					
AUXILIARY VALVE #1 WORKED AS SHOULD. RETURNED					
MACHINE TO SERVICE.					
1	527365D1	KIT, SOLENOID	S	549.68	549.68
1	527366D1	KIT	S	502.55	502.55
		TOTAL PARTS	SEG. 02		1052.23 *
			F/R LBR		468.00 *
		SEGMENT 02 TOTAL			1520.23 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			24.00 T
		MISC. SUPPLIES			50.00 T
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			25.34 T
		INVOICE TOTAL			1,875.57

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,
 PLEASE LET US KNOW AS SOON AS POSSIBLE!
 SHOULD YOU HAVE ANY QUESTIONS REGARDING THIS INVOICE, PLEASE CONTACT
 LARRY PAREDES, CORCORAN STORE MANAGER, AT (559) 992-2193.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable
 [Redacted]
 [Redacted]

Make: CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No: AG0002159
 Machine ID No: AG0002159
 Meter Reading: 1527.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14670

Invoice No. WO740018395

Invoice Date: 04/20/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
PERFORM TA 2 INSPECTION					
REPAIR PROCESS COMMENTS:					
1085 3-8-2023					
PERFORMED A TA INSPECTION ON THE UNIT.					
3-16-2023 1065					
DID AN OUTBOUND AGCO PM360 INSPECTION. FOUND SOME THINGS THAT NEED TO BE ADDRESS.					
			F/R LBR	299.00	*
		SEGMENT 01 TOTAL		299.00	T

PERFORM 2000 SERVICE HOUR MAINT					
REPAIR PROCESS COMMENTS:					
1085 3-8-2023					
DRAINED THE ENGINE OIL. DRAINED THE TRANSMISSION. DRAINED THE HYDRAULIC TANK. DRAINED FRONT AND REAR AXLES.					
1085 3-9-2023					
REMOVED THE ENGINE OIL FILTER, AND INSTALLED A NEW FILTER. REMOVED THE HYDRAULIC FILTERS, AND INSTALLED NEW FILTERS. REMOVED THE TRANSMISSION FILTER, AND INSTALLED NEW FILTER. ADDED OIL TO THE ENGINE. ADDED OIL TO THE TRANSMISSION, AND AXLES. ADDED OIL TO THE HYDRAULIC TANK. INSTALLED NEW ENGINE OIL FILTERS. INSTALLED NEW CAB FILTER.					
1085 3-10-2023					
RAN UNIT AND MADE SURE ALL OIL LEVELS ARE GOOD.					
1085 4-12-2023					
PROVIDED CUSTOMER CASE OF COOLANT PER REQUEST					
1	AG609431	FILTER GATOR GOLD,S		70.36	70.36
1	V837079423	FILTER S		65.82	65.82
1	V837081555	OIL FILTER-D136 H3S		124.28	124.28
1	V837091117	FUEL FILTER KIT S		154.37	154.37
1	501153D1	FILTER/AIR S		38.28	38.28
1	513355D1	ELEMENT/FILTER S		85.85	85.85
3	534039D1	ELEMENT,FILTER S		108.52	325.56
1	565824D1	FILTER ELEMENT S		123.23	123.23
1	565825D1	FILTER ELEMENT S		233.94	233.94
1	570072D1	AIR FILTER-65.4MM S		99.08	99.08
3	15608	BRAKE/PARTSCLEANERS		7.69	23.07
6	QLAB 17	OIL SAMPLE-SHOP S		19.50	117.00
6	238-8648	COOLANT-ELC S		17.89	107.34
64	72626362TRLR	OIL S		7.46	477.44
220	79035450TRLR	OIL-HYD/TRAN 15W40S		7.23	1590.60
		TOTAL PARTS	SEG. 02	3636.22	*
			F/R LBR	1716.00	*
		SEGMENT 02 TOTAL		5352.22	T



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

Attention: Accounts Payable
 [Redacted]

SHIP TO:

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1527.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14670

Invoice No. WO740018395

Invoice Date: 04/20/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
CALIBRATE TRANSMISSION					
REPAIR PROCESS COMMENTS:					
04-10-2023 (2950)					
MACHINE TRANSMISSION NEEDED TO BE BROUGHT UP TO ABOVE 140 DEGREES FOR THE CALIBRATION TO START. MACHINE WAS CONNECTED TO ET THROUGH THE ECM. LOOP HOSES WERE ADDED TO THE HYDRAULIC CONTROL VALVE IN THE REAR OF THE MACHINE TO ADD EXTRA HEAT ON MACHINE TO GET TRANSMISSION UP TO CALIBRATION TEMP. MACHINE WAS DRIVEN IN THE YARD TO GET TRANSMISSION HOT, ALSO TRANSMISSION WAS STALLED TO BRING UP THE TEMP CLOSER TO 140 DEGREES. TRANSMISSION NEEDED TO STAY ABOVE 140 DEGREES DURING THE WHOLE CALIBRATION PROCESS. CALIBRATION WAS COMPLETED AND SUCCESSFUL ON ET THROUGH THE ECM.					
			F/R LBR		429.00 *
		SEGMENT 03 TOTAL			429.00 T
TROUBLESHOOT TRANSMISSION LINES/HOSES					
REPAIR PROCESS COMMENTS:					
04-10-2023 (2950)					
TRANSMISSION SIGHT GLASS HOSE WAS LEAKING, CHANGED O-RING AND TIGHTENED HOSE.					
2	400378X1	SEAL/O-RING 12.83 S		1.56	3.12
		TOTAL PARTS	SEG. 05		3.12 *
			F/R LBR		143.00 *
		SEGMENT 05 TOTAL			146.12 T
TROUBLESHOOT FAN BELT					
PULLEY					
REPAIR PROCESS COMMENTS:					
04-10-2023 2950					
ALTERNATOR IDLER PULLEY BEARING WAS FAILING. NEW ALT IDLER PULLEY WAS INSTALLED, BOLT WAS TORQUED TO SPEC. OLD FAN BELT WAS REMOVED AND NEW FAN BELT WAS INSTALLED. OLD ALTERNATOR BELT WAS REMOVED AND NEW ALTERNATOR BELT WAS INSTALLED.					
1	V837073631	ROLLER-D74/30 PK14S		167.40	167.40
1	565812D1	BELT-1917MM 8PK S		74.13	74.13
1	578628D1	FAN BELT-1747MM 12S		145.93	145.93
		TOTAL PARTS	SEG. 06		387.46 *
			F/R LBR		143.00 *
		SEGMENT 06 TOTAL			530.46 T
		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			24.00 T



10006 Rose Hills Road
City of Industry, CA 90801
(562) 463-4000
www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Accounts Payable
1075 N. WEST ST.
[Redacted]

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1799.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14865

Invoice No. WO740018682

Invoice Date: 07/27/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

TRAVEL TO/FROM MACHINE

HAMPSTRA DAIRY AVE 260 EAST OF RD 68 TULARE, CA

REPAIR PROCESS COMMENTS:

05/21/2023 (1059) TRAVELED TO AND FROM THE CUSTOMERS MACHINE. (36 MILES)

05/22/2023 (1059) TRAVELED TO AND FROM THE CUSTOMERS MACHINE. (36 MILES)

05/25/2023 (1059) TRAVELED TO AND FROM THE CUSTOMERS MACHINE. (36 MILES)

F/R ALL	456.00 *
SEGMENT 01 TOTAL	456.00 T

TROUBLESHOOT HYDRAULIC CONTROL VALVE

REPAIR PROCESS COMMENTS:

05/21/2023 (1059)

MACHINE AD ACTIVE CODE AUXILIARY VALVE #1 SOLENOID OPEN CIRCUIT. REMOVED REAR HYDRAULIC VALVE STACK COVER AND INSPECTED, FOUND #5 AND #6 HUSCO VALVES DISCONNECTED DUE TO SHORTING OUT. FOUND #1 HUSCO VALVE FAILING SWAPPED TO #2 VALVE AND SET SETTING FOR FLOW RATE AND NON CONTINUOUS FLOW AS PER DRIVER. WE DON'T NOT STOCK HUSCO VALVES SO I DID NOT REPLACE ANY.

05/22/2023 (1059)

MACHINE HAD ACTIVE CODES FOR #2 - #6 HUSCO CONTROLLER NOT COMMUNICATIONG. CHECKED THE HUSCO ECM'S AND THEY ARE BAD. DIDN'T HAVE ANY TO INSTALL. ORDERED THE 23-0032 BULLETIN PART'S TO UPDATE.

7-11-2023 1065

THERE WAS A BULLETIN TO UPDATE AND REPLACE THE HUSCO ECM'S TO A NEW IMPROVED SYSTEM. THE KITS ACX3816910 CONTROLLER, ACP0796380 1-4 HARNESS, ACP0796390 5,6, HITCH HARNESS, & ACX3868500 900 SERIES MOUNTING KIT, WAS ORDERED TO CONVERT THIS MACHINE.

CONNECTED EDT AND ET TO THE MACHINE AND DOWNLOADED MACHINE LOGGED CODES. COPIED MACHINE VALVE CALIBRATION SETTINGS. INSTALLED THE UPDATE KITS FOR A 900 SERIES MACHINE WITH 6 VALVES NO HITCH. WHEN CONNECTING THE HARNESS TO THE SOLENOIDS ON VALVES #1 & #2, THE SOLENOID CONNECTOR HOUSING WAS MISSING THE LOCK TAB. THE NEW UPDATE HARNESS CONNECTOR WILL NOT STAY ON THE SOLENOID CONNECTOR.

REPLACED THE TWO SOLENOIDS (527365D1). WITH THE NEW KITS INSTALLED PROGRAMMED THE NEW TWO HUSCO



10006 Rose Hills Road
 City of Industry, CA 91706
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable
 1075 N WEST ST

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1799.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickereil Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14865

Invoice No. WO740018682

Invoice Date: 07/27/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
ECM'S. OPERATED THE MACHINE AND ALL OF THE VALVES WAS WORKING WITH THE NEW ECM'S					
1	ACP0796380	KIT,HARNESS	N	257.55	257.55
1	ACP0796390	KIT,HARNESS	S	311.48	311.48
2	ACX3816910	CONTR HUSCO-SCV	N	2451.03	4902.06
1	ACX3868500	MOUNTING KIT	N	56.43	56.43
2	527365D1	KIT, SOLENOID	S	549.68	1099.36
3	79036407	LUBRICANT-PERMATRAS		145.55	436.65
10	3S-2093	TIE	S	.26	2.60
8	8T-8737	WHITE PLUG	S	.48	3.84
1	102-8804	RECPTACLE KIT 4PINS		7.56	7.56
		TOTAL PARTS	SEG. 02		7077.53 *
		LESS 100%-PARTS			7077.53 -*
		TOTAL LABOR	SEG. 02		2852.72 *
		LESS 100%-LABOR			2852.72 -*
2.00		PART FREIGHT IN			143.00
		TOTAL MISC CHGS	SEG. 02		143.00 *
		LESS 100%-MISC			143.00 -*
		SEGMENT 02 TOTAL			.00 T

TROUBLESHOOT SEAT SUSPENSION PUMP

REPAIR PROCESS COMMENTS:

05/25/2023 (1059)

REMOVED ALL PLASTIC CLIPS AROUND THE ENTIRE SEAT. USED PRY BARS AND WEDGED A BLOCK BETWEEN THE SEAT AS ARMS TO HOLD SEAT UP. SUPPLIES AIR TO THE AIR SUSPENSION WHILE SPRAYING SOAPY WATER ON AIR BAG AND ALL HOSES. FOUND HOSE LEAKING, CUT HOSE WERE BAD SPOT WAS AND HOSE WAS LONG ENOUGH TO REUSE. CUT THE HOSE WITH PROPER TOOLING SO HOSE WOULDN'T CRUSH OR DAMAGE AND REINSTALLED HOSE ON THE AIR COMPRESSOR FITTING. REMOVED BLOCK AND HAD DRIVER HIT ON SEAT WHILE SPRAYING SOAPY WATER AND FOUND NO OTHER VISUAL LEAKS AT THIS TIME.

F/R LBR

468.00 *

SEGMENT 03 TOTAL

468.00 T

TROUBLESHOOT HYDR HOSES

LEAK(S)

REPAIR PROCESS COMMENTS:

05/23/2023 (1059)

REMOVED ALL THE HYDRAULIC HOSE STRAPS, COVERS IN THE ARTICULATION AREA. INSPECTED OIL LEAK. FOUND HOSE LEAKING. LOOKED UP HOSE ONLINE DID NOT STOCK WAS GOING TO TAKE A WEEK LONG TO ORDER. REMOVED HOSE PART# 526727D1 AND BROUGHT HOSE BACK TO SHOP TO MAKE. INSTALLED NEW HOSE AND SEALS. REINSTALLED COVERS AND STRAPS. TOPPED OFF



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

Attention: Account Payable
 [Redacted]

SHIP TO:

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1799.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14865

Invoice No. WO740018682

Invoice Date: 07/27/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
TRANSMISSION OIL TO THE FULL MARK. MACHINE HAD NO EXISTING CODES FOR AUXILIARY VALVES AND RAN MACHINE ON THE ROAD WHILE OPERATING THE AUXILIARY VALVES NO ISSUES HAD THE DRIVER OPERATE MACHINE AND HE UNLOADED 10 TRUCKS AND NO ISSUES AT THIS TIME.					
1	6V-8397	ORFS ORING -6	S	1.34	1.34
1	6V-8398	ORFS ORING -8	S	1.37	1.37
10	7K-1181	STRAP CABLE	S	.49	4.90
1	124-2147	COUPLING	S	18.45	18.45
1	154-0097	COUPLING	S	11.12	11.12
288	456-8435	294 HOSE -8	S	.19	54.72
		TOTAL PARTS	SEG. 04		91.90 *
		LESS 100%-PARTS			91.90-*
		TOTAL LABOR	SEG. 04		1524.12 *
		LESS 100%-LABOR			1524.12-*
1.00		HOSE ASSY CHG			45.00
		TOTAL MISC CHGS	SEG. 04		45.00 *
		LESS 100%-MISC			45.00-*
		SEGMENT 04 TOTAL			.00 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			24.00 T
		AGCO EXT \$0 DED PROTECH COVERED REPAIRS		11734.27	
		TAX EXEMPTION LICENSE FARM 09/01/15			
		STATE SLS TX-AG2.25%			.54 T
INVOICE TOTAL					948.54

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.
 IF THERE IS ANYTHING WE COULD HAVE DONE BETTER,
 PLEASE LET US KNOW AS SOON AS POSSIBLE!
 SHOULD YOU HAVE ANY QUESTIONS REGARDING THIS INVOICE, PLEASE CONTACT
 LARRY PAREDES, CORCORAN STORE MANAGER, AT (559) 992-2193.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Account Payable
 1975 N. WEST ST.

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1879.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14886

Invoice No. WO740018865

Invoice Date: 09/29/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
4	400287X1	WASHER/HARD/11IDX2S		1.66	6.64
2	402847X1	P-CLIP-74.6MM ID S		6.27	12.54
10	159-1503	HOSE CLAMP	S	10.95	109.50
		TOTAL PARTS	SEG. 08		5996.19 *
		LESS 100%-PARTS			5996.19 -*
		TOTAL LABOR	SEG. 08		7140.12 *
		LESS 100%-LABOR			7140.12 -*
		SEGMENT 08 TOTAL			.00 T

REPLACE TURBOCHARGER

2755 8/10/2023
 ENGINE AGAIN AND LET RUN FOR A BIT. REVED ENGINE AND I COULD HEAR A CLUNKING NOISE. LOCATED NOISE COMING FROM LEFT SIDE HIGH PRESSURE TURBO. REMOVED BOOT AND FOUND TURBO IMPELLER NOT SPINNING FREELY. IT WOULD TURN AND LOCK UP. LOOKED UP PARTS AND WE DID NOT HAVE TURBO IN STOCK. NOTIFIED CUSTOMER.

2755 8/11/2023
 REMOVED TURBO FROM MACHINE IN YARD. ARRIVED BACK TO MACHINE, REMOVED EXHAUST CLAMPS AND LIFTED DOC. REMOVED TURBO FASTENERS AND OIL LINES. REMOVED TURBO. REMOVED HOUSING CLAMP FROM USED TURBO AND RE CLOCKED IT. TIGHTEND CLAMP AND INSTALLED TURBO WITH NEW GASKETS. STARTED MACHINE AND LET RUN WHILE CLEANING UP. EVERYTHING SOUNDED GOOD, STALLED MACHINE SEVERAL TIMES. CONTINUED TO LET RUN FOR ABOUT 30 MINUETS. CONNECTED EDT AND PERFORMED HIGH PRESSURE FUEL TEST. RAN TEST AND IT PASSED. INSPECTED FOR FUEL LEAKS FOUND NONE. STALLED MACHINE SOME MORE TO VERIFY REPAIR. LEFT HIGH PRESSURE TURBO STARTED MAKING A GRINDING NOISE. SHUT MACHINE DOWN, AND REMOVED BOOT. IMPELLER WAS LOOSE AND RUBBING HOUSING.

8-12-2023 1065
 THE LEFT SIDE HIGH PRESSURE TURBO WAS NEEDED TO B REPLACED. PARTS WAS ORDERED ALREADY. CONNECTED EDT & ET TO THE MACHINE AND DOWNLAODED MACHINE LOGGED CODES. DISMBLED THE LEFT SIDE TURBO OIL PIPES, AND AIR LINES. REMOVED THE TURBO (ACP0438390) AND INSTALLED A NEW TURBO ASEMBLY. CONNECTED OIL PIPES AND AIR PIPES WITH NEW SEALS AND GASKETS. REINSTALLED THE HOOD GROUP BACK ONTO THE MACHINE. RETURNED THE MACHINE TO THE DRIVER AND LET HIM RU IT AND MONITORED THE MACHINE. AN OIL LEAK CAME UP ON ONE OF THE OIL PIPES ON THE LEFT SIDE OF THE ENGINE. FIXED THE LEAK AND RETURNED THE MACHINE.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

[REDACTED]
 [REDACTED]
 [REDACTED]

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1879.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14886

Invoice No. WO740018865

Invoice Date: 09/29/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
2.00		PART FREIGHT IN			387.00
		TOTAL MISC CHGS	SEG. 02		4193.13 *
		SEGMENT 02 TOTAL			25837.25 T

REPLACE STARTER MOTOR					
REPAIR PROCESS COMMENTS:					
2852 8/11/23					
ONE STARTER WASN'T WORKING, SO REMOVED BOTH STARTERS					
FOUND STARTER BENDEX WAS BAD ON BOTH STARTERS SO					
REPLACED BOTH.					
2	571229D1	STARTER	S	606.28	1212.56
		TOTAL PARTS	SEG. 03		1212.56 *
			F/R LBR		858.00 *
		SEGMENT 03 TOTAL			2070.56 T

REPLACE DOOR CYLINDER					
REPAIR PROCESS COMMENTS:					
2852 8/11/23					
DOOR STRUT WAS BAD SO REPLACED.					
1	501026D1	SPRING/ AS. - GAS	S	48.15	48.15
1	511531D1	PANEL/CABINET	N	102.86	102.86
1	511537D1	DOOR/WA CABINET	N	505.70	505.70
3	511542D1	HINGE/LIFT OFF	N	45.59	136.77
1	511548D1	HANDLE/GRAB	N	87.45	87.45
3	516904D1	LEVER/ADJ LATCH	S	66.64	199.92
		TOTAL PARTS	SEG. 04		1080.85 *
			F/R LBR		143.00 *
		SEGMENT 04 TOTAL			1223.85 T

PERFORM 500 SERVICE HOUR MAINT					
REPAIR PROCESS COMMENTS:					
2852 8/11/23					
DID A 500 HRS CHANGED THE MOTOR OIL AND FILTERS					
AND THE FUEL FILTERS.					
1	V837081555	OIL FILTER-D136 H3S	S	124.28	124.28
1	V837091117	FUEL FILTER KIT	S	154.37	154.37
1	506678D1	BREATHER	S	95.92	95.92
16	1556218	CAT MULTIPURPOSE TS	S	3.42	54.72
68	72626362TRLR	OIL	S	7.46	507.28
36	79035450TRLR	OIL-HYD/TRAN 15W40S	S	7.23	260.28
		TOTAL PARTS	SEG. 06		1196.85 *
			F/R LBR		572.00 *
		SEGMENT 06 TOTAL			1768.85 T

REPLACE PTO PUMP					
HOSE(S)					
REPAIR PROCESS COMMENTS:					
08/03/23 2852					



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

Attention: Account Payable
 1976 N. WEST ST.

SHIP TO:

Make: CHALLENGER	Equipment No:
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1879.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14886

Invoice No. WO740018865

Invoice Date: 09/29/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
		REPLACED DAMAGED 526727D1 HOSE FROM TRANS TO PTO DRIVE.			
1	526727D1	HOSE AS-PTO	N	87.32	87.32
		TOTAL PARTS		SEG. 07	87.32 *
				F/R LBR	702.00 *
		SEGMENT 07 TOTAL			789.32 T

TROUBLESHOOT FUEL SYSTEM

REPAIR PROCESS COMMENTS:

2755 8/7/2023

ARRIVED AT MACHINE, CUSTOMER STATED ENGINE IS IN A DERATE. CONNECTED EDT AND VIEWED FAULT CODES. WITH ENGINE RUNNING HAD ACTIVE FAULT 0.520359.31 (OPEN LOAD OF PRESSURE CONTROL VALVE OUTPUT). WENT THROUGH TROUBLE SHOOTING STEPS FOR PCV. REMOVED LEFT SIDE ECM COVER AND ECM. REMOVED NECESSARY INTAKE PIPING AND COOLANT RESERVOIR. CHECKED CONNECTION FOR PCV AND IT SEEMED TO BE OK. REMOVED RIGHT SIDE ECM COVER AND ELECTRICAL CONNECTORS. DOWNLOADED ELECTRICAL SCHEMATIC AND LOCATED PINS FOR COMPONENT. MEASURED RESISTANCE BETWEEN ECM CONNECTOR AND PCV CONNECTOR. THE WIRING TESTED GOOD. REMOVED NECESSARY FUEL LINES IN ORDER TO REMOVE PCV. ORDERED PARTS.

2755 8/8/2023

ARRIVED BACK TO MACHINE, REMOVED PCV AND INSTALLED NEW ONE. INSTALLED ALL PARTS REMOVED, USED NEW SEALS FOR FUEL LINES. STARTED ENGINE AND LET RUN FOR A BIT. CHECKED FOR LEAKS AND FOUND NONE. HAD ACTIVE FAULT CODE 1239. 14 (RAIL PRESSURE, LEAKAGE DETECTED). SHUT MACHINE DOWN AND STARTED AGAIN. DID NOT SEEM LIKE THERE WAS ANY AIR IN THE SYSTEM. WENT THROUGH TROUBLESHOOTING STEPS FOR RAIL PRESSURE FAULT CODE. RAN HIGH PRESSURE FUEL TEST THEN INSPECTED FOR LEAKS. DID NOT FIND ANY LEAKS. CONTACTED AGCO TC AND HE STATED THERE HAS BEEN OCCURENCES, AFTER REPLACING PCV THE RAIL CRACK OR LEAK INTERNALLY. ORDERED FUEL RAILS AND FUEL LINES. REMOVED HOOD AND AIR CLEANER BOX.

2755 8/9/2023

ARRIVED BACK TO MACHINE, REMOVED ALL INTAKE PIPING, DOC, COOLANT LINES, BRACKETS, RADIATOR SUPPORT, AND TURBO'S. REMOVED EGR COOLERS AND LINES. REMOVED BOTH FUEL RAILS AND FUEL LINES. INSTALLED FUEL RAILS AND FUEL LINES, TORQUED TO SPEC. STARTED REASSEMBLING.

2755 8/10/2023

ARRIVED BACK TO MACHINE, CONTINUED ASSEMBLING.



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

[REDACTED]
 Attention: Account Payable
 [REDACTED]
 [REDACTED]

SHIP TO:

Make: CHALLENGER
 Model: MT955E
 Serial No: C0955AMNNG1005

Equipment No:
 Machine ID No: AG0002159
 Meter Reading: 1879.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14886

Invoice No. WO740018865

Invoice Date: 09/29/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
INSTALLED EGR COOLERS AND COOLANT TUBES WITH NEW HOSES AND CLAMPS. CLEANED EACH PIPE/TUBE BEFORE INSTALLING. INSTALLED OIL LINES AND TURBOS WITH NEW GASKETS. INSTALLED EXHAUST SYSTEM, INTAKE MANIFOLD, AND AIR CLEANER BOX. PRESSURE TESTED COOLING SYSTEM AND IT PASSED. FILLED WITH COOLANT AND KEYS MACHINE ON. CHECKED FOR FAULT CODES AND HAD NONE. PRIMED FUEL SYSTEM AND STARTED ENGINE. SHUT ENGINE DOWN AND CHECKED FOR LEAKS. FOUND ONE SMALL COOLANT LEAK DOWN IN VALLEY. I WAS ABLE TO TIGHTEN CLAMP SOME MORE TO STOP LEAK. STARTED ENGINE AGAIN AND LET RUN FOR A BIT.					
V837074665 RAIL PART CAUSING FAILURE WITH THE V837079834 VALVE IN IT					
8	ACW3397620	GASKET	S	4.66	37.28
8	ACW4030090	STUD BOLT	N	16.74	133.92
8	V521601000	NUT	S	3.44	27.52
8	V581704600	SCREW	S	.93	7.44
8	V581705030	SCREW	S	1.83	14.64
4	V602084783	HOSE CLIP	N	27.21	108.84
2	V614606225	O-RING	S	1.53	3.06
6	V614707625	O-RING	S	2.92	17.52
10	V615870812	WASHER	S	1.99	19.90
26	V615881216	GASKET	S	3.36	87.36
10	V615881420	GASKET	S	2.65	26.50
2	V641086008	VALVE	N	9.70	19.40
2	V836840992	GASKET	S	21.26	42.52
2	V836866454	CLIP	S	86.89	173.78
1	V837074665	RAIL PIPE-6-CYL	S	1067.93	1067.93
2	V837074668	INJECTION PIPE-1.CS	S	120.35	240.70
2	V837074669	INJECTION PIPE-2.CS	S	110.93	221.86
2	V837074670	INJECTION PIPE-3.CS	S	114.74	229.48
2	V837074672	INJECTION PIPE-5.CS	S	104.27	208.54
2	V837074673	INJECTION PIPE-6.CS	S	114.74	229.48
1	V837074768	RAIL PIPE	S	1083.91	1083.91
4	V837074811	CLAMP	S	50.44	201.76
4	V837074813	CLAMP	S	42.61	170.44
6	V837074972	GASKET	S	16.96	101.76
1	V837079834	PRESSURE VALVE	S	450.16	450.16
2	V837081613	FUEL PIPE	S	92.00	184.00
2	V837081786	GASKET	N	42.61	85.22
4	V837084035	RUBBER HOSE	S	20.41	81.64
2	V837084078	BANJO BOLT	N	11.51	23.02
4	V837086286	RUBBER HOSE	S	15.63	62.52
2	V837088280	INJECTION PIPE	S	90.83	181.66
1	V837091117	FUEL FILTER KIT	S	154.37	154.37
2	400054X1	BOLT	S	.99	1.98
10	400125X1	CLAMP	S	16.74	167.40



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

[REDACTED]
 Attention: Account Payable
 [REDACTED]

SHIP TO:

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 995.0

Quinn Store Location: CORCORAN PARTS, 510 Pickereil Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14089

Invoice No. WO740017510

Invoice Date: 05/24/2022

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

TRAVEL TO/FROM MACHINE

HAMPSTRA DAIRY AVE 260 EAST OF RD 68 TULARE, CA

REPAIR PROCESS COMMENTS:

05/16/2022 (1037)

TRAVELED TO THE JOB SITE. (36 MILES)

F/R ALL	143.50 *
SEGMENT 01 TOTAL	143.50 T

TROUBLESHOOT HYDRAULIC SYSTEM

LEAK(S)

CUSTOMER COMPLAINT:

THERE IS AN OIL LEAK UNDER THE CAB.

CAUSE OF FAILURE:

LOOSE BRAKE PRESSURE SENSOR.

REPAIR PROCESS COMMENTS:

05/16/2022 (1037)

REMOVED THE TRANSMISSION BELLY PAN. CLEANED THE AREA OF REPAIR. OPERATED THE MACHINE AND INSPECTED FOR THE SOURCE OF THE LEAK. THE PRESSURE SENSOR ON THE TOP OF THE BRAKE FILTER WAS LEAKING. REMOVED AND INSPECTED THE SEALS ON THE SENSOR. THE SENSOR WAS LOOSE. THERE WAS NO FAULT FOUND WITH THE SEALS. INSTALLED AND TIGHTENED THE SENSOR. OPERATED THE MACHINE TO VERIFY THE REPAIR. THERE ARE NO LEAKS PRESENT AT THIS TIME. INSTALLED THE BELLY PANS. RETURNED THE MACHINE TO SERVICE. 513921D1 PART CAUSING FAILURE.

1	513921D1	KIT/SEAL	N	51.08	51.08
		TOTAL PARTS	SEG. 02		51.08 *
		LESS 100%-PARTS			51.08*-
		TOTAL LABOR	SEG. 02		580.80 *
		LESS 100%-LABOR			580.80*-
		SEGMENT 02 TOTAL			.00 T

TOTAL PARTS DISCOUNT	.00	
ENV/RECYCLE FEE		24.00 T
AGCO STD-24MO/2000HR COVERED REPAIRS	631.88	
TAX EXEMPTION LICENSE FARM 09/01/15		
STATE SLS TX-AG2.25%		.54 T

INVOICE TOTAL 168.04

THANK YOU FOR YOUR BUSINESS.
 HOW DID WE DO? YOUR COMPLETE SATISFACTION IS VERY IMPORTANT TO US.



10006 Rose Hill Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

[Redacted Bill To Information]

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 788.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickereil Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC13849

Invoice No. WO740017348

Invoice Date: 03/30/2022

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

PERFORM TA 2 INSPECTION

F/R ALL

299.00 *

SEGMENT 01 TOTAL

299.00 T

PERFORM 2000 SERVICE HOUR MAINT

REPAIR PROCESS COMMENTS:

3/17/2022 (2006)

COMPLETED THE 2000 HR SERVICE. CHANGED TRANSMISSION, HYDRAULIC, ENGINE, AND FUEL FILTERS. WHEN REPLACING THE FUEL FILTERS STRUGGLED TO REMOVE THE FILTERS DUE TO THEM BEING TOO TIGHT. REPLACED ALL ENGINE AND AC FILTERS. REPLACED THE TRANSMISSION AND HYDRAULIC OIL. USED THE PERMATRAN 821 XL PLUS OIL FOR THE TRANSMISSION. ALSO GREASED ALL GREASE FITTINGS. INSPECTED ALL LIGHTS MADE SURE ALL LIGHTS WERE WORKING PROPERLY. ALSO REPLACED THE DEF FILTER. WHEN FILLING THE TRANSMISSION FOLLOWED PROPER PROCEDURE ON CHECKING THE OIL LEVEL.

1	AG609431	FILTER GATOR GOLD,S		68.69	68.69
1	V837079423	FILTER	S	65.84	65.84
1	V837081555	OIL FILTER-D136 H3S		124.29	124.29
1	V837091117	FUEL FILTER KIT	S	144.86	144.86
1	500143D1	FILTER	S	30.98	30.98
1	501153D1	FILTER/AIR	S	34.96	34.96
1	513355D1	ELEMENT/FILTER	S	80.32	80.32
3	534039D1	ELEMENT,FILTER	S	81.19	243.57
1	547856D1	BREATHER-12 PORT 2S		86.94	86.94
1	565824D1	FILTER ELEMENT	S	123.27	123.27
1	565825D1	FILTER ELEMENT	S	233.80	233.80
1	570072D1	AIR FILTER-65.4MM S		92.35	92.35
1	79035450	821XL TRANS&HYD OIN		1460.02	1460.02
4	QLAB 02	SOS PROBE SAMPLE	S	19.50	78.00
1	QLAB 17	OIL SAMPLE-SHOP	S	19.50	19.50
1	258-8738	SEAL O-RING	S	10.12	10.12
140	1556218	CAT MULTIPURPOSE TS		3.45	483.00
60	5153957	CAT DEO ULS 15W-4 S		4.08	244.80
TOTAL PARTS				SEG. 02	3625.31 *
				F/R LBR	1584.00 *
SEGMENT 02 TOTAL					5209.31 T

CALIBRATE TRANSMISSION

REPAIR PROCESS COMMENTS:

3/17/2022 (2006)

CALIBRATED THE TRANSMISSION. TRANSMISSION PASSED CALIBRATION

F/R LBR

528.00 *



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 463-4000
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

██████████
 Attention: Accounts Payable
 ██████████

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1527.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14670

Invoice No. WQ740016395

Invoice Date: 04/20/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
CALIBRATE TRANSMISSION					
REPAIR PROCESS COMMENTS:					
04-10-2023 (2950)					
MACHINE TRANSMISSION NEEDED TO BE BROUGHT UP TO ABOVE 140 DEGREES FOR THE CALIBRATION TO START. MACHINE WAS CONNECTED TO ET THROUGH THE ECM. LOOP HOSES WERE ADDED TO THE HYDRAULIC CONTROL VALVE IN THE REAR OF THE MACHINE TO ADD EXTRA HEAT ON MACHINE TO GET TRANSMISSION UP TO CALIBRATION TEMP. MACHINE WAS DRIVEN IN THE YARD TO GET TRANSMISSION HOT, ALSO TRANSMISSION WAS STALLED TO BRING UP THE TEMP CLOSER TO 140 DEGREES. TRANSMISSION NEEDED TO STAY ABOVE 140 DEGREES DURING THE WHOLE CALIBRATION PROCESS. CALIBRATION WAS COMPLETED AND SUCCESSFUL ON ET THROUGH THE ECM.					
			F/R LBR	429.00 *	
		SEGMENT 03 TOTAL			429.00 T

TROUBLESHOOT TRANSMISSION LINES/HOSES					
REPAIR PROCESS COMMENTS:					
04-10-2023 (2950)					
TRANSMISSION SIGHT GLASS HOSE WAS LEAKING, CHANGED O-RING AND TIGHTENED HOSE.					
2	400378X1	SEAL/O-RING 12.83 S		1.56	3.12
		TOTAL PARTS	SEG. 05		3.12 *
			F/R LBR	143.00 *	
		SEGMENT 05 TOTAL			146.12 T

TROUBLESHOOT FAN BELT					
PULLEY					
REPAIR PROCESS COMMENTS:					
04-10-2023 2950					
ALTERNATOR IDLER PULLEY BEARING WAS FAILING. NEW ALT IDLER PULLEY WAS INSTALLED, BOLT WAS TORQUED TO SPEC. OLD FAN BELT WAS REMOVED AND NEW FAN BELT WAS INSTALLED. OLD ALTERNATOR BELT WAS REMOVED AND NEW ALTERNATOR BELT WAS INSTALLED.					
:	V837073631	ROLLER-D74/30 PK14S		167.40	167.40
:	S65812D1	BELT-1917MM 8PK S		74.13	74.13
:	S78628D1	FAN BELT-1747MM 12S		145.93	145.93
		TOTAL PARTS	SEG. 06		387.46 *
			F/R LBR	143.00 *	
		SEGMENT 06 TOTAL			530.46 T

		TOTAL PARTS DISCOUNT		.00	
		ENV/RECYCLE FEE			24.00 T



10006 Rose Hills Road
 City of Industry, CA 90601
 (562) 453-4900
 www.quinncompany.com

SERVICE INVOICE

BILL TO:

SHIP TO:

Attention: Accounts Payable
 1085 1153D1
 1085 1153D1

Make: CHALLENGER	Equipment No: AG0002159
Model: MT955E	Machine ID No: AG0002159
Serial No: C0955AMNNG1005	Meter Reading: 1527.0

Quinn Store Location: CORCORAN AG SALES, 510 Pickerell Street, Corcoran, CA 93212 (559) 992-2193

INVOICE DETAIL

Work Order No. ZC14670

Invoice No. WO740018395

Invoice Date: 04/20/2023

QTY	PART NUMBER	DESCRIPTION	STK/NONSTK	UNIT PRICE	EXTENDED PRICE
-----	-------------	-------------	------------	------------	----------------

PERFORM TA 2 INSPECTION

REPAIR PROCESS COMMENTS:

1085 3-8-2023

PERFORMED A TA INSPECTION ON THE UNIT.

3-16-2023 1065

DID AN OUTBOUND AGCO PM360 INSPECTION. FOUND SOME THINGS THAT NEED TO BE ADDRESS.

	F/R LBR	299.00 *
SEGMENT 01 TOTAL		299.00 T

PERFORM 2000 SERVICE HOUR MAINT

REPAIR PROCESS COMMENTS:

1085 3-8-2023

DRAINED THE ENGINE OIL. DRAINED THE TRANSMISSION. DRAINED THE HYDRAULIC TANK. DRAINED FRONT AND REAR AXLES.

1085 3-9-2023

REMOVED THE ENGINE OIL FILTER, AND INSTALLED A NEW FILTER. REMOVED THE HYDRAULIC FILTERS, AND INSTALLED NEW FILTERS. REMOVED THE TRANSMISSION FILTER, AND INSTALLED NEW FILTER. ADDED OIL TO THE ENGINE. ADDED OIL TO THE TRANSMISSION, AND AXLES. ADDED OIL TO THE HYDRAULIC TANK. INSTALLED NEW ENGINE OIL FILTERS. INSTALLED NEW CAB FILTER.

1085 3-10-2023

RAN UNIT AND MADE SURE ALL OIL LEVELS ARE GOOD.

1085 4-12-2023

PROVIDED CUSTOMER CASE OF COOLANT PER REQUEST

1	AG609431	FILTER GATOR GOLD,S		70.36	70.36
1	V837079423	FILTER	S	65.82	65.82
1	V837081555	OIL FILTER-D136 H3S		124.28	124.28
1	V837091117	FUEL FILTER KIT	S	154.37	154.37
1	501153D1	FILTER/AIR	S	38.28	38.28
1	513355D1	ELEMENT/FILTER	S	85.85	85.85
3	534039D1	ELEMENT, FILTER	S	108.52	325.56
1	565824D1	FILTER ELEMENT	S	123.23	123.23
1	565825D1	FILTER ELEMENT	S	233.94	233.94
1	570072D1	AIR FILTER-65.4MM	S	99.08	99.08
3	15608	BRAKE/PARTSCLEANERS		7.69	23.07
6	QLAB 17	OIL SAMPLE-SHOP	S	19.50	117.00
6	238-8648	COOLANT-ELC	S	17.89	107.34
64	72626362TRLR	OIL	S	7.46	477.44
220	79035450TRLR	OIL-HYD/TRAN 15W40S		7.23	1590.60

TOTAL PARTS	SEG. 02	3636.22 *
	F/R LBR	1716.00 *
SEGMENT 02 TOTAL		5352.22 T