



Equipment



Manage the equipment operated by Allan.

[Equipment Active](#)
[Equipment Archived](#)
[Safety Equipment Active](#)
[Safety Archived](#)
[Small Engine & Tools Active](#)
[Small Engine & Tools Archived](#)
[+ Equipment](#)
[Maintenance](#)
[Maintenance Rules](#)
[+ Maintenance Rule](#)
[Availability](#)
[Availability Rules](#)
[Equipment Categories](#)
[LT-16 - Ram 5500 Crew 4x4](#)
[SS-4 - Bobcat S-630](#)
[SS-14 - Bobcat S-630](#)


Equipment Maintenance Summary

Bobcat S-630 SS-14

Generated: January 30, 2026 3:14 PM

Timeframe: 01/01/2014 → 01/30/2026

Scope: Both Maintenance and Repair

	Description	Start	End	Hours/KM	Type	Rule	Created
	Install GPS, Decals, Fire Extinguisher, Check Fluids & Filters, Check Lights & Beacon - Rear work lights not working, changed corroded spade connectors on bulb holder Mechanic = Terry & Colin	11/09/2015 12:00 AM	11/09/2015 12:00 AM	437/-	Repair		11/17/2015 9:32 PM
	lift arm cylinder grease nipple needs changing	N/A	N/A	-/-	Repair		06/09/2016 7:59 AM
	Changed Engine Oil & Filter, Air Filter, Fuel Filters Mechanic = Joe	06/29/2016 12:00 AM	06/29/2016 12:00 AM	698/-	Maintenance	Skid Steer - 500 Hour	06/30/2016 5:11 PM
	Changed Engine Oil & Filter, Air Filter, Fuel Filters Mechanic = Joe	06/29/2016 12:00 AM	06/29/2016 12:00 AM	698/-	Maintenance	Skid Steer - 500 Hour	06/30/2016 5:11 PM

Equipment Categories**+ Equipment Category**

lift arm support brace is missing a pin and spring to keep the brace in storage position. Wire is being used to hold brace up. - Replaced Pin Mechanic = Joe	06/29/2016 12:00 AM	06/29/2016 12:00 AM	698/-	Repair	06/30/2016 5:23 PM
				Repair Request	
				Lift arm support	
				lift arm support brace is missing a pin and spring to keep the brace in storage position. Wire is being used to hold brace up.	
				May 2, 2016 9:13 AM by Trevor Urban	
Change Engine Oil & Filter (5W40), Air Filter Top Up Hydraulic Oil Mechanic = Joe	05/12/2017 12:00 AM	05/12/2017 12:00 AM	923/-	Maintenance	250 Hour- Skid Steer
Change Engine Oil & Filter (5W40), Air Filter Top Up Hydraulic Oil Mechanic = Joe	05/12/2017 12:00 AM	05/12/2017 12:00 AM	923/-	Maintenance	Skid Steer - 500 Hour
Wash - Grease - Adjust Door and Tighten Bolts on Hinges - Check Lights, Beacon, A/C = OK - Install Fire Ext Bracket Mechanic = Joe	05/12/2017 12:00 AM	05/12/2017 12:00 AM	923/-	Repair	05/25/2017 12:30 PM

Re-Seal right lift cylinder - Adjust door latch & hinges - Charge battery - Replace cab filters - Check Block Heater, HVAC, Wipers, Lights, Replace Fire Ext. and Inspection Book - Replace bulb on top right front cab - Replace return line on Bobtach (fitting loose and leaking), Top Up Hydraulic Oil - Grease - Change Air Filter Mechanic = Shawn	01/08/2018 12:00 AM	01/08/2018 12:00 AM	1,123/-	Repair	01/09/2018 9:35 AM
Replace Engine Air Filter and Cab Air Filter Mechanic = Shawn	01/08/2018 12:00 AM	01/08/2018 12:00 AM	1,123/-	Maintenance	01/09/2018 9:36 AM
Change Engine Oil & Filter (10W40 PetroCan Synthetic), Air Filter, Fuel Filter, Hydraulic Oil (Bobcat Hydraulic) & Filter, Grease, Wash	07/26/2018 12:00 AM	07/26/2018 12:00 AM	1,192/-	Maintenance	Skid Steer - 500 Hour 07/26/2018 2:05 PM
Check Over, Fire Ext, Seat Belt, Replace Reverse Alarm, New First Aid Kit - Grease - Wash Mechanic = Jace	07/26/2018 12:00 AM	07/26/2018 12:00 AM	1,192/-	Repair	07/26/2018 2:07 PM
Starter Motor is spinning and not engaging - Found a shim between starter and housing preventing the teeth on the starter from fully engaging the teeth on the flywheel - Replaced starter with new from Earthworks and did not use shim - Kept old starter in inventory at Floral Mechanic = Colin	02/15/2019 12:00 AM	02/15/2019 12:00 AM	1,214/-	Repair	03/01/2019 11:30 AM
				Repair Request Starter Starter Motor is spinning and not engaging February 11, 2019 10:38 AM by Brianne Reynolds	

Window Knob Missing Pass Side Interior Window - Replaced Mechanic = Brianne	05/21/2019 12:00 AM	05/21/2019 12:00 AM	1,225/-	Repair	06/19/2019 2:43 PM
				Repair Request	
				Window Knob	
				Window Knob	
				Missing Pass Side	
				Interior Window	
				May 17, 2019 9:37	
				AM by Chris Bildfell	
Replace Battery Mechanic = Brianne Reynolds	07/22/2019 12:00 AM	07/22/2019 12:00 AM	1,225/-	Repair	07/23/2019 8:24 AM
Swap Demo Tires with Older Set from Floral Yard to Use Up on Sid Buckwold Bridge Mechanic = Jace	04/15/2020 12:00 AM	04/15/2020 12:00 AM	-/-	Repair	04/15/2020 2:54 PM
Lock Pin for Fork Missing, Replace Locking Pin Mechanic = Terry	04/15/2020 12:00 AM	04/15/2020 12:00 AM	-/-	Repair	04/16/2020 8:38 AM
Replaced Battery from First Filter (Group 31) Mechanic = Terry	04/14/2020 12:00 AM	04/14/2020 12:00 AM	1,515/-	Repair	04/16/2020 8:51 AM
Replace Bent Bolt and Missing Bushing for Quick Attach on end of Hydraulic Cylinder Mechanic = Terry	04/16/2020 12:00 AM	04/16/2020 12:00 AM	-/-	Repair	04/20/2020 10:28 AM
Unit Stalling and Randomly Dying and Wont Restart - Checked Battery, Fuses, Relays - Replaced Main Power Relay with Rear Light Relay to Test, Test Drove Machine and Seems OK Mechanic = Terry & Jace	05/04/2020 12:00 AM	05/04/2020 12:00 AM	-/-	Repair	05/08/2020 11:17 AM

Check Lights, Seat Belt, B/U Alarm, Beacon, Belts - Replaced Engine Oil Drain Fitting and Hose - Replaced Coolant - Grease - Top Up Hydraulic Oil Mechanic = Blake	05/29/2020 12:00 AM	05/29/2020 12:00 AM	1,603/-	Repair	06/15/2020 1:04 PM
Replaced Drive Belt Mechanic = Carl	10/15/2020 12:00 AM	10/15/2020 12:00 AM	1,660/-	Repair	10/15/2020 9:20 AM
Change Engine Oil & Filter (9L 10W40 PetroCan Duron UHP Synthetic), Air Filer , Fuel Filter, Hydraulic Filter, Grease, Wash Mechanic = Claude	10/15/2020 12:00 AM	10/15/2020 12:00 AM	1,630/-	Maintenance	Skid Steer - 500 Hour
500 Hour Service - Check GPS it is Not Working Engine Oil = 6678233 Outer Air Filter = 7008043 Inner Air Filter = 7008044 Fuel Filter = 6667352 Hydraulic = 6692337 Tank Hydraulic = 7012314 Seal = 7015308 Cooling Fan = 7319444	N/A	N/A	-/-	Repair	10/29/2020 10:03 AM
					Repair Request 500hr Service - Check GPS 500 Hour Service - Check GPS it is Not Working Engine Oil = 6678233 Outer Air Filter = 7008043 Inner Air Filter = 7008044 Fuel Filter = 6667352 Hydraulic = 6692337 Tank Hydraulic = 7012314 Seal = 7015308 Cooling Fan = 7319444 October 15, 2020 9:42 AM by Carl Hewitt

Check Lights, Fluids, Fire Ext, BU Alarm Mechanic = Carl	10/15/2020 12:00 AM	10/15/2020 12:00 AM	1,630/-	Repair	10/29/2020 10:06 AM
Machine will start if primed but wont stay running - Lift Pump was replaced onsite at Lanigan Mine - Cory Installed New Lift Pump Onsite - Still Kept Dying - Brought it to Floral and Pumped Out the Fuel Tank, Added Fresh Fuel and Changed Fuel Filters = OK Mechanic = Cory & Carl	11/23/2020 12:00 AM	11/23/2020 12:00 AM	1,717/-	Repair	11/23/2020 2:46 PM
				Repair Request	
				Wont Stay Running	
				Machine will start if primed but wont stay running - Lift Pump was replaced onsite at Lanigan Mine	
				October 29, 2020	
				10:13 AM by Chris Bildfell	
Clean electrical starting system(wires and battery corrosion) Washed and greased Knob on door handle reattached Replace weather stripping on front door Knob on throttle lever reattached GPS rewired straight to fuse box and battery Replace air conditioning switch Replace receiver drier filter Replace high/low pressure switch Replace expansion valve Replace freeze up switch Replace air conditioning compressor Recharge air conditioning Reseal roof window Replace shut down solenoid	N/A	N/A	1,753/-	Repair	06/29/2021 2:30 PM

Change Engine Oil (11L PertoCan 10W40 Duron UHP Synthetic) Change Hydraulic Oil (11L Bobcat or Doosan Hydraulic Oil) Engine Oil Filter = 6678233 = Baldwin B163 = Donaldson P551042 Outer Air Filter = 7008043 = Baldwin RS5747 Inner Air Filter = 7008044 = Baldwin RS5748 Fuel Filter = 6667352 = Baldwin BF1257 Hydraulic = 6692337 = No Cross Tank Hydraulic = 7012314 = Baldwin PT23637-MPG Cooling Fan = 7319444 = No Cross Mechanic = Brandon	05/18/2022 12:00 AM	05/18/2022 12:00 AM	1,942/-	Maintenance	Skid Steer - 500 Hour	06/07/2022 4:08 PM
Right Hand Controller Throwing Code H1222 Right Hand Thumb Switch Out of Range Low Replace right hand control No gps in this unit	06/28/2022 3:00 PM	N/A	1,845/-	Repair	Repair Request Right Hand Controller Right Hand Controller Throwing Code H1222 Right Hand Thumb Switch Out of Range Low June 7, 2022 4:53 PM by Chris Bildfell	06/28/2022 12:34 PM

Check the GPS - Remove from unit and send to the city (IT) for testing if needed No gps in this unit	N/A	N/A	-/-	Repair	06/28/2022 12:34 PM
				Repair Request GPS Inspection Check the GPS - Remove from unit and send to the city (IT) for testing if needed	July 6, 2021 9:26 AM by Corey Klimosko
Wiper motor replace and cleaned up splines, set and tested Mechanic JG	N/A	N/A	2,071/-	Repair	12/05/2022 1:22 PM
Resealed Cylinders: LHS & RHS lift and LHS & RHS tilt cylinders Replaced two hyd hoses going to LHS bucket lift cyl Replaced LHS cab mount Cleaned all electrical grounds and power terminals Repaired a cut wire on main harness Replaced main fuse by battery Resealed top end of hydrostatic pump both sides Topped up hydraulic fluid Changed out in tank and charge hydraulic filters Ran machine and adjusted controls -Aidan	01/18/2024 7:00 AM	01/24/2024 3:00 PM	2,219/-	Repair	01/24/2024 3:22 PM
Swap Demo Tires for Skinny Set of Winter Tires	01/24/2024 12:00 AM	01/24/2024 12:00 AM	2,219/-	Repair	03/07/2024 11:34 AM
Change battery with new 31 series automotive post battery Clean electrical connections	N/A	11/25/2024 12:00 AM	2,361/-	Repair	11/25/2024 1:35 PM

Change battery with new 31 series automotive post battery Clean electrical connections	N/A	11/25/2024 12:00 AM	2,361/-	Repair		11/25/2024 1:35 PM
Change engine oil, oil filter, fuel filter, air filter, cab air filter	07/23/2025 12:00 AM	07/30/2025 12:00 AM	2,502/-	Maintenance	Skid Steer - 500 Hour	07/23/2025 7:43 AM
Instal new stop solenoid	07/23/2025 12:00 AM	07/23/2025 12:00 AM	2,502/-	Repair		07/23/2025 7:44 AM
Reseal quick attach hydraulic cylinder, Clarence	01/23/2026 12:00 AM	N/A	2,593/-	Repair		01/23/2026 8:48 AM