

PAID
 .1111. 20 2024
 chg# 1189

JHS Semi Repair Ltd
 505 1ST Ave West Box 100
 Assinibola, SK. S0H0B0
 Phone: 306-640-7364

INVOICE
2341

GST 740847744

INVOICE

Printed Date: 07/04/2024 Work Completed: 07/04/2024

2018 Peterbilt - 579 - Paccar MX-13 PCI 6 CYL
 Lic # : Odometer In : 1031484

VIN # : 1XPBDP9X2 JD489631

Part Description	Qty	Sale	Ext	Labor Description	Ext
New ECM with delete tune	1.00	8,500.00	8,500.00	Scan truck, truck not deleted properly.	130.00
Freight	1.00	40.00	40.00	R&I ECM, plugs full of dirt. Had to drill one out to clear	325.00
ABS sensor R955342	1.00	42.48	42.48	out dirt to unplug.	
Shop Supplies			22.75		
Taxes					
PST					543.61
GST					453.01

Org. Estimate 10,056.85 Revisions 0.00 Current Estimate 10,056.85

Labor:	455.00
Parts:	8,605.23
SubTotal:	9,060.23
Tax:	996.62
Total:	10,056.85
Bal Due:	\$10,056.85

[Payments -]

Vehicle Received: 7/4/2024

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Signature _____ Date _____

Email Address: jhssemi@sasktel.net

Customer Number : 645

103-1

JHS Semi Repair Ltd
 505 1ST Ave West Box 100
 Assiniboia, SK. S0H0B0
 Phone: 306-640-7364

INVOICE

3792

GST 740847744

Invoice from History

Printed Date: 11/03/2025 Work Completed: 10/30/2025

2018 Peterbilt - 579 - Paccar MX-13 PCI 6 CYL

Lic # :

Odometer In : 1043090

VIN # : 1XPBDP9X2 JD489631

Part Description	Qty	Sale	Ext	Labor Description	Ext
Transmission	1.00	4,875.00	4,875.00	Transfer bellhousing and rebuild	270.00
Clutch	1.00	1,607.14	1,607.14	R&I Transmission	2,430.00
Flywheel Resurface	1.00	268.71	268.71	Remove oil cooler and bypass transmission line.	202.50
Freight	1.00	200.00	200.00	Test drive truck. When test driving driving can hear	1,282.50
CD-50	18.00	13.37	240.66	banging noise from back. Diagnose axle 2 diff coming	
Enviro fee oil	18.00	0.18	3.24	apart. Drain oil, found pieces of gear. R&I diff.	
Steel female flare 5/8H-5/8T	2.00	15.91	31.82		
1/2" nylon air brake hose	2.00	1.30	2.60		
Differential	1.00	3,125.00	3,125.00		
Clutch pilot bearing	1.00	46.93	46.93		
Clutch brake 2 M1881	1.00	53.05	53.05		
5" preformed band clamp SS	1.00	12.86	12.86		
Brake Clean	12.00	7.14	85.68		
75W-90	16.00	16.96	271.36		
Enviro fee oil	16.00	0.18	2.88		
Gasket	2.00	4.01	8.02		
Hardware kit	1.00	45.55	45.55		
Coupling 3/8P	1.00	3.28	3.28		
Bushing 3/8P-1/4P	1.00	0.95	0.95		
1/4" NPT 90 elbow	1.00	2.64	2.64		
Hex Nipple Brass 1/4	1.00	1.48	1.48		
Shop Supplies			100.00		
				Taxes	
				PST	910.43
				GST	758.69

Org. Estimate 16,842.97 Revisions 0.00 Current Estimate 16,842.97

Labor:	4,185.00
Parts:	10,988.85
SubTotal:	15,173.85
Tax:	1,669.12
Total:	16,842.97
Bal Due:	\$16,842.97

[Payments -]

Vehicle Received: 10/30/2025

Customer Number : 645

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto.

Signature _____ Date _____

Email Address: jhssemi@sasktel.net