

SERVICE REGISTER

Machine UCR079 - Volvo 40T Articulated Haul Truck

SERIAL NO VCE0A40GC00324404



Date	SMU	Category	Mechanic	Service Notes / Repair Notes
23/11/2022	500	Preventative Maintenance	CJD	500hr service as per maint schedule. 500h oil samples
2/12/2022	689	Parts	Industroquip Safety	Custom Stickers
30/01/2023	767	Preventative Maintenance	UCR	Carried out 750hrs PM Service
2/03/2023	999	Preventative Maintenance	Hastings Deering	500h oil samples
17/05/2023	1,023	Preventative Maintenance	United Safety	12m service on DCP AFFF Fire Suppression system & Fogmaker - detection bottle with 14 bar pressure switch 90-fitting
1/07/2023	1,537	Preventative Maintenance	Hastings Deering	500h oil samples
5/08/2023	2,574	Preventative Maintenance	UCR	Carry out 500hr service. Need to set up engine oil quick fills. Sump plug x2 straight fittings 32mm x 1.5mm threads o ring on fittings. Hose 1300mm long Hose fittings x2 45 deg angle
4/09/2023	2,628	Defect Repair	United Safety	Fire Suppresion 12 month service
4/09/2023	2,628	Defect Repair	UCR	Two way radio broken - Radio removed
5/09/2023	2,628	Defect Repair	UCR	Contaminated fuel suspected to have caused engine running incorrectly. Drained and flushed fuel tank and replaced filters. Tested operation - ok.
13/09/2023	2,628	Preventative Maintenance	UCR	Replace engine oil and filter, SoS engine oil, change and cab air filters
7/10/2023	2,680	Defect Repair	UCR	Error message on screen - No warning lights found on inspection
18/10/2023	2,695	Defect Repair	UCR	1 wheel chock missing - replaced wheel chock RHS
21/10/2023	2,703	Defect Repair	UCR	Small leak around engine fill cap - cleaned engine filters and correctly fitted. No breathsafe - No breathsafe system fitted to machine
1/11/2023	2,735	Defect Repair	UCR	Coolant surge tank just under min level - cleaned surge tank, topped up and no coolant leaks found
2/11/2023	2,737	Defect Repair	UCR	Starving for fuel - Cleaned fuel tank breather. Engine oil filter cap leaking, needs replacing - inspected cap looks to be ok
10/11/2023	2,744	Mechanical Inspection	UCR	Carried out off hire mechanical inspection. Wash clean for transport
16/11/2023	2,752	Mechanical Inspection	CJD	Carried out service, replaced engine oil and filter, replaced fuel filters, checked drive belts, checked propeller shaft movements, checked lubrication, parking brake, emergency stop switch, brake cooling oil level, hydraulic oil level, tyre wear and air pressure, drive axles and dropbox leakage. Needs new hand fuel prime, front diff and dropbox were overful and milky, looks like they've taken in water
16/11/2023	2,628	Preventative Maintenance	CJD	500h oil samples
17/11/2023	2,753	Corrective Maintenance	UCR	R&R U/5 cab filters. Remove tail gate - clean covers & around filters. Remove & replace inner filter. R&R outer cab filter. Remove 3 piece tail gate
17/01/2024	2,899	Corrective Maintenance	Valley Tyres	Replace leaking O-ring seal on Pos 5
14/03/2024	2,940	Preventative Maintenance	Hastings Deering	500h oil samples
15/03/2024	2,940	Preventative Maintenance	UCR	Carry out 1000km Service
31/08/2024	3,507	Planned Maintenance	LeBrocq Plant Hire	500 hour service - all filters and oil. Replaced three lights on roof not working - Installed tailgate
5/09/2024	3,510	Preventative Maintenance	LeBrocq Plant Hire	Replace drop box oil & take sample
21/09/2024	3,516	Preventative Maintenance	CJD	500h oil samples
17/12/2024	3,965	Parts	Hunter Valley Filter Sales	Filters
28/01/2025	4,158	Parts	Hunter Valley Filter Sales	Filters
30/01/2025	4,163	Planned Maintenance	UCR	Carried out 4000 hr service
11/02/2025	4,224	Parts	Hunter Valley Filter Sales	Filters
21/05/2025	4,692	Planned Maintenance	UCR	Carry out 500 hr service
21/08/2025	4,938	Planned Maintenance	UCR	Carry out 250 hr service
22/08/2025	4,939	Preventative Maintenance	CJD	500h oil samples
23/10/2025	5,152	Corrective Maintenance	CJD	CARRY OUT VALVE ADJUSTMENT AS REQUIRED
19/12/2025	5,262	Preventative Maintenance	UCR	Equipment inspection ready for January project. Next service due 5,500 hours.
6/05/2026	5,451	Corrective Maintenance	UCR	Remove and replace filters, remove and replace 2 way radio handpiece
14/05/2026	5,483	Planned Maintenance	CSE Gencom	Service - Replace radio and antenna
15/07/2026	5,535	Planned maintenance	UCR	500 hr service. Fuel filter primer pump needs replacing