

Equipment : 905
 Location: ALL
 Component: ALL
 Reason: ALL
 Owner: ALL

Sort on: Equipment ID/Date

Date Range:
 Meter or Cumulative: Cumulative
 List Parts: No
 PM Jobs Only: No
 Page Break on Sort: No

* Indicates Credit Adjustment

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	04/26/1995 1,666.00	803063533	UNSCHEDULED NOISY	REPAIR ENGINE - ENGINE KNOCKING,DROPPED VALVE,BAD CAMSHF - DROPPED VALVE,CAMSHAFT & LIFTER BAD,ETC. SEE NOTE!!!	0.00	49.00	2,425.50	4,209.65	0.00	6,635.15
905	07/31/1995 1,801.00	808000670	UNSCHEDULED	REPAIR DIFFEREN - DIFFERENTIAL, CLUTCH, & BRAKE - FIXED DIFF, CLUTCH, & BRAKE	0.00	0.00	6,478.50	3,473.04	0.00	9,951.54
905	12/15/1995 2,033.00	820704956	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	40.44	0.00	0.00
905	03/26/1996 2,313.00	829145029	SCHEDULED PLANNED	PM-2 - - MANIFOLD LEAKS	0.00	2.40	0.00	65.21	0.00	0.00
905	06/05/1996 2,517.00	834076713	SCHEDULED PLANNED	PM-1 - - NEEDS RIGHT END BIT, 1.5" ON CUT EDGES	0.00	2.00	0.00	40.44	0.00	0.00
905	08/12/1996 2,781.00	842401965	SCHEDULED PLANNED	PM-4 - - SEE NOTES!!!	0.00	7.80	0.00	80.45	0.00	0.00
905	10/17/1996 3,077.00	845664077	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	40.44	0.00	0.00
905	04/04/1997 3,259.00	860772697	UNSCHEDULED NOT WORK	R&I STARTER - STARTER & BALL JOINT ON THROTTLE LINKAGE - REPLACED STARTER & BALL JOINT ON T.	0.00	0.00	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	05/21/1997 3,378.00	864425737	SCHEDULED PLANNED	LINK PM-2 - -	0.00	2.40	0.00	65.21	0.00	0.00
905	08/06/1997 3,671.00	871080078	SCHEDULED PLANNED	PM-1 - - TIGHTENED TRACKS	0.00	2.00	0.00	40.44	0.00	0.00
905	09/23/1997 3,859.00	880745788	UNSCHEDULED	REPAIR FINAL DR RT - - RESEAL RT FINAL DRV, RESEAL TRACK ADJUST	0.00	0.00	0.00	0.00	0.00	0.00
905	10/10/1997 3,868.00	877133786	SCHEDULED PLANNED	PM-4 - - NO SOS TAKEN! DAVE DROPPED OIL B/F TAKEN	0.00	7.80	0.00	80.45	0.00	0.00
905	11/11/1997 3,965.00	880746318	SCHEDULED WORN	SERVICE UNDERCAR - - SEE NOTE!!!	0.00	0.00	0.00	9,026.37	0.00	9,026.37
905	02/24/1998 4,126.00	888974568	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	40.44	0.00	0.00
905	06/02/1998 4,161.00	589799555		REPACK TRAK ADJ - - REPACK TRACK ADJUSTER	0.00	0.00	0.00	0.00	0.00	0.00
905	08/27/1998 4,418.00	588760101	SCHEDULED PLANNED	PM-2 - - exhaust leak @ muffler adjusted track	0.00	0.00	0.00	0.00	0.00	0.00
905	11/16/1998 4,603.00	598093551		REBUILD ENGINE - - Replace 6 cylinder pack, rebuilt one head, replaced one head. Counterbore one cyl (.007) NOTE: All six cyl already counterbored to 125.000	0.00	0.00	0.00	11,359.69	0.00	11,359.69
905	03/24/1999 4,895.00	607167815	SCHEDULED PLANNED	PM-1 - -	0.00	0.00	0.00	0.00	0.00	0.00
905	04/13/1999 4,958.00	608729951		REPLACE IDLER RT - - REPLACE RIGHT IDLER	0.00	0.00	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	06/23/1999 5,243.00	614788309	SCHEDULED PLANNED	PM-3 - -	0.00	0.00	0.00	0.00	0.00	0.00
905	09/02/1999 5,264.00	621684533		REBUILD BLADE BR - - REBUILD BLADE LINE BORE BOTTOM PIN IN BLADE	0.00	0.00	0.00	0.00	0.00	0.00
905	01/10/2000 5,384.00	639328030		INSTALL TRANSMIS - - Install transmission (spare from shop) Rebuild torque-converter	0.00	0.00	0.00	0.00	0.00	0.00
905	05/05/2000 5,384.00	644673730	SCHEDULED PLANNED	REPACK FINAL DR RT - - Reseal Rt. final drive, repack blade cyl. Replace seal hyd. control valve	0.00	0.00	0.00	0.00	0.00	0.00
905	10/28/2000 5,532.00	658150585	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	02/09/2001 5,588.00	683481530		REBUILD ENGINE - - Rebuild engine SEE NOTE!!!	0.00	0.00	0.00	0.00	0.00	0.00
905	06/26/2001 5,748.00	683468894		REPAIR CLUTCH S - - Reseal steering clutch and pinion shafts	0.00	0.00	0.00	0.00	0.00	0.00
905	07/25/2001 5,776.00	681669286	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00
905	11/01/2001 6,034.00	690656242	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	01/25/2002 6,244.00	709403031	LEAK	REPAIR ENGINE BOT - COMPESSION IN RAD - CUT .003 OFF OF SPACER PLATE,INSTALL NEW HEAD GASKETS	0.00	0.00	0.00	0.00	0.00	0.00
905	02/08/2002 6,246.00	698683808	SCHEDULED PLANNED	PM-4 - -	0.00	7.80	0.00	0.00	0.00	0.00
905	04/22/2002 6,337.00	709461877	LEAK	REBUILD ENG BSIC - COMPRESION IN RAD - PULL ENGINE,CARRY TO STOWERS SHOP ,REPLACE BLOCK FROM USED	0.00	0.00	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	06/21/2002 6,389.00	709402902		PARTS,CHECKED HEADS,REPLACED LINERS,RINGS,GASKET,BEARING - - -	0.00	0.00	0.00	0.00	0.00	0.00
905	08/01/2002 6,526.00	713976556	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	11/08/2002 6,764.00	721674762	MISC WORN	INSTALL STARTER - HARD TO START - R&R STARTER,FROM SLEEPY HOLLOW REBUILDER'S	0.00	0.00	0.00	0.00	0.00	0.00
905	12/06/2002 6,767.00	724258264	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00
905	12/12/2002 6,764.00	745684153	UNSCHEDULED WORN	INSTALL BRAKE OI - - RELINE BRAKES,NEW DRUMS, OR- BANDS	0.00	0.00	0.00	0.00	0.00	0.00
905	12/12/2002 6,764.00	745683872	UNSCHEDULED LEAK	INSTALL FINAL D LEFT - - LEFT FINAL LEAKING,NEW BEARING & SEALS	0.00	0.00	0.00	0.00	0.00	0.00
905	04/19/2003 6,993.00	738073754	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	08/05/2003 7,267.00	744814328	SCHEDULED PLANNED	PM-3 - -	0.00	5.60	0.00	0.00	0.00	0.00
905	10/04/2003 7,538.00	750081955	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	12/10/2003 7,656.00	767458488	UNSCHEDULED WORN	INSTALL UNDERCAR - - install undercarrige,RUBY WELDED UP LT SIDE IDLER RT SIDE GOOD	0.00	0.00	0.00	0.00	0.00	0.00
905	12/10/2003 7,656.00	767458746	UNSCHEDULED WORN	WELD BLADE BR - - WELD IN PUSH PLATE	0.00	0.00	0.00	0.00	0.00	0.00
905	03/12/2004 7,841.00	765105495	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	06/23/2004 7,935.00	777893441	UNSCHEDULED WORN	REPLACE IDLER - - replace rt idler,parts from letts	0.00	0.00	0.00	0.00	0.00	0.00
905	09/09/2004 8,112.00	779820193	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	10/27/2004 8,171.00	793553335	UNSCHEDULED WORN	REBUILD TRAN - - REBUILD TRANS& TOR,RESEAL LT & RT FINAL DRIVE PINIONS. USED MOSTLY CAT CLASSIC PARTS	0.00	0.00	0.00	0.00	0.00	0.00
905	01/17/2005 8,338.00	790592200	SCHEDULED PLANNED	PM-4 - -	0.00	7.80	0.00	0.00	0.00	0.00
905	07/12/2005 8,593.00	805707027	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	10/27/2005 8,864.00	815560325	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00
905	06/23/2006 9,123.00	835782870	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	01/15/2007 9,430.00	853431061	SCHEDULED PLANNED	PM-3 - -	0.00	5.60	0.00	0.00	0.00	0.00
905	04/02/2007 9,735.00	859970341	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	06/06/2007 9,946.00	866101107	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00
905	10/01/2007 10,239.00	875979781	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	06/30/2010 10,412.00	962379564	SCHEDULED PLANNED	PM-4 - -	0.00	7.80	0.00	0.00	0.00	0.00
905	09/13/2010 10,661.00	970038544	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	07/11/2011 10,922.00	994847513	UNSCHEDULED CRACKED	REPLACE CYL HEAD - - 2 new heads,aftermarket	0.00	0.00	0.00	0.00	0.00	0.00
905	07/26/2011 10,922.00	996139856	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	0.00	0.00	0.00
905	10/11/2012 11,200.00	1034433218	UNSCHEDULED LEAK	REPLACE HYD TUBE - - Replace both metal trans. cooler lines under engine	0.00	0.00	0.00	0.00	0.00	0.00
905	10/11/2012 11,200.00	1034779477	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	07/30/2013 11,391.00	1059749304	UNSCHEDULED PV MAINT	INSPECT DRIVE TR - - Need turned ASAP	0.00	0.00	0.00	0.00	0.00	0.00
905	08/13/2013 11,391.00	1060872798	UNSCHEDULED WORN	ROTATE PIN/BUSH - - Turn pin/bsh (Yancey S.A.L.T.) A/M segments, weld grouser bars R&R rear right carrier, R.H.F.roller,build up idlers	0.00	45.00	795.00	4,765.49	0.00	5,560.49
905	11/05/2013 11,463.00	1068139950	SCHEDULED PLANNED	PM-3 - -	0.00	5.60	0.00	0.00	0.00	0.00
905	05/08/2014 11,642.00	1084126360	UNSCHEDULED LEAK	REPLACE GASKET - Coolant leak job500 - R&R all water rail gaskets	0.00	0.00	0.00	0.00	0.00	0.00
905	05/20/2014 11,662.00	1085071613	UNSCHEDULED NOT WORK	REPLACE INST-IND - Job500 - R&R temp gauge for eng.	0.00	0.00	0.00	0.00	0.00	0.00
905	06/06/2014 11,691.00	1086540217	SCHEDULED PLANNED	PM-1 - -	0.00	2.00	0.00	0.00	0.00	0.00
905	09/30/2014 11,814.00	1096531941	UNSCHEDULED BROKEN	REPLACE MUFFLER - Job500 - R&R muffler	0.00	0.00	0.00	450.00	0.00	450.00
905	10/21/2014 11,874.00	1098356150	SCHEDULED PLANNED	INSPECT DRIVE TR - - fine	0.00	0.00	0.00	0.00	0.00	0.00
905	11/12/2014 11,969.00	1100687190	SCHEDULED PLANNED	PM-2 -	0.00	2.40	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	12/10/2014 12,003.00	1102764330	UNSCHEDULED BROKEN	- REPLACE IDLER RT - Job500 - R&R R.H. idler with one taken off 906, bearings went out	0.00	0.00	0.00	0.00	0.00	0.00
905	04/07/2015 12,118.00	1112862081	UNSCHEDULED LEAK	REPLACE MANIFOLD - -	0.00	0.00	0.00	767.66	0.00	767.66
905	07/06/2015 12,170.00	1120763619	SCHEDULED PLANNED	PM-1 - - Done when engine installed	0.00	0.20	0.00	0.00	0.00	0.00
905	07/06/2015 12,170.00	1120641811	UNSCHEDULED CRACKED	REPLACE ENGINE - colling system pressurised, cracked head - R&R engine with one out of 906, used existing torque conv., replaced u-joints in driveline, R&R conv. gauge, set R.P.M. R&R all related gaskets, switched over exhaust sys.	0.00	0.00	4,500.00	1,650.00	0.00	6,150.00
905	08/31/2015 12,339.00	1125564679	UNSCHEDULED LEAK	REPLACE HYD PUMP - - Shaft seal blown, R&R pump with pump out of 906	0.00	0.00	0.00	0.00	0.00	0.00
905	10/28/2015 12,398.00	1130682129	SCHEDULED PLANNED	PM-4 - -	0.00	7.80	0.00	80.45	0.00	80.45
905	07/28/2016 12,611.00	1154198453	SCHEDULED PLANNED	PM-1 - -	0.00	1.00	0.00	0.00	0.00	0.00
905	09/16/2016 12,630.00	1159636027	SCHEDULED PLANNED	INSPECT DRIVE TR - - On run out	0.00	0.00	0.00	0.00	0.00	0.00
905	09/16/2016 12,630.00	1159636643	UNSCHEDULED LEAK	REPLACE SEAL RT - - R&R slack adjuster seal (right side)	0.00	0.00	0.00	0.00	0.00	0.00
905	05/10/2017 12,833.00	1179991300	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	0.00	65.21	0.00	65.21
905	06/30/2017 12,880.00	1183311317	UNSCHEDULED WORN	ADJUST BRAKES - -	0.00	0.00	0.00	0.00	0.00	0.00
905	07/10/2017 12,911.00	1184339843	UNSCHEDULED WORN	CHANGE TRANS OIL - Bad oil samples - R&R transmission oil and filter (filter was	0.00	0.00	0.00	0.00	0.00	0.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	10/10/2017 13,116.00	1192091531	UNSCHEDULED LEAK	collapsed) REPLACE GASKET - Coolant leak at head - R&R water rail and exhaust gaskets	0.00	0.00	0.00	0.00	0.00	0.00
905	11/15/2017 13,130.00	1195220186	SCHEDULED PLANNED	PM-1 - -	0.00	0.20	0.00	0.00	0.00	0.00
905	12/10/2017 13,130.00	1198165510	UNSCHEDULED WORN	REPLACE SEAT CUSHIO - - Seat cushion and arm rests- seat out of 906	0.00	0.00	0.00	0.00	0.00	0.00
905	01/25/2018 13,130.00	1201689169	SCHEDULED PLANNED	INSPECT DRIVE TR - - Good	0.00	0.00	0.00	0.00	0.00	0.00
905	04/19/2018 13,225.00	1208599348	UNSCHEDULED SEIZED	REPLACE ROLLERS - - R&R top roller removed one from old D9 out back	0.00	0.00	0.00	0.00	0.00	0.00
905	05/04/2018 13,246.00	1210170427	UNSCHEDULED NOT WORK	REPLACE ALTENATOR - - R&R altenator assy. and all belts OR Cat	0.00	0.00	0.00	0.00	0.00	0.00
905	07/18/2018 13,341.00	1216890489	UNSCHEDULED LEAK	RESEAL CYLINDER - - Re-seal both blade cylinders	0.00	8.00	180.00	400.00	0.00	580.00
905	09/06/2018 20,535.00	1221067974	SCHEDULED PLANNED	INSPECT UNDERCAR - - Good	0.00	0.00	0.00	0.00	0.00	0.00
905	09/08/2018 13,342.00	1221067670	SCHEDULED PLANNED	INSPECT DRIVE TR - - Monitor- on run out idlers fine	0.00	0.00	0.00	0.00	0.00	0.00
905	10/15/2018 13,410.00	1224143020	SCHEDULED PLANNED	PM-3 - -	0.00	5.60	100.80	80.45	0.00	181.25
905	04/24/2019 13,471.00	1240589610	UNSCHEDULED WORN	REPAIR CLUTCH S - Right side no steer - Steering clutches wont disengage for right side R&R all piston seals for right clutch- R&R outer hub R&R right brake band-pull one out of old 906	0.00	0.00	0.00	125.00	0.00	125.00
905	09/09/2019 13,557.00	1252505702	UNSCHEDULED WORN	REPLACE ALTENATOR - - R&R altenator Cat re-man replace 1 batt	0.00	0.00	0.00	275.00	0.00	275.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	09/20/2019 13,611.00	1254391772	UNSCHEDULED WORN	REPLACE TRANS PUMP - - R&R transmission pump and filters	0.00	0.00	0.00	485.00	0.00	485.00
905	10/22/2019 13,654.00	1256228613	SCHEDULED PLANNED	PM-1 - -	0.00	0.20	4.00	0.00	0.00	4.00
905	11/25/2019 13,656.00	1260611823	UNSCHEDULED WORN	REPLACE BRAKE BAND - - R&R left brake band and all seals, R&R transmission linkages- change trans oil and filters- Cat re-man band	0.00	0.00	0.00	1,400.00	0.00	1,400.00
905	03/24/2020 13,675.00	1270225787	UNSCHEDULED FAILED	REBUILD TRAN - Loud noise coming from trans- wont take gear - R&R all seals, bearings, upper planetary cage and gears, R&R second gear housing, all clutch plates(used) R&R first gear housing, R&R input gear- from old trans, and piston housing- cleaned. after market parts valves re-sealed- Don installed	0.00	0.00	0.00	1,250.00	0.00	1,250.00
905	03/24/2020 13,675.00	1270226279	UNSCHEDULED CONTAMIN	RESEAL TORQUE C - - Teardown and clean from transmission failure re-seal	0.00	0.00	0.00	200.00	0.00	200.00
905	03/24/2020 13,675.00	1270226416	UNSCHEDULED CONTAMIN	REPLACE COOLER - - R&R transmission oil cooler (aftermarket)	0.00	0.00	0.00	900.00	0.00	900.00
905	02/18/2021 13,692.00	1299949192	UNSCHEDULED WORN	REPLACE BATTERY - -	0.00	0.00	0.00	0.00	0.00	0.00
905	03/19/2021 13,693.00	1303634249	UNSCHEDULED WORN	REPLACE TRANS PUMP - - R&R trans pump losing prime	0.00	0.00	0.00	450.00	0.00	450.00
905	11/01/2021 13,696.00	1319621537	UNSCHEDULED WORN	REPLACE CABLE - - R&R all batt. cables	0.00	0.00	0.00	0.00	0.00	0.00
905	11/29/2021 13,720.00	1322737696	UNSCHEDULED LEAK	REPLACE ELBOW - - R&R inlet elbow from transmission to bevel gear- tighten all mounting bolts	0.00	8.00	176.00	200.00	0.00	376.00
905	11/20/2022 13,756.00	1353688133	UNSCHEDULED WORN	PAINT BASIC MA - -	0.00	0.00	0.00	5,500.00	0.00	5,500.00

Equip. ID Owner	Date Meter	Job No	Category Reason	Job Description Problem Labor Findings	Down Hours	Labor Hours	Labor Costs	Material Cost	Consum Cost	Total Cost
905	05/17/2023 13,925.00	1368888339	UNSCHEDULED BROKEN	REPLACE MUFFLER - -	0.00	0.00	0.00	0.00	0.00	0.00
905	06/20/2023 14,130.00	1372334717	SCHEDULED PLANNED	PM-2 - -	0.00	2.40	58.20	65.21	0.00	123.41
905	07/15/2023 14,130.00	1434036018	UNSCHEDULED WORN	REPLACE TURBO - Bad oil sample - Found turbo worn R&R turbo and all gaskets and seals	0.00	0.00	0.00	0.00	0.00	0.00
905	08/02/2023 14,180.00	1383144978	SCHEDULED PLANNED	INSPECT DRIVE TR - - On run out	0.00	0.00	0.00	0.00	0.00	0.00
Sub Totals					0.00	243.20	14,718.00	47,671.74	0.00	61,896.22
Totals					0.00	243.20	14,718.00	47,671.74	0.00	61,896.22