

United Construction & Forestry
80 Southbridge Rd
North Oxford, MA 01537
Phone: (508) 987-8786
Fax: (508) 987-8786
info@uatne.com



Bill To: 625657

BUMBLEBEE LANDSCAPING
184 PLANTATION STREET - APT
2ACCOUNTS PAYABLE
WORCESTER, MA 01604 US
Email: WPUBLICOVER@BBL-
MA.COM;SERVICES@BBL-MA.COM
Phone: 6179992468
Fax:
Tax Exempt #:

Deliver To: 625657

BUMBLEBEE LANDSCAPING
184 PLANTATION STREET - APT 2
WORCESTER, MA 01604 US
Email: WPUBLICOVER@BBL-
MA.COM;SERVICES@BBL-MA.COM
Phone: 6179992468
Fax:

Service Invoice Details:

Invoice #: 11483925
Invoice Date: 13 Feb 2026
Work Order: 3038572
Advisor: Bonnie Parent
Location: 71 - CF-MA North Oxford
Jobsite: BUMBLEBEE LANDSCAPING
Customer PO #:

Make/Model	Serial Number	Meter	Equipment ID	Fleet Number
JOHN DEERE 950J	LU950JX008560	2893	JX008560	

Complaints:

Engine cranks, does not start.
41 Sutton Lane, Worcester MA
Will, 617-999-2468

Diagnostics:

01-28-2026 - Road service call to Sutton Lane, Worcester, MA.
Attached the welder to keep the batteries charged up.
Attached the space heater to warm the engine.
Inspected the electrical system - Found all the powers and grounds are okay.
Attempted to attach the diagnostic device - Found unable to connect.
The customer has asked to look at the cab heat.
Inspected - Found the blower motor needs to be replaced, due to continually blowing a fuse.

Repair:

Removed and replaced the fuel filter, customer supplied - Found full of ice.
Drained the secondary filter and filled with 9/11.
Primed the fuel system.
Allowed the machine to sit for a few minutes and then tried to cranking it and priming it and letting the starter cool and letting the batteries charge - Found finally got smoke and was able to get the machine running.
Ran the machine - Found everything is working properly.
The customer has asked that the blower motor be replaced and a service done on the engine, however, he will take care of the fuel filters.
Ordered the parts needed to complete the repair.

Part Number	Description	Quantity	Unit Price	Extended Price
LW10297295	OIL FILTER	2	\$61.92	\$123.84
TY26675	PLUS-50™II 15w40 CK4/SN 2.5 gl	1	\$70.12	\$70.12
LW10279773	FILTER ELE	1	\$101.51	\$101.51
PS911	POWERSER911	1	\$13.82	\$13.82
LW10279775	FILTER ELE	1	\$208.99	\$208.99
TY26679	PLUS-50™II 15w40 CK4/SN 5 gl	2	\$130.00	\$260.00

Part Number	Description	Quantity	Unit Price	Extended Price
SVCCALLFEE	SERVICE CALL FEE	1	\$100.00	\$100.00

Segment Summary:

Labor	OL&M	Misc	Parts	Subtotal
\$1088.00	\$0.00	\$0.00	\$878.28	\$1966.28

Complaints:

Cab blower motor
41 Sutton Lane, Worcester MA
Will, 617-999-2468

Repair:

02-06-2026 - Road service call to Sutton Lane, Worcester, MA.
Removed the seat and floor pan.
Removed the air conditioning and heater access cover.
Removed the blower motor cover.
Disconnected the blower motor connectors and removed the rotted cap screws.
Rebuilt the end of the harness.
Cut the old blower motor out and removed the rotted hardware.
Removed and replaced the blower motor.
Assembled the machine in reverse order of disassembly.
Performed a machine service.
Changed the engine oil and engine oil filter.
Changed both engine air filters.
THANK YOU FOR YOUR BUSINESS!

Part Number	Description	Quantity	Unit Price	Extended Price
LW10294855	Blower Fan	1	\$2,352.26	\$2352.26

Part Number	Description	Quantity	Unit Price	Extended Price
FREIGHT	FREIGHT	1	\$80.00	\$80.00
SVCCALLFEE	SERVICE CALL FEE	1	\$100.00	\$100.00

Segment Summary:

Labor	OL&M	Misc	Parts	Subtotal
\$1097.00	\$0.00	\$0.00	\$2532.26	\$3629.26

Order Summary:

Parts:	\$3410.54
OL&M:	\$0.00
Misc:	\$0.00
Labor:	\$2185.00
Subtotal:	\$5,595.54
Tax:	\$195.65
Total:	\$5,791.19

Payment Details:

Payment	Check#/Auth#/Override#	Credit card type	Credit card #	Signature	Amount
Check	348335				\$5,791.19

EMV Invoice Details:

Received By: _____

Date: _____

Terms & Conditions:

Payment in full received at the time of invoicing or delivery of goods or services.