



Los Angeles Freightliner - Fontana
A Division of Velocity Vehicle Group
13800 Valley Blvd
Fontana, CA 92335
(909) 510-4000
EPA ID: CAL000204459 ARD: ARD214794
www.VelocityVehicleGroup.com

Please Remit Payment to:
Los Angeles Truck Centers, LLC
PO Box 101284
Pasadena, CA 91189-1284



Date Arrived: 01/12/2023
Date Invoiced: 01/26/2023
SalesType: SR
PO No: DEBIT 8945 YESI
Terms: POS
Advisor: JOSE MAGANA
Email: jmagana@vvgtruck.com
Salesman: JOSE MAGANA
Reviewer: JOSE MAGANA

BILL TO

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

P: F:

DELIVER TO

[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

VIN: 1FUJGEDV7DSBU6548

Fleet Unit #:

Mileage: 544520

Year/Make/Model: 2013

FREIGHTLINER CASCADIA 125

Body ID#:

Engine Model / Serial#:

D471903 / 471903S0122092

License#:

Trans Model / Serial#:

FRO-15210C / P0572946

Axle Ratio: 3.55

Front Axle Model / Serial#:

E1202W3 / MY01000225

Tag#: 939

Rear FWD Axle Model / Serial#:

DS404 / HN03943861

Selling Dealer:

Rear Rear Axle Model / Serial#:

RS404 / HN03943862

Date In Svc: 05/02/2012

JOB #1 02 SR

Express Assessment (Apply to Op 1 Only)

COMPLAINT

EXPRESS ASSESSMENT ** CUSTOMER STATES THAT UNIT IS DERATED. CUSTOMER REPLACED ACM, AND NOW UNIT DOESN'T START AT ALL. CUSTOMER STATES THAT CLUTCH PEDAL HAS TO BE PRESSED ALL THE WAY DOWN, HAVE TO HOLD KEY ON AND THEN START TO RELEASE CLUTCH AND UNIT WILL START, ALBEIT HIGH IDLE. CHECK AND ADVISE. \$500

CAUSE

CORRECTION

check and advise for unit not starting after installing new acm, turn unit on had no throttle, towed unit into shop, checked codes and had codes for not communicating with acm and mcm, checked wires, checked up dates removed mcm connection to checked for voltage and was only receiving 11 volts, open hood and found belt ripped off and zipped tied, installed new belt and unit charge up batteries to 13 volts, performed t/s and ohm out system and all checked out ok, checked cpc checked out ok, installed test mcm and still no communication, continue t/s and found out that they installed an MCM instead of a ACM, got a test ACM and programmed it and all checked out ok. need to replace ACM and verify no other issues. program ACM, installed ACM, installed all parts taken off, reset ash count, cleared codes and all checked out ok, no more check engine light.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	240D/DDE A4719935596	POLY-V-BELT, ACCESSORY, FIXED	60.99	60.99
1	240V/GT 38667	BELT TENSIONER DD13/15	297.49	297.49
1	IBFRT	INBOUND FREIGHT GT 38667	75.00	75.00

Parts: \$358.48 Labor: \$1,512.00 Other: \$75.00 Sublet: \$0.00 \$1,945.48

JOB #2 02 SR

Express Assessment (Apply to Op 1 Only)

COMPLAINT

CUSTOMER STATES THAT AFTER REPLACING ACM, UNIT HAS NO THROTTLE RESPONSE AND BELT KEEPS FLYING OFF. CHECK AND ADVISE. \$500

CAUSE

CORRECTION

Confirmed no throttle response caused by mcm, repairs related to op.1. found belt torn. checked belt tensioner found excessive play. recommend to replace at this time. brought unit, into shop, removed belts removed tensioner, installed tensioner and belts all checked out ok.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	240D/DDE RA0004461554	ECU ACM 2.2 HDEP EPA10 CLASSIC	677.49	677.49
10	240X/IMP 71379	NYLON STR HD .3IN-14.5IN	0.25	2.50
1	240D/DDE RA0004461554-CORE	CORE	500.00	500.00

Parts: \$1,179.99 Labor: \$432.00 Other: \$0.00 Sublet: \$0.00 \$1,611.99

JOB #3 00a SR**Additional Repairs (Add On Op)****COMPLAINT**

MULTIPLE AIR LEAKS. OK TO CHECK AND REPAIR BY ROBERT. 8:37 PM 1/18. \$800 MAX, ANYTHING OVER, NEEDS AUTHORIZATION.

CAUSE**CORRECTION**

PULLED UNIT INTO SHOP. AIRED SYSTEM UP TO MAX. STARTED IN THE ENGINE BAY AND FOUND ALL LINES ON THE BRAKE MANIFOLD ARE LEAKING. CONTINUED INSPECTION AND FOUND 11 AIR LINES ON TOP BRAKE VALVE NEXT TO MANIFOLD LEAKING AT THE FITTINGS. ALSO FOUND MV3 VALVE AND AIR LEAK AT SEAT. RECOMMEND TO REPLACE ALL FITTINGS, AIR MANIFOLD AND MV3 VALVE AT THIS TIME. GOT BRAKE PASSTHRU MANIFOLD IN, AIRED UP UNIT TO MAX AIR. TURNED UNIT OFF. SOAPED UP THE NEW MANIFOLD, AND ALL 11 AIR LINES FOUND ON TOP BRAKE VALVE NEXT TO MANIFOLD ANOTHER LEAKING FITTING. 3/8 TO 3/8 NPT. REPLACED WITH NEW 3/8 X 3/8 RED LINE 7" LONG. REPLACED ANOTHER 3/8 X 3/8 GREEN LINE 7" LONG.

INSTALLED UNDER DASH: 2 3/8X3/8 UNIONS. INSTALLED UNDER DASH 4:1/4 X 1/4 UNIONS. SOAPED ALL UNION FITTING NO LEAKS.....HOLDING AIR PRESSURE NOW.

PARK UNIT AND WAIT FOR SERVICE ADVISER.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	240F/12-21425-002	PASSTHROUGH-SW MANIFOLD,AIR,P3	274.99	274.99
2	240F/23-14392-005	CONN-STR,PTC,.38 MPT TO .38 NT	4.63	9.26
4	240F/23-14393-005	UNION-PTC,.38 NT TO .38 NT	6.24	24.96
4	240F/23-14395-011	ELBOW-45,PTC,.50 MPT TO .62 NT	13.39	53.56
2	240F/23-14396-006	ELBOW-90,PTC,.38 MPT TO .38 NT	5.65	11.30
1	240V/PH 1220 6B RED500	TUBING NYLON HOSE	0.77	0.77
1	240V/WAB 434 100 310 0	VLV CHK PRESS CNTRL AIR DRY *D	56.99	56.99
4	240X/IMP 91200	A/B UNION 1/4 PUSH IN	7.69	30.76

Parts: \$462.59 Labor: \$1,944.00 Other: \$0.00 Sublet: \$0.00 \$2,406.59

JOB #4 00a SR**Additional Repairs (Add On Op)****COMPLAINT**

REPLACE HANDBRAKE VALVE. OK PER ROBERT @ BB&L

CAUSE

DONE

CORRECTION

LOCATE UNIT. PULL UNIT INTO SHOP. DRAIN BOTH AIR TANKS. DRAIN AIR FROM AIR LINES. REMOVE DASH. REMOVE MV-3 VALVE. REMOVE AIR LINES. INSTALL NEW MV-3. INSTALLED LINES. ON A COLD START THIS MORNING FOUND LARGE 5/8 FITTING LEAKING BACK SIDE AIR TANK # 2. REMOVED FITTING INSTALLED NEW. FOUND THREE MORE COLD LEAKS. HAV PICS AND VIDEOS OF NEW LEAKS.. TRACTION PROTECTION VALVE LEAKING MAJOR ON COLD START.....AND HAVE FOUND SEVERAL MORE LEAKS ON THIS COLD START..

AIRED UP TRUCK. SOAPED MV-3 VALVE BEHIND DASH. ALL GOOD NO MORE LEAKS BEHIND DASH.

QTY	ITEM	DESCRIPTION	UNIT PRICE	EXTD PRICE
1	240X/VTC-61862	VALVE	120.99	120.99
1	ibftr	INBOUND FREIGHT VTC-61862	15.00	15.00

Parts: \$120.99 Labor: \$514.50 Other: \$15.00 Sublet: \$0.00 \$650.49

INVOICE

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THERE ARE NO WARRANTIES WHICH EXTEND BEYOND THE DESCRIPTION ON THE FACE HEREOF. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND THE COMPANY NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS WHICH ARE SOLD AS IS AND WITH ALL FAULTS.

WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.

CLIENT AGREES THAT JURISDICTION AND VENUE OF ANY DISPUTE, CLAIMS OR LAWSUITS BETWEEN CLIENT AND THE COMPANY REGARDING ANY MATTER, INCLUDING, BUT NOT LIMITED TO SERVICES PROVIDED OR GOODS SOLD BY THE COMPANY TO CLIENT OR ON CLIENT'S BEHALF, SHALL BE EXCLUSIVELY IN THE STATE AND COUNTY THE REPAIR WAS PERFORMED. AGREES TO BE SUBJECT TO THE JURISDICTION OF STATE AND COUNTY IN ANY SUCH DISPUTE.

PLEASE READ TERMS AND CONDITIONS ON THE NEXT PAGE SIDE BEFORE SIGNING.

AUTHORIZED BY _____ DATE _____

LABOR	\$4,402.50
PARTS	\$2,122.05
OTHER	\$90.00
SUBLET	\$0.00
SUBTOTAL	\$6,614.55
MISCELLANEOUS	\$350.00
TAX	\$191.58
TOTAL	\$7,156.13

Receipt of Sale

Amount:	\$7,156.13	Payment:	\$7,156.13
Type:	CREDIT	Entry:	Chip Read
Media:	DISCOVER	Tran#:	9480333085
Card#:	8945	Auth#:	02688B
AID#:	A0000001523010		
Time:	1/26/23 11:06 am	Type:	Credit/Debit
Signature:			

- (1) OUR TERMS ARE PAYMENT ON DELIVERY@SERVICE CHARGE OF 1 1/2% PER MONTH (18% PER ANNUM)
RECEIVED WITH 30 DAYS OF INVOICE DATE. IF VVG HAS EXTENDED CREDIT TERMS, PAYMENT IS DUE PER THE
CREDIT ARRANGEMENT. IN THE EVENT LEGAL ACTION IS REQUIRED TO ENFORCE PAYMENT, CUSTOMER AGREES TO
PAY VVG ALL COURT COSTS AND ATTORNEY FEES
- (2) A 20% RESTOCKING CHARGE WILL BE CHARGED ON ALL ITEMS RETURNED.
- (3) ALL REQUESTS FOR RETURN MUST BE:
- A. IN ORIGINAL CLEAN CARTON
 - B. UNUSED
 - C. WITHIN 30 DAYS OF INVOICE DATE, AND ACCOMPANIED BY A COPY OF THE INVOICE.
- (4) NO ELECTRICAL ITEMS MAY BE RETURNED.
- (5) NO SPECIAL ORDER ITEMS MAY BE RETURNED.
- (6) ALL PARTS SOLD AND/OR INSTALLED BY VVG ARE WARRANTED BY THE MANUFACTURER. VVG ACCEPTS NO
RESPONSIBILITY FOR FIT, TYPE, OR QUALITY OF ANY VENDOR ITEM.
- (7) KITS AND SETS ARE NOT RETURNABLE IF CARTON IS OPENED
- (8) CORES MUST BE RETURNED WITH 5 WORKING DAYS OF INVOICE DATE AND ACCOMPANIED BY A COPY OF THE
INVOICE. CORES MUST BE DRAINED, ASSEMBLED AND IN ORIGINAL CARTON
- (9) ALL SPECIAL ORDERED PARTS THAT YOU HAVE MADE A DEPOSIT ON MUST BE PICKED-UP WITH 10 DAYS YOUR
DEPOSIT IS FORFEITED.
- (10) VVG IS NOT RESPONSIBLE FOR LOST INCOME OF ANY TYPE WHICH RESULTS FROM A UNITS NON-OPERATION
WHILE BEING REPAIRED. THE DEALER IS NOT RESPONSIBLE FOR UNAVAILABILITY OF PARTS OR DELAYS IN PARTS
SHIPMENT BEYOND DEALER'S CONTROL.
- (11) ALL RETURNED CHECKS ARE SUBJECT TO A \$35.00 HANDLING FEE
- (12) LABOR WARRANTY IS 45 DAYS
- (13) VVG IS NOT RESPONSIBLE FOR LOSS OR DAMAGE TO THE VEHICLE OR ITS CONTENTS DUE TO COLLISION NOT
DUE TO ITS NEGLIGENCE; OR DUE TO THEFT OR OTHER CASUALTY REGARDLESS OF WHETHER OR NOT SUCH FIRE,
THEFT OR OTHER CASUALTY IS DUE TO ITS NEGLIGENCE
- (14) CUSTOMER STATES NO ARTICLES OF PERSONAL PROPERTY HAVE BEEN LEFT IN THE VEHICLE AND DEALER IS
NOT RESPONSIBLE FOR INSPECTION THEREOF
- (15) DUE TO THE TYPE OF SERVICE REQUESTED SOME REPAIRS MUST BE SUBLET
- (16) IF THE VEHICLE DESCRIBED HEREIN IS NOT CALLED FOR WITHIN THREE (3) DAYS AFTER SUCH NOTICE IS GIVEN,
A STORAGE CHARGE OF \$25.00 PER DAY WILL BE MADE FOR EACH DAY THEREAFTER
- (17) SAID DEALER IS AUTHORIZED TO DELIVER THE VEHICLE DESCRIBED HEREIN OR ANY OF ITS CONTENTS TO ANY
PERSON PRESENTING THIS RECEIPT
- (18) **CALIFORNIA PROP 65 WARNING** : DIESEL ENGINE EXHAUST AND/OR CHEMICALS ARE KNOWN TO THE STATE OF
CALIFORNIA TO CAUSE CANCER, REPRODUCTIVE HARM OR BRITH DEFECTS INCLUDING CUMENE, ETHYLBENZENE,
N-HEXANE, METHYL ISOBUTYL KETONA, SILICA, TETRAFLUOROETHYLENE, TITANIUM DIOXICE AND TOLUENE. THESE
CHEMICALS CAN BE FOUND IN ITEMS SOLD IN THE PARTS DEPARTMENT, DISTRIBUTED TO EMPLOYEE IN THE
SERVICE DEPARTMENT OR INHALED ON FACILITY PROPERTY. FOR MORE INFORMATION GO TO
WWW.P65WARNINGS.CA.GOV (TITLE 27 SEC. 25603,25604,25605,25506)