

848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

Customer:

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841 Tax ID Date:

Tax ID:

WILLOW OTREET, TP

YEAR	MAKE / MODEL	VIN	LK	CENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522	AG	57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #	P.O.	NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE		MEMO	TRANS	MISSION MODI	EL/SERIAL#	SERVICE WRITER
						GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	HOURS	0.0

WITH NEW NUT. HUNG DRIVESHAFT WITH NEW STRAP KITS AND FRAME BOLTS FOR

CARRIER BEARING. TORQUED ALL STRAP BOLTS.

TOTAL LABOR TOTAL PARTS

\$315.00 \$165.16

TOTAL FOR OPERATION 6

\$480.16

1 6.5-70-18X 1 20-74-91 1 6.5-70-18X 1 10094142 STRAP KIT U JOINT NUT STRAP KIT U JOINT CARRIER BEARING

\$16.20 \$17.00 \$114.96

\$17.00

MISC. SHOP SUPPLIES

\$806.74

LABOR \$23,049.50
SUBLET SALES \$2,642.91
PARTS \$24,829.51
SHOP SUPPLIES \$806.74
SALES TAX \$3,009.12
4566 CHARGE \$54,337.78

### A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

USTOMER: X	DATE	



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760

SERVICE INVOICE NUMBER SR3510

> **INVOICE DATE** 06-23-25

Customer:

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

717 517-8841

WILLOW STREET, PA 17584

Tax ID I	Date: Tax ID:					
YEAR	MAKE / MODEL	VIN	LI	CENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522	AC	357650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL	# P.O.	NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE	No.	AEMO	TRANS	SMISSION MOD	EL/SERIAL#	SERVICE WRITER
						GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	HOURS	0.0

ROAD SERVICE TO CUSTOMER LOCATION.

TOTAL FOR OPERATION 1

\$0.00

CUSTOMER REMOVED AND REPLACED SDP ENGINE WITH ANOTHER SDP ENGINE BUT HAS SEVERAL HARNESS CONNECTORS THAT DONT APPEAR TO BE CORRECT. INSPECT AND ADVISE.

LOOKED OVER ENGINE SWAP AND DETERMINED NEEDED DIRECTION FOR PROJECT. TOOK ECM BACK TO SHOP TO CHECK CALIBRATION IN DONOR ENGINE. CLEANED UP TRUCK. ADVISED OF ALL SEEN ISSUES WITH DONOR MOTOR, SETUP, ETC AND WHAT WOULD BE NEEDED TO MAKE RUNNING/RIGHT.

- OIL PAN CRACKED
- SDP TWIN TURBOS/EXHAUST PLUMBING ISSUES (OLD ENGINE WAS SINGLE TURBO)
- INCORRECT ROCKER BASE SINGLE ENGINE HARNESS PLUG/WIRE-MATING ISSUES (WHATS UNDER VALVE COVERS IS A MYSTERY)
- INCORRECT ECM/WIRING HARNESS
- WATER INLET PIPING TO WATER PUMP INCORRECT/PLUMBING ISSUES
- MULTIPLE ENGINE ACCESSORIES/SENSORS/MOUNTING ADAPTATION ISSUES TOTAL LABOR

\$314.50

TOTAL FOR OPERATION

\$314.50

TOW TRUCK FROM CUSTOMER LOCATION TO STS. TOWED TRUCK TO SHOP.

TOTAL LABOR

\$370.00

3 TOTAL FOR OPERATION

\$370.00

FINISH ENGINE SWAP. CHECK CAM GEAR AND INJECTORS FOR ECM COMPATABILITY. SWAP WATER INLET FROM OLD ENGINE TO FIT IN CHASSIS. INSTALL MANIFOLD FROM OLD ENGINE AND STS REBUILT TURBO. CHECKED OUT ENGINE - REMOVED BELLY BAR FROM TRUCK. CLEANED QUICK DRAIN FITTING AND DRAINED OIL. DROPPED PAN FROM ENGINE AND INSPECTED -CHUNKS OF METAL, ALUMINUM, RUBBER O RINGS, AND PLASTIC FOUND AT BOTTOM OF PAN. POSSIBLY FROM INJECTORS AND JAKE BRAKES. FOUND OIL WAS SLUDGE.

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

Customer:

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

YEAR	MAKE / MODEL	VIN	LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522	AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #	P.O. NUMBI	ER COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943		04-28-25	7-19
DEL MILEAGE		MEMO	TRANSMISSION MODEL/SERIAL #		SERVICE WRITER
	-			1	GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY HOURS	0.0

REMOVED L/S CAC PIPING AND INSPECTED CLEANED OIL PAN AND BOLTS. ENGINE INLET FOUND EXTREMELY RUSTY AND DIRT LAYING IN INTAKE. ALSO FOUND OIL STILL IN CAC AND PIPING FROM TURBO FAILURE. BARRED ENGINE OVER BY HAND AND VERIFIED MOTOR DOES SPIN. REMOVED PRECOOLER, INTERSTAGE PIPING, ALL TURBO ELBOWS, BRACKETS, MOUNTING PLATES AND OIL LINES. INSPECTED TURBOS - NEITHER TURBO SPINS AT ALL. REMOVED HP AND LP TURBOS AND MOUNTING BRACKETS. REMOVED EXHAUST OUTLET PIPING AND BRACKETS. REMOVED EXHAUST MANIFOLD AND TURBO OIL SUPPLY LINES. MADE UP JUMPER TUBE FOR OIL SUPPLY FITTINGS SO ENGINE COULD BE STARTED AND CHECKED FOR OPERATION. REMOVED ENGINE HARNESS AND ECM. REMOVED BOTH CAMSHAFT SENSORS AND INSPECTED CAM GEAR - FOUND E-MODEL CAM GEAR. REINSTALLED SENSORS. REMOVED VALVE COVERS. NOTED NO CRANKCASE BREATHER PIPING OR VENTING ON ENGINE. INSPECTED VALVE TRAIN. FOUND E-MODEL JAKE HOUSINGS, 3 CAT INJECTORS, 3 AFTERMARKET INJECTORS, BROKEN INJECTOR HARNESS AND 1 BROKEN STUD OFF INJECTOR SOLENOID. ALSO NOTED SUBSTANTIAL AMOUNT OF DIRT/DEBRIS IN TOP OF ENGINE. FLUSHED CYLINDER HEAD AND ALL VALVE TRAIN COMPONENTS. USED BENCH HARNESS AND CONNECTED TO ECM - OK. INSTALLED GOOD USED ECM AND TESTED ENGINE HARNESS. CLEANED STARTER CABLES THAT WEREN'T INSTALLED ON STARTER AND ROUTED INSTALLED. INSTALLED BATTERY CHARGER ON TRUCK. REMOVED AND REPLACED OIL FILTER. TRIED TO START - BATTERY POTENTIAL VERY LOW, WONT HOLD CHARGE. USED 2 JUMP PACKS ON STARTER AND BATTERIES - ENGINE CRANKS EXTREMELY HARD, LOSS OF COMPRESSION IN 1 CYLINDER AND WILL NOT START. MONITORED ECM AND VERIFIED ECM SEEING ENGINE SPEED AND OIL PRESSURE. ENGINE NEEDS DISASSEMBLED FOR FURTHER DIAG.

DRAINED OIL IN CLEAN BUCKETS. REMOVED OIL PAN, PICK UP TUBE AND BLOCK STIFFENER PLATE. RAN A MAGNET THROUGH OIL PAN AND FOUND METAL PIECES. LOOKED OVER PIECES AND FOUND THE MATCH GEAR RETAINER PLATE FROM FRONT OF ENGINE. UNABLE TO SEE ALL GEAR RETAINER PLATES WITH OUT REMOVING FRONT STRUCTURE. REMOVED #2, #4 AND #6 MAIN CAPS. (CRANK LOOKS GOOD). REMOVED REST OF MAIN CAPS AND ROD CAPS AND INSPECTED CRANK, CRANK LOOKED GOOD. NOTICED #7 MAIN CAP DIDNT WANT TO STAY SEATED IN BLOCK AFTER TAPPING IN WITH RUBBER MALLET. STARTED REMOVING HEAD. REMOVED FUEL FILTER HOUSING. LEANED HOOD FRONT, UNBOLTED RAD SUPPORT TO PULL RAD FRONT. REMOVED BELTS AND ACCESSORY BRACKETS, FAN AND FAN HUB TO ACCESS PEANUT COVER BOLTS. REMOVED A/C LINES, FAN HUB AIR SUPPLY AND HARNESS. REMOVED GROUNDS FROM HEAD AND FUEL RETURN LINE. REMOVED UPPER AND LOWER VALVE COVERS. REMOVED ENGINE BRAKE HOUSING, ROCKER SHAFTS, PEANUT COVER, CAM GEAR AND HEAD BOLTS. PULLED HEAD. #4 CYLINDER HAD A

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	 DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

Customer:

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

YEAR	MAKE / MODEL	VIN		LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522		AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #		P.O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE	M	EMO	TR	TRANSMISSION MODEL/SERIAL #		SERVICE WRITER
				1		GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	/ HOURS	0.0

LOT OF RUST BUILD UP LIKE IT GOT WATER OR MOISTURE IN IT AND THE ENGINE SAT FOR A WHILE. WIRE WHEELED CARBON/RUST BUILD UP AT TOP OF LINER. REMOVED ALL PISTONS AND INSPECTED. REMOVED LINERS. CLEANED DECK, WIRE WHEELED AND SANDED. CLEANED BLOCK AND INSPECTED WATER HOLES. RECOMMEND INSERTING ALL WATER HOLES. WIRE WHEELED AND CLEAN UPPER AND LOWER LINER BORES. REMOVED RADIATOR. REMOVED FRONT COVER. WATER PUMP AND OIL COOLER INLET. REMOVED POWER STEERING PUMP AND BRACKET TO FRONT COVER, AIR COMPRESSOR, DAMPER AND ALL BOLTS HOLDING FRONT COVER ON. FRONT COVER WAS SEIZED TIGHT ON THE DOWEL PINS AND TOOK A WHILE TO GET BROKE LOOSE. INSPECTED FOR BROKEN GEAR RETAINER PLATE. NO BROKEN OR DAMAGED PLATE LOCATED. SUSPECT PIECES ARE FROM PREVIOUS FAILURE. REMOVED GEARS AND STUB SHAFTS. REMOVED FRONT STRUCTURE BACK PLATE. CLEANED FRONT OF BLOCK AND BLEW OUT ALL OIL GALLEY HOLES. CLEANED CRANK FROM RUST AND SEAL SURFACE, REMOVED OIL FILTER HOUSING AND OIL COOLER. CLEANED PASSENGER SIDE OF BLOCK, TO PREP FOR PAINT. CLEANED FRONT STRUCTURE, VALVE COVERS, RISER, MOTOR MOUNT AND FRONT COVER. DEGREASED AND POWER WASHED. REPLACED FRONT STRUCTURE THROUGH STUDS AND SEALS. WIRE WHEELED AND CLEANED GASKET OFF FRONT COVER. CLEANED AND WIRE WHEELED DRIVER SIDE OF BLOCK. CLEANED AND TAPPED HEAD BOLT HOLES. STRIPPED HEAD TO SEND TO MACHINE SHOP. REBUSHED BULL GEAR, IDLER GEAR AND ADJUSTABLE IDLER CAM GEAR. REMOVED PARTS OFF OLD ENGINE NEEDED FOR ENGINE OVERHAUL. MACHINED COUNTER BORES. MACHINED AND INSERTED ALL WATER HOLES IN DECK. REMOVED CAB MOUNT BOLTS AND RAISED CAB FOR ACCESS TO FOUR REAR MOST WATER HOLES IN DECK. SET CAB BACK DOWN AFTER INSERTING AND REINSTALLED BOLTS. INSTALLED FRONT STRUCTURE PLATE AND BULL GEAR STUB SHAFT, PINNED ENGINE AND INSTALLED FRONT GEAR TRAIN STUB SHAFTS AND GEARS. CLEANED OIL PAN AND PAINTED. INSTALLED FRONT STRUCTURE COVER, WATER PUMP, FUEL PUMP, POWER STEERING ADAPTER AND OIL FILL TUBE. REMOVED OIL COOLER AND OIL FILTER HOUSING ON 6NZ IN PARKING LOT TO USE ON ENGINE TO MATCH OTHER COMPONENTS. OIL COOLER HOUSINGS OFF OF ENGINE IN TRUCK AND PARTS ENGINES BOTH HAD VERY ERRODED SEALING SURFACES.

POLISHED ROD AND MAIN JOURNALS INSTALLED MAIN BEARINGS AND MAIN CAPS. BENZOENED #1 LOWER LINER BORE AREA DUE TO PITTING. INSTALLED LINERS, PISTONS AND CONNECTING RODS. CLEANED WIRE WHEELED FITTINGS/PLUGS FOR HEAD. INSTALLED REAR CAM CAP WITH NEW O RING. INSTALLED REAR LIFTING BRACKET AND RETURN FUEL LINE. INSTALLED CYLINDER HEAD WITH NEW SPACER PLATE AND HEADGASKET. INSTALLED NEW SPRINGS AND PLUNGERS IN OIL FILTER HOUSINGS. INSTALLED OIL FILTER HOUSING, OIL COLER AND BONNETS. NOTICED

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

7-19

SERVICE

04-28-25

**Customer:** 

MASON DIXON CONTRACTORS LLC

MAKE / MODEL

PETERBILT / 379

**OPEN DATE / TIME** 

02-11-25 / 11:05AM

MEMO

4566

YEAR

2007

**DEL DATE** 

**DEL MILEAGE** 

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

VIN	LICENSE	MILEAGE	AUTH
1XP5DBEXX7D732522	AG57650	821211M	
ENGINE MODEL / SERIAL #	P.O. NUMBER	COMPLETE	UNIT/STOCK

TRANSMISSION MODEL/SERIAL #

/ SDP14943

ABS CABLE AND AIR LINE TO PASSENGER SIDE BRAKES WERE SMASHED (MOST LIKELY FROM ENGINE INSTALL). REPLACED BRAKE AIR LINE AND ABS HARNESS TO PASSENGER SIDE STEER. INSTALLED CAMSHAFT, THRUST ADAPTER AND PLATE. INSTALLED CAM GEAR AND INJECTORS. REMOVED AND REPLACED INJECTOR SOLENOID ON DAMAGED INJECTOR WITH GOOD USED SOLENOID. SET TIMING AND CAM GEAR BACK LASH. INSTALLED ROCKER ASSEMBLIES AND ENGINE BRAKES. ADJUSTED VALVES, INJECTORS AND ENGINE BRAKES. INSTALLED FUEL AND COOLANT CROSS OVER HARD LINES. RAN/REROUTED COOLANT LINES TO OIL COOLER HAD TO RE ROUTE DUE TO CONVERTING THE OIL COOLER TO THE OLDER STYLER COOLER AND BONNETS. REPINNED INJECTOR HARNESS TO MATCH ENGINE BRAKE SOLENOIDS. INSTALLED PEANUT COVER, VALVE COVER BASE AND VALVE COVERS WITH BREATHER PROVISION PRESENT. INSTALLED GOOD USED ENGINE HARNESS TO MATCHE ECM. INSTALLED ROAD DRAFT TUBE. TRANSFERRED FAN HUB STUDS FROM OLD ENGINE TO NEWER ENGINE. INSTALLED FAN HUB AND DAMPER. FOUND ENGINE ACCESSORY BRACKET WORN AND DAMAGED. INSTALLED A/C COMPRESSOR, ALTERNATOR, TENSIONERS AND PULLEYS AND BELTS. INSTALLED EXHAUST MANIFOLD HARDWARE, MANIFOLD AND TURBO. REPAIRED COOLANT MANIFOLD IN FRAME RAIL THAT HAD A BROKEN CLAMP. ROUTED EXHAUST PIPING, ADDED SPACERS UNDER 5" U BOLT STYLE CLAMP TO GET ELBOW AWAY FROM LEAF SPRING. REMOVED AND REPLACED CHARGE AIR COOLER (OLD COOLER HAD EXCESSIVE AMOUNT OF OIL AND DEBRIS FROM PREVIOUS TURBO FAILURE) INSTALLED RADIATOR, CAC AND INTAKE PIPING. FILLED WITH OIL AND COOLANT. REPLACED AIR, OIL AND FUEL FILTERS. STARTED AND RAN ENGINE, OK. CHECKED FOR LEAKS, OK. ATTEMPTED TO MOVE TRUCK AND FOUND CLUTCH WILL NOT DISENGAGE EVEN WITH PEDAL TO FLOOR. DROVE TRUCK BACK AND FORTH WITH CLUTCH DEPRESSED FULLY ATTEMPTING TO BREAK CLUTCH FREE WITH NO SUCCESS. AIR HAMMERED PRESSURE PLATE WITH CLUTCH PEDAL DEPRESSED AND GOT CLUTCH DISC TO BREAK FREE OF FLYWHEEL. CHECKED CLUTCH OPERATION WHILE DRIVING, CLUTCH SEEMS OK.

PLACED ON DYNO, STRAPPED DOWN AND CONNECTED ALL LEADS. CHECKED FUEL PRESSURE - FOUND 300 PSI AT IDLE. REMOVED FUEL RETURN CHECK VALVE -FOUND FULL OF OLD INJECTOR O-RING PIECES. FLUSHED OUT FUEL RETURN LINE/MANIFOLD. REMOVED AND REPLACED FUEL RETURN CHECK VALVE. CHECKED FUEL PRESSURE - 200 PSI AT IDLE. REMOVED SPRING KIT FROM FUEL TRANSFER PUMP - FOUND EXTRA HEAVY, NOT OEM SPRING INSTALLED INSIDE TRANSFER PUMP. INSTALLED CATERPILLAR HP SPRING KIT. CHECKED FUEL PRESSURE 95 PSI AT IDLE. CLEARED ALL CODES. WARMED UP ENGINE AND BROKE IN. ADJUSTED ECM FOR SAFE POWER LEVEL. MADE POWER RUNS. UPON RETURNING TO IDLE, CEL CAME ON. FOUND ACTIVE CODE FOR CAM/CRANK POSITIONS. REMOVED

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

Terms: Net payable upon receipt. Our finance charge is computed by a single periodic rate of 1 1/2% per month, or 18% annu	ual
percentage rate. Parts ordered on emergency basis are not returnable. Items received in satisfactory condition.	

CUSTOMER: X	DATE	



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

**Customer:** 

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date:

Tax ID:

		h dead	11051105	THE CASE	4117714
YEAR	MAKE / MODEL	VIN	LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522	AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #	P.O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943		04-28-25	7-19
DEL MILEAGE	A	MEMO	TRANSMISSION MO	DEL/SERIAL #	SERVICE WRITER
			1		GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	nn ST	BY HOURS	0.0

CAM SENSOR - INCORRECT PART NUMBER. REMOVED AND REPLACED CAM SENSOR WITH CORRECT ONE, WARMED UP ENGINE AND MADE POWER RUNS TIMING LIGHT CAME BACK ON. LOOSENED FAN HUB. REMOVED PEANUT COVER AND PINNED ENGINE. MEASURED CAM GEAR BACKLASH - .015". TIMING MARK STRAIGHT UP. REINSTALLED PEANUT COVER AND TIGHTENED FAN HUB. TRIED FLASHING IN MULTIPLE DIFFERENT TIMING CALIBRATIONS TO CUSTOMER SUPPLIED ECM -TIMING LIGHT STILL COMING ON AT OPERATING TEMP. LOOSENED FAN HUB AND REMOVED PEANUT COVER. PINNED ENGINE. REMOVED IDLER GEAR. MADE MULTIPLE ADJUSTMENTS TO TIMING GEAR BACKLASH UNTIL CAM GEAR WAS SLIGHTLY ADVANCED WITH .012" GEAR BACKLASH. CLEANED ALL HARDWARE, APPLIED LOCTITE AND TORQUED. REINSTALLED PEANUT COVER AND FAN HUB. CHECKED WIRING DIAGRAM AGAINST CURRENT JAKE WIRING AND VERIFIED CORRECT WIRING FOR LOW/MEDIUM/HIGH. CHECKED JAKE SWITCH INTERACTION - ALL OK. REINSTALLED VALVE COVERS AND ECM PLUG. CLEARED ALL CODES. WARMED UP ENGINE AND MADE POWER RUNS. RAN AT VARYING LOADS AND CONFIRMED CODE FOR TIMING SENSORS DOES NOT BECOME ACTIVE. REMOVED ALL LEADS, REMOVED FROM DYNO. ROAD TESTED - OK. CUSTOMER AWARE ECM HAS BAD ENGINE FAN OUTPUT CAUSING ENGINE FAN TO STAY ON CONSTANTLY. 556HP/1964TQ FLYWHEEL WITH ENGINE FAN ON. 123 DEGREES MAX INTAKE AIR TEMP (70 DEGREES AMBIENT), 33 PSI MAX BOOST, 102 PSI MIN FUEL PRESSURE AT 1250 RPM'S, 830 DEGREES MAX ON PYRO AT 1250 RPM'S.

TOTAL LABOR TOTAL PARTS		\$22,050.00 \$24,664.35
TOTAL SUBLET PARTS		\$623.51
TOTAL SUBLET LABOR		\$1,955.00
TOTAL FOR OPERATION	4	\$49,292.86

SH07C SH07C A3	6 3 1 1 1 1 1	80038100 80Lw038 ZEP 1R1808 1R0749 FS1000FLG 35010 36000 14969880000RMAN 1685248	BOLT 3/8X1 USS GR. 8 WASHER LOCK 3/8 PARTS CLEANER FILTER OIL FILTER FUEL CAT FILTER FUEL(10 MICRON) SET SS STUD(CAT) SPACER SET STAINLESS TURBO REMAN GASKET OIL PAN(C15)	\$3.24 \$0.96 \$25.83 \$46.51 \$29.18 \$22.95 \$240.00 \$220.00 \$1,200.00 \$343.25
AJ	i	ZEP	PARTS CLEANER	\$8.61

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

SERVICE

WRITER

**Customer:** 

MASON DIXON CONTRACTORS LLC

4566

YEAR

2007

**DEL DATE** 

**DEL MILEAGE** 

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

MAKE / MODEL

PETERBILT / 379

**OPEN DATE / TIME** 

02-11-25 / 11:05AM

MEMO

VIN	LICENSE	MILEAGE	HTUA
1XP5DBEXX7D732522	AG57650	821211M	
ENGINE MODEL / SERIAL #	P.O. NUMBER	COMPLETE	UNIT/STOCK
/ SDP14943		04-28-25	7-19

TRANSMISSION MODEL/SERIAL #

SHO2B WL6C WL6C B6I A3 A3 DOOR2	40 11 11 11 11 11 11 11 11 11 11 11 11 11	15W40-BULK GAT-G25230-0808 GAT-G25239-0808 85982 80N012 3/16-FW ZEP EB1 EB1 1018468 1304698 1317123 2341904 7481 B101 ZEP-45 0R9449 20R9847 2764637 4553839 4256526 606114 FIS5410 614421 2271204 614362 ZEP 700-99-307 51813PTX 5900196	OIL ROTELLA 15W40 BULK FITTING HYD FLAT FACE FITTING HYD FLAT FACE HOSE OIL AIR #8 PER FT.300DEG NUT 1/2 USS GR. 8 WASHER FENDER PARTS CLEANER DEGREASER ENGINE DEGREASER ENGINE BEARING SLEEVE BUSHING BEARING IDLER GEAR KIT FRONT STRUCTURE ROLOC CLEANING DISC CLEANER CARB/GUM CUTTER PENETRATING SPRAY PUMP OIL WATER PUMP(10R8660) NOZZLE PISTON COOLING VALVE COVER W/BREATHER HARNESS INJECTOR CAC PB20B/PET17703ED INSERT WATER CAT PLATE CAT HEAD C15 .338 GASKET SPACER PLATE SHIM LINER .03433071 PARTS CLEANER PAINT GLOSS BLACK SEALANT PAINT GLOSS BLACK SEALANT PAINT CAT YELLOW CAT PRIMER PAINT O'RING CLEANER CARB/GUM CUTTER COOLER OIL KIT OIL COOLER SEAL ELBOW TURBO DRAIN O'RING TURBO LINE O'RING OIL LINE BOLT 3/8X21/4 USS GR 8 WASHER FLAT 3/8 SAE GR. 8	\$220.00 \$19.04 \$27.18 \$15.99 \$0.92 \$0.07 \$8.61 \$7.72 \$60.60 \$56.46 \$55.62 \$665.17 \$3.94 \$20.83 \$836.96 \$959.99 \$850.98 \$217.49 \$308.12 \$1,100.00 \$122.88 \$452.26 \$100.55 \$130.99 \$8.61 \$13.21 \$22.89 \$47.16 \$35.60
	2	4589582	CAT PRIMER PAINT	\$35.60 \$21.87
	1	B101	CLEANER CARB/GUM CUTTER	\$5.94
WL6D	1	1330125CAT	COOLER OIL	\$636.77
DET	1	1891814	KIT OIL COOLER SEAL	\$2/4.56 \$120 01
PJT	1	6V5266	O'RING TURBO I INE	\$123.01
	ī	1142687	O'RING OIL LINE	\$6.72
	2	80038214	BOLT 3/8X21/4 USS GR 8	\$2.60
WALL	2	81FW038	WASHER FLAT 3/8 SAE GR. 8	\$0.52

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE	
CUSTOMER: X	DATE	_



**848 LANCASTER PIKE QUARRYVILLE, PA 17566** Tel.: (717) 284-3760

**SERVICE INVOICE NUMBER** SR3510

> **INVOICE DATE** 06-23-25

STBY HOURS

GNG\*GNG

0.0

**Customer:** 

MASON DIXON CONTRACTORS LLC

0.0

4566

**PO BOX 220** 

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

0.0

WILLOW STREET, PA 17584

717 517-8841

**ENGINE HOURS** 

Tax ID	Date: Tax ID:				
YEAR	MAKE / MODEL	VIN	LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522	AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #	P.O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943		04-28-25	7-19
DEL MILEAGE	M	EMO	TRANSMISSION MOD	EL/SERIAL #	SERVICE WRITER

**REEFER HOURS** 

	1	4N0699	GASKET	\$2.34
	2	07447	PAD SCOTCH-BRITE	\$3.58
	ī	7FP	PARTS CLEANER	\$8.08
	2	5089	RRAKE CLEAN	\$21.04
	4	2385080	OPTNG DRATH DLUG	\$28.80
	$\vec{1}$	15770	O'DING DIVIN FEOD	\$20.00 \$0.50
	1	T3//2	O KING MID	\$0.33
		ZEP 07447	PARIS CLEANER	\$0.00 ¢1.70
	1	0/44/	PAD SCOICH-RKITE	\$1.79 ¢10.20
	1 2 2 2 2	105	LUBRIPLATE ASSM LUBE	\$18.29
	2	7481	ROLOC CLEANING DISC	\$3.94
	2	7480	ROLOC CLEANING DISC	\$3.94
	2	ZEP	PARTS CLEANER	\$16.16
	2	5H15O4	WASHER HEAD BOLT	\$4.06
	1	51813PTX	SEALANT	\$22.89
	1	5H15O4	WASHER HEAD BOLT	\$2.03
в6А	1	1241855	BOLT HEAD(SHORT)	\$24.25
	1	5H15O4	WASHER HEAD BOLT	\$2.03
в6А	1 1 1 6	1241855	BOLT HEAD(SHORT)	\$24.25
_ 4	6	0313185	BOLT CAMSHAFT GEAR	\$163.38
	6	859191	BOLT INJECTOR (GRADE 9)	\$26.58
	ĭ	4589582	CAT PRIMER PAINT	\$17.80
	2	7FP	PARTS CLEANER	\$16.16
А3	2 1 2 2 2 1	1761363	RASE OTL ETLTER	\$369.55
A3	2	4N8150	SPRING RELIEF OIL	\$26.72
	2	3020208	DI HNGED DELTEE ATI	\$73.50
	5	2222700	OPTNC BLUC	\$23.30
	1	230300 <del>4</del>	DOLT 2/9V21/4 LICE CD 9	\$23.30
	1	00000014	DULI 3/0X31/4 USS UK. 0	\$0.30
DE0710 1	$ar{1} \\ 1$	171-0	PRACUET	\$4.30 ¢1 000 00
PE8719.1	Ţ	2390382	BRACKET	\$1,090.09 \$72.12
	1	K955341	SENSUK ABS	\$72.13
	1	HE598/	HUSE BRAKE 25(20-03425-022)	\$39.23
	12	9L8925	VALVE COVER BOLT B MODEL	\$3.84
	1	24200PTX	THREADLOCKER BLUE	\$7.96
	2	ZEP	PARTS CLEANER	\$16.16
	2	5900196	PAINT CAT YELLOW	\$47.16
	2 1 6	TA-29	SEALANT GREY RTV	\$8.56
	6	7E6508	CAP INJECTOR	\$75.24
	1	3824514	PAINT CUMMINS BLACK	\$29.16
	2	BRZ-9236	CLAMP SILICONE HOSE	\$3.26
	1	1262702	GASKET PAD SCOTCH-BRITE PARTS CLEANER BRAKE CLEAN ORING DRAIN PLUG O'RING HYD PARTS CLEANER PAD SCOTCH-BRITE LUBRIPLATE ASSM LUBE ROLOC CLEANING DISC ROLOC CLEANING DISC PARTS CLEANER WASHER HEAD BOLT SEALANT WASHER HEAD BOLT BOLT HEAD(SHORT) BOLT CAMSHAFT GEAR BOLT INJECTOR(GRADE 9) CAT PRIMER PAINT PARTS CLEANER BASE OIL FILTER SPRING RELIEF OIL PLUNGER RELIEF OIL ORING PLUG BOLT 3/8x31/4 USS GR. 8 FITTING 3/8 PIPE PLUG BRACKET SENSOR ABS HOSE BRAKE 25(26-03425-022) VALVE COVER BOLT B MODEL THREADLOCKER BLUE PARTS CLEANER PAINT CAT YELLOW SEALANT GREY RTV CAP INJECTOR PAINT CUMMINS BLACK CLAMP SILICONE HOSE GASKET TURBO LINE	\$14.54

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE



848 LANCASTER PIKE **QUARRYVILLE, PA 17566** Tel.: (717) 284-3760

**SERVICE INVOICE NUMBER** SR3510

> **INVOICE DATE** 06-23-25

Customer:

MASON DIXON CONTRACTORS LLC

4566

**PO BOX 220** 

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

YEAR	MAKE / MODEL	VIN		LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522		AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL	# P.	O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE	. Secondary	NEMO	TRA	NSMISSION MOD	EL/SERIAL#	SERVICE WRITER
				1	100 CUP - 100 -	GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	HOURS	0.0

PE8793.1 B6D	11112212221110311223511211124111122111111	1986068 4988280CUM 154295 AUV-3957 80038114 81FW038 2109246 80038114 80LW038 81FW038 1993212 1367226 2233505 WT15W 3669748 ZEP 1016596 GAT-G25180-0606 85981 5-030 SP5678 2644297 2385080 BRZ-9210 1375636 1946724 VL2443 1712-128 HE3755 5-032 6V5048 GAT-G25175-0606 GAT-G25180-0606 85981 5-030 10604 80038100 80LW038 80FW038 2769507	GASKET GASKET POWER STEERING GASKET TURBO MTG T6 PLUG CUP EXPANSION 3/4 BOLT 3/8x11/4 USS GR. 8 WASHER FLAT 3/8 SAE GR. 8 O'RING BOLT 3/8x11/4 USS GR. 8 WASHER LOCK 3/8 WASHER LOCK 3/8 WASHER FLAT 3/8 SAE GR. 8 LINE TURBO FEED O'RING GASKET AIR COMPRESSOR WIRE TIE 15 WIDE KIT IPR & IVA PIGTAIL PARTS CLEANER HOSE COMPRESSOR FITTING HYDRAULIC 90 HOSE OIL AIR #6 PER FT.300DEG LOOM 3/4 BY FT. GASKET V/CVR(6295774) SENSOR ORING DRAIN PLUG CLAMP SILICONE HOSE DRAIN TUBE SENSOR AIR INLET PRESSURE VALVE PETE WATER FITTING HOSE NIPPLE HOSE HTR 3/4 SIL(INCH) LOOM 1 BY FT. O'RING BOOST SENSOR FITTING HYDRAULIC	\$13.96 \$5.61 \$11.84 \$0.63 \$1.22 \$0.16 \$12.55 \$1.22 \$0.30 \$0.16 \$111.46 \$6.75 \$21.81 \$5.30 \$123.21 \$8.08 \$48.74 \$70.12 \$29.08 \$1.32 \$111.90 \$70.91 \$7.20 \$2.76 \$282.19 \$254.06 \$44.71 \$26.10 \$20.88 \$0.60 \$5.21 \$32.27 \$35.06 \$20.88 \$0.15 \$31.98
-----------------	---	--	--	---

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CUSTOMER: X	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

**Customer:** 

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

YEAR	MAKE / MODEL	VIN		LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522		AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL	#	P.O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE	Maria de la companya	IEMO	100000	TRANSMISSION MODI	EL/SERIAL#	SERVICE WRITER
			S-45-	- I		GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	HOURS	0.0

	2	RD7_0210	CLAMP STITCONE HOSE	\$2.76
	1	81058112	ROLT 5/8Y11/2 SAF GR 8	\$3.04
PE8800.1		2078128	TURE ROEATHED	\$52.88
r LOGOO. I	ī	80N038	NUT 3/8 USS GR 8	\$0.17
	10	60N030	WIDE TIE 15 WINE	\$5.30
	10	MITAM	WINE TIE 13 WIDE	\$1.10
	6	WIO	WIRE TIE 0	\$0.66
	2	WIO Dewe	MAKE ITE O	\$0.00 \$6.02
	6	U5W54	MOUNT ZIP IIE	\$0.02 \$0.66
	1	W10 K121020UD	MIKE ITE O	\$0.00 ¢102.00
	1	K121039HD	BELI	\$103.00
	1	KU6U5Z5HU	BELI	\$42.00 \$35.50
	2	XUU//85-515	CLAMP PREFORMED 3 STAINLESS	\$40.00 ¢150.70
	1	EPSOFF30111A	PIPE EXHAUST LOWER 90	\$T20./3
	1	P206607	CLAMP TURBO 5	\$57.34
	4	13-03096	ISOLATOR CAC	\$133.92
	2	TWT-20	WIRE TIE MOUNTABLE	\$9.70
	1 2 1	80014034	BOLT 1/4X3/4 USS GR. 8	\$0.22
	2	81FW014	WASHER FLAT 1/4 SAE GR. 8	\$0.14
		80LN014	NUT LOCK 1/4 USS GR. 8	\$0.10
	1	17589	CLAMP_INSULATED 2 X 3/8	\$3.09
	1	80516100	BOLT 5/16X1 USS GR. 8	\$0.40
	1	80FW516	WASHER FLAT 5/16 USS GR. 8	\$0.22
	1	81Fw516	WASHER FLAT 5/16 SAE GR. 8	\$0.06
	1	80LN516	NUT LOCK 5/16 USS GR. 8	\$0.14
	1	PB-13002	PIPE TURBO	\$183.07
	1	ZEP	PARTS CLEANER	\$8.08
	2	HE9622	HOSE CAC	\$72.02
	4	B9224-0406	CLAMP CAC HOSE	\$36.92
	1	J000232	CLAMP EXHAUST 5	\$16.05
	1	5900196	PAINT CAT YELLOW	\$23.58
	$ar{ extbf{1}}$	80FW516	WASHER FLAT 5/16 USS GR. 8	\$0.22
	1	80LN516	NUT LOCK 5/16 USS GR. 8	\$0.14
	$ar{ extbf{1}}$	10606	CLAMP INSULATED 1-1/4 X 3/8	\$2,63
	1	80516100	BOLT 5/16X1 USS GR. 8	\$0.40
	2	81FW516	WASHER FLAT 5/16 SAE GR. 8	\$0.12
	ī	80LN516	NUT LOCK 5/16 USS GR. 8	\$0.14
	12	FF50300ST	PTPF FXHAUST FLEX 5 BY TNCH	\$29.40
	1	x004484	CLAMP BAND 5 STATNLESS	\$21.21
	ī	TOM-5406-P-4	FITTING 1/4 PIPE PLUG STEEL	\$0.60
PE8803.1	ī	1063942	CLAMP SILICONE HOSE BOLT 5/8X11/2 SAE GR. 8 TUBE BREATHER NUT 3/8 USS GR. 8 WIRE TIE 15 WIDE WIRE TIE 8 WIRE TIE 8 MOUNT ZIP TIE WIRE TIE 8 BELT BELT CLAMP PREFORMED 5" STAINLESS PIPE EXHAUST LOWER 90 CLAMP TURBO 5 ISOLATOR CAC WIRE TIE MOUNTABLE BOLT 1/4x3/4 USS GR. 8 WASHER FLAT 1/4 SAE GR. 8 NUT LOCK 1/4 USS GR. 8 CLAMP INSULATED 2 X 3/8 BOLT 5/16X1 USS GR. 8 WASHER FLAT 5/16 USS GR. 8 WASHER FLAT 5/16 USS GR. 8 NUT LOCK 5/16 USS GR. 8 PIPE TURBO PARTS CLEANER HOSE CAC CLAMP CAC HOSE CLAMP EXHAUST 5 PAINT CAT YELLOW WASHER FLAT 5/16 USS GR. 8 NUT LOCK 5/16 USS GR. 8 PIPE EXHAUST FLEX 5 BY INCH CLAMP BAND 5 STAINLESS FITTING 1/4 PIPE PLUG STEEL BLOCK	\$156.13

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

energetch. V	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

**Customer:** 

MASON DIXON CONTRACTORS LLC

4566

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

MASON DIXON CONTRACTORS LLC

WILLOW STREET, PA 17584

717 517-8841

Tax ID Date: Tax ID:

Tax ID	Date. Tax ID.					
YEAR	MAKE / MODEL	VIN		LICENSE	MILEAGE	AUTH
2007	PETERBILT / 379	1XP5DBEXX7D732522		AG57650	821211M	
DEL DATE	OPEN DATE / TIME	ENGINE MODEL / SERIAL #		P.O. NUMBER	COMPLETE	UNIT/STOCK
	02-11-25 / 11:05AM	/ SDP14943			04-28-25	7-19
DEL MILEAGE		МЕМО		TRANSMISSION MODI	EL/SERIAL#	SERVICE WRITER
				1		GNG*GNG
ENGINE HOURS	0.0	REEFER HOURS	0.0	STBY	HOURS	• 0.0

221221211121122032111110623242241111124411	07-02552 05-09057 80LN038 CT-300-L-SS 10601 16-4206 P181186 ZEP 1090072 1090078 16-4208 F31-6063 16-4210 16-4212 TWT-20 WT15W R134A 5H7704 4150ATC 62032 90-N-038 7238-12 15W40-BULK 2431159 BRZ-9216 5-032 TWT-20 CT-350-L-SS BRZ-HTM700 D1029-8701 B9224-0406 TOM-5502-12 14-01661 62096 7481 BRZ-9216 HE5420 WT15W 15W40-BULK 2644297	BUSHING RADIATOR SUPPORT WASHER PETE MOTOR MOUNT NUT LOCK 3/8 USS GR. 8 CLAMP HOSE CONSTANT TORQUE CLAMP INSULATED 1/2 X 3/8 O'RING #6 GREEN FILTER AIR PARTS CLEANER O'RING OIL LINE O'RING OIL LINE O'RING OIL LINE A/C ORING #8 ACCUMULATOR O'RING #10 A/C O'RING #12 A/C WIRE TIE MOUNTABLE WIRE TIE 15 WIDE FREON O'RING AIR INTAKE SCHRADER VALVE CLAMP HOSE NUT 3/8 STAINLESS USS PLUG ORING OIL ROTELLA 15W40 BULK BOLT VALVE COVER CLAMP LOOM 1 BY FT. WIRE TIE MOUNTABLE CLAMP HOSE CONSTANT TORQUE CLAMP HOSE CAC CLAMP CAC HOSE FITTING STREET L 90 STEEL SHEILD HEAT 5 CLAMP HOSE ROLOC CLEANING DISC CLAMP HOSE HEATER 1 WIRE TIE 15 WIDE OIL ROTELLA 15W40 BULK SENSOR	\$28.22 \$25.92 \$0.22 \$16.24 \$3.26 \$0.40 \$298.12 \$0.76 \$133.11 \$0.76 \$133.11 \$0.70 \$5.30 \$84.78 \$34.18 \$6.85 \$0.73 \$7.32 \$20.00 \$2.84 \$1.80 \$32.88 \$1.80 \$32.88 \$235.92 \$43.35 \$1.54 \$1.97 \$2.84 \$31.97 \$2.84 \$31.97 \$2.84 \$31.97 \$2.84 \$31.97 \$2.84 \$31.97
--	---	---	---

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

CHOTOMES, V	DATE



848 LANCASTER PIKE QUARRYVILLE, PA 17566 Tel.: (717) 284-3760 SR3510

INVOICE DATE 06-23-25

MILEAGE

821211M

COMPLETE

04-28-25

AUTH

UNIT/STOCK

7-19 SERVICE

WRITER GNG\*GNG

**Customer:** 

MASON DIXON CONTRACTORS LLC

MAKE / MODEL
PETERBILT / 379

**OPEN DATE / TIME** 

02-11-25 / 11:05AM

MEMO

4566

YEAR

2007

**DEL DATE** 

**DEL MILEAGE** 

PO BOX 220

WILLOW STREET, PA 17584

Ship To:

VIN

1XP5DBEXX7D732522

**ENGINE MODEL / SERIAL #** 

/ SDP14943

MASON DIXON CONTRACTORS LLC

LICENSE

AG57650

P.O. NUMBER

TRANSMISSION MODEL/SERIAL #

717 517-8841

Tax ID Date: Tax ID:

WILLOW STREET, PA 17584

	ENGINE HOURS	0.0		REEFER H	OURS	0.0	STBY HOURS	0.0
		·			·			
	1	8L2786			O'RING	SENSOR		\$7.20
	1	1P0436			GASKET	PRIMING PUM	P	\$2.22
	1	2255222			VALVE :	SAFETY		\$26.06
	1	BRZ-9216			CLAMP			\$1.42
	1	2812725				CHECK (136722	7 ORING)	\$50.62
	1	1367227			O'RING			\$8.09
	1	3394983			KIT SP			\$103.57
	3	WT15			WIRE T	IE 15		\$0.90
B6E	1	2016617				CAM POSITIO		\$223.70
	1	2033940			O'RING	1945338 SEN	SOR	\$3.22
	1	05103			CLEANE	R CONTACT		\$18.99
	1 3	24200PTX			THREAD	LOCKER BLUE		\$7.96
		8т8737			PLUG			\$1.80
	2	WT8			WIRE T		_	\$0.22
	1	3561448B				LVER DECOMP		
	1	13253 <b>17</b> U				S ENG GOOD U		\$364.50
	14	EC3555BULK				EEZE ELC CAT		\$138.88
в5н	5	9Y3368				INER .032362	2	\$259.80
S586	1	SUBP			SUBLET			\$623.51
	_		SEALS,	SEATS,		GS, ORINGS		44 000 00
S586	1	SUBL		,	SUBLET			\$1,955.00
		CLEAN/TI	EST/SUR	FACE/RE	BUILD C	YL HEAD		

5 DURING REPAIRS FOUND PASSENGER STEER TIRE FLAT. REMOVED PASSENGER STEER TIRE/WHEEL AND SENT OUT TO HAVE REPAIRED. REINSTALLED AFTER REPAIRS.

TOTAL SUBLET LABOR

\$64.40

TOTAL FOR OPERATION 5

\$64.40

S594 1 SUBL SUBLET LABOR \$6.90
TIRE STEM
S594 1 SUBL SUBLET LABOR \$57.50
REPAIR FLAT TIRE

6 DURING REPAIRS FOUND CARRIER BEARING RUBBER OUT OF PLACE.
WHILE RUNNING ON DYNO, SMELLED SMOKE AND FOUND CARRIER BEARING SMOKING
EXCESSIVELY. REMOVED FRONT DRIVESHAFT ASSEMBLY. HEATED, BEAT AND
PULLED FROZEN YOKE OFF DRIVESHAFT. CUT OFF OLD CARRIER BEARING.
CLEANED DRIVESHAFT AND YOKE. R&R CARRIER BEARING. REINSTALLED YOKE

A 3% SURCHARGE WILL BE APPLIED IF PAYING BY CREDIT CARD.

		DATE	
CUSTOMER: X		DAIE	

# Horsepower Run Report

Susquehanna Trur 848 Lancaster Quarryville PA

Dynamometer Expense THAT MEASURES UP WWW. Laybordyno. Com

MDX

Customer Address: Customer City /State/Zip: Customer Phone: Customer Mobile Phone

Customer Contact:

aylor	Dynamometer	EXPERIENCE THAT MEASURES UP
<u> </u>		EXPER

(717) 284-3760	EXPERIENC
2500	
2000	
nde 1500	
bilgmA 007 009	6

Bynamometer Dynamometer EXPERIENCE THAT MEASURES UP	
ruck Service ster Pike 17566 1-3760	

-- Est\_Flywheel\_HP (HP)
-- Est\_Flywheel\_Trq (LBS-FT)

Dyno Operator:		
Vehicle Cerial Mumber	720600	
Vellice Serial Manifest.	13535	
Vehicle Make:	PETERBILT	
Vehicle Model:	389	
Vehicle Plate Number:	AG57850	
Mileage:	821211	
Year	2007	
Color	RED	
Other Vehicle Info		

1250.00 1291.25 1340.50 37.66£1 1453.50 1505.00 1220.75 1587.25 1611.75 1639.25 1672.25 1704.00 1728.75 1754.25 1805.00

1826.00

1826.00 27.3881 1912,75 1939.50 1965.25 2000.00 2027.50 2078.00 2109.75

210012 2100.75 2120.50

200

SDP14943 CAT C15

Engine ID No: Engine Make Engine Model Other Engine info: W.O. No.

SR3510

Pre Test Comments

Post Test Comments:

1		0.0	A CONTRACTOR		- 10 March 201 M	The second secon	The same of the same of	STREET, SQUARE, SALES	STATE OF THE PERSON NAMED IN	CHARLES AND ADDRESS OF	THE PARTY AND THE
٥	(x1)	(×1)	(x1)	(x1)	(x1)	(x1)	(x1)	(x1)	(x1)	(x1)	
								School of the last	The same of the same of		The Part of the last
=	(man)	(HP)	(HP)	(LBS-FT)	(Deg F.)	(Deg F.)	(isd)	(PSI)	(6)	(Deg F)	
gir	Engine_Speed	C_VPwr	Est_Flywheel_HP	Est	e_Eng_Coolant_T emp	e_int_Mfld_Temp	e_Boost_Press	Boost_PSI	Fuel_Press (PSI	Exh_Temp_Post_T urbo	
10	120.50	18	20	48	183.0	102.0	80	80	122	527.4	
2	120.50	18	20	48	183.0	102.0	œ	00	120	525.5	
~	118.50	18	20	90	183.0	102.0	00	œ	120	525.6	
ı	115.00	22	24	9	183.0	100.0	00	თ	120	523.5	
N	109.75	32	¥	82	183.0	100.0	ത	Ø	120	523.4	
2	100.75	45	20	125	183.0	100.0	o	9	121	523.5	
N	102.50	89	72	180	183.0	100.0	ത	1	119	523.6	
N	113.25	91	86	243	183.0	100.0	7	12	118	523.6	
•	106.00	113	124	310	183.0	100.0	13	13	119	525.5	
1 (	104.25	143	157	392	183.0	100.0	14	15	120	527.5	
	100.75	171	189	474	183.0	100.0	16	17	118	529.5	
ı	2097.25	204	227	568	183.0	100.0	16	18	121	534.9	
1 0	00 660	242	266	667	183.0	100.0	18	21	118	539.3	
2	106.00	285	317	790	183.0	100,0	21	22	118	543,1	
Ň	106.00	320	357	889	183.0	100.0	23	24	120	547.3	

(x1)	(Ded F)	EX	553.2	557.2	0000	S C S C S C S C S C S C S C S C S C S C	586.8	594.6	600.8	614 5	618.4	620.5	624.5	630.3	632.3	634.3	636.3 638.3	640.4	644.1	646.1	650.1	652.1	654.0	657.8	6619 9	664.0	665.8	669.9	673.9	675.9	677.8	677.9	681.7	683.7	685.7	685.6	7.689	689.7	691.6	691.6	693.6	0.000	695.5	695.5	697.6	92.6
(x1)	(6)	Fuel Press (PSI	116	116	811	117	117	118	116	4 7 1 4	114	116	113	115	115	116	113	115	112	41.	111	116	111	112	117	113	115	4 4	114	113	115	111	109	110	115		1 -	112	113	112	109	4 6	90	108	109	110
(x1)	(PSI)	Boost PSI	26	27	7 2	28 62	28	28	8 8	% 68 80 88	8 2	29	3 33	7 Z	29	29	F 60	28	29	စ္က ဇ	9 8	30	30	9 30	5 m	31	31	5 3	, <sub>(v)</sub>	31	31	33	9 6	32	32	3 22	32 8	32	32	35	3 52	3 6	35 85	32	32	33
(x1)	(isd)	e_Boost_Press	25	28	8 8	27	27	27	78 78	7 K	7 Kg	28	28 38	28 28	28	29	50 50	29	29	3 5	7 8 7 8	38	30	o 9	2 6	8	30	9 90	8 8	30	31	3 3		31	ક સ		3 6	34	32	32	. c	300	32	32	32	32
(x 1)	(Deg F.)	e Int Mfld Temp	102.0	102.0	102.0	104.0	105.0	105.0	107.0	107.0	109.0	109.0	109.0	111.0	111.0	113.0	113.0	113.0	113.0	113.0	113.0	114.0	114.0	114.0	114.0	116.0	116.0	116.0	116.0	116.0	116.0	118.0	118.0	118.0	118.0	118.0	118.0	118.0	118.0	120.0	120.0	120.0	120.0	120.0	120.0	120.0
(x1)	(Deg F.)	e_Eng_Coolant_T	183.0	183.0	183.0	185.0	185.0	185.0	185.0	186.0	186.0	186.0	186.0	186.0	186.0	188.0	188.0	188.0	188.0	188.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190.0	190,0	190.0	192.0
(x1)	(LBS-FT)	Est_Flywheel_Trq	991	1073	113/	1222	1239	1260	1271	1280	1296	1295	1302	1327	1339	1346	1360	1364	1367	1377	1402	1399	1403	1412	1411	1446	1448	1453	1470	1476	1485	1493	1513	1517	1522	152/	1532	1547	1555	1562	1558	1503	1585	1600	1605	1612
(x1)	(HP)	Est_Flywheel_HP	398	429	404	486	490	497	497	489	200	200	501	506	510	510	512 513	512	512	514	519	517	518	520	524 524	528	527	528	532	533	534	534	537	538	538	538 538	537	540	541	542	540 543	242	545 545	543	543	543
(x 1)	(HP)	C_VPwr	358	386	/04 204	435	439	443	445	445	446	444	448	453	454	457	4 4 5 8 8 5 8	459	459	459	4 6 6 8	462	465	465	4 4 0 6 0 8	470	471	471	474	476	477	478	479	480	479	24. 4 E 04.	480	483	481	484	45 4	484	487	486	486	484
(x 1)	(mdu)	Engine_Speed	2109.75	2099,00	07 /807	2088.50	2078.00	2069.50	2055.75	2034.00	2027.50	2025.75	2021.00	2003.25	2000.00	1990.50	1992.00	1973.00	1965.25	1962.25	1942.50	1941.00	1939.50	1932.00	1921.50	1917.00	1912.75	1909,75	1899.75	1896,75	1886,75	1879.75	1865.50	1862.75	1856.00	1845,00	1839.50	1831.50	1826.00	1820,75	1820.75	1801.00	1805.00	1784,50	1778,00	1770.50
Abs	/erage	Ā	16 16	17	p 6	20	21	22	23	25.55	2 2	27	28	3 00	31	32	34	35	36	37	36	4	41	2 5	3 4	45	46 i	747	0 4	50	51	52	54	55	20	, ic	200	90	61	22	200	+ 14 2 C	99	67	68	69

⋝
Ω.,
용
0
23
8
S
28
4

		Ŋ	]																																															
(x1)	(Deg F)	Exh_Temp_Post_T	6888	9.669	701.5	c.ru/	/03.5	703.5	02.0	707.5	5,007	709.3	711.5	712.2	713.4	713.4	715.3	4.017	717.4	710.2	719.3	721.3	721.3	721.3	723.3	725.2	725.3	727.2	727.5	729.2	731.2	731.2	733.2	733.3	735.2	737.1	730.1	739.1	741.1	743.0	743.1	745.0	747	750.7	753.0	755.0	756.9	759.0	760.9	766.8
(x 1)	(B)	Fuel_Press (PSt	111	113	108	901	112	110	112	108	101	10,	107	106	109	109	106	110	9 6	1 2		105	109	108	107	108	110	108	109	109	105	106	90	108	107	105	10.	106	104	105	105	105	103	105	104	104	104	104	104	104
(x 1)	(PSI)	Boost_PSI	33	33	33	88	සි	8	88	e e		3 8	3 8	3 8	33	33	33	e 6	3 8	3 6	3 8	3 8	33	33	33	, ,	3 8	88	3 8	33	33	88	9 C	8 8	33	88	n c	32 83	32	32	32			- ce	30	30	29	29	29	28
(x1)	(isd)	e_Boost_Press	32	32	32	32	32	32	32	32	2 6	3 6	32	32	32	32	32	32	32	3 6	32	32	32	32	32	2 23	32	3 6	32	32	32	32	3 8	3 8	32	32	32	32 53	32	32	34	<u>8</u>	3 3	30.	8 8	59	29	29	28	28
(x1)	(Deg F.)	e_Int_Mfld_Temp	120.0	120.0	120.0	120.0	120.0	120.0	120.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	122.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123.0	123 0	123.0	123 0	123.0	123.0	123.0	123.0	123.0
(x1)	(Deg F.)	e_Eng_Coolant_T	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	182.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0	192.0
(x1)	(LBS-FT)	Est_Flywheel_Trq	1615	1621	1620	1627	1640	1649	1652	1657	1672	1685	1690	1698	1710	1715	1722	1727	1733	1/44	1751	1767	1777	1795	1790	1801	1809	1014	1824	1839	1839	1857	1863	1868	1876	1885	1882	1090	1917	1912	1922	1913	1939	1943	1939	1946	1943	1944	1949	1938
(x1)	(HP)	Est_Flywheel_HP	542	542	540	541	544	545	544	545	547	548	549	24 c	549	551	551	220	550	220	295	552	554	556	554	2021	222	200	255 556	220	556	556	554	554	554	553	553	550 551	549	548	546	541	541	80 46 60 46	220	527	522	518	516	508
(x1)	(HP)	C_VPwr	484	484	483	482	483	487	487	488	487	490	488 88 80 80 80	490 490	4 4 00 00	482	491	491	491	493	492	404	496	494	496	495	496	480	490	497	495	496	496	490	494	495	484	492	489	487	486	483	482	480	47.5	471	466	461	459	454
(x1)	(mar)	Engine_Speed	1763 00	1754 25	1750.75	1745.75	1741.00	1736.00	1728.75	1727.75	1719.25	1707.50	1705.25	1704.00	1686.75	1688.00	1682.25	1672.25	1666.50	1655.50	1655.50	1630.25	1637 25	1627.50	1626.50	1617.00	1611,75	1602.50	1604.50	1588 25	1587.25	1571.25	1560.50	1558.50	1550.75	1541.25	1542.25	1524.25	1505.00	1504.25	1492.50	1486.25	1466.25	1453.50	1449.25	1423.75	1411.50	1399.75	1390.25	1377.25
Abs	Average	Channel	Name 70	2.5	72	73	74	75	9/	77	78	4	& &		2 68	8 8	82	98	87	89	60	S 5	- 6	93	95	92	98	60 0	xx	5	5 5	102	103	104 205	106	107	108	9	2 -	112	113	114	115	116	17.	5 5	120	121	122	123

	(x1)		(Deg F)	Exh_Temp_Post_T	768.8	772.7	774.7	778.6	782.8	788.5	792.5	798.4	802.3	806.3	815.2	820.1	826.1	830.1
	(x1)	THE RESERVE OF THE PERSON NAMED IN	((b)	Fuel_Press (PSI	103	103	103	103	102	103	102	102	102	102	102	102	102	102
	(x 1)		(PSI)	Boost PSI	28	27	27	27	56	58	25	25	25	25	24	24	24	23
	(x1)		(bsi)	e_Boost_Press	28	27	56	26	56	56	25	22	24	24	24	24	23	23
	(x1)		(Deg F.)	e_Int_Mfld_Temp	123.0	123.0	122.0	122.0	122.0	122.0	122.0	122.0	120.0	120.0	120.0	120.0	120.0	120.0
The state of the s	(x1)		(Deg F.)	e_Eng_Coolant_T	192.0	192.0	192.0	192.0	194.0	194.0	192.0	194.0	194.0	194.0	194.0	194.0	194.0	194.0
	(x1)		(LBS-FT)	Est_Flywheel_Trq	1940	1941	1947	1937	1930	1944	1947	1955	1949	1964	1963	1963	1958	1958
	(x1)		(HP)	H H	505	501	497	493	486	485	484	481	478	476	473	469	466	466
	(x1)		(HP)	C_VPwr	451	446	442	439	436	434	430	429	426	424	421	419	417	415
	(x 1)		(mdu)	Engine_Speed	1366.75	1356.50	1340.50	1336.75	1323.50	1309.50	1304.75	1291.25	1289.25	1272.75	1264.50	1255.50	1250.00	1249.25
Abs	Scale	Average	Units	Channel	124	125	126	127	128	129	130	131	132	133	<u>\$</u>	135	136	137