

Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420

Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 Weyburn 306-842-2629

www.youngs.ca

Ship To:



		WITIG	CI IOI SC		300 224 2110
Branch					
REGINA		*REPRINT*			
Date	Time				Page
10/24/24	22:	00:13	(B)		01
Account #	Phone #			Inv #	#
Ship Via		Purchase Order #			
Tax ID #					
		Salesperson			
		S35			
			•		

SERVICE INVOICE

STK#/FLEET#

HRS PIN/EIN WARRANTY DATE

HRS

002724

COMBINE 1680

3829 018084

SEGMENT# 1 C 14019 NA REPLACE SIEVE BUSHINGS 10/09/24 10/10/24

CORRECTION:

- Disassembled shaker drive and removed pit-man arms. Found bearings were bad in both pit-man arms. Replaced bearings and bushings. Also replaced bushings on the front shoe drive arms. Had to remove top sieve and bow ties in order to perform job. Reassembled everything and checked operation.

Everything works as it should.

186597C1	BUSHING	4	39.53	158.12
193132C91	BEARING	2	395.32	790.64
			PARTS	948.76
			LABOR	1790.00
11008001		SEGMENT	TOTAL==>	2738.76

SEGMENT# 2 C 14019 NA

10/09/24 10/10/24

CHANGE ROTOR GEAR CASE OIL

CORRECTION:

- Dismounted dip stick tube and laid it down. Drained oil from gearbox. Also, jacked up right side of combine to help drain oil. Lowered combine and filled gearbox with new oil. Checked oil level after awhile so that the oil could settle in the gearbox.

EHCOIL EHC CHARGE .05 .20 77400001US ULTRACTION BULK 5.92 23.68 23.88 PARTS LABOR 179.00 11008001 202.88 SEGMENT TOTAL ==>

CONTINUED ON PAGE 02

Leading The Way In A Thriving Agricultural Community!

Received By

Thank You! We Appreciate Your Business

I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collisions, fie, thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc.

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s

employees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment the reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Stimates are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs performed on equipment that has been modified.



Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7 Phone: 306-565-2405 • Fax: 306-565-2420

Assiniboia 306-642-5991 Chamberlain 306-638-4516 Davidson 306-567-3074 Moose Jaw 306-694-1800 Raymore 306-746-2288 Watrous 306-946-3387 306-842-2629 Weyburn Windthorst 306-224-2110

www.youngs.ca

Ship To:

Invoice To:	

Branch					
REGINA					
Date	Time				Page
10/24/24	22:	00:13	(B)		02
Account #	Phone #			Inv #	ŧ
Ship Via	Purchase Order #				
Tax ID #					
		Sale	Salesperson		
				S35	

SERVICE INVOICE

STK#/FLEET#

002724

COMBINE

HRS PIN/EIN 3829 018084

WARRANTY DATE

HRS

1680

SEGMENT# 3 C 14019 NA

10/09/24 10/10/24

FIND OUT WHAT IS SLIPPING WHEN ENGAGING SEPARATOR **CORRECTION:**

-Installed hyd gauge to check PTO circuit. Ran combine and found the PTO pressure was low. (180 psi). Adjusted PTO pressure to spec. at 235 psi. After information was given from customer, started to diagnosed the issue. Found the torque sensing unit wasn't operating as it should. Disassembled torque sensing unit and noticed the spring was below free length measurement. Also found the cams and bushings were bad. Ordered parts needed for repair. Cleaned all parts while waiting for new parts to show up. Reassembled torque sensing unit and installed a new rotor belt, upon customers request. Hung up original rotor belt for future use. Adjusted and aligned rotor belt. Adjusted limit switches, while running the combine. Checked operation of the rotor speed switch. Everything worked as they should. Returned combine back to service

chey bhoara. Recarnea	combine back to betvice.			
в94621	TORQUE/BEAR/KIT	1 N	366.77	366.77
110844A2	SPRING 500	1	189.15	189.15
244422A4	BELT	1	574.44	574.44
			PARTS	1130.36
			LABOR	2148.00
11008001		SEGMENT	TOTAL==>	3278.36

SEGMENT# 4 C 14019 OC

10/09/24 10/10/24

Young's Complimentary QuickCheck Inspection

***** WORK ORDER TOTALS *****

Received By

anCONTINUED ON PAGE 03 I hereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and SONTH, TANUED the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of Testing, diagnosing, inspecting, repairing, and/or delivering at my risk. Young's Equipment Inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, fig., thet, or any other cause, except where such loss and/or damage is the to negligence on the part of Young's Equipment Inc. Young's Equipment Inc. Soung's Equipment Inc. Soung'

Young's Equipment Inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s emptoyees at own risk.

An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum), Young's Equipment her reserves the right, at its sole discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.

Standars are for the items specifically identified in the estimate only, and are non-binding.

Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs per formed on equipment that has been modified.

Leading The Way In A Thriving Agricultural Community!





Box 3117 • Highway #1 East North Service Road Regina, SK S4P 3G7

Phone: 306-565-2405 • Fax: 306-565-2420 www.youngs.ca

Assiniboia 306-642-5991 Chamberlain 306-638-4516 306-567-3074 Davidson Moose Jaw 306-694-1800 306-746-2288 Raymore Watrous 306-946-3387 Weyburn 306-842-2629

Ship To:

Invoice To:

	****	idti ioi st		300-224-2110		
Time				Page		
22:	00:13	(B)		03		
Phone #			In∨ ₹	#		
Ship Via			Purchase Order #			
			Salesperson			
			S35			
	22:	Time 22:00:13 Phone #	22:00:13 (B) Phone # Purchase Order Sale:	Time 22:00:13 (B) Phone # Inv #		

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

002724 3829 COMBINE 018084

1680

PARTS 2103.00 LABOR 4117.00 shop supplies 300.00 6520.00 SUB TOTAL ==> GST 5% 326.01 6846.01 TOTAL CREDIT CARD

00567Z

• Thereby authorize the above repair work to be completed, including any necessary materials, labour, and/or other charges as may be applicable. Young's Equipment Inc., its employees, and assigns may operate the above-noted vehicle, as well as other equipment that may be necessary to operate said vehicle, for the purposes of testing, diagnosing, inspecting, repairing, and/or delivering at mry risk. Young's Equipment inc. is not responsible for any loss of and/or damage to the equipment, or its contents, whether due to collision, lire, theft, or any other cause, except where such loss and/or damage is due to negligence on the part of Young's Equipment inc. is hereby released from any and all claims follows and/or anage not caused by the negligence of Young's Equipment inc. is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptable to that customer is in place at all times while Young's Equipment inc. is working on, and/or in possession of the above-noted equipment.

• It is the customer's responsibility to ensure that a level of insurance, including physical damage insurance, that is acceptance to mat customer is in piace at an universement countries.
• Young's Engineent inc. does not assume any responsibility whatsoever for equipment left for repairs, storage, or other purposes, nor for articles left in vehicles. Vehicles driven by Young's Equipment Inc.'s employees at own risk.
• An express mechanic's Lien is acknowledged on the above-noted equipment to secure the amount of repairs thereto. Terms are cash on receipt of invoice. Interest will be charged at the rate of 2% per month (24% per annum). Young's Equipment her reserves the right, at it is ode discretion, to refuse the release and/or delivery of equipment until such a point as invoices have been paid.
• Stianates are for the items specifically identified in the estimate only, and are non-bindings.
• Young's Equipment Inc. and any other manufacturers do not provide warranty, neither expressed nor implied, on any repairs in the comment of the provide on equipment that has been modified.

Received By

