



Bobcat[®]
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 01 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS |
|------------------------------|------------------------------|------|-----------|---------------|-----|
| P109434 | S66 C68 SJC | 5805 | B4SA22479 | | |
| | S66 T4 | 2 | | | |
| ***** UNIT DESCRIPTION ***** | | | | | |
| * M0347 | S66 C68 SJC | | | | * |
| * M0347-P07-C68 | C68 Comfort Package | | | | * |
| * M0347-R01-C04 | Selectable Joystick Controls | | | | * |
| * 99695180-63001 | FREIGHT-SSL | | | | * |
| * 9974751 | Document Fee | | | | * |
| ***** | | | | | |

| | | | | |
|--|-------------------|---|-------|--------|
| SEGMENT# 1 5 3293 NA | 11/20/25 12/17/25 | | | |
| INSPECT AND QUOTE | | | | |
| INSPECTION FOR REPAIR BEFORE RETURNING TO LEASING COMPANY. | | | | |
| : jtiemeyer@mamgt.com; ashleyd2@illinois.edu | | | | |
| FRTO | FREIGHT | 5 | 25.65 | 128.25 |
| | | | PARTS | 128.25 |
| | | | LABOR | 465.00 |
| 10722020 | SEGMENT TOTAL==> | | | 593.25 |

| | | | | |
|-----------------------|-------------------|--|------|--|
| SEGMENT# 2 5 3293 N/A | 11/20/25 12/17/25 | | | |
| SERVICE | | | 6.00 | |

COMPLAINT:

DUE FOR SERVICE

CORRECTION:

1. changed inline fuel filter, and main fuel filter
2. changed all three hyd filters
3. changed the inner and outer air filters
4. greased machine
5. changed the engine oil, and filter
6. put new hyd oil in the machine
7. topped off all fluids

CONTINUED ON PAGE 02

X

Authorized By



Bobcat
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 02 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS |
|--------------------------------|-----------------|------|------------------|---------------|---------|
| P109434 | S66 C68 SJC | 5805 | B4SA22479 | | |
| | S66 T4 | 2 | | | |
| <u>ADDITIONAL DESCRIPTION:</u> | | | | | |
| ANNUAL SERVICE | | | | | |
| 46825328 | FUEL FILTER | 1 | | 122.26 | 122.26 |
| 46923666 | ELEMENT FILTER | 1 | | 59.42 | 59.42 |
| 6687884 | GREASE, H | 2 | | 8.15 | 16.30 |
| 7334208 | ELEMENT FILTER | 1 | | 50.34 | 50.34 |
| 7343102 | FILTER OIL ENGI | 1 | | 41.68 | 41.68 |
| 7348032 | FILTER FUEL IN- | 1 | | 53.79 | 53.79 |
| 7354877 | OIL 10W30 2.5 G | | RETAIL | 84.53 | |
| | | 1 | | 60.38 | 60.38 |
| 7386224 | FILTER AIR INNE | 1 | | 29.08 | 29.08 |
| 7386225 | FILTER AIR OUTE | 1 | | 43.96 | 43.96 |
| 7414582 | KIT FILTER SERV | 1 | | 95.94 | 95.94 |
| 7486193 | FLUID HYD VG68 | 2 | | 89.94 | 179.88 |
| 7496373 | CAP CANISTER HY | 1 | | 79.18 | 79.18 |
| | | | | PARTS | 832.21 |
| | | | | LABOR | 930.00 |
| 10722020 | | | SEGMENT TOTAL==> | | 1762.21 |

SEGMENT# 3 5 3293 N/A 11/20/25 12/17/25
LIFT/TILT CYLINDER REPLACEMENT 16.00 16.00

COMPLAINT:

LIFT AND TILT CYLINDERS WORN BEYOND REPAIR

CORRECTION:

1. raised the arms of the machine
2. removed the hoses from the lift cylinders
3. removed the pins from the machine
4. removed the lift cylinders
5. drove the bushings out
6. installed new bushings and pins in the lift arms

CONTINUED ON PAGE 03

X

Authorized By



Bobcat
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 03 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS |
|-------------|-------------|------|-----------|---------------|-----|
| P109434 | S66 C68 SJC | 5805 | B4SA22479 | | |
| | S66 T4 | 2 | | | |

7. removed the hoses for the tilt cylinders
8. removed the pins from the tilt cylinders
9. removed the tilt cylinders
10. drove the old bushings out.
11. installed new bushings in the bob tach plate
12. installed new cylinders with new pins
13. installed new grease fittings on all the new pins on the machine, and greased

ADDITIONAL DESCRIPTION:

TILT AND LIFT CYLINDER REPLACEMENT
PIVOT PIN REPLACEMENT

| | | | | | |
|----------|----------------|---|---|---------|---------|
| 27CM1030 | BOLT | 4 | N | 5.20 | 20.80 |
| 28CM1025 | BOLT | 2 | N | 3.92 | 7.84 |
| 29CM1025 | BOLT | 4 | N | 2.84 | 11.36 |
| 43DM10 | NUT | 2 | N | 2.63 | 5.26 |
| 46933664 | PIN PIVOT | 1 | N | 81.95 | 81.95 |
| 51DM10 | NUT | 4 | | 3.87 | 15.48 |
| 6534111 | WASHER, 5 | 2 | | 3.26 | 6.52 |
| 6534154 | RING, RETAINER | 2 | | 10.30 | 20.60 |
| 7JM55 | RING SNAP | 2 | N | 9.79 | 19.58 |
| 7155413 | NUT | 4 | N | 9.16 | 36.64 |
| 7313815 | SPACER TUBE | 2 | | 21.84 | 43.68 |
| 7313935 | LINK ASSEMBLY | 1 | | 2014.48 | 2014.48 |
| 7317861 | PIN PIVOT | 2 | | 91.70 | 183.40 |
| 7353010 | BUSHING WEAR | 2 | N | 88.38 | 176.76 |
| 7353011 | BUSHING WEAR | 4 | | 65.87 | 263.48 |
| 7353148 | PIN PIVOT | 2 | N | 94.43 | 188.86 |
| 7377353 | BUSHING WEAR | 2 | | 57.27 | 114.54 |
| 7377355 | PIN PIVOT | 2 | N | 62.50 | 125.00 |
| 7377357 | PIN PIVOT | 2 | | 110.23 | 220.46 |

CONTINUED ON PAGE 04

X

Authorized By



Bobcat
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 04 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS | |
|-------------|-----------------|------|-----------|---------------|------------------|----------|
| P109434 | S66 C68 SJC | 5805 | B4SA22479 | | | |
| | S66 T4 | 2 | | | | |
| 7395895 | PIN PIVOT | | | 2 | 117.47 | 234.94 |
| 7395897 | BUSHING WEAR | | | 4 | 67.41 | 269.64 |
| 7408178 | LINK CONNECTING | | | 2 | 453.17 | 906.34 |
| 7408181 | PIN PIVOT | | | 2 | 51.81 | 103.62 |
| 7408504 | CYLINDER HYDRAU | | | 2 N | 1096.41 | 2192.82 |
| 7419195 | PIN PIVOT | | | 2 | 113.17 | 226.34 |
| 7445852 | PLATE STOP | | | 2 N | 39.24 | 78.48 |
| 7478408 | HOSE HYDRAULIC | | | 2 | 68.28 | 136.56 |
| 7498476 | CYLINDER HYDRAU | | | 2 M | 869.26 | 1738.52 |
| | | | | | PARTS | 9443.95 |
| | | | | | LABOR | 2480.00 |
| 10722020 | | | | | SEGMENT TOTAL==> | 11923.95 |

| SEGMENT# | 4 | 5 | 3293 | N/A | 11/20/25 | 12/17/25 | | | |
|--|---|---|------|-----|-----------------|----------|------|-------|-------|
| | | | | | | | 7.50 | 7.50 | |
| <u>COMPLAINT:</u> | | | | | | | | | |
| DOOR HINGES ARE WORN BEYOND REPAIR | | | | | | | | | |
| CAB HOLD DOWNS ARE BROKEN/MISSING | | | | | | | | | |
| <u>CORRECTION:</u> | | | | | | | | | |
| 1. removed the old cab hold down assemblies | | | | | | | | | |
| 2. cleaned the holes up | | | | | | | | | |
| 3. installed new cab hold down assemblies | | | | | | | | | |
| 4. removed the front door and installed new hinges on the door | | | | | | | | | |
| 5. removed the old hinge brackets, and installed new ones | | | | | | | | | |
| <u>ADDITIONAL DESCRIPTION:</u> | | | | | | | | | |
| DOOR HINGES AND CAB HOLD DOWN BOLTS NEED REPLACED | | | | | | | | | |
| 39DM12 | | | | | NUT | | 2 | 1.27 | 2.54 |
| 7286606 | | | | | ISOLATOR VIBRAT | | 2 | 35.56 | 71.12 |
| 7286607 | | | | | ISOLATOR VIBRAT | | 2 | 35.48 | 70.96 |

CONTINUED ON PAGE 05

X

Authorized By



Bobcat
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|----------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 05 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS |
|-------------|-----------------------|------|-----------|------------------|---------|
| P109434 | S66 C68 SJC S66 T4 | 5805 | B4SA22479 | | |
| 7314020 | WASHER FLAT | 2 | | 4.90 | 9.80 |
| 7363745 | WASHER CAB MOUN | 2 | | 36.74 | 73.48 |
| 7412593 | WASHER CAB MOUN | 2 | | 12.28 | 24.56 |
| 7414109 | SPRING GAS | 1 | | 82.73 | 82.73 |
| 7431261 | SCREW HEX HD 10 | 2 | | 5.22 | 10.44 |
| 7436274 | HINGE ASSEMBLY | 2 | | 18.30 | 36.60 |
| | | | | PARTS | 382.23 |
| | | | | LABOR | 1162.50 |
| 10722020 | | | | SEGMENT TOTAL==> | 1544.73 |

| SEGMENT# | | | | | |
|---|-----------------|----------|----------|-------|--------|
| 5 5 3293 NA | | 11/20/25 | 12/17/25 | | |
| REAR DOOR LATCH | | | | 3.00 | 3.00 |
| <u>CORRECTION:</u> | | | | | |
| 1. removed the old door latch assembly | | | | | |
| 2. inspected the latch mount | | | | | |
| 3. installed new rear door latch bar, lever, and spring | | | | | |
| 4. operated the rear door to verify fixes | | | | | |
| <u>ADDITIONAL DESCRIPTION:</u> | | | | | |
| REAR DOOR LATCH NO LONGER WORKS | | | | | |
| 38CM1250 | BOLT SHOULDER | 1 | | 11.03 | 11.03 |
| 39DM10 | NUT | 1 | | 2.85 | 2.85 |
| 46933664 | PIN PIVOT | 2 N | | 81.95 | 163.90 |
| 6810132 | SPRING | 1 | | 8.65 | 8.65 |
| 7319798 | BUSHING SPACER | 1 | | 13.09 | 13.09 |
| 7319799 | ROLLER TAILGATE | 1 | | 8.79 | 8.79 |
| 7322141 | PIN COTTER | 1 | | 1.74 | 1.74 |
| 7322142 | MOUNT STRIKER | 2 | | 60.37 | 120.74 |
| 7442194 | LATCH TAILGATE | 1 | | 41.86 | 41.86 |
| 7492355 | PIN CLEVIS | 1 | | 9.77 | 9.77 |
| | | | | PARTS | 382.42 |

CONTINUED ON PAGE 06

X

Authorized By



Bobcat
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 06 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS | |
|-------------|-----------------------|-----------|-----------|------------------|-----|--------|
| P109434 | S66 C68 SJC S66 T4 | 5805 2 | B4SA22479 | | | |
| | | | | LABOR | | 465.00 |
| 10722020 | | | | SEGMENT TOTAL==> | | 847.42 |

| | | | | | | |
|--------------------------------|--|--|--|------------------|-------|---------|
| SEGMENT# 6 5 3293 N/A | 11/20/25 12/17/25 | | | | | |
| FRAME REPAIRS | | | | 18.00 | 18.00 | |
| <u>COMPLAINT:</u> | RH LIFT ARMSTOP MISSING/BROKEN | | | | | |
| <u>CORRECTION:</u> | 1. removed the old broken arm stop pad 2. ground down the mounting plate to be able to install new stops 3. welded the left side steel to the frame for stop to mount on 4. cut and drilled a piece of steel for the right side for the arm stop pad to mount to 5. ran the machine arms up and down to verify the fix | | | | | |
| <u>ADDITIONAL DESCRIPTION:</u> | FRAME REPAIRS NEEDED | | | | | |
| | | | | LABOR | | 1240.00 |
| 10722020 | | | | SEGMENT TOTAL==> | | 1240.00 |

| | | | | | | |
|------------------------|--|--|--|------|------|--|
| SEGMENT# 7 5 3293 NA | 12/26/25 12/26/25 | | | | | |
| replace back up camera | | | | 1.00 | 1.00 | |
| <u>COMPLAINT:</u> | customer states machine has code for camera | | | | | |
| <u>CAUSE:</u> | The back up camera is not working correctly and needs to be replaced | | | | | |
| <u>CORRECTION:</u> | 1. removed the rear door cover | | | | | |

CONTINUED ON PAGE 07

X

Authorized By



Bobcat[®]
of Effingham

1206 Main Street • Teutopolis, IL 62467
(217) 717-4550

Corporate Office
401 West Outer Road
Valley Park, MO 63088
(636) 225-2900
Fax: (636) 225-4344

Ship To: IN STORE PICKUP

| | | |
|-------------------------|----------------------------|-----------------------|
| Branch EFFINGHAM | | |
| Date 12/29/25 | Time 12:08:47 (O) | Page 07 |
| Account No. UNIVE029 | Phone No. 224-612-0301 | Invoice No. W05600 |
| Ship Via | Purchase Order P2945477 | |

Invoice To: UNIVERSITY OF ILLINOIS DAIRY FARM
1207 W GREGORY DR
URBANA IL 61801

| |
|--------------------|
| Salesperson 699 |
|--------------------|

SERVICE PRELIMINARY

| STK#/FLEET# | | HRS | PIN/EIN | WARRANTY DATE | HRS |
|-------------|------------------------------------|------|-----------|------------------|--------|
| P109434 | S66 C68 SJC | 5805 | B4SA22479 | | |
| | S66 T4 | 2 | | | |
| | 2. removed the camera and mount | | | | |
| | 3. installed new camera, and mount | | | | |
| | 4. ran the machine to verify fix | | | | |
| 7384581 | KIT CAMERA REAR | | | 1 | 661.22 |
| | | | | | 661.22 |
| | | | | | 661.22 |
| | | | | | 155.00 |
| 10722020 | | | | SEGMENT TOTAL==> | 816.22 |

***** WORK ORDER TOTALS *****
 PARTS 11830.28
 LABOR 6897.50
 TOTAL CREDIT CARD 18727.78

X

Authorized By