



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 01
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	COMBINE		X YKG239558			
	8250	692	14787579			

SEGMENT# 1 S 06673 MISC1 02/24/26 02/24/26 .50 HRS
REPLACE CAB FILTERS

CORRECTION:

- removed inner cab filter housing cover.
- removed old filter.
- unboxed new filter, marked with date and engine hours at time of installation.
- re-installed housing cover.
- removed outer cab filter housing cover.
- removed old filter and cleaned housing of dust.
- unboxed new filter & marked with date and engine hours at time of installation.
- re-installed filter housing cover.

ADDITIONAL DESCRIPTION:

HRS
1. REPLACE CAB FILTERS (MISC1) 0.50
Remove Filter cover, clean out any debris Remove and replace filter. Mark with hours.

Quantity		=====	x1	=====	
		0.50			
AF25557	FILTER	1	87.31		87.31
360260A2	FILTER AIR CAB	1	159.99		159.99
	PARTS				247.30
	LABOR				87.50
13500062	SEGMENT TOTAL==>				334.80

SEGMENT# 2 S 06673 FEEDER15 02/24/26 02/24/26

CONTINUED ON PAGE 02

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch		
KINDERSLEY		
Date	Time	Page
03/16/26	17:17:04 (O)	02
Account No.	Phone No.	Reference No.
TRIDA002	3069322306	W24860
Ship Via	Purchase Order	
	W24798	
	G.S.T. No.	
SW-6-32-19W3	79759 4660 RT0001	
Credit Card No.	Salesperson	
	L86	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430		X YKG239558			
COMBINE					
8250	692	14787579			

FEEDER DRIVE SPROCKET WORN 15.00 HRS

CORRECTION:

- brought machine into work bay.
- brought feeder house splitting stand into work bay and set up.
- attached lifting sling to front lifting mounts of feeder house and attached to overhead crane, lifted slightly on feeder house to remove weight to feeder house lift cylinders front pins, removed retaining hardware, removed pins and laid cylinders down on shop floor.
- positioned feeder house splitting stand under feeder house and lowered feeder house into position with over head crane, set rear support to correct height.
- removed feeder house height sensor from right hand feeder house pivot pin.
- removed all applicable shields to left hand side of feeder house to gain access to drive line steady bearings, universal joints and yolks, main feeder house valve block and left hand pivot pin.
- disconnected applicable hydraulic and electrical connectors to main valve block and feeder house harness, capped and plugged hydraulic fittings upon removal, marked electrical harness's for proper re-installation.
- loosened and removed retaining bolts to feeder house drive line yolk and split yolk, loosened and removed mounting hardware to drive line steady bearings and laid drive line out of way to access left hand pivot pin.
- removed feeder house gear box input yolk as well to gain access to left hand pivot pin.
- using angled pry bar removed feeder house pivot pins from

CONTINUED ON PAGE 03

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 03
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

machine.

- attached fork lift to front of feeder house splitting stand with lifting chain and slowly separated feeder house from combine.
- with feeder house adequately away from machine, removed hardware to rear product guides and removed guides.
- removed right hand rear feeder house access shield to gain access to beater and sprocket shaft retaining bolts, loosened both bolts.
- removed retaining bolts to header drive line shield and slid shield inwards to gain access to drive line yolk retaining bolts, loosened and removed yolk bolts to allow for removal of drive line from feeder house gear box stub shaft, (removed applicable shields at feeder house gearbox to remove drive line yolk).
- removed tension to feeder chain (before removing tension rotated around to access connector links at top of feeder house).
- installed lifting hook to feeder house gearbox and attached lifting chain to hook and attached to fork lift.
- removed gearcase mounting bolts and removed gearcase from feeder house, set on shop floor.
- removed both beater and sprocket shaft right hand mounting bolts, removed both shafts bearing retaining hardware and removed right hand bearings.
- removed beater shaft out rear of feeder house and set on shop floor.
- loosened and removed mounting hardware to feeder house front plate and removed plate.
- loosened and removed retaining nuts to feeder chain

CONTINUED ON PAGE 04

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch		
KINDERSLEY		
Date	Time	Page
03/16/26	17:17:04 (O)	04
Account No.	Phone No.	Reference No.
TRIDA002	3069322306	W24860
Ship Via	Purchase Order	
	W24798	
	G.S.T. No.	
SW-6-32-19W3	79759 4660 RT0001	
Credit Card No.	Salesperson	
	L86	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430		X YKG239558			
COMBINE					
8250	692	14787579			

connecting links and removed links allowing feeder chain to fall out front of feeder house, (while removing connector links found one stuck in chain and due to orientation could not get removed, had to cut link to free from chain)

- removed sprocket shaft from rear of feeder house.
- removed retaining bolts to sprocket shaft drive coupler and attempted to remove coupler from sprocket shaft
- cleaned coupler of all old grease and installed to new sprocket shaft with new retaining bolts, tightened bolts to spec.
- installed new stripper plate to coupler with new hardware and tightened to spec.
- filled coupler with fresh grease.
- removed feeder house top cover to gain access through top of feeder house for re-installation of feeder gearcase to sprocket shaft splines.
- lifted new sprocket shaft into feeder house, set left hand side on wooden block and suspended right hand side with ratchet strap, set sprocket shaft to correct height with strap and re-installed right hand bearing along with mounting hardware (left loose).
- re-installed right hand retaining bolt to sprocket shaft.
- filled coupler of beater shaft with fresh grease and lifted beater shaft back into feeder house (followed same procedure as sprocket shaft to set and install beater shaft).
- removed old worn foam seals from feeder house gearcase and replaced with new.
- cleaned out feeder house gearcase mounting area of all chaff and straw.

CONTINUED ON PAGE 05

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch		
KINDERSLEY		
Date	Time	Page
03/16/26	17:17:04 (O)	05
Account No.	Phone No.	Reference No.
TRIDA002	3069322306	W24860
Ship Via	Purchase Order	
	W24798	
	G.S.T. No.	
SW-6-32-19W3	79759 4660 RT0001	
Credit Card No.	Salesperson	
	L86	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430		X YKG239558			
COMBINE					
8250	692	14787579			

- lifted gearcase with fork lift and brought back into place at feeder house and installed, tightened gearcase mounting bolts to spec.
- tightened down both beater and sprocket shaft right hand retaining bolts and bearing hardware, torqued right hand retaining bolts to spec, (after gearcase had been remounted when shafts were turned over by hand slight ticking could be heard from left hand side of feeder house, upon inspection it was found left hand sprocket shaft stripper was making contact with stripper plate mounted to sprocket shaft, loosened off stripper mounting hardware and slid stripper down until no contact was being made, tightened hardware back down).
- ran old feeder chain lengths through feeder house and around sprocket shaft, attached to feeder chain and rotated beater shaft to pull feeder chain back through feeder house.
- once chain was fully re-installed to feeder house re-installed connector links and tightened retaining hardware.
- re-set tension to feeder chain and verified chain ran straight through feeder house.
- re-installed removed feeder house front plate, tightened all hardware down, also re-installed removed right hand shield.
- ran buffing wheel through bore holes for feeder house pivot pins to clean of all rust.
- re-installed product guides at rear of feeder house and tightened hardware.
- re-installed header drive shaft to feeder house gearcase,

CONTINUED ON PAGE 06

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 06
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430		X YKG239558			
COMBINE					
8250	692	14787579			

re-installed yolk retaining bolts and tightened down and re-installed plastic shields.
 -brought fork lift over and maneuvered feeder house to re-installed to machine.
 -buffed all rust from feeder house pivot pins before re-installing to machine, (when installing applied coating of anti-seize to pins to prevent rusting in place), re-installed pin retaining bolts once pins re-installed to machine.
 -attached lifting hooked to front of feeder house and attached to lifting sling and over head crane, lifted feeder house up off of splitting stand and removed stand from under machine.
 -using over head crane adjusted feeder house height to match lift cylinders, re-installed removed front pins and re-installed retaining hardware.
 -re-installed removed yolk from feeder house gearbox in put shaft and tightened retaining hardware.
 -lifted feeder house drive shaft back into place and re-installed mounting hardware to steady bearings and tightened down.
 -brought drive line yolks together, re-installed hardware and tightened down.
 -re-installed drive line shields.
 -hooked hydraulic and electrical connections back up.
 -re-installed feeder house valve block cover.

ADDITIONAL DESCRIPTION:

HRS
 1. FEEDER DRIVE SPROCKET WORN (FEEDER15) 15.00
 Remove side shield, remove hydraulic valve block and

CONTINUED ON PAGE 07

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 07
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

harness. Remove upper and lower driveshafts. Loosen of feeder chain. Remove top access covers. Rotate and split feeder chain. Remove upper section of feeder floor to access shaft. Loosen and remove feeder gear box and support with Come along. Lower feeder sprocket out of feeder housing. Install new feeder shaft and RH brg. Install floor, panels, gearbox, drive shafts, harness. Install chain and tension. Run and test operation. Verify tension.

Quantity

=====
x1
=====
15.00

NAP11402	ZERK	1	1.49	1.49
131-616	NUT 5/16" TINN	1	9.57	9.57
48182587	LINK, 960H CONN	1	31.50	31.50
86588003	IDLER	1	200.90	200.90
87021759	BOLT	1 N	18.57	18.57
90508334	DIA Kit	1	3691.02	3691.02
92116331	BEARING ASSY	1	222.32	222.32
	PARTS			4175.37
	LABOR			2625.00
13500062	SEGMENT TOTAL==>			6800.37

SEGMENT# 3 S 06673 FEEDER16 02/24/26 02/24/26
BEATER BLADES 1.50 HRS

COMPLAINT:

ONE SMOOTH ROCK TRAP BEATER BLADE DENTED

CONTINUED ON PAGE 08

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 08
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

CORRECTION:

- removed all mounting hardware to beater blades and removed blades from beater shaft.
- installed new blades to beater with new hardware, ensured new blades were set to correct position on beater shaft.
- tightened and torqued all mounting hardware to spec.

ADDITIONAL DESCRIPTION:

- HRS
1. BEATER BLADES (FEEDER16) 1.50
Lower feeder house Open Rock trap and remove blades.
Unbolt
4 beater blades and remove. Install and torque beater blades. Install top cover and test operation.

Quantity		=====			
		x1			
		=====			
		1.50			
48195712	KIT	1	695.19		695.19
			PARTS		695.19
			LABOR		262.50
13500062			SEGMENT TOTAL==>		957.69

SEGMENT# 4 S 06673 FEEDER19 02/24/26
CHANGE FEEDER GEARBOX OIL .80 HRS

CORRECTION:

- level feeder house
- remove drain plug on feeder gearbox
- once all oil is out, reinstall and torque drain plug
- fill feeder gearbox with new oil up to line on sight glass
- level good, torque fill plug back in place

CONTINUED ON PAGE 09

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 09
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

-job complete, level good

ADDITIONAL DESCRIPTION:

HRS

- 1. CHANGE FEEDER GEARBOX OIL (FEEDER19) 0.80
Drain oil and replace. Run and verify levels after operation.

Quantity

=====
x1
=====
0.80

LABOR 140.00

13500062

SEGMENT TOTAL==> 140.00

SEGMENT# 5 S 06673 FEEDER23	02/24/26	
HEADER DRIVE GEAR BOX OIL CHANGE		.40 HRS

CORRECTION:

- remove drain plug on header drive gearbox
- drain oil completely
- reinstall and torque drain plug
- fill gearbox up to level with fresh new oil
- torque plug
- job complete

ADDITIONAL DESCRIPTION:

HRS

- 1. HEADER DRIVE GEAR BOX OIL CHANGE (FEEDER23) 0.40
REMOVE SHEILD TO ACCESS GEARBOX. DRAIN OIL, REFILL, RUN AND TOP OFF.

Quantity

=====
x1

CONTINUED ON PAGE 10

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 10
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	COMBINE		X YKG239558			
	8250	692	14787579			

=====
0.40

13500062

LABOR 70.00
SEGMENT TOTAL==> 70.00

SEGMENT# 6 S 06673 NA 02/24/26 02/27/26
REPAIR R/H MID CONCAVE 3.00 HRS

COMPLAINT:

2 WIRE GUIDES BENT, WIRES OUT OF ALL SEAtS - ALL CONCAVES

CORRECTION:

- removed separator covers from both left and right hand sides of machine.
- loosened and removed concave mounting hardware and removed concaves from machine.
- drove concave wires back into their seats with hammer.
- struck bent wire guides with hammer and straightened back to correct position.
- re-installed concaves to machine and tightened all mounting hardware.
- re-installed removed separator covers.

13500062

LABOR 525.00
SEGMENT TOTAL==> 525.00

SEGMENT# 7 S 06673 PROCESSOR2 02/24/26 02/27/26
PROCESSOR GEARBOX OIL .80 HRS

CORRECTION:

- removed fill plug from gearcase.
- removed drain plug for gearcase and allowed oil to drain into rags (catch pan could not be placed in suitable spot to catch oil, due to low amount of oil in gearcase rags

CONTINUED ON PAGE 11

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 11
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

were sufficient catch)
 -once oil stopped flowing from gearcase, re-installed drain plug.
 -refilled gearcase to spec with fresh oil and re-installed fill plug.

ADDITIONAL DESCRIPTION:

HRS
 1. PROCESSOR GEARBOX OIL (PROCESSOR2) 0.80
 -Remove fill and level plug
 -Use air to blow oil out of the elbow gearbox
 -Refill with new oil
 -Run unit and recheck level

Quantity

=====
 x1
 =====
 0.80

13500062

LABOR 140.00
 SEGMENT TOTAL==> 140.00

SEGMENT# 8 S 06673 GRAIN11	02/24/26 02/27/26	.50 HRS
ELEVATOR CHAIN ADJUSTMENT		

COMPLAINT:

TIGHTEN CLEAN GRAIN PADDLE CHAIN; LOOSE ON SPROCKET

CORRECTION:

-loosened off tensioner rod jam nut
 -adjusted elevator paddle chain tension to spec.
 -tightened tensioner rod jam nut.

ADDITIONAL DESCRIPTION:

HRS
 1. ELEVATOR CHAIN ADJUSTMENT (GRAIN11) 0.50

CONTINUED ON PAGE 12

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 12
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			
	ADJUST ELEVATOR CHAIN TO SPEC					

Quantity

=====
x1
=====
0.50

1350062	LABOR	87.50
	SEGMENT TOTAL==>	87.50

SEGMENT# 9 S 06673 NA	02/24/26 02/24/26			
CHANGE UPPER AND LOWER UNLOADER GEARBOX OILS		1.25	HRS	

CORRECTION:

- removed drain plug(s) and allowed oil to drain from gearcase(s).
- once oil stopped flowing re-installed drain plug(s)
- re filled each gearcase to spec with fresh oil.

OIL1	ENVIRO OIL LTR	19	.18	3.42
73344313	80W90 GL 5G	1	165.75	165.75
	PARTS			169.17
	LABOR			218.75
1350062	SEGMENT TOTAL==>			387.92

SEGMENT#10 S 06673 NA	02/24/26 02/26/26			
CHANGE OIL IN INCLINE AUGER GEARBOX OIL		1.00	HRS	

CORRECTION:

- climb into grain tank, drain both bubble up auger gearboxes
- remove old oil pans from grain tank
- reinstall and torque drain plugs
- remove fill plugs, fill both gearbox to level
- reinstall and torque fill plugs
- close up

CONTINUED ON PAGE 13

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 13
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	8250	692	X YKG239558 14787579			
	- job complete					
				LABOR		175.00
13500062				SEGMENT TOTAL==>		175.00

SEGMENT#	DESCRIPTION	DATE	HRS	LABOR	PARTS	LABOR	SEGMENT TOTAL==>
11	S 06673 ENGINE9 FUEL TANK VENT CORRECTION: -remove clamps holding old vent -remove and discard old vent -install new fuel tank vent -tighten clamps -job complete ADDITIONAL DESCRIPTION: 1. FUEL TANK VENT (ENGINE9) - Remove and replace fuel tank vent	02/24/26 02/24/26	.50	0.50			
	Quantity			x1			
47437399	FUEL VENT FILTE			1	79.72		79.72
					PARTS		79.72
					LABOR		87.50
13500062				SEGMENT TOTAL==>			167.22

SEGMENT#	DESCRIPTION	DATE	HRS
12	S 06673 MISC20 AIR FILTER REPLACEMENT COMPLAINT: CUSTOMER SUPPLIED 84303930 X1 PRIMARY AIR FILTER CORRECTION:	02/24/26 02/24/26	.30

CONTINUED ON PAGE 14

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 14
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via SW-6-32-19W3	Purchase Order W24798	
Credit Card No.	G.S.T. No. 79759 4660 RT0001	
	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

- remove old air filters
- discard both
- clean out air filter housing
- install new air filters inner and outer
- reinstall air filter housing cap
- job complete

ADDITIONAL DESCRIPTION:

HRS
1. AIR FILTER REPLACEMENT (MISC20) 0.30
Remove cover, remove primary and secondary air filters.
Clean housing. Install new filter and mark with current
hours. Install cover, reset service reminder in cab.

Quantity

x1

=====
0.30

84305935	AIR FILTER, INN	1	274.12	274.12
	PARTS			274.12
	LABOR			52.50
13500062	SEGMENT TOTAL==>			326.62

SEGMENT#13 S 06673 ENGINE6 02/24/26 02/24/26
CRANKCASE BREATHER 1.00 HRS

CORRECTION:

- remove crankcase breather hose clamps and hose
- remove crankcase breather cover
- remove 3 screws holding breather filter in place
- remove old filter, discard
- set new filter in place
- tighten 3 screws to hold in place

CONTINUED ON PAGE 15

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 15
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

- clean cover
- install cover, install and torque all cover screws
- install breather hose and tighten clamps
- job complete

ADDITIONAL DESCRIPTION:

- HRS
1. CRANKCASE BREATHER (ENGINE6) 1.00
- Clean breather cap and cover
 - Remove bolts holding the cover onto the engine breather filter
 - Remove cover and filter
 - Clean excess oil from the back of the engine
 - Install o-rings onto the new filter and install onto the unit
 - Torque all bolts to spec

Quantity

=====
x1
=====
1.00

FIL1	ENVIR FILT<8"	1	.55	.55
504387088	GASKET	1	59.08	59.08
5949768015	FILTER	1	104.14	104.14
	PARTS			163.77
	LABOR			175.00
13500062	SEGMENT TOTAL==>			338.77

SEGMENT#14 S 06673 HYD2 02/24/26 02/24/26
PTO GEARBOX OIL & FILTERS

1.00 HRS
CONTINUED ON PAGE 16

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 16
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - - -
136430	8250	692	X YKG239558 14787579			

COMPLAINT:

CUSTOMER SUPPLIED HF6554 X1 HYDRAULIC FILTER

CORRECTION:

-located gearcase drain on machine and opened allowing oil to drain into catch pail.

-once oil stopped flowing out of gearcase closed drain petcock.

-re-filled gearcase with fresh oil to spec.

ADDITIONAL DESCRIPTION:

HRS
1. PTO GEARBOX OIL & FILTERS (HYD2) 1.00
Start unit and warm up oil. Set up pails and drain PTO gearbox oil. Close drain. Fill oil to proper level.
Start and run rotor. Recheck and top off oil. Rinse work area

Quantity

x1

1.00

OIL2	ENVIRO OIL>30	28	.06	1.68
73344271	HYTRAN BULK 1L	28	6.80	190.40
	PARTS			192.08
	LABOR			175.00
13500062	SEGMENT TOTAL==>			367.08

SEGMENT#15 S 06673 ROTOR12 02/24/26 02/26/26 .50 HRS
GEARBOX OIL CHANGE

CORRECTION:

-removed drain plug from feeder house drive gearcase and allowed oil to drain into catch pail.

CONTINUED ON PAGE 17

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 17
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	8250	692	X YKG239558 14787579			

-once oil stopped flowing re-installed drain plug.
-removed fill port plug and filled gearcase with fresh oil to spec, re-installed fill plug.

ADDITIONAL DESCRIPTION:

HRS
1. GEARBOX OIL CHANGE (ROTOR12) 0.50
Drain rotor gearbox oil. Replace with new oil.
dispose of
oil, run and recheck levels and top off.

Quantity

=====
x1
=====
0.50

OIL2	ENVIRO OIL>30	4	.06	.24
73344271	HYTRAN BULK 1L	4	6.80	27.20
	PARTS			27.44
	LABOR			87.50
13500062	SEGMENT TOTAL==>			114.94

SEGMENT#16 S 06673 HYD1 02/24/26 02/24/26 1.00 HRS

COMPLAINT:

CUSTOMER SUPPLIED HF06684 X 1 AND HF35305 X 1

CORRECTION:

-removed old filters and replaced with new.
-marked new filters with date and engine hours at time of install.

ADDITIONAL DESCRIPTION:

HRS
1. FILTERS (HYD1) 1.00

CONTINUED ON PAGE 18

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 18
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	8250	692	X YKG239558 14787579			

- Clean filter area
- Remove and drain filters
- Install new filters and label with hours
- Run machine, check for leaks,
- Top off Hydraulic oil

Quantity

=====
x1
=====
1.00

OIL2	ENVIRO OIL>30	17	.06	1.02
73344271	HYTRAN BULK 1L	17	6.80	115.60
	PARTS			116.62
	LABOR			175.00
13500062	SEGMENT TOTAL==>			291.62

SEGMENT#17 S 06673 NA 02/24/26 02/25/26
CHANGE TRANSMISSION OIL 1.00 HRS

CORRECTION:

- removed fill plug from transmission housing.
- removed drain plug and allowed oil to drain into catch pail.
- once oil stopped flowing, re-installed drain plug.
- filled transmission with fresh oil to spec.
- re-installed fill port plug.

OIL2	ENVIRO OIL>30	10	.06	.60
73344271	HYTRAN BULK 1L	10	6.80	68.00
	PARTS			68.60
	LABOR			175.00
13500062	SEGMENT TOTAL==>			243.60

CONTINUED ON PAGE 19

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 19
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	COMBINE		X YKG239558			
	8250	692	14787579			
SEGMENT#18 S 06673 NA		02/24/26	02/27/26			
CHANGE LH & RH FINAL DRIVE OILS					1.25 HRS	

CORRECTION:

- removed fill plug from right hand final drive.
- removed drain plug and allowed oil to drain into catch pail.
- once oil stopped running from final drive re-installed drain plug.
- re-filled final drive with fresh oil to spec.
- re-installed fill plug.
- (preformed same procedure to Left hand final drive)

LABOR	218.75
13500062	
SEGMENT TOTAL==>	218.75

SEGMENT#19 S 06673 LIGHT1	02/24/26	02/24/26			
REAR BEACON					.50 HRS

COMPLAINT:

PART IS IN SERVICE ALREADY - CUSTOMER ORDERED IN REPAIR REAR BEACON LIGHT HARNESS; DAMAGED @ CONNECTOR

CORRECTION:

- loosened rear body panel hardware to allow for removal of harness plug between panel and machine frame.
- loosened and removed beacon light mounting hardware and removed beacon light.
- installed new beacon light to machine and re-installed mounting hardware.
- hooked harness back up and tightened down body panel hardware.
- tested operation of light, operated as should.

51485581	BEACON	1	157.63	157.63
CONTINUED ON PAGE 20				

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch		
KINDERSLEY		
Date	Time	Page
03/16/26	17:17:04 (O)	20
Account No.	Phone No.	Reference No.
TRIDA002	3069322306	W24860
Ship Via	Purchase Order	
	W24798	
	G.S.T. No.	
SW-6-32-19W3	79759 4660 RT0001	
Credit Card No.	Salesperson	
	L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	8250	692	X YKG239558 14787579			
				PARTS		157.63
				LABOR		87.50
13500062				SEGMENT TOTAL==>		245.13

SEGMENT#	DESCRIPTION	DATE	HRS	PARTS	LABOR	TOTAL
20	S 06673 NA REPLACE PROCESSOR IDLER	02/24/26 02/24/26	.50			
	<u>COMPLAINT:</u> PLAY IN PULLEY					
	<u>CORRECTION:</u> -loosened off processor drive belt tension and removed belt from idler. -loosened idler mounting hardware and removed idler from machine. -removed mounting bolt along with spacers and washers from old idler and installed to new. --installed new idler to machine and tightened mounting hardware. -re-installed drive belt and set to correct tension.					
86588003	IDLER		1	200.90		200.90
				PARTS		200.90
				LABOR		87.50
13500062				SEGMENT TOTAL==>		288.40

SEGMENT#	DESCRIPTION	DATE	HRS	PARTS	LABOR	TOTAL
21	S 06673 NA REPLACE REAR SHAKER SHOE SEAL; MISSING	02/24/26 02/24/26	2.00			
	<u>CORRECTION:</u> -installed new seal to rear of shaker shoe with new rivets. -extra time was taken due to having to disassemble and repair shop pneumatic rivet gun (approx. 1hr spent repairing gun).					

CONTINUED ON PAGE 21

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch KINDERSLEY		
Date 03/16/26	Time 17:17:04 (O)	Page 21
Account No. TRIDA002	Phone No. 3069322306	Reference No. W24860
Ship Via	Purchase Order W24798	
SW-6-32-19W3	G.S.T. No. 79759 4660 RT0001	
Credit Card No.	Salesperson L86	

Description of Work and Parts

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	COMBINE 8250	692	X YKG239558 14787579			
445395	RIVET	10		.75		7.50
84989486	PLATE, FIXING	1 N		252.24		252.24
87318656	SEAL	1 N		167.37		167.37
				PARTS		427.11
				LABOR		350.00
13500062				SEGMENT TOTAL==>		777.11

SEGMENT#22 S 06673 ENGINE2	02/24/26 02/24/26				1.00 HRS	
BATTERIES R&R						
<u>COMPLAINT:</u>						
BATTERIES NEEDED TO BE REPLACED TO BRING INTO SHOP - ALREADY INSTALLED						
<u>ADDITIONAL DESCRIPTION:</u>						
HRS						
1. BATTERIES R&R (ENGINE2)				1.00		
- Remove and install batteries						
Quantity				=====	x1	=====
						1.00
CCMF31GSW	BATTERY	2		210.06		420.12
SCR3	1.5 UNIT CORE			22.50		45.00
SCR3	1.5 UNIT CORE	2-		22.50		45.00-
				PARTS		420.12
				LABOR		175.00
13500062				SEGMENT TOTAL==>		595.12

SEGMENT#23 S 06673 MISC2	02/24/26 03/11/26				2.25 HRS	
FINAL TEST RUN AND RUN UP						
<u>CORRECTION:</u>						
CONTINUED ON PAGE 22						

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$ _____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)



ROCKY MOUNTAIN EQUIPMENT

Rocky Mountain Equipment LP o/a Rocky Mountain Equipment

Please Remit to:
Box 1600
Kindersley, SK S0L 1S0
Tel: (306) 463-4651
Fax: (306) 463-4607

INVOICE

Ship to:

C - TRIDAN FARMS
DAN MACDONALD 306-932-7140

Invoice to:

TRIDAN FARMS LTD
BOX 175
PLENTY SK S0L 2R0

Branch		
KINDERSLEY		
Date	Time	Page
03/16/26	17:17:04 (O)	22
Account No.	Phone No.	Reference No.
TRIDA002	3069322306	W24860
Ship Via	Purchase Order	
	W24798	
	G.S.T. No.	
SW-6-32-19W3	79759 4660 RT0001	
Credit Card No.	Salesperson	
	L86	

Description of Work and Parts

STK#/FLEET#	COMBINE	HRS	PIN/EIN	WARRANTY DATE	HRS	Fold - - -
136430	8250	692	X YKG239558 14787579			
-while preforming final run u found rotor did not engage properly, adjusted cable accordingly and verified engagement, worked as should).						
-all other functions worked as should.						
<u>ADDITIONAL DESCRIPTION:</u>						
HRS						
1. FINAL TEST RUN AND RUN UP (MISC2) 2.25						
FINAL TEST RUN AFTER ALL REPAIRS COMPLETED. QUALITY CONTROL FORM COMPLETED. OPERATIONAL TEST- VERIFY ALL FUNCTIONS						
=====						
Quantity					x1	
=====						
					2.25	
MRKDIS		MARKETING DISC		1-	741.51	741.51-
					PARTS	741.51-
					LABOR	393.75
13500062				SEGMENT TOTAL==>		347.76-

***** WORK ORDER TOTALS *****

PARTS	6673.63
LABOR	6571.25
DISCOUNT	657.14-
SUB TOTAL==>	12587.74
GST 797594660	629.46
VISA	13217.20

I hereby authorize the above work to be done along with the use of necessary materials. You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk. I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full, an express mechanic's lien is acknowledged on above machine to secure the amount of repairs thereto. It is understood that the company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while being tested. Estimates are for labour only, materials additional.

(signature)

(date)

I hereby acknowledge my indebtedness in the amount of \$_____ being the total amount owing or balance owing as shown hereon.

(signature)

(date)