

TR Repair Inc

1 of 1

Box 44 Site 206 RR#2**Saskatoon, SK S7K3J5 (tr.repair.sk@gmail.com)****Phone: (306) 370-3454**

1

Invoice#: 00000488	Technician: Tyson	Date: 2026-02-04	Completed: 2026-02-05
Company: Yas-Farms LTD Name: Leonard Yasieniuk Address: RR1 Richard SK S0M2P0 Phone: H W		2014 KENWORTH T8 Series Odometer: 888832 License: VIN: 1XKDDP0XXEJ965515 Tag#: PO#:	

Hrs.	Labor Description	Total
0.50	C&R BOTH CAB AIRBAGS HAVE CORDS SHOWING R&R both cab airbags	72.50
0.30	C&R LEAK AT AIR COMPRESSOR Remove air fitting. Install new oring and install fitting.	43.50
0.80	C&R COOLANT LEAK Drain coolant. Replace lower rad hoses. Fill with coolant.	116.00
0.40	C&R TRAILER CORD END CORRODED. Cut off corroded wires. Install new trailer cord plug and boot.	58.00

Qty.	Part #	Part Description	Total
1.00	SSI	N SAFETY STICKER	25.00
1.00	SAFETY	N Sask Safety	250.00
1.00	15740	N TRAILER CORD BOOT	3.27
2.00	AS71090	N BUNK AIRBAG	49.96
1.00	15720	N TRAILER CORD SOCKET	17.99
1.00	74055	N COOLANT 50/50	14.58
4.00	B9226-0275TRP	N 2.5 RAD CLAMP	9.33
1.00	561.75250	N 2.5 FORMED 90 RAD HOSE	61.44
1.00	5515250	N 2.5 RAD HOSE	45.16

BALANCE is due 30 days from the date of invoice.
TR Repair Inc PST #7768799 GST# 73190 0940

Parts Total:	554.68
Labor Total:	290.00
Special Repairs Total:	0.00
Sub-Total:	844.68
GST:	43.23
PST:	36.88
Supply Charges:	20.00
Shipping:	0.00

Sub Total:	944.79	Discount:	0.00
CC Fee:	0.00	Total:	944.79
		Paid:	0.00
On Acct:	0.00	Balance:	944.79

Authorized by Signature:

I hereby authorize the repair work hereinafter set forth to be done along with the necessary material and agree that you are not responsible for the loss or damage to vehicle artifacts left in the vehicle in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of inspection. An express mechanics lean is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

TR Repair INC is not responsible for any damages or subsequent repairs of any systems that have been modified or altered in any way from OEM standards. Any warranties on parts sold are those made by the manufacturer.