⊕ STATUS			
✓ Done			
	WORK TYPE	REQUEST	
1h	Reactive	#4741814	
■ DESCRIPTION			
Changed headlight bulb th	at was out and replaced was	sher fluid pump	
ASSIGNEES BY BY BY BY BY BY BY BY BY B			
	•	Trucks	
O LOCATION	ASSET		
	MT 103		
WORK ORDER INFO			
Created by: Keith Murphy			
Last updated on 10/11/202 Completed on 10/11/2024,			
Requested by Josh Gonza		4, 6:11 AM	
WORK ORDER HISTORY			
	requested the work order		
Keith Murphy created work	corder		
Keith Murphy logged time 10/11/2024, 7:30 AM	20m 00s (Work).		
Keith Murphy logged time 10/11/2024, 7:30 AM	and was assigned to this wo	rk order.	
Keith Murphy completed th	ne work order.		
	_		Signed off by
			Date