



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		*REPRINT*
Date	Time	Page
03/25/25	23:04:38 (B)	01
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 9662 10-000-200-1 10/24/24 01/17/25
PLATINUM INSPECTION 27.00 HRS
*PLEASE PREFORM GOLD CERTIFICATION USING GREENLIGHT INSPECTION CHECKLIST FROM HORIZON VELOCITY
*TRANSFER GREENLIGHT ESTIMATE CREATOR AND INSPECTION TO SERVICE MANAGER. PLEASE NOTE PRESSURES TAKEN. CONSULT WITH OWNER OF MACHINE
TO WHICH REPAIRS WE RECOMMEND AND WHICH THEY WISH US TO DO.
HAVE SEGMENTED WORKORDER CREATED, FOR WORK TO BE DONE.
THIS DOES NOT INCLUDE ANY MAJOR CLEANING OR BLOWING OF THE DUST CHAFF OFF.
-ADD ARROWS TO FEEDERHOUSE AND PLATFORM FOR EASE OF ALIGNMENT AND HOOKING UP
*TECHNICIAN COMMENTS*****
*
*PERFORMED GREENLIGHT CHECKLIST-WENT THROUGH WITH CUSTOMER *

***** TECHNICIANS COMMENTS *****
*
*Removed all panels. Performed trade inspection. Composed *
*estimate and forwarded to service office. Performed final *
*running checks. *
*

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	02
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
				LABOR	3499.00
	16001001			SEGMENT TOTAL==>	3499.00

SEGMENT# 2 C 9662	10-000-003	10/24/24	01/29/25		
TRADE COMBINE- CLEAN AND WASH EXTERIOR TIN WORK ONLY				5.00	HRS
TOUCH UP PAINT ON COMBINE					
LUBE ALL CHAINS					
GREASE MACHINE ENTIRELY AFTER WASH					
PARK IN LINE UP					
***** TECHNICIANS COMMENTS *****					
* *					
*Blew off combine before inspection.					
* *					

				LABOR	180.00
	16001001			SEGMENT TOTAL==>	180.00

SEGMENT# 3 C 9662	NA	01/28/25	01/28/25		
DIAGNOSE AND REPAIR LHS SHROUD ACTUATOR FAULT				2.00	HRS
***** TECHNICIANS COMMENTS *****					
* *					
*Confirmed fault was an active code. Removed the rear					
*tailboard cover. Brought unit to wash bay and cleaned					
*remaining debris. Ran the shroud and found no codes. Cycled					
*the CTD and no codes appeared. Determined fault was due to					
*debris build up. Reinstalled the tailboard cover.					
* *					

				LABOR	360.00
	16001001			SEGMENT TOTAL==>	360.00

CONTINUED ON PAGE 03

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	03
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000

SEGMENT# 4 C 9662 NA 01/28/25 01/29/25
DIAGNOSE AND REPAIR ACTIVE HAD 522468.18 UNLOAD SWING LATCH 2.00 HRS

***** TECHNICIANS COMMENTS *****

*
*Calibrated latch and the calibration passed. The latch was
*functioning as it should. Suspected the cold weather caused
*latch faults.
*

LABOR 180.00
SEGMENT TOTAL==> 180.00

SEGMENT# 5 C 23001 NA 01/28/25 01/28/25
CAB ROOF WARPED 3.00 HRS
-REPLACE FRONT CAP AND SEAL

***** TECHNICIANS COMMENTS *****

*
*Removed front roof cap on X9. Removed the wiring
*harnesses. Reinstalled wiring harnesses and roof caps.
*

AXE15090	.91"ID COFLEX	15	10.58	158.70
	N20 A-E Indirect Materials			
AXE69323	Roof	RETAIL	1626.60	
		1 N	1576.50	1576.50
AXE92948	Roof	1 N	1593.51	1593.51
RE590453	Cover	1 N	127.42	127.42
RE595168	Name Badge	1 N	88.08	88.08

PARTS 3544.21

CONTINUED ON PAGE 04

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	04
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
				LABOR	540.00
	16001001		SEGMENT TOTAL==>		4084.21

SEGMENT# 6 C 9662 NA	01/28/25 01/28/25	
4600 COMMAND CENTER BUTTON BAR DOES NOT WORK	2.00 HRS	
-REPLACE BUTTON STRIP		
***** TECHNICIANS COMMENTS *****		
*Replaced strip/module and confirmed the strip lit up.		

AXE83172	Module	1 N 692.72 692.72
		PARTS 692.72
		LABOR 180.00
16001001	SEGMENT TOTAL==>	872.72

SEGMENT# 7 C 9662 NA	01/28/25 01/28/25	
RETHRESHER CLUTCH WORN	3.00 HRS	
-INSPECT SHAFT		
-REPLACE CLUTCH		
***** TECHNICIANS COMMENTS *****		
*Loosened belt tension. Removed pulley. Removed bolts and		
*shims. Pressed clutch out of sheave. Installed new clutch		
*and original shims. Installed and torqued bolts. Installed		
new key in shaft. Installed clutch on shaft and torqued nut.		

AXE92005	Slip Clutch	1 N 2422.12 2422.12
49M4111	KEY-7X8X40MM	1 8.50 8.50
CONTINUED ON PAGE 05		

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	05
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
				PARTS	2430.62
				LABOR	540.00
	16001001		SEGMENT TOTAL==>		2970.62

SEGMENT# 8 C 9662 NA	01/28/25 01/28/25			
FEEDER DRIVE CHAIN STRETCHED PAST MIN SPEC		1.00 HRS		
AND LOWER SUPPORT WORE OFF				
-REPLACE CHAIN AND SUPPORT				
***** TECHNICIANS COMMENTS *****				
*		*		
*Installed new drive chain and tensioned.		*		
*		*		

AXE82777	FDR DRIVE CHAIN	1	848.63	848.63
			PARTS	848.63
			LABOR	135.00
	16001001	SEGMENT TOTAL==>		983.63

SEGMENT# 9 C 9662 NA	01/28/25 01/28/25			
LOAD AUGER DRIVE BELT HAS HOLES		1.00 HRS		
-REPLACE BELT				
***** TECHNICIANS COMMENTS *****				
*		*		
*Loosened belt tension. Removed hopper panel. Replaced and		*		
*tensioned belt. Reinstalled panel.		*		
*		*		

HXE166678	BELT	1	121.12	121.12
			PARTS	121.12
			LABOR	117.00
CONTINUED ON PAGE 06				

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	06
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
	16001001		SEGMENT TOTAL==>		238.12

SEGMENT#10 C 9662 NA	01/28/25 01/28/25			
ACCELERATOR BELT AND PULLEY SMOKED	1.00 HRS			
-REPLACE BELT				
-VERIFY IF PULLEY IS STILL OPERATABLE				
***** TECHNICIANS COMMENTS *****				
*				
*Replaced accelerator belt. Ensured belt depth in pulley				
*was good. Tension belt.				

HXE171261	V-Belt	1	255.41	255.41
			PARTS	255.41
			LABOR	99.00
16001001		SEGMENT TOTAL==>		354.41

SEGMENT#11 C 9662 NA	01/28/25 01/28/25			
REPLACE CRACKED AND PUNCTURED ACCELERATOR CASE DRIVE BELT	1.00 HRS			
***** TECHNICIANS COMMENTS *****				
*				
*Replaced belt and tension.				

HXE124204	BELT	1	597.60	597.60
			PARTS	597.60
			LABOR	90.00
16001001		SEGMENT TOTAL==>		687.60

SEGMENT#12 C 9662 NA 01/28/25 01/28/25

CONTINUED ON PAGE 07

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	07
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
REPLACE PUNCTURED AND RIPPED RHS PRIMARY BELT				1.50	HRS
***** TECHNICIANS COMMENTS *****					
*Removed shoe belt. Removed accelerator case drive belt.					
*Removed RHS primary belt. Installed new belt. Tensioned					
*belt.					

HXE176241	V-Belt	1		288.33	288.33
				PARTS	288.33
				LABOR	270.00
16001001			SEGMENT TOTAL==>		558.33

SEGMENT#13 C 9662 NA	01/28/25	01/28/25			
OUTER ROTARY SCREEN BELT MISSING			.50	HRS	
-INSTALL NEW BELT					
***** TECHNICIANS COMMENTS *****					
*Installed new belt.					

HXE168680	BELT	1	85.48	85.48	
			PARTS	85.48	
			LABOR	90.00	
16001001			SEGMENT TOTAL==>		175.48

SEGMENT#14 C 9662 NA	01/28/25	01/28/25			
REPLACE PUNCTURED AND CRACKED DISCHARGE BEATER BELT			3.00	HRS	
***** TECHNICIANS COMMENTS *****					
*					

CONTINUED ON PAGE 08

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	08
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
*Loosened chopper and thresher belt tension. Removed upper *					
*feeder belt tension and belt. Removed tension rod. Opened *					
*rotor sheaves. Removed rotor belt. Removed chopper belt. *					
*Removed discharge drive belt. Installed new discharge drive *					
*belt. Tensioned chopper belt. *					

HXE124189	V-Belt	1	487.52	487.52	
			PARTS	487.52	
			LABOR	540.00	
16001001	SEGMENT TOTAL==>		1027.52		

SEGMENT#15 C 9662 NA 01/28/25 01/28/25 2.50 HRS

ROTOR BELT MISSING LUGS
-REPLACE ROTOR BELT
-SET SHEAVE GAP

***** TECHNICIANS COMMENTS *****

*
*Rotor tension bolt was damaged and stripped out. Cut out
*the bolt and installed a new one. Installed new belt and
*tensioned. While tensioning, the belt rolled over. Ensured
*belt was seated correctly and set sheave gap.
*

HXE107859	ROTOR BELT	1	1505.40	1505.40
H152450	EYEBOLT	1	81.01	81.01
14M7291	NUT-16MM FLG HD	2	4.97	9.94
	PARTS		1596.35	
	LABOR		360.00	
16001001	SEGMENT TOTAL==>		1956.35	

CONTINUED ON PAGE 09

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	09
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000

SEGMENT#16 C 9662 NA	01/28/25 01/28/25			
REPLACE TORN AND PUNCTURED RETHRESHER BELT		3.00 HRS		
***** TECHNICIANS COMMENTS *****				
* * *				
*R & R belt and tension.				
* * *				

HXE176242	V-Belt	1	480.76	480.76
			PARTS	480.76
			LABOR	270.00
16001001		SEGMENT TOTAL==>		750.76

SEGMENT#17 C 9662 NA	01/28/25 01/28/25			
REPLACE TORN REAR FEEDER BELT		1.00 HRS		
***** TECHNICIANS COMMENTS *****				
* * *				
*Routed and tensioned rear feeder belt. Connected meg				
*piston line.				
* * *				

HXE175039	BELT FEEDERHOUS	1	808.58	808.58
11M7021	COTTER-5/32 X 1	1	.68	.68
			PARTS	809.26
			LABOR	180.00
16001001		SEGMENT TOTAL==>		989.26

SEGMENT#18 C 9662 NA	01/28/25 01/28/25			
REAR FEEDER IDLER BEARINGS SHOT		2.50 HRS		
-REPLACE BEARINGS IN IDLER				

CONTINUED ON PAGE 10

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	10
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
-VERIFY BELT ALIGNMENT					
***** TECHNICIANS COMMENTS *****					
*Removed idler shaft assembly. Removed arms. Pressed shaft					
*and bearing out. Pressed new bearing onto shaft. Pressed					
*shaft into pulley. Reinstalled snap ring. Remounted					
*assembly onto unit. Laser lined pulley. Will verify					
*tracking during run up.					

AXE87376	Ball Bearing	1 N	286.32	286.32	
			PARTS	286.32	
			LABOR	450.00	
16001001		SEGMENT TOTAL==>	736.32		

SEGMENT#19 C 9662 NA	01/28/25 01/31/25	
CHOPPER HAMMERS WORN AND SMASHED	2.50 HRS	
-FLIP HAMMERS		
***** TECHNICIANS COMMENTS *****		
*Flipped hammers.		

	LABOR	270.00
16001001	SEGMENT TOTAL==>	270.00

SEGMENT#20 C 9662 NA	01/28/25 01/28/25	
CLEAN GRAIN ELEVATOR PADDLES CUPPED AND BANGING	3.00 HRS	
-REPLACE CHAIN AND SPROCKETS		
***** TECHNICIANS COMMENTS *****		

CONTINUED ON PAGE 11

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to: JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to: INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	11
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000

*Removed panels in grain tank. Loosened drive belt tension. *					
*Removed elevator chain. Removed upper drive sheave. Removed *					
*inner bearing. Removed shaft assembly. Installed new *					
*sprocket and key. Reinstalled shaft assembly. Installed *					
*inner bearing. Installed sheave and torqued. Removed lower *					
*auger bearing. Removed boot plate. Removed sprocket and *					
*key. Installed new sprocket and key. Installed boot plate *					
*and bearing. Torqued hardware. Opened chain crate. Pulled *					
*new chain up elevator shaft. Connected master and tensioned *					
*chain. Installed and tensioned elevator belt. Reinstalled *					
*all panels in hopper. *					

AH220541	CON.LK557 BLTED	1	21.99	21.99	
AXE86232	Roller Chain	1 N	1668.90	1668.90	
HXE22459	Chain Sprocket	2 S	199.71	399.42	
49M6480	KEY-7X8X50MM	2	5.40	10.80	
			PARTS	2101.11	
			LABOR	540.00	
16001001			SEGMENT TOTAL==>	2641.11	

SEGMENT#21 C 9662 NA 01/28/25 01/28/25
REPLACE FRONT CLEANING FAN BELT AS IT HAS HOLES 2.00 HRS

***** TECHNICIANS COMMENTS *****

*Removed variable sheave hydraulic line and fully opened *

*rear sheave. Removed fire extinguisher bracket. Removed *

*panel and toolbox. Loosened fixed fan belt tension. *

*Loosened variable sheave mounting bolts. Moved variable *

CONTINUED ON PAGE 12

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	12
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
*drive in. Removed variable fan belt. Removed fixed fan				*	
*belt. Installed new fixed fan belt. Installed rethresher				*	
*belt behind variable fan belt. Routed, tensioned and set				*	
*sheave gap on variable belt. Installed fan sheave bracket.				*	
*Torqued all bolts. Tensioned fixed fan belt. Reconnected				*	
*hydraulic line. Installed panel and fire extinguisher				*	
*bracket.				*	

HXE176244	V-Belt	1		234.33	234.33
				PARTS	234.33
				LABOR	270.00
16001001			SEGMENT TOTAL==>		504.33

SEGMENT#22 C 9662 NA 01/28/25 01/28/25
MULTICOUPLER COVER SNAPPED OFF 1.00 HRS
-REPLACE COVER
-ADD SPARE SHEAR PINS

***** TECHNICIANS COMMENTS *****

* *

*Installed new multicoupler cover and latches. Built spring *

*and pins. Installed missing shear pins. *

* *

AXE77006	Hinge	1	257.86	257.86
AXE77813	Cover	1 N	215.30	215.30
14M7264	LOCK NUT	4	.52	2.08
19M9326	SHEARBOLT M4X30	4	1.93	7.72
			PARTS	482.96
			LABOR	180.00

CONTINUED ON PAGE 13

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	13
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via	Purchase Order	
	Salesperson	
	KK	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
	16001001			SEGMENT TOTAL==>	662.96

SEGMENT#23	C 9662 NA	01/28/25 02/03/25	
STATIONARY KNIVES WORN		1.50 HRS	
-FLIP KNIVES			
***** TECHNICIANS COMMENTS *****			
*Removed stationary knife bank. Disassembled and flipped			
*knives.			

	LABOR	180.00	
16001001	SEGMENT TOTAL==>	180.00	

SEGMENT#24	C 9662 NA	01/28/25 02/03/25	
SPREADERS LOOSE ON HUBS		4.00 HRS	
INSPECT AND ADVISE			
***** TECHNICIANS COMMENTS *****			
*Removed some spreader fins. Inspected shaft and pin.			
*Spreader seemed tight on shaft. Suspected play is normal			
*gearcase backlash. Reassembled fins.			

	LABOR	225.00	
16001001	SEGMENT TOTAL==>	225.00	

SEGMENT#25	C 9662 NA	01/28/25 01/28/25	
REPLACE REAR BEACON AS IT DOES NOT WORK		.50 HRS	
***** TECHNICIANS COMMENTS *****			

CONTINUED ON PAGE 14

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	14
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
*				*	
*Removed rear beacon. Found wiring harness torn and a				*	
*damaged connector. Installed a new harness and old beacon.				*	
*Secured harness as required. Returned beacon.				*	

AXE82493	Wiring Harness	1 N	194.19	194.19	
			PARTS	194.19	
			LABOR	90.00	
16001001		SEGMENT TOTAL==>	284.19		

SEGMENT#26 C 9662 NA	01/28/25 01/28/25			
REPLACE CRACKING HEADER CLUTCH BELT		1.00 HRS		
***** TECHNICIANS COMMENTS *****				
*		*		
*Removed and replaced front feeder belt. Set tension.				*

HXE175042	V-Belt	1	794.51	794.51
			PARTS	794.51
			LABOR	180.00
16001001		SEGMENT TOTAL==>	974.51	

SEGMENT#27 C 9662 NA	01/28/25 01/28/25			
GRAIN QUALITY CAMERAS CAKED FROM ROTTEN GRAIN		1.00 HRS		
-CLEAN CAMERAS				
-REPLACE DESICANT				
***** TECHNICIANS COMMENTS *****				
*		*		
*Removed return camera. Cleaned and scraped lens. Replaced				*

CONTINUED ON PAGE 15

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	15
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
*desiccant. Removed clean grain camera. Cleaned lens and				*	
*replaced desiccant.				*	
*****				*	
KXE10744	Desiccant	2		321.34	642.68
				PARTS	642.68
				LABOR	180.00
16001001			SEGMENT TOTAL==>		822.68

SEGMENT#28 C 9662 NA	01/28/25 01/30/25	
ADJUST TAILINGS CHAIN OUT OF ADJUSTMENT		.50 HRS
***** TECHNICIANS COMMENTS *****		
*Tensioned tailings chain. Did not require half link		
*removal.		

	LABOR	90.00
16001001	SEGMENT TOTAL==>	90.00

SEGMENT#29 C 9662 NA	01/28/25 01/30/25	
REPLACE MISSING HARDWARE ON ENGINE LANDING		.50 HRS
***** TECHNICIANS COMMENTS *****		
*Removed upper railing off unit. Cut the broken pin out of		
*the railing. Grind flush. Installed new pivot pin and		
*welded. Cleaned, primed and painted. Reinstalled landing		
*railing.		

CONTINUED ON PAGE 16

**A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.**

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



St. Paul
Box 1468 St Paul, AB T0A 3A0
Tel: 780.645.4437 Fax: 780.645.4016
www.horizonagturf.com

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

INTERNAL CUSTOMER
Horizon Ag & Turf
Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	16
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
R106297	Pin Fastener	1		20.29	20.29
				PARTS	20.29
				LABOR	90.00
	16001001		SEGMENT TOTAL==>		110.29

SEGMENT#30 C 9662 NA 01/28/25 01/28/25
SERVICE: 6.00 HRS

- ENGINE OIL/FILTER
- FUEL FILTERS
- ACCELERATOR GEARCASE
- ALL AIR FILTERS
- TOP UP COOLANT
- LOAD AUGER GEARCASES BURNT AND DIRTY - REPLACE OIL

***** TECHNICIANS COMMENTS *****

*
*Drained engine oil. Replaced cab and engine air filters.
*Replaced engine oil filter and both fuel filters. Cleaned
*sediment bowl. Drained accelerator gearcase. Topped up
*coolant. Sucked oil out of the load auger gearcases.
*Refilled load auger gearcases, accelerator gearcase, and
*engine oil. Ran unit and topped up fluids as
*required. Greased unit. Updated to the latest software
*payload.
*

AXE70605	Air Filter REC	1	35.75	35.75
DZ124761	FUEL FILTER PR.	1	149.17	149.17
DZ124786	FUEL FIL SEC	1	143.31	143.31
ENVO114	OIL ENVIRO FEE	3	1.14	3.42
ENV06	OIL ENVIRO FEE	4	.06	.24

CONTINUED ON PAGE 17

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:

JD X9 1100 HI WAY 29 TRD - (815090)

Invoice to:

 INTERNAL CUSTOMER
 Horizon Ag & Turf
 Lloydminster AB T9V 3A2

Branch		
ST. PAUL		
Date	Time	Page
03/25/25	23:04:38 (B)	17
Account No.	Phone No.	Invoice No.
INTER01A	7808754471	W00596
Ship Via		Purchase Order
		Salesperson
		KK

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
151083A	JOHN DEERE X9 1100	1233	1H0X911XAME815090	09/29/22	
	X9 1100	868		09/27/25	1000
ENV100	ENVIRO CHARGE	2		1.25	2.50
ENV114	CONTAIN ENV FEE	2		1.14	2.28
ENV12	CONTAIN ENV FEE	4		.12	.48
ENV227	CONTAIN ENV FEE	3		2.27	6.81
ENV50	ENVIRO CHARGE	1		.55	.55
ENV57	OIL ENVIRO FEE	2		.57	1.14
HXE11090	AIR FILTER PRM.	1		421.93	421.93
HXE11091	AIR FILTER SEC.	1		297.72	297.72
RE284091	CAB FILTER	1		111.24	111.24
RE572785	ENG OIL FILTER	1		138.38	138.38
TY22062	HYGARD 9.46L	2		77.09	154.18
TY26408	HD460 SYN.G.OIL	4		44.63	178.52
TY26679	15W40+50II 19L	3		154.45	463.35
	Plus-50 II Oil 15W40 CK4/SN				
				PARTS	2110.97
				LABOR	1080.00
	16001001			SEGMENT TOTAL==>	3190.97

***** WORK ORDER TOTALS *****

	INTERNAL	CUSTOMER
PARTS	19105.37	
LABOR	11455.00	
Shop Supplies	250.00	
INTERNAL TOTAL	30810.37	

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO