



West Edmonton
17104 - 118 Ave., Edmonton, AB, T5S 2L7
Tel: 780.452.2790 Fax: 780.451.2678
www.horizonagturf.com

Ship to: IN STORE PICKUP

Invoice to: INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch		
EDMONTON		*REPRINT*
Date	Time	Page
03/12/25	23:00:22 (B)	01
Account No.	Phone No.	Invoice No.
INTER01		S75951
Ship Via		Purchase Order
		Salesperson
		JES

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
143740A	JOHN DEERE X9 1100	719	1H0X911XLMB815089	08/02/23	
	X9 1100	433		08/02/27	1750 P

Have you heard about MyDealer yet? We have a great new way to help you stay connected to your equipment. Either mobile or laptop - look up parts, order them online, view past purchases, or book a service appointment, you are in control. Ask a parts or service member about MyDealer today!

SEGMENT# 1 C 2306 NA 02/13/25 02/13/25

ROTARY SCREEN BELT

CORRECTION:

Brought unit inside and let the rotary screen thaw out to the point that it would turn. Removed center bolt on rotary screen. Removed belt guide and old belt. Installed new belt in its place. Tensioned belt and started engine to confirm repair.

ADDITIONAL DESCRIPTION:

Rotary screen on the machine was frozen due to sitting in the yard. When the engine was started the belt could not turn and failed. Need to replace belt.

HXE168680	V-Belt	1	85.48	85.48
			PARTS	85.48
			LABOR	208.80
16001001		SEGMENT TOTAL==>		294.28

SEGMENT# 2 C 2269 NA 02/13/25 02/13/25

Replace missing front end drive components" 2.00 HRS

Tech 2306 ordered parts. No labor was put on this work order as non revenue tech performed the repairs.

Reinstalled key on shaft and installed pulley back onto the shaft. Reinstalled belt and tension arm assembly.

CONTINUED ON PAGE 02

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO



West Edmonton
17104 - 118 Ave., Edmonton, AB, T5S 2L7
Tel: 780.452.2790 Fax: 780.451.2678
www.horizonagturf.com

Ship to:

IN STORE PICKUP

Invoice to:

INTERNAL CUSTOMER
INTERNAL CUSTOMER
INTERNAL W/O AB T5S 2L7

Branch			
EDMONTON			
Date	Time	Page	
03/12/25	23:00:22 (B)	02	
Account No.	Phone No.	Invoice No.	
INTER01		S75951	
Ship Via		Purchase Order	
		Salesperson	
		JES	

SERVICE INVOICE

STK#/FLEET# HRS PIN/EIN WARRANTY DATE HRS

143740A JOHN DEERE X9 1100 719 1H0X911XLMB815089 08/02/23

X9 1100 433 08/02/27 1750 P

Reinstalled nut on end of shaft and torqued nut to spec.
Reinstalled hydraulic fitting. Tensioned belt to spec after ensuring good belt alignment.

AXE82530	Idler	1 N	634.84	634.84
AXE82928	Arm	1 N	473.18	473.18
HXE115528	Thrust Washer	1 N	43.79	43.79
HXE175039	V-Belt	1	808.58	808.58
N404644	Nut 45 mm	1 N	60.76	60.76
11M7015	COTTER PIN	1	.48	.48
14M7275	HEX NUT	1	1.84	1.84
19M7825	SCREW	1	12.36	12.36
24M7178	WASHER	1	.97	.97
26H90	SHAFT KEY	2 N	7.38	14.76
	PARTS			2051.56
	LABOR			360.00
16001001	SEGMENT TOTAL==>			2411.56

SEGMENT# 3 C 2269 NA 02/13/25 02/25/25

N/A

SEGMENT# 4 C 2269 NA 02/13/25 02/25/25

Diagnose RH Heated Mirror Assembly Issue .70 HRS

The unit had an active code for the RH side heated mirror assembly. I went through the DTC procedure and found that the mirror assembly was internally shorted and needed to be replaced.

Removed heated mirror panel from RH mirror assembly.

Removed mirror assembly and installed new assembly. Plugged

CONTINUED ON PAGE 03

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH
(24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,



SIGNATURE

RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO

Ship to:	IN STORE PICKUP
Invoice to:	INTERNAL CUSTOMER
	INTERNAL CUSTOMER
	INTERNAL W/O AB T5S 2L7

Branch			
EDMONTON			
Date	Time	Page	
03/12/25	23:00:22 (B)	03	
Account No.	Phone No.	Invoice No.	
INTER01		S75951	
Ship Via		Purchase Order	
		Salesperson	
		JES	

SERVICE INVOICE

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
143740A	JOHN DEERE X9 1100	719	1H0X911XLMB815089	08/02/23	
	X9 1100	433		08/02/27	1750 P
in and installed heated mirror panel. Cleared DTC in the display and no new codes showed up. Repair complete.					
AXE88601	Mirror		1 M	734.21	734.21
RE592939	Lamp		1	99.48	99.48
				PARTS	833.69
				LABOR	126.00
16001001			SEGMENT TOTAL==>		959.69

***** WORK ORDER TOTALS *****		
	INTERNAL	CUSTOMER
PARTS	2970.73	
LABOR	694.80	
Shop Supplies	69.48	
INTERNAL TOTAL	3735.01	

A SERVICE CHARGE ON OVERDUE ACCOUNTS AT THE RATE OF 2 % PER MONTH (24 % PER ANNUM). STORAGE FEES WILL BE CHARGED AFTER 30 DAYS.

I hereby authorize the above work to be done along with the use of necessary materials, You and your employees may operate above machine for purposes of testing, Inspection or delivery at my risk, I agree to pay cash on delivery of machine or on terms satisfactory with you and until paid in full an express mechanics lien is acknowledged on above machine to secure the amount of repairs thereto, It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, sale, repair or while field testing, Items left for 30 days after completion date will be subject to storage fees,

SIGNATURE
RECEIVED ABOVE IN GOOD ORDER AND TERMS AGREED TO