

	4. Sale	
3-6	PC600LC-8	30001
3-4-13	1000	8403
6-4-13	250	8674
8-15-13	500	8957
11-11-13	5000	9221
8-5-14	250	9475
10-16-14	500	9800
8-29-17	750	10,056
4-6-18	2,000	10,338
9-16-19	250 (New Engine)	10,585
10-30-19	brakin oil change	10,627
1-17-20	500	10,828
5-29-20	750	11,054
7-22-20	1,000	11,307
5-10-21	Swap engine with 3-13	11,443 hrs
9- -21	oil changed	11,443
10-16-24	2000 500	11,705

9-16-19

New Engine Installed

10,585 hrs

Removed SN 530213 Installed 530012

Removed 530213

4-2020

Reseal both boom cyls.