

FFUN Motor Sports
141 Motor Way
Saskatoon, Saskatchewan S7P 0E9
Phone: (306)934-3717
GST/HST #: 829376086 PST: 2496453

SERVICE INVOICE

O U T	I hereby authorize the repair work hereinafter set forth to be made with the necessary material and agree that you are not responsible for loss or damage to the vehicle or articles left in same in case of fire, theft or any other cause beyond your control or for any delays caused by unavailability of parts, or delays in parts shipments by the supplier or transporter. I hereby grant you and your employees permission to operate the vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto or the amount of the estimate. All items subject to sales tax. A storage and handling fee of \$8.00 per day will commence 10 business days from the date of repair. Ffun Motor Sports Inc. DBA as Ffun Motor Sports and/or Community Moto DATE _____ AMT \$889.88 SIGNATURE _____					
	ADVISOR	TECHNICIAN	KEY TAG	INVOICE DATE :	INVOICE NO.	
	DLinton	SBlachord		8/11/2025	275552-S	
	LABOR RATE	LICENSE NO.	MILEAGE IN	MILEAGE OUT	DATE IN	STATUS
			125	126	8/5/2025	Paid
	YEAR/MAKE/MODEL			STOCK NO.	UNIT TYPE	
	2014 BRP CAN-AM			30956	Can-Am	
	SUBMODEL/SUB-SUBMODEL	LOCATION		PURCHASE DATE	COMPLETED DATE	
	OUTLANDER 650 XT 2PEA			7/20/2013	8/11/2025	
	VIN/SERIAL/HULL #	COLOR		PROMISE DATE	PRINTED DATE	
	3JBLKCJ11EJ000128	YELLOW		8/5/2025	8/11/2025	
PHONE	CHASSIS/TRAILER	REF. DOC		TRANSACTION TYPE		
				Customer Service - Bombardier		

Package Service Info

Engine Number:M7958270

DIAGNOSIS

CONCERN:

Customer is selling this unit

Customer has removed a number of panels and therefore there are loose panels

CAUSE:

machine has good compression
oil level is over full with just oil
need new spark plugs
evidence of mice in air box need new air filter as mice have chewed
no codes that are relevant low battery and a over heat code from a long time ago
recommend oil change
new plugs
good greasing
new air filter

CORRECTION:

replaced spark plugs
vacuumed mouse nest out of air box and replaced air filter

LABOR	ST	HRS	TECH	DESCRIPTION	RETAIL	SAVINGS	TOTAL
CUSBRP	-	1.00	SBlacho	Customer Pay - BRP	159.95		159.95
				TOTAL LABOR			159.95
PARTS	ST	QTY	TECH	DESCRIPTION	RETAIL	SAVINGS	TOTAL
715900637	H	2.00	JTurcott	DCPR8E SPARK PLUG	8.19		16.38
9779259	H	1.00	JTurcott	CAN-AM OIL CHANGE KIT 0W40 500 CC + V2	81.99		81.99
707800371	H	1.00	JTurcott	AIR FILTER	51.99		51.99
				TOTAL PARTS			150.36
DIAGNOSIS TOTAL							310.31

INFO