



Fort Worth Autowerks
7500 West Vickery
C
Fort Worth, TX 76116
(817) 780-0080
rafael@fortworthautowerks.com
fortworthautowerks.com

Invoice #8397

Created: 06/04/2026 at 9:42AM
Invoiced: 06/11/2026 at 8:50AM
Payment Term: On Receipt
Payment Due: 06/11/2026
Service Writer: David Hayes

Nicolas Agudelo
Mobile: (832) 622-7750

2012 BMW 128i Base
VIN: WBAUP7C59CVP22844
License Plate: RZZ3087
Mileage: 152,340 mi

Customer Comments	Recommendations
** CEL light is coming on and off **Customer will be dropping off his car tonight **Diag and Report ** Hears a noise coming from the belt or something coming from a belt of some sort ** Customer is looking to sell what the issue is before he sells it.	** Tech found noise and confirms that the noise is coming from the oil filter housing gasket ** Tech recommends replacing the Gasket ** Tech replaced tensioner new belt was not needed **Tech stated that the noise is still there and verified that the noise is coming from the Valve cover not the Oil Filter housing **Belt Tensioner replaced by FWA on 6/11/2026

CEL is coming off and on - Diag and Report	
Description	Subtotal
Labor: CEL is coming off and on - Diag and Report	\$97.50
Shop Supplies (4%): \$3.90 Total: \$101.40	

Thank you for choosing Fort Worth Autowerks for all your European vehicle service and repair needs. Our business grows by word of mouth and by your reviews! Please leave your thoughts on Google for us by clicking the following link: <https://g.page/fortworth-autowerks/review?rc>

Signature _____

Totals only include authorized services

Labor	\$97.50
Parts	\$0.00
Subtotal	\$97.50
Shop Supplies	\$3.90
EPA	\$0.00
Tax	\$0.00
Grand Total	\$101.40
Paid to Date	(\$101.40)

REMAINING BALANCE \$0.00

Payments		
6/5/2026	Credit card ending in 6814	\$101.40
Total Payments		\$101.40

Appointments

Nicolas A. / CEL is coming off and on - Diag and Report	
Fri 6/05/26 8:00 AM – 8:30 AM	



Fort Worth Autowerks
7500 West Vickery
C
Fort Worth, TX 76116
(817) 780-0080
rafael@fortworthautowerks.com
fortworthautowerks.com

Invoice #8397

Created: 06/04/2026 at 9:42AM
Invoiced: 06/11/2026 at 8:50AM
Payment Term: On Receipt
Payment Due: 06/11/2026
Service Writer: David Hayes

Declined

Replace oil Filter housing Gasket			
Description	Price	QTY	Subtotal
Labor: Installation Labor			\$585.00
Part: Oil Filter Housing Gasket - Klbi	\$39.00	1	\$39.00
		Tax (8.25%): \$3.22	Total: \$627.22

Belt Tensioner			
Description	Price	QTY	Subtotal
Labor: Installation Labor			\$585.00
Part: Belt Tensioner	\$165.00	1	\$165.00
		Tax (8.25%): \$13.61	Total: \$763.61

Valve cover replacement- N52, plastic			
Description	Price	QTY	Subtotal
Labor: Installation labor			\$838.50
Part: New valve cover	\$499.00	1	\$499.00
Part: Eccentric shaft sensor seal	\$6.99	1	\$6.99
		Tax (8.25%): \$41.74	Total: \$1,386.23