

P.O Box 5287
Victoria Point Queensland 4165
ABN: 75687910704



Licence:
AIRCON LICENCE AU57719
APPROVED INSPECTION STATION
13303
Tel:0448929128
Email: admin@seqtruckrepairs.com.au
Website: www.seqtruckrepairs.com.au

TAX INVOICE

Tax Invoice Number:7356
Date: 28/05/2026
Due Date:26/06/2026
Payment Term:COD

FOR:
Service
Odometer:771,059 Kms
Engine Hours:9,592.5 Hrs
Model:KENWORTH K200
Reg No:ABMC
Next Service Date:19/09/2026
Next Service Odometer:821,059 Kms
VIN: 6F5000000NA473480
Body Type:PRIME MOVER
Year: 2022

D e s c r i p t i o n	Q t y .	U n i t P r i c e	A m o u n t
Heavy Vehicle Truck Service			

Labour	15.0	\$150.00	\$2,250.00
inspected fan as to why it was constantly running , no faults for engine or cab controllers. connected aircon gauges inspected pressures all okay, checked for blockages in radiator ok, checked coolant level ok, suspect faulty aircon pressure sensor, Inspected gearbox air leak found leak was in split at gear shift knob, order new part.			
Carried out service inspection, complete front end, drained oil, inspected gearbox and oil level, grease all points,			
Completed engine service Took longer as fuel pro was dirty and needed a good clean Filled engine oil			
Removed lines off adblue sender Removsender and blew out brether line Fitted sender and connected lines and plug Fitted new bolt and washer to intake pipe bracket Carried out icepack inspection Greased 2nd drive slackies and tubes Greased cab mount, rhs steer shackle and cab lock linkages Replaced hub oils Cleaned rim, hub cap and chrome cover Spun wheels and topped up oil Fitted covers Dropped steer axle onto ground Removed cat walk Removed both airbox lids Cleaned air filters Fitted filters and lids Fitted cat walk Checked drive axles suspension components Checked diff oil levels and quality Checked diffs for leaks Checked jack shaft Adjusted all brakes Dropped cab Topped up coolant Secured bullbar Adjusted clutch Cleaned cabin filter Removed covers on steering column Dropped column down Unplugged indicator stalk Removed stalk Fitted new stalk Connected plugs Secured wiring together Fitted column Tested wipers and indicators - ok Fitted all covers Removed gear knob cover Disconnected air lines Removed knob Fitted new fittings into new knob Fitted knob and connected air lines Built up pressure and tested for leaks and operation - ok Fitted new cover Checked all lights Checked all cabin components Packed away all tool Cleaned up area Fitted service sticker			

Drove to brown and hurley yatala to pick up solenoid Drove to yard Dropped bullbar and lifted cab Disconnected plug and both air lines Removed solenoid Disassembled solenoid Swapped over fittings to new solenoid Fitted new exhaust to new solenoid Cut off plug from old solenoid Fitted insulation to new wires Stripped back wiring and soldered plug to new solenoid Wrapped both wires in electrical tape and then more over the insulation Fitted new solenoid Connected plug and both air lines Secured lines and wiring with zipties Ran engine to tested fan - fan turned on and off with switch and while watching it did 5 cycles on automatic engagement Dropped cab Secured bullbar Packed away tools Cleaned up area Emptied all rubbish out of ute Kms - 774903 Hours - 9641.1			
P A R T S			
Ryco Truck Filter Service Kit	1.0	\$215.00	\$215.00
RUBIA WORKS 4000	53.0	\$11.12	\$589.36
Dynatrans DA 85w140	1.0	\$9.95	\$9.95
AC7 HD Coolant Premix Gr	5.0	\$8.65	\$43.25
SWITCH-FAN OVERRIDE	1.0	\$322.97	\$322.97
RANGE VALVE ERGONOMIC 18 SPEED P2-01	1.0	\$339.51	\$339.51
Truck & Farm Grease 450g	1.0	\$14.95	\$14.95
FITTING 1/16NPT 5/32"(PUSH)	4.0	\$36.18	\$144.72
WORKSHOP CHARGES			
Environmental Compliance Fee	1.0	\$20.00	\$20.00
SUNDRIES	1.0	\$12.50	\$12.50

Subtotal	\$3,962.21
GST	\$396.22
Total	\$4,358.43
Paid	\$0.00
Balance Due	\$4,358.43

THANKS FOR YOUR BUSINESS!

We are now an approved inspection station, also offering Brake roller testing!

SEQ TRUCK & TRAILER REPAIRS PTY LTD
BSB 013265
ACC 162012661

PLEASE REMEMBER TO CHECK YOUR TRUCK SERVICE INTERVAL REGULARLY AND BOOK IN WHEN YOU
ESTIMATE YOU ARE 3 WEEKS OUT TO AVOID DISAPPOINTMENT.

ALL CARD PAYMENTS WILL INCUR A 1.18% SURCHARGE

Terms of trade are available on request.