

VEHICLE MAINTENANCE SUMMARY - (ALL)

Generated by Transport Compliance PRO

Keetah

Total for period **\$13,922.80** From 27/07/2017 To 20/04/2026

Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$	
TRUCK				Work Orders	404	\$13,922.80

NO PICTURE AVAILABLE	REGO #	674XHR	BUILD DATE	002017	404	\$13,922.80
	FLEET #	BB	TARE WEIGHT	11.2		
	MAKE	Mack	GVM / GCM	28500 / 90000		
	MODEL	Superliner	NOTES	1/8/17		

B TRUCK SERVICE **108** **\$0.00**

W/ORDER	445020	KLMS	5443 / HRS	94	6/10/2017	1st Service		\$0.00
				1	6/10/2017		MACK TRUCKS	\$0.00
W/ORDER	445021	KLMS	27210 / HRS	495	17/11/2017	B Service Completed 2. Service Ice Pack		\$0.00
				1	17/11/2017		HAMISH - KEETAH	\$0.00
				2	17/11/2017		HAMISH - KEETAH	\$0.00
W/ORDER	445022	KLMS	55555 / HRS	937	2/03/2018	B Service Completed 2. Replaced Wiper Inserts 3. Removed Drive Nut Covers		\$0.00
				1	2/03/2018		SIMON - KEETAH	\$0.00
				2	2/03/2018		SIMON - KEETAH	\$0.00
				3	2/03/2018		HAMISH - KEETAH	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	445023	KLMS	76401	/ HRS	1272	26/04/2018	B Service Completed 2. Pressure Relief (Compressor) 3. Replaced O Ring in Air Fitting at Transmission 4. Topped Up Hyd Tank with 10L		\$0.00
					1	26/04/2018	HAMISH - KEETAH		\$0.00
					2	26/04/2018	HAMISH - KEETAH		\$0.00
					3	26/04/2018	HAMISH - KEETAH		\$0.00
					4	26/04/2018	HAMISH - KEETAH		\$0.00
W/ORDER	445024	KLMS	97233	/ HRS	1632	14/06/2018	B service Completed		\$0.00
					1	14/06/2018	HAMISH - KEETAH		\$0.00
W/ORDER	445025	KLMS	125431	/ HRS	2093	3/09/2018	B Service Completed		\$0.00
					1	3/09/2018	HAMISH - KEETAH		\$0.00
W/ORDER	445026	KLMS	151280	/ HRS	2507	29/10/2018	B Service Completed 2. Replace 8 x Drive Tyres (4 x Supply & Fit, 4 x Strip & Fit Keetah Stock) 3. Flip Steers on Rims, Rebalance.		\$0.00
					1	29/10/2018	HAMISH - KEETAH		\$0.00
					2	29/10/2018	BRIDGESTONE		\$0.00
					3	29/10/2018	BRIDGESTONE		\$0.00
W/ORDER	445027	KLMS	176160	/ HRS	2888	19/12/2018	B Truck Service Completed - Air F		\$0.00
					1	19/12/2018	HAMISH - KEETAH		\$0.00
W/ORDER	445028	KLMS	200790	/ HRS	3257	2/03/2019	B Service Completed 2. Repair, Adj W/Screen Washers, Fitted New Wiper Blades 3. Replace Water Seperator Filter 4. Replace Air Drier Cassette		\$0.00
					1	2/03/2019	MACK TRUCKS		\$0.00
					2	2/03/2019	MACK TRUCKS		\$0.00
					3	2/03/2019	MACK TRUCKS		\$0.00
					4	2/03/2019	MACK TRUCKS		\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	445029	KLMS 228283 / HRS 3694	26/04/2019	B Service Completed - Air F 2. Replace 2x Batteries		\$0.00
		1	26/04/2019	HAMISH - KEETAH		\$0.00
		2	26/04/2019	HAMISH - KEETAH		\$0.00
W/ORDER	567020	KLMS 362055 / HRS 5873	6/04/2020	B Service Completed 2. Replace Coolant Tank 3. Service Ice Pack 4. Replace Trailing Arn Bushes Axle 3 Both Sides 5. Sump - Due to Worn Out Sump Threads 6. Replace Sump Gasket 7. Replace Missing Sump Bolt RH Side 8. Replace Sump Bung 9. Replace Water Drain on Air Tank 10. Drive Rotation - Front to Rear		\$0.00
		1	6/04/2020	HAMISH - KEETAH		\$0.00
		2	6/04/2020	HAMISH - KEETAH		\$0.00
		3	6/04/2020	HAMISH - KEETAH		\$0.00
		4	6/04/2020	HAMISH - KEETAH		\$0.00
		5	6/04/2020	HAMISH - KEETAH		\$0.00
		6	6/04/2020	HAMISH - KEETAH		\$0.00
		7	6/04/2020	HAMISH - KEETAH		\$0.00
		8	6/04/2020	HAMISH - KEETAH		\$0.00
		9	6/04/2020	HAMISH - KEETAH		\$0.00
		10	6/04/2020	HAMISH - KEETAH		\$0.00
W/ORDER	567021	KLMS 407172 / HRS 6491	30/06/2020	B Service Completed 2. Replace RH Axle Shock Absorber 3. Replace Breather for Diff Oil Airlines 4. Replace Diff Oil Axle 2 & 3 5. Repair Water Leak at W/Screen 6. Replace Gearbox Filter 7. Replace Number Plate Light		\$0.00
		1	30/06/2020	HAMISH - KEETAH		\$0.00
		2	30/06/2020	HAMISH - KEETAH		\$0.00
		3	30/06/2020	HAMISH - KEETAH		\$0.00

				<i>Job #</i>	<i>DATE</i>	<i>MAINTENANCE TYPE</i>	<i>REPAIRER / SUPPLIER</i>	<i>INVOICE #</i>	<i>TOTAL \$</i>
				4	30/06/2020		HAMISH - KEETAH		\$0.00
				5	30/06/2020		HAMISH - KEETAH		\$0.00
				6	30/06/2020		HAMISH - KEETAH		\$0.00
				7	30/06/2020		HAMISH - KEETAH		\$0.00
W/ORDER	567022	KLMS	436700 / HRS	7016	29/10/2020	B Service Completed			\$0.00
				1	29/10/2020		HAMISH - KEETAH		\$0.00
W/ORDER	567023	KLMS	476302 / HRS	7666	2/02/2021	B Service Completed 2. Strip, Clean, Fit New Wheel Seal LH Axle 3 3. Replace Ride Height Valve (Leaking)			\$0.00
				1	2/02/2021		HAMISH - KEETAH		\$0.00
				2	2/02/2021		HAMISH - KEETAH		\$0.00
				3	2/02/2021		HAMISH - KEETAH		\$0.00
W/ORDER	567024	KLMS	513283 / HRS	8256	7/05/2021	B Service Completed			\$0.00
				1	7/05/2021		Trucks On The Run P/L		\$0.00
W/ORDER	567025	KLMS	549522 / HRS	8861	24/08/2021	B Truck Service Completed. 2. Replace all 4x rear wheel seals. 3. Replace all 4x rear brake pads & brake drums. 4. Replace axle 3 LH shock absorber. 5. Replace axle 2 RH air bag. 6. Re-attach RH speaker inside cab. 7. Move turn table forward. 8. Restraighten steering wheel. 9. RH window tint. 10. Replace LH & RH windscreen.			\$0.00
				1	24/08/2021		SIMON - KEETAH		\$0.00
				2	24/08/2021		SIMON - KEETAH		\$0.00
				3	24/08/2021		SIMON - KEETAH		\$0.00
				4	24/08/2021		SIMON - KEETAH		\$0.00
				5	24/08/2021		SIMON - KEETAH		\$0.00
				6	24/08/2021		SIMON - KEETAH		\$0.00
				7	24/08/2021		SIMON - KEETAH		\$0.00
				8	24/08/2021		SIMON - KEETAH		\$0.00

					Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
					9	16/08/2021		Reef City Tinting	INV-0666	\$0.00
					10	23/08/2021		Pronto Autoglass	INV10508	\$0.00
W/ORDER	567026	KLMS	580365	/ HRS	9452	12/11/2021	B Truck Service Completed.			\$0.00
					1	12/11/2021		HAMISH - KEETAH		\$0.00
W/ORDER	567027	KLMS	620074	/ HRS	10082	10/02/2022	B Truck Service Completed. 2. Check fuel oil leak on ice pack. 3. AdBlue fault. 4. Replace AdBlue filter. 5. Replace AdBlue breather filter.			\$0.00
					1	10/02/2022		HAMISH - KEETAH		\$0.00
					2	10/02/2022		HAMISH - KEETAH		\$0.00
					3	10/02/2022		CT Mechanical		\$0.00
					4	10/02/2022		HAMISH - KEETAH		\$0.00
					5	10/02/2022		HAMISH - KEETAH		\$0.00
W/ORDER	567028	KLMS	659218	/ HRS	10690	13/05/2022	B Truck Service Completed			\$0.00
					1	13/05/2022		HAMISH - KEETAH		\$0.00
W/ORDER	567029	KLMS	690444	/ HRS	11265	2/08/2022	B Truck Service Completed.			\$0.00
					1	2/08/2022		Andersen Truck and Tractor	R33658	\$0.00
W/ORDER	4450210	KLMS	252185	/ HRS	4118	25/06/2019	B Service Completed			\$0.00
					1	25/06/2019		HAMISH - KEETAH		\$0.00
W/ORDER	4450211	KLMS	276543	/ HRS	4479	21/08/2019	B Service Completed - Air F 2. Replace O Rings in Airtake & Refit			\$0.00
					1	21/08/2019		HAMISH - KEETAH		\$0.00
					2	21/08/2019		HAMISH - KEETAH		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4450212	KLMS	296488	/ HRS	4840	24/10/2019	B Service Completed 2. Replace Steering Uni Joint in the Middle		\$0.00
					1	24/10/2019	HAMISH - KEETAH		\$0.00
					2	24/10/2019	HAMISH - KEETAH		\$0.00
W/ORDER	4450213	KLMS	326160	/ HRS	5328	31/12/2019	B Service Completed		\$0.00
					1	31/12/2019	HAMISH - KEETAH		\$0.00
W/ORDER	5670210	KLMS	723544	/ HRS	11851	6/11/2022	B Truck Service Completed. 2. Replace NHVR sticker. 3. Replace exhaust flex. 4. Check plug / wire to front diff. 5. Repair to ice pack.		\$0.00
					1	6/11/2022	HAMISH - KEETAH		\$0.00
					2	6/11/2022	HAMISH - KEETAH		\$0.00
					3	6/11/2022	HAMISH - KEETAH		\$0.00
					4	6/11/2022	HAMISH - KEETAH		\$0.00
					5	6/11/2022	HAMISH - KEETAH		\$0.00
W/ORDER	5670211	KLMS	756682	/ HRS	12511	15/02/2023	B Truck Service Completed. 2. Replace wheel seal.		\$0.00
					1	15/02/2023	CT Mechanical	2795	\$0.00
					2	15/02/2023	CT Mechanical	2795	\$0.00
W/ORDER	5670212	KLMS	793296	/ HRS	13111	11/05/2023	B Truck Service Completed. 2. Replace LH front drive slack adjuster.		\$0.00
					1	11/05/2023	WTG (Western Truck Group)	6305487 -	\$0.00
					2	11/05/2023	WTG (Western Truck Group)	6305487 -	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	5670213	KLMS	828920	/ HRS	13727	24/08/2023	B Truck Service Completed. 2. Fix air leaks. 3. Replace window regulator, LH. 4. Replace broken switch pod RH door card. 5. Replace RH window tint. 6. Replace batteries.		\$0.00
					1	<i>24/08/2023</i>	<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
					2	<i>24/08/2023</i>	<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
					3	<i>24/08/2023</i>	<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
					4	<i>24/08/2023</i>	<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
					5	<i>24/08/2023</i>	<i>Reef City Tinting</i>		<i>\$0.00</i>
					6	<i>24/08/2023</i>	<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
W/ORDER	5670214	KLMS	856244	/ HRS	14231	7/11/2023	B Truck Service Completed.		\$0.00
					1	<i>7/11/2023</i>	<i>DUNS BROS</i>	<i>323657</i>	<i>\$0.00</i>
W/ORDER	5670215	KLMS	893361	/ HRS	14862	29/02/2024	B Truck Service Completed. 2. Found turn table jaw out of spec & required replacing. Remove & replace turn table jaw. Adjust turn table. 3. Found diff oil contaminated with water. Remove & replace diff oil. Replace diff filter. 4. Replace windscreen wipers as required. 5. Replace air hose for diff breather as it was chaffed through. 6. Found air compressor discharge hose relief kept opening. Remove discharge hose & check for blockages, no blockages present. Remove & replace discharge hose relief (customer supplied). Replace air dryer filter. 7. Test operation, all ok.		\$0.00
					1	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					2	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					3	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					4	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					5	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					6	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>
					7	<i>29/02/2024</i>	<i>LANGTREE'S MACHINERY</i>	<i>24702</i>	<i>\$0.00</i>

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	5670216	KLMS 922689 / HRS 15366	15/05/2024	B Truck Service Completed. 2. Replace RH indicator. 3. Repair LH clearance lights. 4. Replace strut in steering wheel. 5. Remove & repair damaged hose, LH front.		\$0.00
		1	<i>15/05/2024</i>	<i>WTG (Western Truck Group)</i>	<i>6306949 -</i>	<i>\$0.00</i>
		2	<i>15/05/2024</i>	<i>WTG (Western Truck Group)</i>	<i>6306949 -</i>	<i>\$0.00</i>
		3	<i>15/05/2024</i>	<i>WTG (Western Truck Group)</i>	<i>6306949 -</i>	<i>\$0.00</i>
		4	<i>15/05/2024</i>	<i>WTG (Western Truck Group)</i>	<i>6306949 -</i>	<i>\$0.00</i>
		5	<i>15/05/2024</i>	<i>WTG (Western Truck Group)</i>	<i>6306949 -</i>	<i>\$0.00</i>
W/ORDER	5670217	KLMS 962218 / HRS 16123	16/09/2024	B Truck Service Completed. 2. Inspect air dryer. 3. Inspect air leak on gearbox. 4. Check all fluid levels. 5. Carry out general inspection. 6. Remove, inspect & refit air cleaners. 7. Remove & replace air dryer filter. 8. Lubricate all grease points. 9. Adjust brakes.		\$0.00
		1	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		2	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		3	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		4	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		5	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		6	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		7	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		8	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
		9	<i>16/09/2024</i>	<i>Andersen Truck and Tractor</i>	<i>R37653</i>	<i>\$0.00</i>
W/ORDER	5670218	KLMS 990612 / HRS 16840	9/01/2025	B Truck Service Completed.		\$0.00
		1	<i>9/01/2025</i>	<i>SIMON - KEETAH</i>		<i>\$0.00</i>
W/ORDER	5670219	KLMS 1021861 / HRS 17405	22/04/2025	B Truck Service Completed. 2. Replace RH front park bulb.		\$0.00
		1	<i>22/04/2025</i>	<i>SIMON - KEETAH</i>		<i>\$0.00</i>
		2	<i>22/04/2025</i>	<i>SIMON - KEETAH</i>		<i>\$0.00</i>

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$	
C TRUCK SERVICE					115	\$0.00	
W/ORDER	446020	KLMS	27210 / HRS	495	17/11/2017	C Service Completed	\$0.00
			1	17/11/2017		HAMISH - KEETAH	\$0.00
W/ORDER	446021	KLMS	41461 / HRS	714	16/01/2018	C Service Completed 2. Replace Fan Belt	\$0.00
			1	16/01/2018		HAMISH - KEETAH	\$0.00
			2	16/01/2018		HAMISH - KEETAH	\$0.00
W/ORDER	446022	KLMS	76401 / HRS	1272	26/04/2018	C Service Completed	\$0.00
			1	26/04/2018		HAMISH - KEETAH	\$0.00
W/ORDER	446023	KLMS	111396 / HRS	1868	18/07/2018	C Service Completed 2. Replace 2 x Shockies LH Axle 3 & RH Axle 2, MACK WARRANTY	\$0.00
			1	18/07/2018		HAMISH - KEETAH	\$0.00
			2	18/07/2018		HAMISH - KEETAH	\$0.00
W/ORDER	446024	KLMS	153084 / HRS	2532	1/11/2018	C Service Completed 2. Replace Wheel Seal LH Axle 2 3. Replace 2 x Shockies LH Axle 2, RH Axle 3 4. Service Ice Pack (Hrs 1129)	\$0.00
			1	1/11/2018		HAMISH - KEETAH	\$0.00
			2	1/11/2018		HAMISH - KEETAH	\$0.00
			3	1/11/2018		HAMISH - KEETAH	\$0.00
			4	1/11/2018		HAMISH - KEETAH	\$0.00
W/ORDER	446025	KLMS	176160 / HRS	2888	19/12/2018	C Service Completed	\$0.00
			1	19/12/2018		HAMISH - KEETAH	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	446026	KLMS	219846 / HRS	3558	8/04/2019	C Service Completed 2. Replace Steering Uni's 3. Replace Steering Dampener 4. Rotate Drive Front to Rear 5. Service Ice Pac (1966h)			\$0.00
				1	8/04/2019		HAMISH - KEETAH		\$0.00
				2	8/04/2019		HAMISH - KEETAH		\$0.00
				3	8/04/2019		HAMISH - KEETAH		\$0.00
				4	8/04/2019		HAMISH - KEETAH		\$0.00
				5	8/04/2019		HAMISH - KEETAH		\$0.00
W/ORDER	446027	KLMS	255797 / HRS	4167	1/07/2019	C Service Completed			\$0.00
				1	1/07/2019		HAMISH - KEETAH		\$0.00
W/ORDER	446028	KLMS	294635 / HRS	4814	21/10/2019	C Service Completed 2. Replace Cab Rubber Spring RH Side 3. Replace both Windscreen Wipers 4. Replace Shock Axle 2 RH Side			\$0.00
				1	21/10/2019		HAMISH - KEETAH		\$0.00
				2	21/10/2019		HAMISH - KEETAH		\$0.00
				3	21/10/2019		HAMISH - KEETAH		\$0.00
				4	21/10/2019		HAMISH - KEETAH		\$0.00
W/ORDER	446029	KLMS	326160 / HRS	5328	31/12/2019	C Service Completed			\$0.00
				1	31/12/2019		HAMISH - KEETAH		\$0.00
W/ORDER	4460210	KLMS	362055 / HRS	5873	6/04/2020	C Service Completed			\$0.00
				1	6/04/2020		HAMISH - KEETAH		\$0.00
W/ORDER	4460211	KLMS	407172 / HRS	6491	30/06/2020	C Service Completed			\$0.00
				1	30/06/2020		HAMISH - KEETAH		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4460212	KLMS	421747 / HRS	6744	10/09/2020	C Service Completed 2. Replace Axle 2 Brake Booster RH Side 3. Replace RH Mirror Lights & Rewire LH Mirror Lights			\$0.00
				1	10/09/2020		HAMISH - KEETAH		\$0.00
				2	10/09/2020		HAMISH - KEETAH		\$0.00
				3	10/09/2020		HAMISH - KEETAH		\$0.00
W/ORDER	4460213	KLMS	457132 / HRS	7395	31/12/2020	C Service Completed 2. Steering Damper Replaced 3. Torque Rod Axle 3 Replaced 4. Replace Drive Tyres - Supply & Fit - Ocean			\$0.00
				1	31/12/2020		HAMISH - KEETAH		\$0.00
				2	31/12/2020		HAMISH - KEETAH		\$0.00
				3	31/12/2020		HAMISH - KEETAH		\$0.00
				4	31/12/2020		OCEAN TYRES		\$0.00
W/ORDER	4460214	KLMS	488018 / HRS	7855	4/03/2021	C Service Completed 2. Pick Up From Rocky 3. Replace Steer Tyres - Supply & Fit 4. Repair Air Leaks 5. Check Fridge 6. Replace Batteries x4 7. Paint Roof - Warranty 8. RH Cab Mount - Supply & Fit			\$0.00
				1	4/03/2021		HAMISH - KEETAH		\$0.00
				2	4/03/2021		HAMISH - KEETAH		\$0.00
				3	4/03/2021		OCEAN TYRES		\$0.00
				4	4/03/2021		HAMISH - KEETAH		\$0.00
				5	4/03/2021		HAMISH - KEETAH		\$0.00
				6	4/03/2021		HAMISH - KEETAH		\$0.00
				7	4/03/2021		WTG (Western Truck Group)		\$0.00
				8	4/03/2021		WTG (Western Truck Group)		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4460215	KLMS	528454 / HRS	8507	16/06/2021	C Service Completed 2. Replace Fan Belt Bearing RH Side Both 3. Replace all 4 Exhaust Pipe Cover Rubber Mounts 4. Replace RH Axle 2 Shock Absorber 5. Replace Axle 2 3 Drive Diff Oils and Transmission Oils 6. Replace Transmission Oil Filter 7. Replace RH Park Light 8. Check all Drive Shaft Bearings 9. Clean RH Window Side to Fix Window going up & down 10. Check Toe In/Out			\$0.00
				1	16/06/2021		HAMISH - KEETAH		\$0.00
				2	16/06/2021		HAMISH - KEETAH		\$0.00
				3	16/06/2021		HAMISH - KEETAH		\$0.00
				4	16/06/2021		HAMISH - KEETAH		\$0.00
				5	16/06/2021		HAMISH - KEETAH		\$0.00
				6	16/06/2021		HAMISH - KEETAH		\$0.00
				7	16/06/2021		HAMISH - KEETAH		\$0.00
				8	16/06/2021		HAMISH - KEETAH		\$0.00
				9	16/06/2021		HAMISH - KEETAH		\$0.00
				10	16/06/2021		HAMISH - KEETAH		\$0.00
W/ORDER	4460216	KLMS	580365 / HRS	9452	12/11/2021	C Truck Service Completed. 2. Replace LH park light. 3. Service ice pack. 4. Install HML tracker. 5. Check for fault in lights. 6. Check remote for hydraulics.			\$0.00
				1	12/11/2021		HAMISH - KEETAH		\$0.00
				2	12/11/2021		HAMISH - KEETAH		\$0.00
				3	12/11/2021		HAMISH - KEETAH		\$0.00
				4	11/11/2021		TIM BARKER	128789	\$0.00
				5	12/11/2021		HAMISH - KEETAH		\$0.00
				6	11/11/2021		TIM BARKER	B11358	\$0.00
W/ORDER	4460217	KLMS	595126 / HRS	9688	16/12/2021	C Truck Service Completed. 2. Replace drivers side reverse light. 3. Replace transmission air fitting under cab.			\$0.00
				1	16/12/2021		SIMON - KEETAH		\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
	2	16/12/2021		SIMON - KEETAH		\$0.00
	3	16/12/2021		SIMON - KEETAH		\$0.00
W/ORDER	4460218	KLMS 642314 / HRS 10416	25/03/2022	C Truck Service Completed. 2. Replace steer tyres. 3. Replace adblue air filter. 4. Tim Barker to check & repair AC controls. 5. Replace cracked exhaust manifold.		\$0.00
	1	24/03/2022		HAMISH - KEETAH		\$0.00
	2	24/03/2022		OCEAN TYRES	4251893	\$0.00
	3	24/03/2022		HAMISH - KEETAH		\$0.00
	4	24/03/2022		TIM BARKER	B11517	\$0.00
	5	25/03/2022		WTG (Western Truck Group)	6303513 -	\$0.00
W/ORDER	4460219	KLMS 673761 / HRS 10960	20/06/2022	C Truck Service Completed. 2. Replace headlight bulb. 3. Replace "O" ring cooling system. 4. Replace wiper blades. 5. Add 30ltrs hydraulic oil. 6. Remove RH rear fuel tank for repair.		\$0.00
	1	20/06/2022		HAMISH - KEETAH		\$0.00
	2	20/06/2022		HAMISH - KEETAH		\$0.00
	3	20/06/2022		HAMISH - KEETAH		\$0.00
	4	20/06/2022		HAMISH - KEETAH		\$0.00
	5	20/06/2022		HAMISH - KEETAH		\$0.00
	6	27/06/2022		Drinnan's Diesel & Automative	INV-4908	\$0.00
W/ORDER	4460220	KLMS 713232 / HRS 11622	23/09/2022	C Truck Service Completed.		\$0.00
	1	23/09/2022		Andersen Truck and Tractor	R34029	\$0.00
W/ORDER	4460221	KLMS 742928 / HRS 12283	11/01/2023	C Truck Service Completed 2. Replace Steer Tyres 3. Replace Drive Shockies 4. Replace RH Front Cab Bush 5. Replace RH Cab Shockie		\$0.00
	1	11/01/2023		HAMISH - KEETAH		\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
	2	11/01/2023		OCEAN TYRES		\$0.00
	3	11/01/2023		HAMISH - KEETAH		\$0.00
	4	11/01/2023		HAMISH - KEETAH		\$0.00
	5	11/01/2023		HAMISH - KEETAH		\$0.00
W/ORDER	4460222	KLMS 768590 / HRS 12704	14/03/2023	C Truck Service Completed. 2. Replace both windscreens. 3. Replace isolator. 4. Repair wiring for spotlights.		\$0.00
	1	14/03/2023		HAMISH - KEETAH		\$0.00
	2	14/03/2023		Pronto Autoglass	INV14165	\$0.00
	3	15/03/2023		TIM BARKER	B11979	\$0.00
	4	15/03/2023		TIM BARKER	B11979	\$0.00
W/ORDER	4460223	KLMS 811099 / HRS 13426	30/06/2023	C Truck Service Completed. 2. Replace mudguard bolts x4. FR#255301 3. Replace leaking pinion seal. 4. Replace RH windscreen. FR#255301 5. Replace indicator stalk. FR#255302 6. Replace leaking tractor protection valve. 7. Replace 2x torque rods. FR#255301 8. Replace front engine mount. FR#255301		\$0.00
	1	30/06/2023		HAMISH - KEETAH		\$0.00
	2	30/06/2023		HAMISH - KEETAH		\$0.00
	3	30/06/2023		HAMISH - KEETAH		\$0.00
	4	30/06/2023		Pronto Autoglass	INV14899	\$0.00
	5	30/06/2023		HAMISH - KEETAH		\$0.00
	6	30/06/2023		HAMISH - KEETAH		\$0.00
	7	30/06/2023		HAMISH - KEETAH		\$0.00
	8	30/06/2023		HAMISH - KEETAH		\$0.00
W/ORDER	4460224	KLMS 841238 / HRS 13942	3/10/2023	C Truck Service Completed. 2. Replace wiper blades. 3. Replace RH windscreen. 4. Replace broken peep window, LH door. 5. Replace heater hose.		\$0.00
	1	3/10/2023		HAMISH - KEETAH		\$0.00

					Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
					2	3/10/2023		HAMISH - KEETAH		\$0.00
					3	3/10/2023		Pronto Autoglass	INV15543	\$0.00
					4	3/10/2023		Pronto Autoglass	INV15543	\$0.00
					5	3/10/2023		HAMISH - KEETAH		\$0.00
W/ORDER	4460225	KLMS	874407 /	HRS	14555	18/01/2024	C Truck Service Completed. 2. Replace RH exhaust elbow. 3. Replace 300 B&M of exhaust stack.			\$0.00
					1	18/01/2024		HAMISH - KEETAH		\$0.00
					2	18/01/2024		HAMISH - KEETAH		\$0.00
					3	18/01/2024		HAMISH - KEETAH		\$0.00
W/ORDER	4460227	KLMS	931876 /	HRS	15534	4/06/2024	C Truck Service Completed. 2. Replace wiper blades. 3. Replace roof light. 4. Replace worn AC belt & fan belt. 5. Replace drive tyres. 6. Fit new scales etc. 7. Safety recall - C0234 Battery Cable Breakage.			\$0.00
					1	4/06/2024		HAMISH - KEETAH		\$0.00
					2	4/06/2024		HAMISH - KEETAH		\$0.00
					3	4/06/2024		HAMISH - KEETAH		\$0.00
					4	4/06/2024		HAMISH - KEETAH		\$0.00
					5	4/06/2024		OCEAN TYRES	4273083	\$0.00
					6	4/06/2024		HAMISH - KEETAH		\$0.00
					7	4/06/2024		CT Mechanical		\$0.00
W/ORDER	4460228	KLMS	967304 /	HRS	16222	4/10/2024	C Truck Service Completed. 2. Replace spot lights. 3. Replace compressor head leaking out of nipple. 4. Replace exhaust heat shield rubber mounts. 5. Drain oil, remove diff head front drive, clean, reseal & refit. 6. Replace oil, both diffs. 7. Organise ACES to check AC. 8. Replace adblue tank breather. 9. Replace diff breather.			\$0.00
					1	4/10/2024		HAMISH - KEETAH		\$0.00

	<i>Job #</i>	<i>DATE</i>	<i>MAINTENANCE TYPE</i>	<i>REPAIRER / SUPPLIER</i>	<i>INVOICE #</i>	<i>TOTAL \$</i>
	2	4/10/2024		HAMISH - KEETAH		\$0.00
	3	4/10/2024		HAMISH - KEETAH		\$0.00
	4	4/10/2024		HAMISH - KEETAH		\$0.00
	5	4/10/2024		HAMISH - KEETAH		\$0.00
	6	4/10/2024		HAMISH - KEETAH		\$0.00
	7	4/10/2024		ACES - Automative &		\$0.00
	8	4/10/2024		HAMISH - KEETAH		\$0.00
	9	4/10/2024		HAMISH - KEETAH		\$0.00
W/ORDER	4460229	KLMS 990612 / HRS 16840	9/01/2025	C Truck Service Completed. 2. Replace shockie, RH axle 2. 3. Replace 2x bolts, axle 2. (Completed by Paul Townsend)		\$0.00
	1	9/01/2025		SIMON - KEETAH		\$0.00
	2	9/01/2025		SIMON - KEETAH		\$0.00
	3	9/01/2025		SIMON - KEETAH		\$0.00
W/ORDER	4460230	KLMS 1021861 / HRS 17405	22/04/2025	C Truck Service Completed.		\$0.00
	1	22/04/2025		SIMON - KEETAH		\$0.00
D TRUCK SERVICE						10
						\$0.00
W/ORDER	447020	KLMS 111396 / HRS 1868	18/07/2018	D Service Completed		\$0.00
	1	18/07/2018		HAMISH - KEETAH		\$0.00
W/ORDER	447021	KLMS 255797 / HRS 4167	1/07/2019	D Service Completed 2. Replace Drive Shockie LH Axle 3 3. Replace Cab Shockie RH Front 4. Replace Brake Booster LH Axle 3		\$0.00
	1	1/07/2019		HAMISH - KEETAH		\$0.00
	2	1/07/2019		HAMISH - KEETAH		\$0.00
	3	1/07/2019		HAMISH - KEETAH		\$0.00
	4	1/07/2019		HAMISH - KEETAH		\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	447022	KLMS 407172 / HRS 6491	30/06/2020	D Service Completed		\$0.00
		1	30/06/2020	HAMISH - KEETAH		\$0.00
W/ORDER	447023	KLMS 549522 / HRS 8861	24/08/2021	D Truck Service Completed		\$0.00
		1	24/08/2021	SIMON - KEETAH		\$0.00
W/ORDER	447024	KLMS 673761 / HRS 10960	20/06/2022	D Truck Service Completed.		\$0.00
		1	20/06/2022	HAMISH - KEETAH		\$0.00
W/ORDER	447025	KLMS 811099 / HRS 13426	30/06/2023	D Truck Service Completed.		\$0.00
		1	30/06/2023	HAMISH - KEETAH		\$0.00
W/ORDER	447026	KLMS 931876 / HRS 15534	4/06/2024	D Truck Service Completed.		\$0.00
		1	4/06/2024	HAMISH - KEETAH		\$0.00
FAULT REPORT					6	\$0.00
W/ORDER	448020	KLMS 811099 / HRS 13426	30/06/2023	1. Banging down in front. 2. Steering going to left. 3. LH park light. 4. Mudguard bolt (front replaced by Butch but to short). 5. Cracked windscreen.		\$0.00
		1	30/06/2023	HAMISH - KEETAH		\$0.00
		2	30/06/2023	HAMISH - KEETAH		\$0.00
		3	30/06/2023	HAMISH - KEETAH		\$0.00
		4	30/06/2023	HAMISH - KEETAH		\$0.00
		5	29/06/2023	Pronto Autoglass	INV14899	\$0.00
W/ORDER	448021	KLMS 811099 / HRS 13426	30/06/2023	Indicator switch on steering wheel sometimes works by itself other times got to hold it on.		\$0.00
		1	30/06/2023	HAMISH - KEETAH		\$0.00

		Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
Repair						165	\$13,922.80
W/ORDER	449020	KLMS	2388 / HRS	40	10/08/2017	1. Move Turntable Forward	\$0.00
				1	<i>10/08/2017</i>	<i>SIMON - KEETAH</i>	<i>\$0.00</i>
W/ORDER	449021	KLMS	2388 / HRS	40	11/08/2017	Wire Drive Lights	\$0.00
				1	<i>11/08/2017</i>	<i>SIMON - KEETAH</i>	<i>\$0.00</i>
W/ORDER	449022	KLMS	5443 / HRS		17/11/2017	Mirror LED Broken - Replaced	\$0.00
				1	<i>17/11/2017</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
W/ORDER	449023	KLMS	13141 / HRS	225	14/12/2017	1. A/C Hot - Temp Repair	\$0.00
						2. Replace W/Screen Wiper Arm	
				1	<i>14/12/2017</i>	<i>R & R Rural - Mack Sublet</i>	<i>\$0.00</i>
				2	<i>14/12/2017</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
W/ORDER	449024	KLMS	39120 / HRS	706	30/01/2018	ALL WARRANTY: 1. Cab Leaning to Right 2. Hood Rubbing LH Side 3. Driver's Side Exhaust has Movement 4. Dust Getting In Cab 5. No Range for Radio 6. Repair Roof 7. Icepack - Ran Extra Wire for Icepack Autostart 8. Spot Lights Not Bright- Replaced Lamp LED	\$0.00
				1	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				2	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				3	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				4	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				5	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				6	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>
				7	<i>30/01/2018</i>	<i>MACK TRUCKS</i>	<i>\$0.00</i>

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
				8	30/01/2018		MACK TRUCKS		\$0.00
W/ORDER	449025	KLMS	47050 / HRS		2/02/2018	2 x Fit Tyres, Rotate Steers on Rims & Balance			\$0.00
				1	2/02/2018		OCEAN TYRES		\$0.00
W/ORDER	449026	KLMS	58608 / HRS	986	13/03/2018	Excessive Clutch Slip Warning Coming Up. Check & Clear All Inactive Fault Codes. Carry Out Clutch Wear Check, 25.2, Actual Wear 1mm, All Ok.			\$0.00
				1	13/03/2018		MACK TRUCKS		\$0.00
W/ORDER	449027	KLMS	81810 / HRS	1383	7/05/2018	Replace Steer Tyres - Supply & Fit			\$0.00
				1	7/05/2018		Moura Tyre Centre		\$0.00
W/ORDER	449028	KLMS	116489 / HRS	1960	2/08/2018	Rear Most Oil Filter Leaking Oil - Replaced			\$0.00
				1	2/08/2018		MACK TRUCKS		\$0.00
W/ORDER	449029	KLMS	125102 / HRS	2087	24/08/2018	Rotate Drives Front to Rear			\$0.00
				1	24/08/2018		HAMISH - KEETAH		\$0.00
W/ORDER	4490210	KLMS	131378 / HRS	2182	26/09/2018	AC Stops Working After 2-3 Mins - Replace Sensor & Control MACK WARRANTY			\$0.00
				1	26/09/2018		MACK TRUCKS		\$0.00
W/ORDER	4490211	KLMS	155270 / HRS	2566	5/11/2018	1. Check Ice Pack, No Repairs, All Good 2. 4 x Tyres Keetah Stock, 4 x Tyres Supply & Fit, Flip Steer Tyres on Rims. 4 x Axle 2 & 4 x Axle 3.			\$0.00
				1	5/11/2018		HAMISH - KEETAH		\$0.00
				2	5/11/2018		BRIDGESTONE		\$0.00
W/ORDER	4490212	KLMS	159666 / HRS		14/11/2018	Cab Fan Not Working. Faulty Blower Motor. Excess Water in Rear Housing of Fan. Blower Motor Replaced			\$0.00
				1	14/11/2019		MACK TRUCKS		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490213	KLMS	/	HRS	25/01/2019	1. Fibre Glass Repairs, Paint & Pin Stripe 2. Design & Install 2 x Bulldog & Aussie Flag Prints on Sleeper Cab			\$0.00
				1	25/01/2019		Iron Shadow		\$0.00
				2	25/01/2019		Iron Shadow		\$0.00
W/ORDER	4490214	KLMS	141750	/	HRS	2334	8/10/2018	Received Invoice 21/2/19, Work Done 8/10/18 1. AC Not Working - Replaced Compressor & Drier 2. Trailer Brake Button Won't Stay In - Realigned 3. Replace Wiper Blades x 2	\$0.00
				1	8/10/2018		MACK TRUCKS		\$0.00
				2	8/10/2018		MACK TRUCKS		\$0.00
				3	8/10/2018		MACK TRUCKS		\$0.00
W/ORDER	4490215	KLMS	205157	/	HRS	3325	8/03/2019	Fit & balance tyres x2	\$0.00
				1	8/03/2019		Hughenden Tyre Centre		\$0.00
W/ORDER	4490216	KLMS	216519	/	HRS	3504	25/03/2019	WARRANTY 1. Replace blower motor for A/C 2. Replace interior blower fan 3. Replace Leaking Fitting for Air leak at air drier.	\$0.00
				1	25/03/2019		MACK TRUCKS		\$0.00
				2	25/03/2019		MACK TRUCKS		\$0.00
				3	25/03/2019		MACK TRUCKS		\$0.00
W/ORDER	4490217	KLMS	244358	/	HRS	3998	10/06/2019	1. Replace Header Tank 2. Replace Mudflaps Rear	\$0.00
				1	10/06/2019		HAMISH - KEETAH		\$0.00
				2	10/06/2019		HAMISH - KEETAH		\$0.00
W/ORDER	4490218	KLMS	247993	/	HRS	4055	18/06/2019	Check & Replace Addblue Pump	\$0.00
				1	18/06/2019		HAMISH - KEETAH		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490219	KLMS	328740	/ HRS	5370	9/01/2020	1. Replace Cab Shock Absorber RHS 2. Replace All 3 Uni Joints on Steering Column 3. Replace Feet Pads on Turntable Both Sides 4. Replace Steering Column Boot 5. Replace Both Air Filters 6. Replace Steer Tyres - Supply & Fit		\$0.00
				1	<i>9/01/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
				2	<i>9/01/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
				3	<i>9/01/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
				4	<i>9/01/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
				5	<i>9/01/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
				6	<i>9/01/2020</i>		<i>OCEAN TYRES</i>		<i>\$0.00</i>
W/ORDER	4490220	KLMS	341843	/ HRS	5565	5/02/2020	1. Air Dryer Leaking - Replaced 2. New Ad Blue Pump Fitted		\$0.00
				1	<i>5/02/2020</i>		<i>MACK TRUCKS</i>		<i>\$0.00</i>
W/ORDER	4490221	KLMS	390127	/ HRS	6254	29/05/2020	1. Pronto - Replace RH Screen 2. Strip/Flip/ReBalance Steer Tyres - Ocean		\$0.00
				1	<i>29/05/2020</i>		<i>Pronto Autoglass</i>		<i>\$0.00</i>
				2	<i>29/05/2020</i>		<i>OCEAN TYRES</i>		<i>\$0.00</i>
W/ORDER	4490222	KLMS	393516	/ HRS	6303	9/06/2020	Supply & Fit Bull Bar - Due to Accident		\$0.00
				1	<i>9/06/2020</i>		<i>WTG (Western Truck Group)</i>		<i>\$0.00</i>
W/ORDER	4490223	KLMS	401896	/ HRS	6418	19/06/2020	1. Temp Repair - Compressor Line - Air Pipe Blown Off Compressor 2. Replace Compressor Line		\$0.00
				1	<i>18/06/2020</i>		<i>Crokers Truck Centre</i>		<i>\$0.00</i>
				2	<i>19/06/2020</i>		<i>HAMISH - KEETAH</i>		<i>\$0.00</i>
W/ORDER	4490224	KLMS	418516	/ HRS	6675	21/08/2020	Replace Bonnet (After Accident)		\$0.00
				1	<i>21/08/2020</i>		<i>WTG (Western Truck Group)</i>		<i>\$0.00</i>

			Job #		DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490225	KLMS	432379	/ HRS	6935	14/10/2020	WTG - Replace Turbo (Done by Sublet Crokers)		\$0.00
			1		14/10/2020		WTG (Western Truck Group)		\$0.00
W/ORDER	4490226	KLMS	436700	/ HRS	7016	29/10/2020	1. Replace Rear Cab Shock Absorber LH side 2. Replace Exhaust Elbow Both Sides 3. Replace Both Exhaust Flex Muffler 4. Replace Both Exhaust Elbow Clamps RH Side 5. Replace Both Exhaust Pipe Guards Mount Bushes RH Side 6. Replace Both Fuel Filters 7. Supply & Fit Steer Tyres 8. Replace Rubber between W/Screen & Bonnet		\$0.00
			1		29/10/2020		HAMISH - KEETAH		\$0.00
			2		29/10/2020		HAMISH - KEETAH		\$0.00
			3		29/10/2020		HAMISH - KEETAH		\$0.00
			4		29/10/2020		HAMISH - KEETAH		\$0.00
			5		29/10/2020		HAMISH - KEETAH		\$0.00
			6		29/10/2020		HAMISH - KEETAH		\$0.00
			7		27/10/2020		OCEAN TYRES	4238905	\$0.00
			8		29/10/2020		HAMISH - KEETAH		\$0.00
W/ORDER	4490227	KLMS		/ HRS		28/10/2020	Check Icepack Operations - Remove Suspect Harness - Make New Harness & Fit. Wire Pressure Switch Correctly.		\$0.00
			1		28/10/2020		TIM BARKER		\$0.00
W/ORDER	4490228	KLMS		/ HRS		23/11/2020	Repaired Icepack Wiring & Mirror Light Wiring		\$0.00
			1		23/11/2020		Venning Auto		\$0.00
W/ORDER	4490229	KLMS	475911	/ HRS	7660	29/01/2021	1. Adj Valves & Unit Injectors 2. Stick Stickers on Bonnet & Bug Deflector		\$0.00
			1		29/01/2021		WTG (Western Truck Group)		\$0.00
			2		29/01/2021		WTG (Western Truck Group)		\$0.00
W/ORDER	4490230	KLMS	476761	/ HRS	7672	9/02/2021	Coolant Leak from Water Pump - Water Pump Failure - Replaced		\$0.00
			1		9/02/2021		WTG (Western Truck Group)		\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490231	KLMS 481546 / HRS 7756	24/02/2021	Fault Light on Dash - Back Pressure Sensor - Replaced		\$0.00
	1	24/02/2021		WTG (Western Truck Group)		\$0.00
W/ORDER	4490232	KLMS 482830 / HRS 7776	25/02/2021	Ad Blue Fault Broken Data Link Wire		\$0.00
	1	25/02/2021		WTG (Western Truck Group)		\$0.00
W/ORDER	4490233	KLMS / HRS	5/03/2021	Check Isolator Set Up and Check Battery.		\$0.00
	1	5/03/2021		TIM BARKER		\$0.00
W/ORDER	4490234	KLMS / HRS	14/04/2021	1. Hook Up Lap Top - Check Faults 2. Strip RH Steer Axle Clean ABS Reader & Sensor - Re Fit- Test Drive 3. Re Check Faults 4. Replace Wiper Blades		\$0.00
	1	14/04/2021		HAMISH - KEETAH		\$0.00
	2	14/04/2021		HAMISH - KEETAH		\$0.00
	3	14/04/2021		HAMISH - KEETAH		\$0.00
	4	14/04/2021		HAMISH - KEETAH		\$0.00
W/ORDER	4490235	KLMS 487902 / HRS 7853	25/03/2021	1. Paint Peeling from Cab Roof 2. Back Pressure Faults - Replace Harness to Back Pressure Sensor 3. Replaced leaking Power Steer Dip Stick 4. Replace RH Front Cab Mount 5. Removed & Replaced RH Front Cab Mount 6. Removed Hood Lining & Lights Ready for Painting - Drop Truck off to be painted. Pick up & Reassembled		\$0.00
	1	25/03/2021		MACK TRUCKS		\$0.00
	2	25/03/2021		MACK TRUCKS		\$0.00
	3	25/03/2021		MACK TRUCKS		\$0.00
	4	25/03/2021		MACK TRUCKS		\$0.00
	5	25/03/2021		MACK TRUCKS		\$0.00
	6	25/03/2021		MACK TRUCKS		\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490236	KLMS	540766	/ HRS	8715	15/07/2021	Fault codes reading		\$0.00
				1	15/07/2021		<i>WTG (Western Truck Group)</i>	6006586 -	\$0.00
W/ORDER	4490237	KLMS	541450	/ HRS	8725	19/07/2021	1. Ad-Blue faults. 2. Check coolant leak & report.		\$0.00
				1	19/07/2021		<i>WTG (Western Truck Group)</i>	6302429 -	\$0.00
				2	19/07/2021		<i>WTG (Western Truck Group)</i>	6302429 -	\$0.00
W/ORDER	4490238	KLMS	546151	/ HRS		29/07/2021	Diagnose & rectify issue with oil leaking near filters.		\$0.00
				1	29/07/2021		<i>Dusty's AEM</i>	1003204	\$0.00
W/ORDER	4490239	KLMS	550203	/ HRS	8872	26/08/2021	NOX faults on dash - faulty adblue pump (no pressure built up). New pump fitted & system tested, all ok.		\$0.00
				1	26/08/2021		<i>WTG (Western Truck Group)</i>	6302685 -	\$0.00
W/ORDER	4490240	KLMS	565753	/ HRS		29/09/2021	1x Strip & Fit tyre. 2x Wheel Balances.		\$0.00
				1	29/09/2021		<i>TYREPOWER DALBY</i>	147355	\$0.00
W/ORDER	4490241	KLMS	573116	/ HRS	9295	19/10/2021	1. Replace axle 3, LH airbag. 2. Replace steer tyres.		\$0.00
				1	19/10/2021		<i>HAMISH - KEETAH</i>		\$0.00
				2	19/10/2021		<i>OCEAN TYRES</i>	4248111	\$0.00
W/ORDER	4490242	KLMS	574470	/ HRS		26/10/2021	1. Check & repair cause for ice pack to leak. 2. Check & repair cause for air leak.		\$0.00
				1	26/10/2021		<i>Kenway and Clark</i>	GZCSG44400	\$0.00
				2	26/10/2021		<i>Kenway and Clark</i>	GZCSG44400	\$0.00
W/ORDER	4490243	KLMS		/ HRS		2/12/2021	Ice Pack Repairs.		\$0.00
				1	2/12/2021		<i>TIM BARKER</i>	B11384	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490245	KLMS	594581	/ HRS	9674	10/12/2021	Rectify coolant leak.		\$0.00
				1	14/12/2021		<i>WTG (Western Truck Group)</i>	6303075 -	\$0.00
W/ORDER	4490246	KLMS	603739	/ HRS	9828	11/01/2022	1. Remove fan belts, supply & refit new belts. 2. Adjust steering wheel. 3. Remove, supply & fit new wiper blades. 4. Replace AC compressor & regas. 5. Check wiring in dash for light playing up.		\$0.00
				1	11/01/2022		<i>HAMISH - KEETAH</i>		\$0.00
				2	11/01/2022		<i>HAMISH - KEETAH</i>		\$0.00
				3	11/01/2022		<i>HAMISH - KEETAH</i>		\$0.00
				4	11/01/2022		<i>TIM BARKER</i>	B11413	\$0.00
				5	11/01/2022		<i>TIM BARKER</i>	B11413	\$0.00
W/ORDER	4490247	KLMS	626377	/ HRS	10176	22/02/2022	Breakdown - vehicle won't start.		\$0.00
				1	22/02/2022		<i>Crokers Truck Centre</i>	6851536 -	\$0.00
W/ORDER	4490248	KLMS	631802	/ HRS	10255	4/03/2022	1. Front diff pinon seal leaking. 2. PTO controller INOP. 3. Fridge not cold.		\$0.00
				1	4/03/2022		<i>WTG (Western Truck Group)</i>	6303419 -	\$0.00
				2	4/03/2022		<i>WTG (Western Truck Group)</i>	6303419 -	\$0.00
				3	4/03/2022		<i>WTG (Western Truck Group)</i>	6303419 -	\$0.00
W/ORDER	4490249	KLMS	648921	/ HRS	10518	7/04/2022	Repair AUX bar (pogo stick) electrical box.		\$0.00
				1	7/04/2022		<i>SIMON - KEETAH</i>		\$0.00
W/ORDER	4490250	KLMS	650992	/ HRS	10550	12/04/2022	PTO engaging but won't lift body.		\$0.00
				1	12/04/2022		<i>Crokers Truck Centre</i>	6851842 -	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490251	KLMS	651871	/ HRS 10565	14/04/2022	1. Clutch cylinder faults. 2. Replace LH front drive air bag. 3. Replace cab AC fan.			\$0.00
				1	14/04/2022		WTG (Western Truck Group)	6303616 -	\$0.00
				2	14/04/2022		WTG (Western Truck Group)	6303616 -	\$0.00
				3	14/04/2022		WTG (Western Truck Group)	6303616 -	\$0.00
W/ORDER	4490252	KLMS	652355	/ HRS 10579	22/04/2022	Replace drive tyres.			\$0.00
				1	22/04/2022		OCEAN TYRES	4252623	\$0.00
W/ORDER	4490253	KLMS		/ HRS	30/05/2022	1. Replace air bag on RH rear drive. 2. Adjust turntable.			\$0.00
				1	30/05/2022		Kenway and Clark	GZCSG45894	\$0.00
				2	30/05/2022		Kenway and Clark	GZCSG45894	\$0.00
W/ORDER	4490254	KLMS	669168	/ HRS	9/06/2022	Fit adblue pump (under warranty).			\$0.00
				1	9/06/2022		Andersen Truck and Tractor	R33356	\$0.00
W/ORDER	4490255	KLMS	685562	/ HRS 11122	18/07/2022	Fit new coolant pipe.			\$0.00
				1	18/07/2022		WTG (Western Truck Group)	6010487 -	\$0.00
W/ORDER	4490256	KLMS	717004	/ HRS 11693	12/10/2022	1. Test air system, found purge valve faulty. 2. Replace purge valve & test, all ok.			\$0.00
				1	12/10/2022		HAMISH - KEETAH		\$0.00
				2	12/10/2022		HAMISH - KEETAH		\$0.00
W/ORDER	4490257	KLMS	734390	/ HRS 12087	6/12/2022	Repairs to Icepack.			\$0.00
				1	6/12/2022		Butler's Mechanical	94391	\$0.00
W/ORDER	4490258	KLMS	734390	/ HRS 12087	6/12/2022	Repairs / replacement of adblue pump. ** WARRANTY **			\$0.00
				1	6/12/2022			243063	\$0.00

	Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490259	KLMS 749690 / HRS	27/01/2023	Fit safety valve.		\$0.00
	1	27/01/2023		Rod Bianchi Motors Pty Ltd	32039A	\$0.00
W/ORDER	4490260	KLMS 788212 / HRS 13016	28/04/2023	Replace coupler & hose.		\$0.00
	1	28/04/2023		Enzed Toowoomba	104926	\$0.00
W/ORDER	4490261	KLMS 790013 / HRS 13053	4/05/2023	Replace adblue pump. ** WARRANTY **		\$0.00
	1	4/05/2023		CT Mechanical	3127	\$0.00
W/ORDER	4490262	KLMS 790410 / HRS 13061	5/05/2023	Replace drive tyres.		\$0.00
	1	5/05/2023		OCEAN TYRES	4262300	\$0.00
W/ORDER	4490263	KLMS 796917 / HRS 13166	17/05/2023	Replace steer tyres.		\$0.00
	1	17/05/2023		OCEAN TYRES	4262587	\$0.00
W/ORDER	4490264	KLMS 806107 / HRS 13332	6/06/2023	1. Rectify leak at sump. 2. Rectify leak at steering pump.		\$0.00
	1	6/06/2023		WTG (Western Truck Group)	6305556 -	\$0.00
	2	6/06/2023		WTG (Western Truck Group)	6305556 -	\$0.00
	3	6/06/2023		WTG (Western Truck Group)	6305556 -	\$0.00
W/ORDER	4490265	KLMS 853926 / HRS 14176	1/11/2023	Make up lead for isolator on truck.		\$0.00
	1	1/11/2023		WSB DISTRIBUTORS	97-377004	\$0.00
W/ORDER	4490266	KLMS 856000 / HRS 14225	6/11/2023	1. Remove & replace turbo. 2. Remove after cooler, wash out with brake cleaner to remove oil, let drain overnight. 3. Refit after cooler.		\$0.00
	1	6/11/2023		Heath Transport	410271	\$0.00
	2	6/11/2023		Heath Transport	M26317	\$0.00
	3	6/11/2023		Heath Transport	M26317	\$0.00

	<i>Job #</i>	<i>DATE</i>	<i>MAINTENANCE TYPE</i>	<i>REPAIRER / SUPPLIER</i>	<i>INVOICE #</i>	<i>TOTAL \$</i>
	4	6/11/2023		Heath Transport	M26317	\$0.00
W/ORDER	4490267	KLMS 858191 / HRS	10/11/2023	Diagnose engine light, adblue fault.		\$0.00
	1	10/11/2023		DUNS BROS	323731	\$0.00
W/ORDER	4490268	KLMS 867620 / HRS 14430	5/12/2023	1. Replace air manifold on firewall. 2. Replace fan speed resistor. 3. Flip steer tyre on rim.		\$0.00
	1	5/12/2023		HAMISH - KEETAH		\$0.00
	2	5/12/2023		HAMISH - KEETAH		\$0.00
	3	5/12/2023		OCEAN TYRES	4267920	\$0.00
W/ORDER	4490269	KLMS 878946 / HRS 14640	5/02/2024	Replace steer tyres.		\$0.00
	1	5/02/2024		Moura Tyre Centre	38391	\$0.00
W/ORDER	4490270	KLMS 893351 / HRS 14860	27/02/2024	Check electrical fault with AC system, advised customer of repairs.		\$0.00
	1	27/02/2024		TOWNLEC AUTO ELECTRICAL	4635	\$0.00
W/ORDER	4490271	KLMS 898691 / HRS 14922	15/03/2024	Replace RH drive shockies x2. (Completed by Leon Perry)		\$0.00
	1	15/03/2024		SIMON - KEETAH		\$0.00
W/ORDER	4490272	KLMS 900193 / HRS 14972	18/03/2024	1. Replace 2x steering uni. 2. Replace dust boot on top steering shaft. 3. Retighten exhaust clamp under cab. 4. Replace rusty exhaust elbow, LH.		\$0.00
	1	18/03/2024		HAMISH - KEETAH		\$0.00
	2	18/03/2024		HAMISH - KEETAH		\$0.00
	3	18/03/2024		HAMISH - KEETAH		\$0.00
	4	18/03/2024		HAMISH - KEETAH		\$0.00

			Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490273	KLMS	/ HRS	3/04/2024	Replace 2x tyres.			\$0.00
			1	3/04/2024		TYREPOWER DALBY	159513	\$0.00
W/ORDER	4490274	KLMS	933829 / HRS	15580	20/06/2024	Organise WTG to carry out repairs. 1. Driver's side front axle wheel seal leaking. 2. Investigate water leak.		\$0.00
			1	20/06/2024		WTG (Western Truck Group)	6307104 -	\$0.00
			2	20/06/2024		WTG (Western Truck Group)	6307104 -	\$0.00
			3	20/06/2024		WTG (Western Truck Group)	6307104 -	\$0.00
W/ORDER	4490275	KLMS	933829 / HRS	15580	20/06/2024	Organise WTG Rockhampton to complete C0235 recall - replace power cable, battery to main switch.		\$0.00
			1	20/06/2024		WTG (Western Truck Group)	8503495 -	\$0.00
W/ORDER	4490276	KLMS	941354 / HRS	15724	5/07/2024	Replace adblue pump.		\$0.00
			1	5/07/2024		Andersen Truck and Tractor		\$0.00
W/ORDER	4490277	KLMS	955880 / HRS	16006	30/08/2024	1. Repair oil leak at back of engine. 2. Diagnose & service Icepack. 3. Replace bonnet strap. 4. Repair wiring & fit new conduit around coolant sensor.		\$0.00
			1	30/08/2024		WTG (Western Truck Group)	6307504 -	\$0.00
			2	30/08/2024		WTG (Western Truck Group)	6307504 -	\$0.00
			3	30/08/2024		WTG (Western Truck Group)	6307504 -	\$0.00
			4	30/08/2024		WTG (Western Truck Group)	6307504 -	\$0.00
W/ORDER	4490278	KLMS	962468 / HRS		16/09/2024	Breakdown, call out. Vehicle is low on power.		\$0.00
			1	16/09/2024		Andersen Truck and Tractor	R37681	\$0.00
W/ORDER	4490279	KLMS	/ HRS		12/10/2024	Vehicle not building up air.		\$0.00
			1	12/10/2024		JC MECHANICAL	INV-0472	\$0.00

				Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490280	KLMS	970339 / HRS	16292	14/10/2024	1. Check for Brake Drag 2. Strip LHS Axle 3 3. Replace Booster/Slack Adjuster/ S Cam Bushes & Seals 4. Reassemble & Test All Ok			\$0.00
				1	14/10/2024		HAMISH - KEETAH		\$0.00
				2	14/10/2024		HAMISH - KEETAH		\$0.00
				3	14/10/2024		HAMISH - KEETAH		\$0.00
W/ORDER	4490281	KLMS	980137 / HRS		12/11/2024	Replace steer tyres.			\$0.00
				1	12/11/2024		TYRERIGHT	COSI0130938	\$0.00
W/ORDER	4490282	KLMS	990561 / HRS		8/01/2025	Organise KJP to carry out Play Detection. 2. Check bearings & suspension. 3. Adjust LH rear brake.			\$231.00
				1	8/01/2025		KJP Haulage	2425 780	\$143.00
				2	8/01/2025		KJP Haulage	2425 780	\$44.00
				3	8/01/2025		KJP Haulage	2425 780	\$44.00
W/ORDER	4490283	KLMS	995784 / HRS	16959	5/02/2025	Low boost. Replace shutter valve.			\$2,410.67
				1	5/02/2025		CT Mechanical	5620	\$2,410.67
W/ORDER	4490284	KLMS	995826 / HRS	16961	6/02/2025	1. Replace intercooler. 2. Tested power & earth in 7 pin plug.			\$704.00
				1	6/02/2025		CT Mechanical	5631	\$704.00
				2	6/02/2025		CT Mechanical	5631	\$0.00
W/ORDER	4490285	KLMS	1004326 / HRS	17095	24/02/2025	1. Replace turntable pads. 2. Tighten RH rear guard pole to chassis.			\$673.68
				1	24/02/2025		LANGTREE'S MACHINERY	29524	\$673.68
				2	24/02/2025		LANGTREE'S MACHINERY	29524	\$0.00

			Job #	DATE	MAINTENANCE TYPE	REPAIRER / SUPPLIER	INVOICE #	TOTAL \$
W/ORDER	4490286	KLMS 1008232 / HRS	17150	28/02/2025	1. Replace brake booster, pos 6. 2. Adjust pos 3,4,5,6 brakes.			\$0.00
			1	28/02/2025		LANGTREE'S MACHINERY	29611	\$0.00
			2	28/02/2025		LANGTREE'S MACHINERY	29611	\$0.00
W/ORDER	4490287	KLMS 1012744 / HRS	17243	21/03/2025	Replace 4x batteries.			\$0.00
			1	21/03/2025		SIMON - KEETAH		\$0.00
W/ORDER	4490288	KLMS 1014914 / HRS	17281	28/03/2025	Replace thermostat.			\$784.30
			1	28/03/2025		WTG (Western Truck Group)	6308452 -	\$784.30
W/ORDER	4490289	KLMS 1043482 / HRS	17780	16/06/2025	Replace muffler.			\$2,385.54
			1	16/06/2025		CT Mechanical	6087	\$2,385.54
W/ORDER	4490290	KLMS 1043733 / HRS	17785	17/06/2025	CALL OUT - Inspect / repair over boosting issue.			\$4,822.93
			1	17/06/2025		CT Mechanical	6089	\$4,822.93
W/ORDER	4490291	KLMS 1045565 / HRS		11/03/2026	Run Out Fitted			\$71.00
			1	11/03/2026		THG Tires	23119	\$71.00
W/ORDER	4490292	KLMS 1045685 / HRS	17827	26/03/2026	Low Boost - Split Intercooler			\$0.00
			1	26/03/2026		WTG (Western Truck Group)		\$0.00