



DOBBS PETERBILT

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383



EXCLUSIVE CARRIER COMPANY

***** Customer Review *****
Date / Time: 12/8/2023 11:58:11AM
Repair Order: 4281
Customer: 413689
Branch: Seat
Invoice Total: \$69,621.00
Open Account - Charge
Page 1 of 6

Bill To: Hos Brothers Construction
7733 W Bostian Rd
PO Box 1788
Woodinville Outside, WA 98072
Shop: 4252363961

Ship To: Hos Brothers Construction
21820 87th Ave SE

Customer P/O:

Created By:

tdolan

Completion Date:

Unit Number: 1842

Model Year: 2015

Make/Model: Peterbilt 367

Type: Truck

VIN: 1NPTX4EX9FD277892

Meter: 372452 Miles

ECM Reading: 17161

Task: 1 521

Engine Assembly - Miscellaneous Repair

Department: Service

Complaint: Swing Engine

Cause: Old ESN: 79752094

Correction:

Inspected truck, found coolant in fuel water separator and fuel tank caved in from bottom. Established communication to ECM and collected an image, no major faults found. Customer requests engine replacement. Started engine, built up air, and pulled into shop. Drained engine oil, coolant, and power steering fluid. Connected A/C machine, found no refrigerant in system. Found A/C compressor disconnected and plug zip tied away from connector. Lines to A/C compressor look like they've been leaking and hold-down bolt for lines isn't fully seated. Removed hood, charge air pipes, fresh air pipes, upper and lower radiator pipes, fresh air plumbing, EGR crossover tube, charge and start harness, OEM wiring harness, air compressor discharge line, refrigerant lines from compressor, cooling package, fan shroud, fan hub, remaining heater hoses, OEM wiring harness, shift tower cover, shift tower, drive shaft, hydraulic pump, transmission cooler, clutch linkage, transmission, and clutch. Supported engine and removed rear motor mount bolts. Found front engine mount bolts seized in front cross member. Removed damper, front engine bracket, and front cross member. Removed engine and set up to groom new engine. Groomed engine. Removed damper for access to swap front engine mount. Removed and replaced coolant fittings. A/C line, fan hub, mega bracket, A/C compressor, alternator, starter, ECM, dipstick tube, flywheel, and rear mounting brackets. Cleaned threads on all used bolts. Pressed seized engine mounts out of front cross member. Cleaned cross member and installed with new front engine mounts. Replaced rear engine mounts and installed engine. Removed and installed fan hub and pulleys. Installed fan, shroud, radiator assembly, charge air plumbing, charge/start harness, OEM wiring harness, and A/C lines. Replaced upper and lower radiator hoses with new clamps. Installed upper and lower radiator pipes, clean air plumbing, exhaust pipe, power steering pump, fuel lines, and power steering lines. Installed hood assembly. Found coolant level sensor pins and connector damaged. Crimped new pins and installed to new connector shell. Removed passenger step, aftertreatment belly pan. Removed DPF and DOC. Removed sensors from DPF. Turned aftertreatment in to parts for cleaning. Installed clean DPF, DOC, cover and step. Removed driver and passenger mirror brackets. Removed air filter covers and replaced air filters. Installed covers and mirror brackets. Replaced fuel water separator filter. Installed new customer supplied clutch. Installed transmission, transmission cooler, coolant hoses, electrical wiring, shift tower, shift tower cover, drive shaft kits, PTO, and hydraulic pump. Filled power steering system. Filled engine with new oil and coolant. Verified transmission oil level. Firmed fuel system and started engine. Ran to build up air. Checked for leaks and topped off fluids. Reset aftertreatment maintenance and fuel injectors. Needs Road Test/QC.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Ext Price
PTBPR	05-16401	MOUNT-ENGINE FRONT	EA	2.00	27.93	55.86
SEA21	1D262	CONTACT CLEANER	EA	1.00	28.84	28.84
CUM10	2866337CUM	GASKET-CIRCULAR 5"	EA	2.00	12.91	25.82
CUM10	2871453CUM	GASKET-DPF ASSY	EA	2.00	33.12	66.24
CUM15	3163075	APEX RED (ISX) PAINT	EA	1.00	23.45	23.45
CUM10	488280CUM	GASKET-PUMP HYDRAULIC	EA	1.00	4.41	4.41
BCA10	6306LLU1C3/2E	BEARING	EA	1.00	13.93	13.93
Levin15	AMRZA734	ZEP N/C BRAKE CLNR 12/14OZ	EA	2.00	7.45	14.90
TRP	CT9444TRP	CLAMP-CONSTANT TORQUE #44	Part	8.00	6.91	55.28



DOBBS PETERBILT



3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383

*** Customer Review ***
Date / Time: 12/8/2023 11:58:11AM
Repair Order: 4281
Customer: 413689
Branch: Seat
Invoice Total: \$69,621.00
Open Account - Charge
Page 2 of 6

Ship To: Hos Brothers Construction
21820 87th Ave SE

Bill To: Hos Brothers Construction
7733 W Bostian Rd
PO Box 1788
Woodinville Outside, WA 98072
Shop: 4252363961

Customer P/O: Created By: Completion Date: Need

PTBPR D1030-2650 HOSE-RADIATOR #40 J20R1-A

DYC10 D84-1000-6061620 BELT-POLY 6 RIBS X 1620 E

TRP D84-1000-6122180 BELT-POLY 12 RIBS X 2180

TRPCT EC3501 COOLANT-TRP ELC 50/50 JUG

PTBPN F04-6006 ELBOW-RUBBER SILICONE 90D

PTBPN F50-1548 HOSE-SILICONE 2.5"

PTBPN F50-6308 EPA/HOSE-COOL 2-1/2" SIL BLUE

MMF10 HWC04428 BOLT-HEX M20-2.50X120 CL1

MMF10 HWC05722 WASHER-ROUND M20X37X4 HDN

PTBPR K169-163-20CA NUT-HEX SL NYL

M20-2.50X22.15T CAD

PACPR K37-1004 FILTER-FUEL/WATER PACCAR

Part EA 1.00 46.18 REAR ENGINE MOUNT

Automann15 M17496

SEA21 MISC PARTS

DON10 P625128 AIR FILTER RADIAL SEAL

CUM10 DR7080RXCUM ENGINE-ISX 15 13 B 600@1900

Part EA 1.00 45,682.10

Inherent 1.00 9,020.71

Misc (1.00) 300.00

Misc (4.00) (300.00)

BAKE

MISC BAKE

PACPR A22-1016-002 PLATE-MOUNTING FRONT ENGI

Part EA 1.00 13.02

PTBPR W34-1095-070 BOLT-FLANGE M16X2X70 10.9

PTBVN 12110293 CONNECTOR-3 WAY MP150 SEA

TRP CN26400 TERMINAL-F SPADE 16-20GA

TRP CN50200 SEAL-PACKARD

CUM10 3102802CUM SEAL-ORING

PTBPR SB200 CLUTCH BRAKE

TRP 9208TRP CLAMP-HOSE W/LINER #8

TRPCT EC3501 COOLANT-TRP ELC 50/50 JUG

Part JG 2.00 10.65

Part EA 2.00 21.30

SPC10 250-70-18X KIT-BEARING RETAINER

FUL10 4305294 GASKET-SHIFT LEVER HOUSIN

WUR10 10765161 USS HEX BT 5/16X1 GRD8

WUR10 140802516 FLT WASH SAE G8 YELCHROM

Part EA 6.00 1.32

Part EA 2.00 0.58

TRPFS HWC07496 1/4-20X1-1/2 TR

Part EA 1.00 3.40

MMF10 5133-50S2DB RING-RETAINING 1/2" E TYP

Part EA 1.00 4.92

MMF10 HWC03106 WASHER-ROUND 1/2X1-1/16X0

Part EA 1.00 3.82

PACPR M13-6004 BUSHING-PIN, ISOLATOR

SEA21 PCD69S-44 1/4x1/4 quik swivel

Part EA 1.00 12.11

Part EA 1.00 7.73

Part EA 1.00 3.82

Part EA 1.00 4.92

Part EA 1.00 3.40

Part EA 1.00 12.11

Part EA 1.00 7.73

Part EA 1.00 3.82

Part EA 1.00 4.92

Part EA 1.00 3.40

Part EA 1.00 12.11

Part EA 1.00 7.73

Part EA 1.00 3.82

Part EA 1.00 4.92

Part EA 1.00 3.40

Part EA 1.00 12.11



DOBBS PETERBILT



3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383

Bill To: Hos Brothers Construction
7733 W Bostian Rd
PO Box 1788
Woodinville Outside, WA 98072
Shop: 4252363961

Ship To: Hos Brothers Construction
21820 87th Ave SE

Customer P/O:

Created By: *tdolan*

Completion Date:

PACPR	RK55734	KIT-W/F SENSOR W/18" JUMP	Part	EA	1.00	82.10	82.10
CUM10	DR7080RXCUM-C	Core Group:DR0658800 D/Core	Part	EA	(1.00)	9,020.71	(9,020.71)

Task 1 Subtotals:							
Parts:						\$48,549.98	
Core Chg:						\$9,020.71	
Core Ret:						(\$9,020.71)	
Labor:						\$9,964.00	
Miscellaneous:						(\$304.00)	
Task 1 Totals:						\$58,209.98	

Task: 4 520 Fuel System - Miscellaneous Repair

Department: Service

Complaint: R&R fuel tank

Correction: Removed damaged fuel tank and straps. Drilled hole in side of old tank to remove remaining fuel and coolant from tank. Cut bung core out of old tank. Installed fittings and fuel level sender to new tank. Checked for leaks, none found. Needs GC.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Ext Price
-------	------	--------------------------	-----	----------	-------	-----------

PTBPR	11-04833-070T075U	TANK-FUEL ALUM 26" 135GAL	Part	EA	1.00	2,937.20	2,937.20
PTBPR	11-04833-070T075U-C	CORE TBRB	Inherent		1.00	454.02	454.02
PTBPN	11-04551-001P	STRAP ASSY-T BOLT 26" DIA	Part	EA	1.00	217.40	217.40
PTBPR	11-04517-45720	STRAP-RUBBER LINER 1=1 FO	Part	EA	4.00	18.05	72.20
PTBPN	11-04551-001P	STRAP ASSY-T BOLT 26" DIA	Part	EA	1.00	217.40	217.40
Tac Scr15	624-012	BLUE ABRASIVE 3" X 1/32"	Part	EA	1.00	5.84	5.84
PTBPR	11-04833-070T075U-C	CORE TBRB	Part	EA	(1.00)	454.02	(454.02)
TRP	HWC12501	NUT-HEX SL NYL M16-2.00X1	Part	EA	2.00	3.46	6.92
MMF10	HWC12514	NUT-HEX SL NYL M12-1.75X1	Part	EA	2.00	2.16	4.32
Task 4 Subtotals:							
Parts:						\$3,461.28	
Core Chg:						\$454.02	
Core Ret:						(\$454.02)	
Labor:						\$1,060.00	
Task 4 Totals:						\$4,521.28	

Task: 5 521 Engine Assembly - Miscellaneous Repair

Department: Service

Complaint: Repair Verification

Correction: Performed break-in road test and stationary regeneration. No issues found with work performed. Complete.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Ext Price
-------	------	--------------------------	-----	----------	-------	-----------

Task 5 Subtotals:							
Parts:						\$0.00	
Labor:						\$318.00	
Task 5 Totals:						\$318.00	

*** Customer Review ***
Date / Time: 12/8/2023 11:58:11AM
Repair Order: 4281
Customer: 413689
Branch: Seat
Invoice Total: \$69,621.00
Open Account - Charge
Page 3 of 6

Payment Method
Charge

Totals	Total Parts:	\$52,011.26
	Total Core Chg:	\$9,474.73
	Total Core Ret:	(\$9,474.73)
	Total EHC:	\$0.00
	Total Labor:	\$11,342.00
	Total Miscellaneous:	(\$304.00)
	Total Environmental Fee:	\$25.44
	Total Shop Supplies:	\$47.70
	Invoice Subtotal:	\$63,122.40
	Total Tax:	\$6,498.60
	Invoiced Total:	\$69,621.00

Customer P/O: Created By: Completion Date: Need: fdoian

Bill To: Hos Brothers Construction
 7733 W Bostian Rd
 PO Box 1788
 Woodinville Outside, WA 98072
 Shop: 4252363961

Ship To: Hos Brothers Construction
 21820 87th Ave SE

Customer Review
 Date / Time: 12/8/2023 11:58:11AM
 Repair Order: 4281
 Customer: 413689
 Branch: Seat
 Invoice Total: \$69,621.00
 Open Account - Charge
 Page 4 of 6

3707 Airport Way S.
 Seattle, Washington 98134
 TF: (800) 255-7383





DOBBS PETERBILT



CRANE CARRIER COMMUNITY

3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383

Bill To: Hos Brothers Construction
7733 W Bostian Rd
PO Box 1788
Woodinville Outside, WA 98072
Shop: 4252363961

Ship To: Hos Brothers Construction
21820 87th Ave SE

LIMITED WARRANTY

Customer P/O:	Created By:	Completion Date:
	folian	

THIS LIMITED WARRANTY GIVES YOU SPECIFIC LEGAL RIGHTS AND YOU MAY ALSO HAVE OTHER RIGHTS, WHICH VARY FROM STATE TO STATE. WHO IS COVERED: The Dealership issuing this invoice (the "Dealership") offers this limited warranty to only you, the customer listed on this repair order/invoice. It does not extend to any subsequent owner. It cannot be transferred to any other person.

WHAT IS COVERED: The Dealership warrants the workmanship of our labor performed in conjunction with repairs for 90 days (the "Warranty Period"). Said Warranty Period commence on the date ("Invoice Date") that the repairs are completed. The following items will void this Limited Warranty: if the failure was caused by misuse, abuse, lack of or improper maintenance, accident, alterations, overheating, and/or lack of lubrication or coolant. For any failure caused by the Dealership's workmanship (labor) covered by this Limited Warranty, the Dealership will either repair or replace such failure, at its option, in the Dealership facility.

YOUR RESPONSIBILITIES: All items must be returned to our shop with transportation charges prepaid for our inspection and determination within 60 days from the date of the sales invoice covering said items. The customer is required to return the vehicle to the Dealership or authorized repair facility at the customer's expense. You must retain copies of your Repair Orders/Invoices, and, upon request, be able to present them to us when requesting coverage under this Limited Warranty. Upon return of the vehicle to you, you must pay for any parts, labor, products, expenses, freight and taxes that the Dealership is not obligated to provide or pay for under this Limited Warranty.

WHAT IS NOT COVERED: Repairs which are still covered by a manufacturer's warranty or recall or other third party warranty/service contract. The Dealership's Limited Warranty shall be secondary to any such warranty or service contract that provides coverage for repair claims covered hereunder. Damage caused by you for failure to use manufacturer approved fluids, or the lack thereof, including but not limited to oil, antifreeze, and DEF. Any failure or damage resulting from your failure to perform maintenance in accordance with the manufacturer's recommendations; your failure to maintain appropriate fluid levels (e.g. oil, water, DEF, transmission fluid); your continued operation of the vehicle after warning light notification; modification or operation of the vehicle in a manner that is not in conformance with the manufacturer's specifications or intended use; an accident or collision; your use of improper or contaminated fluids including fuel, and/or misuse, abuse, tampering, negligence, theft, vandalism, or acts of nature or God. Parts installed and/or repairs performed on vehicles used primarily for road competition or engaging in a contest of speed or endurance of any type.

INSPECTION RIGHTS: The Dealership reserves the right to inspect the vehicle and any parts removed from or installed in the vehicle both prior to and after a repair is performed pursuant to a claim made under this Limited Warranty.

EXCLUSIVE REMEDY: The performance of labor to effect repairs is the exclusive remedy available under this written Limited Warranty. THE PERFORMANCE OF LABOR TO EFFECT REPAIRS IS YOUR SOLE AND EXCLUSIVE REMEDY AND OUR ENTIRE LIABILITY FOR ANY BREACH OF THIS LIMITED WARRANTY. OUR LIABILITY SHALL UNDER NO CIRCUMSTANCES EXCEED THE ACTUAL AMOUNT PAID BY YOU FOR THE LABOR WE SUPPLIED, NOR SHALL WE UNDER ANY CIRCUMSTANCES BE LIABLE FOR ANY CONSEQUENTIAL, INCIDENTAL, SPECIAL OR PUNITIVE DAMAGES OR LOSSES, WHETHER DIRECT OR INDIRECT.

SOME STATES DO NOT ALLOW THE EXCLUSION OR LIMITATION OF INCIDENTAL OR CONSEQUENTIAL DAMAGES, SO THE ABOVE LIMITATION OR EXCLUSION MAY NOT APPLY TO YOU.

IMPLIED WARRANTY DISCLAIMER: The only warranty on parts and products sold in conjunction with repairs performed by the manufacturer or supplier of said parts or products. Except for the limited warranty on the workmanship of our labor, the Dealership expressly disclaims all implied warranties including any implied warranties of the merchantability and fitness for a particular purpose for any period beyond the Warranty Period. WE LIMIT THE DURATION AND REMEDIES OF ALL IMPLIED WARRANTIES, INCLUDING WITHOUT LIMITATION THE WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE TO THE DURATION OF WARRANTY PERIOD.

SOME STATES DO NOT ALLOW LIMITATIONS ON HOW LONG AN IMPLIED WARRANTY LASTS, SO THE ABOVE LIMITATION MAY NOT APPLY TO YOU. NO ASSUMPTION OF LIABILITY: The Dealership does not authorize any other person to assume for it any liability in connection with the sales of any parts or products of this repair.

THE FOLLOWING APPLIES TO ALL OF OUR CUSTOMERS

STORAGE CHARGES: I understand and agree that a daily storage charge may be assessed if I fail to pick up the vehicle after being notified that the repairs have been completed. Storage charges will accrue at the rate of \$45.00 per day beginning 15 days after the repair has been completed. Storage fees will also accrue at the same charge if I fail to authorize repairs to be performed within three days after the date of communication from the Dealership. DISASSEMBLY/REASSEMBLY CHARGES: If you authorize disassembly of the vehicle or a vehicle component to provide an estimate or commencement of repairs and do not authorize completion of a repair or service, a charge will be imposed for disassembly, reassembly or partially completed work and you agree to pay the same. Such charges will be directly related to the actual amount of labor and parts involved in the inspection, repair or service. I have been advised that disassembly of the vehicle may prevent restoration of the vehicle to its prior condition.



DOBBS PETERBLIT



3707 Airport Way S.
Seattle, Washington 98134
TF: (800) 255-7383

Bill To:

Hos Brothers Construction
7733 W Bostian Rd
PO Box 1788
Woodinville Outside, WA 98072

Ship To:

Hos Brothers Construction
21820 87th Ave SE

Shop: 4252363961

Customer P/O:

Created By

Completion Date:

Need

fdolan

DELAYS AND LEGAL LIABILITY: I understand and agree that the Dealership is not responsible for any delays caused by unavailability of parts or shipping by the supplier or transporter or any losses or downtime relating to such delays, nor is it responsible for loss or damage to the vehicle or articles left in the vehicle in the event of fire, theft, or any other cause beyond its control. The Dealership will not be responsible for personal property. You and your representative agree to hold the Dealership harmless and not liable for any missing or damaged property.

WARNING: Products being sold to you can expose you to chemicals which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.

Customer Signature: _____ Date: _____

Open Account - Charge
Page 6 of 6

Invoice Total: \$69,621.00
Branch: Seat
Customer: 413689
Repair Order: 4281

Date / Time: 12/8/2023 11:58:11AM

*** Customer Review ***