

Registration 641KNL Next Service Litres

MakeFREIGHTLINERRego DueTransN/AModelPRIME MOVEREngine #AirYes

Model Series VIN 1FVYTMDB8WH937741 Cyl 0

Model Code Build Date 1998 Body PRIMEMOVER

ColourWHITEOdometer643817Prod

Invoice No.	Date	Odometer	Description	Туре
61164	01/07/2025	643817	DEFECTS	Invoice

STARTED VEHICLE AND THEN STOPPED

CHECKED FUEL SYSTEM FOUND NO FUEL IN TANKS

FILLED TANK WITH FUEL

FILLED FUEL FILTER

PRIMED SYSTEM

STARTED ENGINE

MOVED VEHICLE + THEN STOPPED AGAIN

REFILLED FUEL FILTER

FILLED WITH FUEL AND RE-STARTED

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.
PHONE THE STORE FOR PRICING ON - 07 3260 8950

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60767 01/04/2025 643751 ADJUST TURNTABLE Invoice

REMOVED TURNTABLE SKID PLATE BOLTS

MEASURED UP FOR NEW POSITION

MOVED SKID PLATE BACK TO NEW POSITION

MOUNTED PLATE WITH 4 BOLTS

DRILL 8 HOLES AND BOLT UP

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE THE STORE FOR PRICING ON - 07 3260 8950

RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP

60733 25/03/2025 643745 DEFECTS Invoice

JUMP STARTED VEHICLE WITH 2 X JUMP PACKS

PLACED VEHICLE ON CHARGE

ADJUST CLUTCH

USE TRUCK TO MOVE VEHICLE AROUND

USE TRUCK TO JUMP START ANOTHER VEHICLE

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND

Registration 641KNL Next Service Litres

MakeFREIGHTLINERRego DueTransN/AModelPRIME MOVEREngine #AirYes

Model Series VIN 1FVYTMDB8WH937741 Cyl 0

Model CodeBuild Date1998BodyPRIMEMOVER

Colour WHITE Odometer 643817 Prod

Invoice No. Date Odometer Description Type

MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950

***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE -

HEAVY VEHICLE WORKSHOP***

60581 19/02/2025 643707 REPAIR SQUEAL IN DRIVE LINE Invoice

PARKED IN WORKSHOP CHECKED FOR SQUEALING NOISE COMING FROM VEHICLE FOUND DRIVELINE PLATE HITTING CENTRE BEARING REMOVED AND REPAIRED PLATE

REFITTED TO DRIVELINE

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE THE STORE FOR PRICING ON - 07 3260 8950

60314 17/12/2024 643428 DEFECTS Invoice

REMOVED BLUE SUZI COIL REMOVED RED SUZI COIL

INSTALLED FITTINGS ON NEW COILS

INSTALLED RED COIL

INSTALLED BLUE COIL

SWAPPED ELECTRICAL PLUG ON NEW COIL

INSTALLED NEW ELECTRICAL COIL

HELPED MERV MAKE A WALKWAY PLATE FOR THE FREIGHTLINER

CHECKED RH WINDOW NOT WINDING DOWN

REPAIRED WINDOW REGULATOR

LUBRICATED CHANNELS

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE COREY FOR PRICING ON - 07 3260 8950

59828 11/09/2024 643428 CHECK ENGINE OIL Invoice

CHECK ENGINE OIL

59513 09/07/2024 643428 ATTEND TO AIR LEAK FROM RIDE Invoice

REPLACE RIGHT REAR MUDGUARD

REFIT TAILIGHT

DIAGNOSE AIR LEAK - FOUND RIDE HEIGHT VALVE UNDER TURNTABLE FAILED

REMOVED RIDE HEIGHT VALVE

FIT NEW RIDE HEIGHT VALVE AND ALL FITTINGS TO TRUCK

TESTED OPERATION - ALL OKAY

CLEAN UP OLD PARTS AND PACK AWAY TOOLS

COMPLETE PAPERWORK

REFITTED ELECTRICAL SUZI TO BACK OF CAB

Registration 641KNL Next Service Litres

MakeFREIGHTLINERRego DueTransN/AModelPRIME MOVEREngine #AirYes

Model Series VIN 1FVYTMDB8WH937741 Cyl 0

Model CodeBuild Date1998BodyPRIMEMOVERColourWHITEOdometer643817Prod

Invoice No. Date Odometer Description Type

SECURED AIRLINE AND ELECTRICAL SUZI TO REAR OF CAB

CHECKED FOR AIR LEAK - ALL OKAY

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE JEFF FOR PRICING ON - 07 3260 8950

59472 01/07/2024 643332 REPLACE BATTERY Invoice 59330 04/06/2024 643332 B SERVICE, CHECK COOLANT AND Invoice

PARK VEHICLE IN WORKSHOP

CARRY OUT B SERVICE AS PER SERVICE SHEET

CARRY OUT WALK AROUND VISUAL INSPECTION

SECURE HOIST ON TRUCK

CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS

CHECK WIPER AND WASHER OPERATION

CHECK BATTERY LEVELS, TERMINALS AND CLAMPS

LIFT CAB/BONNET TO ACCESS ENGINE BAY

REPLACE CABIN AND ENGINE AIR FILTERS

CHECK ALL BELTS AND MOUNTS

LIFT TRUCK ON HOIST

CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)

DRAIN ENGINE OIL AND CHANGE FILTER

ADJUST BRAKES AND CHECK BRAKE THICKNESSES

CHECK AND ADJUST CLUTCH IF APPLICABLE

CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CARRY OUT GREASING OF TRUCK

LOWER TRUCK

FIL ENGINE OIL AND CHECK ENGINE OIL

TOP-UP COOLANT IF REQUIRED

LOWER CAB/BONNET AND SECURE IN PLACE

FIT SERVICE STICKER

COMPLETE PAPERWORK

REMOVE HOIST

DRAINED G/BOX + DIFF OIL AND REFILLED

DRAINED AND REFILLED COOLANT

REPLACED 2 X REAR AIRBAGS

REPLACED 2 X FRONT DRIVE AXLE AIRBAGS

REPLACED SHOCKS

CHECKED FOR AIR LEAKS - ALL GOOD

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -

STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

PHONE JEFF FOR PRICING ON - 07 3260 8950

59247 22/05/2024 642983 FIT TYRES + DISPOSAL Invoice

Registration 641KNL Next Service Litres

MakeFREIGHTLINERRego DueTransN/AModelPRIME MOVEREngine #AirYes

Model Series VIN 1FVYTMDB8WH937741 Cyl 0

Model CodeBuild Date1998BodyPRIMEMOVERColourWHITEOdometer643817Prod

Invoice No. Date Odometer Description Type

REMOVE, REPLACE AND REFIT 8 NEW DRIVE TRAIN TYRES

HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD -STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950

58938 19/03/2024 642983 BRAKE BOOSTER Invoice

REPLACED LH #1 DIFF BRAKE BOOSTER

58272 06/12/2023 642537 C SERVICE Invoice

PARK VEHICLE IN WORKSHOP

CARRY OUT C SERVICE AS PER SERVICE SHEET

CARRY OUT WALK AROUND VISUAL INSPECTION

SECURE HOIST ON TRUCK

CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS

CHECK WIPER AND WASHER OPERATION

CHECK BATTERY LEVELS, TERMINALS AND CLAMPS

LIFT CAB/BONNET TO ACCESS ENGINE BAY

REPLACE CABIN AND ENGINE AIR FILTERS

CHECK ALL BELTS AND MOUNTS

LIFT TRUCK ON HOIST

CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)

DRAIN ENGINE OIL AND CHANGE FILTER

ADJUST BRAKES AND CHECK BRAKE THICKNESSES

CHECK AND ADJUST CLUTCH IF APPLICABLE

CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED

CARRY OUT GREASING OF TRUCK

LOWER TRUCK

FIL ENGINE OIL AND CHECK ENGINE OIL

TOP-UP COOLANT IF REQUIRED

LOWER CAB/BONNET AND SECURE IN PLACE

FIT SERVICE STICKER

COMPLETE PAPERWORK

REMOVE HOIST

FOUND BOTTOM HOSE ON OIL FILL PIPE LEAKING - TIGHTENED HOSE CLAMP AND DEGREASED

FOUND WINDSCREEN WASHERS NOT WORKING - FOUND HOSE HAD JUST COME OFF - RE-CONNECTED HOSE AND TESTED WASHERS - ALL GOOD

GEARBOX HAS SMALL LEAK FROM FLANGE ON LHS REAR AT THE BOTTOM

GEARDON HAS SWALL LEAR FROM FLANGE ON LITS REAL AT THE I

REAR AXLE AIRBAGS CRACKED AND PERISHED - MONITOR

2ND AXLE LHS SHOCKY WEEPING - MONITOR

TIE RODS ENDS HAVE MINOR MOVEMENT - MONITOR

FOUND OIL IN AIR TANKS AND COMING OUT OF AIR DRYER EXHAUST - COMPRESSOR MAY NEED REPLACING SOON

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

Registration 641KNL **Next Service** Litres Make **FREIGHTLINER** Rego Due **Trans** N/A Engine # Model PRIME MOVER Yes Air VIN 1FVYTMDB8WH937741 **Model Series** Cyl 0

Model Code Build Date 1998 **Body PRIMEMOVER**

Colour WHITE Odometer 643817 **Prod**

Invoice No.	Date	Odometer	Description	Туре
58220	28/11/2023	642431	CHECKED AIR CON	Invoice

CHECKED AIR CON - LIMITED / VERY LOW AIR FLOW FOUND **CLEANED OFF 90% BLOCKED EVAPORATOR CORE AS REQUIRED**

FITTED NEW POLLEN FILTER AS REQUIRED AND RECHECKED AIR CON - ALL OK

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

SPLIT COOLANT HOSE 57863 17/10/2023 Invoice

DRAIN COOLANT REMOVE SPLIT COOLANT HOSE PICK UP NEW PARTS FROM SUPPLIER FLUSH COOLANT SYSTEM TWICE

TAKE TRUCK FOR A DRIVE TO GET IT ON OPERATING TEMP

REFUELED THE TRUCK

ALL OK

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57785 10/10/2023 MARKER LIGHTS NOT WORKING Invoice

FOUND MARKER LIGHTS ON TRAILERS NOT WORKING WHEN HOOKED UP THE FREIGHTLINER PULLED APART TRAILER PLUG AND FOUND BROWN WIRE BROKEN AND CLAMP IN PLUG BROKEN CUT WIRES SHORTER AND REPLACED TRAILER PLUG **TESTED PLUG - ALL GOOD CLOSED UP WORKSHOP**

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57623 12/09/2023 6419189 REPLACED 1 X 295/80R22.5 STEER TYRE Invoice

STRIP AND FIT NEW TYRE 1 X 295/80R22.5 STEER TYRE

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE **TODAY FOR SIZING AND PRICING.**

04/09/2023 0 REPLACE LED STOP LAMP ASSEMBLY 57562 Invoice

Registration641KNLNext ServiceLitresMakeFREIGHTLINERRego DueTransN/AModelPRIME MOVEREngine #AirYesModel SeriesVIN1FVYTMDB8WH937741CvI0

Model SeriesVIN1FVYTMDB8WH937741Cyl0Model CodeBuild Date1998BodyPRIMEMOVER

Colour WHITE Odometer 643817 Prod

Invoice No. Date Odometer Description Type

REPLACE INOPERATIVE LED STOP LAMP ASSEMBLY.

REPLACE WEEPING TURBO GASKET.

REMOVED AND REPLACED TAIL LIGHT ASSEMBLY.

REMOVED AND REPLACED WEEPING TURBO GASKET.

57512 28/08/2023 0 CLUTCH ADJUSTMENT, MARKER LIGHTS Invoice

CARRIED OUT CLUTCH ADJUSTMENT

FOUND MARKER LIGHTS WEREN'T WORKING ON TRAILERS WHEN WORKSHOP FREIGHTLINER HOOKED UP TO THEM - TRACED FAULT TO BROWN WIRE COMING LOOSE IN TRAILER PLUG

RE-FIT WIRE AND TESTED - ALL OK

57318 11/07/2023 641486 A SERVICE AND REPAIRS Invoice

CARRY OUT A SERVICE AS PER SERVICE SHEET

- PARK TRAILER IN SHED
- APPLY AIR TO TRAILER
- TEST LIGHTING FUCTION
- LIFT TRAILER WITH HOIST
- CHECK WHEEL BEARINGS FOR MOVEMENT
- CHECK SUSPENSION COMPONENTS
- CHECK KING PIN BOLT TENSION
- CHECK SKID PLATE
- CHECK UNDERCARAGE OF TRAILER
- CARRY OUT GREASING OF AXLES
- CARRY OUT ADJUSTMENT OF BRAKES
- LOWER TRAILER
- CHECK WHEEL TENSION
- CHECK WHEEL BEARING GREASE FOR CONTAMINENTS
- CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
- INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE
- CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
- APPLY SERVICE STICKER
- COMPLETE PAPER WORK
- CLEAN WORK AREA
- MOVE TRAILER OUT OF WORKSHOP

CHECKED FOR AIRLEAKS @ AIRBAGS

56636 10/05/2023 0 INSPECTION AND CHECK OVER Invoice

GREASED FREIGHTLINER

CHECKED LIGHTS, TURNTABLE, FLUIDS AND VISUAL CHECKOVER OF TRUCK

TOPPED UP POWER STEERING FLUID

FOUND CAB SHOCK NEEDS REPLACING, OIL FILL PIPE LEAKING, WEEPING FROM BACK OF GEARBOX,

COOLANT IS DISCOLOURED

56123 28/02/2023 640188 A/C BLOCKED AGAIN Invoice

CHECKED A/C - BLOCKED AGAIN - WATER ON FLOOR

REMOVED FAN / BLOWER ASSEMBLY TO GAIN ACCESS TO EVAPORATOR COIL AND DRAIN PIPE TO TREAT WITH COIL CLEANER AND ALSO CLEAN OUT DRAIN TUBE / TEST OK

Registration 641KNL **Next Service** Litres Make **FREIGHTLINER** Rego Due **Trans** N/A Model Engine # PRIME MOVER Air Yes **Model Series** VIN 1FVYTMDB8WH937741 Cyl 0

Model CodeBuild Date1998BodyPRIMEMOVERColourWHITEOdometer643817Prod

Invoice No.DateOdometerDescriptionType5604420/02/2023639968A/C ISSUESInvoice

CHECKED A/C - FOUND AND CLEANED OFF 100% BLOCKED EVAPORATOR FACE / TEST - OK

RE-CHECKED A/C PRESSURES AND OPERATION - ALL OK

56011 17/02/2023 639926 LHS HEADLIGHT NEEDS A GLOBE Invoice

MADE TESTS / CHECKS TO LHS HEADLIGHT REMOVED / REPLACED U/S GLOBE - ALL OK

55730 12/01/2023 0 REPAIT PUNCTURE Invoice

BOLT IN TREAD. REMOVE BOLT AND REPAIR PUNCTURE

55693 09/01/2023 0 REPLACE TEFLON PADS Invoice

REPLACED DAMAGED TEFLON PLATES ON TURNTABLE WHEN HOOKING UP TO TRAILER REPLACED TEFLON PADS - FOUND USED/NEW PARTS ON THE SHELF. REMAINS OF OLD KITS THAT WERE FULLY CHARGED ON OTHER JOBS.

55590 22/12/2022 0 CARRY OUT REPAIRS - REPAIR Invoice

CHECKED FOR TURNTABLE FAULT

REMOVED TURNTABLE

DROVE TO BUCCINI YARD

REMOVED TURNTABLE FROM 370RGR

FITTED OLD PLATE FROM 641KNL TO 370RGR

RETURNED TO WORKSHOP

FITTED 370RGR TURNTABLE TO 641KNL

TESTED OPERATION

MOVED TURNTABLE SKID PLATE BACK 120MM

DRILLED NE HOLE IN FLANGE

TIGHTENED BOLTS

REPLACED TURNTABLE HANDLE

TESTED OPERATION

REMOVED LOCKING BAR LEVER ARM

FITTED NEW LEVER REFITTED HANDLE

ADJUSTED TURNTABLE

TESTED OPERATION - ALL OK

55569 15/12/2022 0 CARRY OUT C SERVICE Invoice 55281 04/11/2022 633811 AIR LEAK Invoice

CHECKED FOR AIR LEAKS

REPLACED AIR LINE SUZI COIL AIR COUPLINGS

TESTED OPERATION - ALL OK

53783 03/03/2022 637782 REPAIR GUARDS Invoice

3/3/2022

REPAIRED RH #2 DIFF MUDGUARD POLE

TIGHTENED MUDGUARD

STRAIGHTENED RH MARKER PLATE AND LIGHT AND LIGHT HOUSING

REMOVED BROKEN REVERSE LIGHT

CLEANED OUT INSIDE OF CAB

Registration 641KNL **Next Service** Litres Make **FREIGHTLINER** Rego Due Trans N/A Model PRIME MOVER Engine # Air Yes VIN **Model Series** 1FVYTMDB8WH937741 Cyl 0

Model Code Build Date 1998 Body

Colour WHITE Odometer 643817 Prod

Invoice No.	Date	Odometer	Description	Туре
53760	17/02/2022	637749	ENGINE SLOW TO FIRE	Invoice

PRIMEMOVER

17/2/2022

ENGINE SLOW TO FIRE 'FAULT' FOUND, LOW VOLTAGE CODE STILL PRESENT IN ECU

REPLACE CORODED ECU FUSES AND ONE SMALL TERMINAL AT POSITIVE BATTERY POST END

RECHECKED INTERMITTENT FUEL, AIR, ENGINE START/RUN ERRORS

FOUND VERY POOR FUEL SUPPLY LINE (HOSE) JUNCTION NEAR FILTER AS LEAKING AIR IN (NO VISIBLE FUEL LEAKS)

CLEANED OUT FUEL FILTER OF WATER - ABOUT 11/2 CUPS AND DEBRIS

START UP ENGINE - ALL APPEARS TO OK

53683 10/02/2022 637737 TRUCK NOT STARTING Invoice

9/2/2022

TRUCK WOULD'T START, PUT 15L OF FUEL IN TANK, TRUCK STILL WOULDN'T START

REMOVED FUEL FILTER & FILLED WITH FUEL, RE-FIT FILTER & TRIED TO START. TRUCK STARTED BUT DIED

WITHIN A COUPLE OF SECONDS. ATTACHED JUMPER CABLES TO BATTERY

TRIED PRESSURING TANK TO FORCE FUEL THROUGH, DIDN'T WORK

TOOK OFF EACH SECTION BETWEEN TANK & LIFT PUMP & PRESSURIZED TANK TO GET FUEL THROUGH EACH SECTION

RE-FILLED FUEL FILTER & STARTED TRUCK, TRUCK STAYED RUNNING

DROVE TO STRIKE FUELS TO FILL UP, TRUCK STRUGGLED TO START AND STALLED A FEW TIMES AT STRIKE

DROVE TRUCK BACK TO WORKSHOP- FOUND ONE SEAL LINER TO THE LIST PUMP HAD AN AIR LEAK

#1 FIXED, STARTED AND RAN OK

10/2/2022

REMOVED LH WHEEL ARCH COVER, TESTED FOR POWER AND FUEL SOLENOID - CHECKED OPERATION

REMOVED FUEL RETURN HOSE/PIPE ASSEMBLY AND REPLACED FUEL SOLENOID SWASH PLATE

START/STOP/RUN - ALL OK

53674 31/01/2022 0 REPLACED SUZI COILS Invoice

REMOVED AND REPLACED SUZI COILS

AIR LINE BLEW WHEN MOVING TRAILERS AROUND

53564 19/01/2022 637681 REPLACED SUZI PLUGS AND REPAIRED Invoice

INSPECTED VEHCILE FOR A/C FAULT

FOUND FUSE HOLDER MELTED

REPLACED FUSE HOLDER IN FIREWALL

REPLACED 12V RELAY AT FIREWALL

REPLACED ELECTRICAL SUZI TRAILER PLUG

53358 09/12/2021 637598 CARRY OUT C SERVICE Invoice

CARRY OUT C SERVICE ON VEHICLE

ADJUSTED BRAKES

FILLED RADIATOR WITH COOLANT AND PRIMED COOLING SYSTEM

JUMP STARTED VEHICLE FROM STARTER MOTOR

DEFECTS:

SMALL LEAK AT THE BACK OF GEARBOX

SMALL LEAK FROM FITTING ON POWER STEERING PUMP

ENGINE OIL WEEPING FROM SUMP GASKET AND POSSIBLY FILL PIPE - REQUIRES DEGREASING

53129 09/11/2021 0 FUEL UP VEHICLE Invoice

DROVE TRUCK TO STRIKE FUELS FUELLED UP VEHICLE

RETURNED TO WORKSHOP

 Registration
 641KNL
 Next Service
 Litres

 Make
 FREIGHTLINER
 Rego Due
 Trans
 N/A

 Model
 PRIME MOVER
 Engine #
 Air
 Yes

 Model Series
 Yes
 Yes
 Yes
 Yes

Model Series VIN 1FVYTMDB8WH937741 Cyl 0

Model CodeBuild Date1998BodyPRIMEMOVERColourWHITEOdometer643817Prod

Invoice No.DateOdometerDescriptionType5278131/08/20210REKIT TURNTABLEInvoice

REPAIRED TURNTABLE AND HANDLE

REMOVED TURNTABLE, WEAR RING AND TURNTABLE JAW

FITTED NEW JAW KIT

REFITTED TURNTABLE AND ADJUSTED

TESTED OPERATION - ALL OK

52716 20/08/2021 0 COOLANT FLUSH Invoice

CHECKED YARD VEHICLE OVER FOUND COOLANT BROWN AND SLUDGY

DRAINED OLD COOLANT AND FLUSHED WITH WATER

ONCE WELL FLUSHED ADDED COOLANT FLUSH TO SYSTEM

DILUTED COOLANT FLUSH WITH WATER AND RAN VEHICLE TO TEMP FOR AN HOUR

DRAINED COOLANT FLUSH AND CLEANED OUT SYSTEM WITH WATER

FILLED WITH COOLANT AND TEST DROVE

REFILLED COOLANT LEVEL - ALL OK

52235 08/06/2021 637029 CARRY OUT REPAIRS Invoice

CHECKED FUEL GUAGE INOP

FOUND TO BE PPOR TANK SENDER CONNECTIONS AND INCORRECT FLOAT STOPPER ADJUSTMENT INSIDE TANK LEVEL SENSOR

CLEANED UP ALL SENDER CONNECTIONS

ADJUSTED FLOAT STOPPER, REFIT AND TESTED ALL OK.

REPLACED AIR VALVE ASSEMBLY IN RHS OF DASH

REPLACED AIR LINE ASSEMBLY (DISCHANGE) FROM COMPRESSOR TO DRIER

INSPECTED AIR LEAK AT RETURN PIPE BETWEEN DIRER AND AIRTANK

REMOVED SECTION OF LINE DAMAGED AND REPLACED WITH NEW

CLEANED AND RESEALED FITTINGS ON AIR COMPRESSOR OUTPUT MAIN PRESSURE AND CHECKED - ALL OK

REPLACED TREDAL VALVE - LEAKING AIR

51989 30/04/2021 636943 CARRY OUT REPAIRS Invoice

CHECKED TURNTABLE HANDLE FAULT

REMOVED HANDLE AND STRAIGHTENED OUT.

REFITTED HANDLE AND TESTED OPERATION - ALL OK.

51859 09/04/2021 636919 SHACKLE PINS AND BUSHES Invoice

BROUGHT VEHICLE INTO WORKSHOP AND JACK UP.

THERE IS A LOUD CLUNK FROM THE FRONT END WHEN TURNING, FOUND THE FRONT SPRING REAR PINS AND BUSHES WERE WERE OUT.

PLACE NEW BUSHES IN FREEZER FOR EASY INSTALLATION

REMOVED STEER GUARDS AND SPRING HANGERS

REFITTED SPRING HANGER AND REPLACED SPRING EYE BUSHES

REPLACE PINS TO BUSHES

REFITTED SPRING SHACKLES AND MUDGUARDS

GREASED PIVIOTS.

TEST DROVE AND CHECKED ALL OK.

51695 17/03/2021 636764 REPLACE TRAILER PLUG Invoice

REPLACED 7 PIN ELECTRICAL PLUG BEHIND CAB

TESTED LIGHTS - OK

50996 30/11/2020 636441 AIR BRAKE VALVE Invoice

Registration 641KNL **Next Service** Litres Make **FREIGHTLINER** Rego Due **Trans** N/A Model Engine # PRIME MOVER Yes Air **Model Series** VIN 1FVYTMDB8WH937741 Cyl 0

Model Code Build Date 1998 Body

Colour WHITE Odometer 643817 Prod

Invoice No. Date Odometer Description Type

PRIMEMOVER

DATE WORK CARRIED OUT: 20/11/2020

WORK CARRIED OUT:

REMOVED AIR BRAKE VALVE AND STRIP EXISTING FITTINGS

PUT OLD FITTINGS ONTO NEW VALVE FOUND 1 OF THE FITTINGS WAS STRIPPED

REPLACED FITTING

FITTED NEW VALVE TO TRUCK AND TESTED FOR LEAKS - ALL OK

ADJUSTED REAR BRAKES

50698 20/10/2020 CARRIED OUT B SERVICE Invoice

DATE WORK CARRIED OUT: 20/10/2020

WORK CARRIED OUT:

CARRIED OUT B SERVICE AS PER HVW SERVICE SHEET.

FOUND CONTAMINATED COOLING SYSTEM

DRAINED SLUDGE FROM COOLING SYSTEM AND REFILLED WITH WATER

RAN UNTIL WARM AND REDRAINED

THE WATER WAS STILL VERY DARK BROWN

FLUSHED AGAIN AND DRAINED

REFILLED AND ADDED COOLING SYSTEM RESTORER (CLEANER)

RAN FOR 90 MINUTES AND DRAINED

FILLED COOLING SYSTEM WITH COOLANT

50392 27/08/2020 635973 REPAIRS Invoice

DATE WORK CARRIED OUT: 27/08/2020 - 31/08/2020

WORK CARRIED OUT:

CHECKED / REPAIRED LHS INTERIOR LAMP & TESTED - OK

CHECKED / REPAIRED WINDSCREEN WASHERS & TESTED - OK

CHECKED REVERSE ALARM - FOUND TO BE FAULTY UNIT,

REMOVED & REPLACED ALARM

CHECKED / REPAIRED BAD EARTH TO REAR CAB WORK LIGHTS & TESTED - OK