

Asset Serial Number	Make	Model	Sample Meter	Hour meter unit of measure	Sample Date	Fluid Sample	Lab report number	Severity	Recommendation	Hours Value	Service Meter Unit	Analysis Date
IFB00551	CAT	637E_CAT	42,000.00	h	27/03/2025 00:00	RADIATOR FRONT	T120-55094-3106	Monitor Component	Results indicate slight copper corrosion; decreasing NO2 and foaming. This may be due to air entering the cooling system. Suggest investigation of places where air entry may occur. Recommend resampling 250 hours later to monitor. For all sample information update requests please contact our EMC reception on 02 4964 5237. For technical enquiries regarding this evaluation; please contact Darren Rowley. Phone (02) 4964 5057.	42,000.00	h	10/04/2025 17:21