

# Experian AutoCheck Report

Report run: 02/03/2026 14:27:52 EST

## 2017 Ford F-150 King Ranch / Lariat / Platinum / XL / XLT

Crew Cab 4D (5.0L V8 SMPI Flex Fuel)

VIN:	1FTEW1CF8HKD47702
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	9 year(s)
Last Reported Odometer:	112,697 (11/14/2025)

Owners - 2



Vehicle Usage  
Government



### AutoCheck Score

Similar vehicles usually range between 83 and 91

#### Vehicle History at a Glance



State Title Brand



Auction Brand / Issues



Accident / Damage

Multiple Damage Events



CLEAN



NO ISSUE



MINOR



Open Recall Check



Insurance Loss / Transfer



Odometer Check

Last reported odometer:  
112,697 (11/14/2025)



NO OPEN RECALLS



NO ISSUE



NO ISSUE



Certified Pre-Owned



Service / Repair



Additional History



NO CPO INFO AVAILABLE



NO ISSUE



NO ISSUES REPORTED




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)



Accident & Damage



Airbag Deployed



Structural Damage



Overturned



Minor

Damage Date	Damage Type	Severity
03/05/2018	Collision	Minor
11/06/2018	Collision	Minor
06/02/2022	Collision	Minor
05/05/2024	Collision	Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

## Odometer Check



### Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



#### State Title Odometer Check

No issues reported



#### Auction Odometer Check

No issues reported



#### Odometer Calculation Check

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2017 Ford F-150 King Ranch / Lariat / Platinum / XL / XLT (1FTEW1CF8HKD47702) Report Run Date: 02/03/2026 14:27:52 EST

2017

### Vehicle Prep and Other Pre-Titling Events

Preparation Date: 04/2017

Event Date	Location	Odometer	Data Source	Details
04/18/2017			Independent Source	Vehicle Manufactured and Shipped to Dealer

2017

### Owner 1

Location: FL

Owned From: 05/2017

Usage: Government

Event Date	Location	Odometer	Data Source	Details
05/16/2017	FL	19	Motor Vehicle Dept.	Odometer Reading from DMV
05/16/2017	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal
05/16/2017	TAMPA, FL		Motor Vehicle Dept.	Registration Event/Renewal
05/16/2017	TAMPA, FL		Motor Vehicle Dept.	Local Government

Event Date	Location	Odometer	Data Source	Details
07/25/2017	TAMPA, FL		Motor Vehicle Dept.	Title>Title #:0127992321
03/05/2018	FL		State Agency	Left Rear Impact with Another Vehicle(Case #:9355898) Minor Damage Reported
03/08/2018	TAMPA, FL		Damage Report	Accident or Damage Reported Minor Damage Reported Left Side Damage or Repair Reported
09/06/2018			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown
09/26/2018			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 18N03 Warranty Extension - Single Repair: DOOR LATCH FREEZING CONCERNS LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown
11/06/2018	TAMPA, FL		Damage Report	Accident or Damage Reported Minor Damage Reported Right Side Damage or Repair Reported Front Damage or Repair Reported Damage or Repair to Fender Reported
06/30/2021			Manufacturer	Manufacturer Service Bulletin Mfr. Recall 20M04 Customer Satisfaction Program - Multi Repair: POWER DOOR LOCK ACTUATOR FAILURE LOCATE YOUR NEAREST AUTHORIZED <b>FORD DEALER</b> TO SCHEDULE REPAIR. Status: Remedy Unknown
06/02/2022	TAMPA, FL		Damage Report	Accident or Damage Reported Minor Damage Reported Right Side Damage or Repair Reported Damage or Repair to Grille Reported Damage or Repair to Windshield Reported
05/05/2024	FL		Police Report	Right Side Impact with Another Vehicle(Report #:L2024-00728) Vehicle Was Towed
11/14/2025	FL	112,697	Motor Vehicle Dept.	Odometer Reading from DMV

2025

## Owner 2

Location: FL

Owned From: 12/2025

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
12/29/2025	MC ALPIN, FL		Motor Vehicle Dept.	Title>Title #:0127992321

### AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### Buyback Protection Terms and Conditions

This vehicle (1FTEW1CF8HKD47702) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpters](http://www.autocheck.com/bbpters) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

### Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.