

Experian AutoCheck Report


Report run: 06/30/2026 14:15:51 EDT

2022 Ford F-150 Lariat / XL / XLT

Extended Cab 4D (5.0L V8 DI Flex Fuel)

VIN:	1FTEX1C59NKD11484
Class:	Pickup - Fullsize
Country of Assembly:	United States
Vehicle Age:	4 year(s)
Estimated In Service:	09/01/2021
Last Reported Odometer:	25 (09/20/2022)

One Owner
AutoCheck
Vehicle Usage
 Personal



AutoCheck Score

Similar vehicles usually range between 90 and 95

Vehicle History at a Glance

<p>State Title Brand</p> <p>CLEAN</p>	<p>Auction Brand / Issues</p> <p>NO ISSUE</p>	<p>Accident / Damage</p> <p>MODERATE</p>
<p>Open Recall Check</p> <p>3 OPEN RECALL(S)</p>	<p>Insurance Loss / Transfer</p> <p>NO ISSUE</p>	<p>Odometer Check</p> <p>Last reported odometer: 25 (09/20/2022)</p> <p>NO ISSUE</p>
<p>Certified Pre-Owned</p> <p>NO CPO INFO AVAILABLE</p>	<p>Service / Repair</p> <p>2 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p>Additional History</p> <p>NO ISSUES REPORTED</p>




This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)



Accident & Damage



Damage Date	Damage Type	Severity
07/18/2025	Collision	Moderate
<p>Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.</p>		

 **Open Recall Check**



Information Reported: AutoCheck found 3 open recall(s).

It is recommended that this vehicle be taken to the nearest dealer to have the recalled components replaced or fixed. Service bulletins if available are not part of open recalls and can be found in the vehicle history details.

Recall Date - 01/09/2023

Recall Type - Safety

NHTSA / OEM Recall No. - 22V842 / 22S71

Campaign Description - Safety Recall: WINDSHIELD WIPER MOTOR REPLACEMENT
Status: Remedy Available

Recall Date - 09/12/2023

Recall Type - Safety

NHTSA / OEM Recall No. - 23V509 / 23S35

Campaign Description - Safety Recall: 2021-2023 F150 SUSPECT WIRING HARNESS CHAFE TO REAR AXLE
Status: Remedy Unknown

Recall Date - 07/08/2025

Recall Type - Safety

NHTSA / OEM Recall No. - 25V455 / 25S75

Campaign Description - Safety Recall: LOW PRESSURE FUEL PUMP FAILURE
Status: Remedy Not Available

[More information](#) including remedy or risk factors. Locate your nearest authorized [Ford Dealer](#) to schedule repair.

 **Recommended Maintenance**

OEM Recommended Maintenance Schedule

Based on your vehicle's last reported mileage, these are the most recent and upcoming recommended maintenance intervals from your vehicle's manufacturer.

OEM Recommended Services

Please contact your local dealer or visit the OEM's website for details.

 **Odometer Check**



Your Vehicle Checks Out

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.



State Title Odometer Check

No issues reported



Auction Odometer Check

No issues reported



Odometer Calculation Check

No issues reported

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2022 Ford F-150 Lariat / XL / XLT (1FTEX1C59NKD11484) Report Run Date: 06/30/2026 14:15:51 EDT

2022

Vehicle Prep and Other Pre-Titling Events

Location: SC

Preparation Date: 06/2022

Event Date	Location	Odometer	Data Source	Details
06/07/2022	SC	5	Service Record	Vehicle Recall Service Performed Vehicle Detailed Promotional Service Performed
09/13/2022	SC	10	Service Record	Vehicle Detailed

2022

Owner 1

Location: IL

Owned From: 09/2022

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
09/20/2022	SC	25	Motor Vehicle Dept.	Odometer Reading from DMV Registration Event/Renewal
09/22/2022	SC		Motor Vehicle Dept.	Title(Title #:770550430932420)
01/09/2023			Manufacturer	Manufacturer Recall NHTSA Recall 22V842 / Mfr. Recall 22S71 Safety Recall: WINDSHIELD WIPER MOTOR REPLACEMENT LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Available
09/12/2023			Manufacturer	Manufacturer Recall NHTSA Recall 23V509 / Mfr. Recall 23S35 Safety Recall: 2021-2023 F150 SUSPECT WIRING HARNESS CHAFE TO REAR AXLE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Unknown
11/30/2023	SC		Motor Vehicle Dept.	Registration Event/Renewal
09/24/2024	SC		Motor Vehicle Dept.	Registration Event/Renewal
07/08/2025			Manufacturer	Manufacturer Recall NHTSA Recall 25V455 / Mfr. Recall 25S75 Safety Recall: LOW PRESSURE FUEL PUMP FAILURE LOCATE YOUR NEAREST AUTHORIZED FORD DEALER TO SCHEDULE REPAIR. Status: Remedy Not Available
07/18/2025	RICHLAND COUNTY, SC		State Agency	Right Rear Impact with Another Vehicle(Case #:25542336) Moderate Damage Reported














Unreported Event Dates

The following events have been reported to AutoCheck without a specified date.

Event Date	Location	Odometer	Data Source	Details
Unreported			Independent Source	Vehicle Manufactured and Shipped to Dealer

Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	35,881	-		36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	3 months		60 months / Unlimited miles Perforation only.
Powertrain 	59,881	3 months		60 months / 60000 miles
Roadside Assistance 	59,881	3 months		60 months / 60000 miles
Safety Restraint 	59,881	3 months		60 months / 60000 miles

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

Buyback Protection Terms and Conditions

This vehicle (1FTEX1C59NKD11484) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbpterm or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.