



## Vehicle History

### Vehicle Details

Registration	306QLB	Next Service	Litres	
Make	OPHEE	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2001

Invoice No.	Date	Odometer / Hours	Description	Type
61161	30/06/2025	150786/20469	DEFECTS	Invoice

PARK TRAILER IN WORKSHOP  
CARRY OUT A SERVICE AS PER SERVICE SHEET  
APPLY AIR TO TRAILER  
TEST LIGHTING FUNCTION  
LIFT TRAILER WITH HOIST  
CHECK WHEEL BEARINGS FOR MOVEMENT  
CHECK SUSPENSION COMPONENTS  
CHECK KING PIN BOLT TENSION  
CHECK SKID PLATE  
CHECK THE UNDERCARRIAGE OF THE TRAILER  
CARRY OUT GREASING OF AXLES  
CARRY OUT ADJUSTMENT OF BRAKES  
LOWER TRAILER  
CHECK WHEEL TENSION  
CHECK WHEEL BEARING GREASE FOR CONTAMINANTS  
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL  
INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE  
CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY  
APPLY SERVICE STICKER  
COMPLETE PAPERWORK  
CLEAN WORK AREA  
MOVE TRAILER OUT OF WORKSHOP  
NOTE  
REPAIRED SHOCK MOUNT  
CHECKED FOR AIR LEAK  
FIT REFLECTORS  
TIGHTENED RH SAFETY ROPE  
REMOVED RH #2 AXLE BROKEN SHOCK ABSORBER MOUNT + SHOCK ABSORBER  
REFIT SHOCKY AFTER REPAIR  
REPLACED #1 AXLE SERVICE BRAKE RELAY VALVE  
REPLACED AIR LINE FROM #1 AIRTANK TO #2 AIRTANK  
PARKED TRAILER AT SHED 24  
RETURN TO WORKSHOP

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950**

\*\*\*RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP\*\*\*

## Vehicle Details

Registration	306QLB	Next Service	Litres	
Make	OPHEE	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2001

Invoice No.	Date	Odometer / Hours	Description	Type
60391	13/01/2025	136997/20469	REPLACED AIR BAG	Invoice

REPLACED 2ND AXLE LHS AIR BAG  
REPLACED AIR BRAKE HOSE 2ND AXLE  
RETURN TRAILER TO SHED 24

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950**

60041	28/10/2024	129980/20469	DAMADGED TWIST LOCK	Invoice
59919	03/10/2024	120205/20469	LABOUR - BUCCINI	Invoice

REPLACED LH REAR INDICATOR INSERT  
CHECKED FOR AIR LEAKS  
SPRAYED SOAPY WATER ON VALVES AND AIR FITTINGS  
FOUND DOCK LEVELLING VALVE LEAKING  
REPLACED DOCK LEVELLING VALVE  
TESTED OPERATION - ALL OKAY  
RETURN VEHICLE TO SHED 24

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

59667	06/08/2024	98176/20469	A SERVICE AND REPAIRS	Invoice
-------	------------	-------------	-----------------------	---------

FITTED REFLECTOR TO RH REAR SIDE OF BAR  
REMOVED RH #1 AXLE, BOTH #2 AXLE, LF #3 AXLE SHOCK ABSORBER AND MOUNTING BOLT  
GROUND SHOCKY BOLT AND REWELDED TO SPRING HANGER  
MEASURED SHOCK ABSORBER STRAPS AGAINST SHOCK ABSORBERS  
INCORRECT SHOCK ABSORBERS  
REMOVED LH #1 AXLE SHOCK ABSORBER  
CUT RH #3 AXLE SHOCK ABSORBER SEIZED @ TOP MOUNTING BOLT  
OXY CUT SHOCKY SLEEVE FROM MOUNTING BOLT  
CARRY OUT A SERVICE AS PER SERVICE SHEET  
APPLY AIR TO TRAILER  
TEST LIGHTING FUNCTION  
LIFT TRAILER WITH HOIST  
CHECK WHEEL BEARINGS FOR MOVEMENT  
CHECK SUSPENSION COMPONENTS  
CHECK KING PIN BOLT TENSION  
CHECK SKID PLATE  
CHECK THE UNDERCARRIAGE OF THE TRAILER  
CARRY OUT GREASING OF AXLES  
CARRY OUT ADJUSTMENT OF BRAKES  
LOWER TRAILER  
CHECK WHEEL TENSION  
CHECK WHEEL BEARING GREASE FOR CONTAMINANTS  
CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL

**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
			INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP	

<b>59597</b>	<b>22/07/2024</b>	<b>120205/20469</b>	<b>TRAILER WILL NOT EXTEND TO 40FT</b>	<b>Invoice</b>
--------------	-------------------	---------------------	--	----------------

DROVE TO BUCCINI YARD + SHED 24 TO FIND TRAILER  
RETURNED TO WORKSHOP  
MEASURED UP TRAILER TO FIT 48FT CONTAINER  
DROVE TO BT YARD TO PLACE CONTAINER ON TRAILER  
RETURN TO WORKSHOP + PARKED TRAILER IN WORKSHOP  
REMOVED AIR RAM, AIR SWITCH AND WIRING TO TAIL LIGHTS  
REMOVED SEIZED TAIL LIGHT BAR/ EXTENSION BAR  
REMOVED RUSTEDSLIDE PLATES + SAFETY BRACKETS  
REMOVED RUST @ CHASSIS SLIDE  
CUT NEW WEAR PLATES  
RUST CONVERTED RUSTED AREA  
WELDED SIDE REAR PADS TO TRAILER  
FITTED REAR TAILLIGHT BAR/ EXTENSION BAR  
WELDED BRACKETS TO SECURE EXTENSION  
SANDED WELDS AND SLIDES  
CONNECTED WIRING TO TAIL LIGHTS  
PAINTED WELDS AT SLIDES  
SECURED JUNCTION BOX AND REFITTED NUMBER PLATE  
FITTED REAR MUDFLAPS (PLAIN) - NO BUCCINI MUDFLAPS IN STOCK  
FITTED NEW DG FLIP SIGN  
REPLACED REAR TAIL LIGHT BAR EXTENSION AIR RAM  
FITTED NEW AIR SWITCH TO REAR TWISTLOCK BEAM  
CONNECTED AIRLINES FROM VALVE TO AIR RAM  
REPLACED LEAKING AIR FITTING  
LUBRICATED EXTENSION SLIDE  
TESTED OPERATION  
REPLACED LH #3 AXLE AIR BRAKE HOSE CLAMP  
SECURED RH MARKER PLATES  
PARK TRAILER IN WORKSHOP

## Vehicle Details

Registration	306QLB	Next Service	Litres	
Make	OPHEE	Rego Due	Trans	N/A
Model	ATM OVER 4.5T	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SEMITRAILER
Colour		Odometer/Hr	Prod	2001

Invoice No.	Date	Odometer / Hours	Description	Type
<b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				

59103	18/04/2024	98176/20469	C SERVICE	Invoice
-------	------------	-------------	-----------	---------

PARK TRAILER IN WORKSHOP

CARRY OUT C SERVICE AS PER SERVICE SHEET  
 APPLY AIR TO TRAILER  
 TEST LIGHTING FUNCTION  
 LIFT TRAILER WITH HOIST  
 CHECK SUSPENSION COMPONENTS  
 CHECK KING PIN BOLT TENSION  
 CHECK SKID PLATE  
 CHECK THE UNDERCARRIAGE OF THE TRAILER  
 CARRY OUT GREASING OF AXLES  
 CARRY OUT DE-ADJUSTMENT OF BRAKES  
 REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS  
 REMOVE BEARINGS FROM HUBS  
 CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES  
 CLEAN BEARINGS IN TURBO WASH  
 CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED  
 REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS  
 INSTALL BEARINGS TO HUBS  
 INSTALL INNER HUB SEALS  
 INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS  
 SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS  
 REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS  
 CARRY OUT ADJUSTMENT OF BRAKES  
 LOWER TRAILER  
 CHECK WHEEL NUT TENSION  
 CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL  
 INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE  
 CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY  
 APPLY SERVICE STICKER  
 COMPLETE PAPERWORK  
 CLEAN WORK AREA  
 MOVE TRAILER OUT OF WORKSHOP

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

57619	13/09/2023	98176	A SERVICE + REPLACING LEG HANDLE	Invoice
-------	------------	-------	----------------------------------	---------

CARRY OUT A SERVICE AS PER SERVICE SHEET  
 PARK TRAILER IN WORKSHOP  
 APPLY AIR TO TRAILER

**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
			TEST LIGHTING FUNCTION - FOUND TRAILER SOCKET DAMAGED CARRIED OUT REPLACEMENT OF DAMAGED LIGHT SOCKET AND TESTED LIGHT FUNCTION TESTED ALL OK LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER - FOUND MULTIPLE DAMAGED AIRBAGS, CARRIED OUT REPLACEMENT OF RHR AIRBAG DUE TO CRACKING AROUND THE BELLOW, CARRIED OUT REPLACEMENT OF BOTH MIDDLE AXLE AIRBAGS DUE TO CRACKING, FOUND LH #1 SPRING DAMAGED - CARRIED OUT REMOVAL OF WHEELS ON LEFT-HAND SIDE OF AXLE, REMOVED TRAILING ARM PINS FROM LHS AND RHS ON #1 AXLE, CARRIED OUT REMOVAL OF SHOCK ABSORBERS AND LOWERED AXLE, CARRIED OUT REMOVAL OF LHS U BOLTS TO REMOVE Z SPRING AND SPRING WRAP, CARRIED OUT REPLACEMENT OF DAMAGED SPRING, FIT NEW SPRING AND SPRING WRAP INSTALL TO AXLE AND TENSION U-BOLTS, LIFT AXLE INTO POSITION AND REINSTALL TRAILING ARM PINS, AND TORQUE TRAILING ARM BOLTS, REINSTALL SHOCK ABSORBERS AND TENSION SHOCK ABSORBER BOLTS, REINSTALL LHS WHEEL AND TENSION WHEEL NUTS, RECHECK ALL BOLTS AND TORQUE TO SPECIFICATION, FOUND UPON INSPECTION OF TRAILER RIDE HEIGHT CONTROL VALVE LEAKING CARRIED OUT REPLACEMENT OF RIDE HEIGHT CONTROL VALVE AND ADJUSTED TO SUIT TESTED OPERATION TESTED ALL OK, CARRIED OUT INSPECTION OF TRAILER FOR CRACKING WELDS FOUND ON CROSS MEMBER CRACKED CARRIED OUT GRINDING OF CRACKED WELDS AND PREPARED SURFACE TO CARRY OUT WELDING REPAIRS, CARRIED OUT WELDING TO CRACKED CROSS MEMBER CLEANED WORK AREA, CLEANED WEDLED SURFACES AND PAINTED CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS - CARRIED OUT ADJUSTMENT OF LH #1 & LH # 3 WHEEL BEARINGS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY - FOUND LANDING LEG JACK HANDLE DAMAGED CARRIED OUT REPLACEMENT AND TESTED FUNCTION TESTED ALL OK, FOUND LH SAFTEY ROPE DAMAGED REMOVED OLD SAFTEY ROPE AND REPLACED SAFTEY ROPE AND SPRING TESTED ALL OK, APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP AND TRANSPORT TO SHED 24	

**HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.**

57175	10/07/2023	92062	REPLACE LHR TWISTLOCK	Invoice
REMOVE AND REPLACE LHR TWISTLOCK				

56480	19/04/2023	84298	A SERVICE	Invoice
COLLECTED TRAILER FROM BUCCINI YARD BROUGHT INTO WORKSHOP CARRIED OUT A SERVICE REPLACED 2 X RED REFLECTORS AND 1 X AMBER REFLECTOR TIGHTENED BOOSTER HOSE				

**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
TOOK TRAILER BACK TO BUCCINI YARD NOTE- RECOMMEND ALL LININGS REPLACED NEXT SERVICE (BRAKE LININGS)				
55760	17/01/2023	74459	C SERVICE AND REPAIRS	Invoice
COLLECTED TRAILER FROM SHED 24 PARKED IN WORKSHOP CARRIED OUT C SERVICE REPLACED LEFT HAND REAR MARKER LIGHT AND STRAIGHTENED PINS ON TRAILER BASE STRIPPED DOWN TRAILER FOR RE-PACK REPLACED LEAKING BRAKE BOOSTER RE-PACKED BEARINGS CLEAN HUBS AND STUB AXLES RE-ASSEMBLE HUBS AND INSTALL TO TRAILER ADJUST WHEEL BEARINGS				
55127	12/10/2022	62426	REPLACE SECTION OF AIR LINE	Invoice
REPLACED SECTION OF AIR LINE THAT HAD RUBBED THROUGH				
54687	04/08/2022	57296	CUT AND REFIT ROPE GOING THROUGH	Invoice
CUT AND REFIT ROPE GOING THROUGH THE TWIST LOCK BEAMS				
54314	08/07/2022	53198	REPAIRS - SHOCK ABSORBER AND	Invoice
FITTED 2 X TWIST LOCKS AND RE-FITTED LOOSE LIGHT HOUSING COLLECTED TRAILER FROM BUCCINI YARD AND PARKED IN THE WORKSHOP REMOVED #2 AXLE LH OLD SHOCK ABSORBER BUSHES REMOVED TOP MOUNTING BOLT TO HANGER FITTED NEW SHOCK ABSORBER, STRAP AND BRACKETS PARKED TRAILER AT SHED 24				
54297	08/06/2022	53198	CARRY OUT A SERVICE	Invoice
CARRIED OUT A SERVICE REPLACED KING PIN AND BOLT REPLACED SERVICE BRAKE AIR COUPLING REPLACED FRONT & REAR REFLECTORS				
53823	15/03/2022	47751	REPAIRS FROM SERVICE	Invoice
15/3/2022 WELDED UP CRTACKS IN REAR BAR				

**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
REMOVED BUMP STOPS AND GRINDED BUMP STOP STUDS FLAT WELDED NEW STUDS TO REAR BAR MADE NEW BUMP STOPS AND FITTED TO REAR BAR PAINTED ALL WELDS				
53755	24/02/2022	47751	A SERVICE AND REPAIRS	Invoice
24/2/2022 CARRY OUT A SERVICE WHEEL BEARINGS ADJUSTED NOTES: TAILGATE HOUSING / REAR BAR IS CRACKED MIDDLE AXLE TYRES BALD SURFACE RUST ALL OVER TRAILER REAR BAR BENT REAR BUMP STOPS U/S				
53108	08/11/2021	38391	LANDING LEGS AND REPAIRS	Invoice
INSPECT TRAILER FOR DAMAGE AFTER DEHITCHING FROM 877VAL.DIAGNOSED THAT THE TRAILER DEHITCHING WAS NOT CAUSED BY THE ANY FAULTS WITH THE TRAILER. WHEN THE TRAILER DEHITCHED IT BENT THE LEGS BACKWARDS APPROXIMATLEY 45 DEG, THIS IN TURN BENT THE LEG MOUNTING BRACKETS WHICH ARE WELDED TO THE CHASSIS RAILS. ALSO BENT WERE THE MAIN LEG SUPPORTS THAT ARE ATTACHED TO THE CHASSIS. STRIPPED OFF DAMAGED METALWORK AND LEGS. MEASURED OLD BRACKETS AND CROSS MEMBERS  CUT AGL EFOR LANDING LEG MOUNTING BRACKET DRILLED HOLES IN BRACKETS AND FABRICATED ANGLE TO FIT ON CHASSIS POSITIONED AND WELDED LANDING LEG BRACKETS WELDED CROSS BRACE CHANNEL TO MOUNTINGS WELDED SUPPORT PLATE TO CHANNEL AND DRILLED HOLES FIT NEW LANDING LEGS, FEET, HANDLE AND CROSS BAR TO TRAILER WELDED BRACKETS TO LANDING LEGS CUT ANGLE FOR SUPPORT BRACES DRILLED HOLES IN SUPPORT BRACES FITTED SUPPORT BRACES AND PAINTED SUPPORT BRACES TESTED OPERATION OF LANDING LEGS - ALL OK REMOVED AND REPLACED DAMAGED MAXI SIDE AIR FITTING REMOVED AND REPLACED DAMAGED TRAILER PLUG TESTED LIGHTING - ALL OK				
52957	29/09/2021	35309	TWIST LOCK REPAIRS	Invoice
TWIST LOCK DAMAGED ON TRAILER REMOVED BROKEN TWIST LOCK AND REPLACED WITH NEW TESTED OPERATION - ALL OK				
52842	13/09/2021	33560	CARRY OUT C SERVICE	Invoice
CARRY OUT C SERVICE FRESH GREASE ADDED TO BEARINGS - GREASE WAS CLEAN ADJUSTED WHEEL BEARINGS - ALL OK NOTE: SHOCKIE STRAPS WILL REQUIRE REPLACING NEXT SERVICE				



**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
52395	30/06/2021	29079	DAMAGED TWISTLOCK	Invoice
TRAILER CAME IN WITH A BENT TWIST LOCK HANDLE REMOVED HANDLE AND HEATED WITH OXY STRAIGHTENED HANDLE BACK INTO SHAPE REFITTED BACK TO TRAILER AND TESTED - ALL OK				
51922	19/04/2021	24076	ATTEND BREAKDOWN BRAKES STUCK	Invoice
ATTEND TO BREAKDOWN BOOSTER AIR LINE HAD POPPED OFF FITTING THAT ATTACHES TO BOOSTER AND THE HOSE CLAMP WAS BROKEN. REMOVED AND REPLACED HOSE CLAMP - TESTED FOR AIR LEAKS OK. RETURNED TO WORKSHOP				
51632	05/03/2021	20469	A SERVICE	Invoice
CARRY OUT A SERVICE  REAR AXLE LOW TREAD ON ALL 4 TYRES RUST FORMING AROUND "U" BOLT MOUNTS - NEEDS MONITORING FRONT AXLE - LHS HAS SLIGHT MOVEMENT - NEEDS MONITORING BUMP-STOP RUBBERS ON REAR OF TRAILER ARE WORN CRACKING AROUND 1ST AXLE SHOCK MOUNTING - RE-WELDED & PAINTED				
51619	25/02/2021	0	REMOVE & REFIT LH #1 & #3 AIR BAGS	Invoice
CHECKED FOR AIRBAGS NOT INFLATING FOUND LH #1 & #3 AXLE AIRBAGS RUBBING UP AGAINST TYRES REMOVED LH #1 & #3 AXLE AIRBAGS REPLACED AIRBAGS & TESTED OPERATION ALL OK				
51166	30/12/2020	14451	A SERVICE	Invoice
DATE WORK CARRIED OUT: 30/12/2020  WORK CARRIED OUT: CARRIED OUT A SERVICE  DEFECTS NOTED <ul style="list-style-type: none"><li>• AXLE OUT OF ALIGNMENT</li><li>• LH #1 &amp; #3 BEARINGS NEED ADJUSTING (SLIGHT ADJUSTMENT)</li><li>• LH FRONT REFLECTOR</li><li>• REAR REFLECTOR</li><li>• RH REAR TWISTLOCK HANDLE BENT &amp; HOUSING</li><li>• 7 PIN ELECTRICAL SOCKET NEEDS REPLACING</li></ul>				
51156	30/12/2020	14453	REPAIRS NOTED ON SERVICE	Invoice
DATE WORK CARRIED OUT: 30/12/2020				



**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
<b>WORK CARRIED OUT:</b> REMOVED RR CONTAINER LOCK PIN DISASSEMBLED & STRAIGHTENED FITTED NEW NUT, BOLT AND REASSEMBLED REMOVED F/L U BOLTS AND ROLL AXLE FORWARD TO REALIGN FRONT WHEELS TIGHTENED UP U BOLTS REMOVED F/L & L/R WHEEL BEARING CAPS ADJUSTED WHEEL BEARING TO SPEC & FITTED CAPS REPLACED REAR REFLECTORS WELDED UP AXLE REAR U BOLTS AFTER IT WAS ALIGNED & PAINTED				
50803	02/11/2020	0	REPLACE LANDING LEGS	Invoice
DATE WORK CARRIED OUT: 02/11/2020  WORK CARRIED OUT: REMOVED AND REPLACED LANDING LEGS LOOSENEED THE CROSS BRACES AND FOUND THE 2 DIAGONAL ONES WERE TOO BENT TO RE-FIT MADE UP BRACKETS & PAINTED  ASSEMBLED BRACKETS				
50776	29/10/2020	9206	ATTEND BRAKEDOWN PINKENBA	Invoice
DATE WORK CARRIED OUT: 29/10/2020  WORK CARRIED OUT: ATTEND BREAKDOWN AT PINKENBA TRAILER WASN'T BUILDING UP AIR  CONNECTED AIR COMPRESSOR FROM VAN AND PURGED THE MAXI LINE A COUPLE OF TIME AND RE-CONNECTED. TRAILER NOW BUILDS UP AIR				
50791	29/10/2020	9238	A SERVICE	Invoice
DATE WORK CARRIED OUT: 29/10/2020  WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET NOTE: LANDING LEGS ARE BENT				

**Vehicle Details**

<b>Registration</b>	306QLB	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	OPHEE	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	ATM OVER 4.5T	<b>Engine #</b>	<b>Air</b>	No
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	SEMITRAILER
<b>Colour</b>		<b>Odometer/Hr</b>	<b>Prod</b>	2001

Invoice No.	Date	Odometer / Hours	Description	Type
<b>FURTHER ACTION REQUIRED -</b>  RR TWIST LOCK BENT LANDING LEGS NEED REPLACING.				
50346	27/08/2020	54414	BREAKDOWN - LANDING LEGS	Invoice
DATE WORK CARRIED OUT: 27/08/2020  WORK CARRIED OUT: ATTEND BREAKDOWN AT DOBOY @ CANBERRA STREET LANDING LEGS HARD TO WIND UP LANDING LEGS ARE HARD TO WIND UP AS THERE IS 30 TONNE LOAD ON THE TRAILER AND THE LEGS ARE BENT/BOWED & WILL REQUIRE REPLACING				
50260	19/08/2020	4752	CARRY OUT SERVICE A & REPAIRS	Invoice
DATE WORK CARRIED OUT: 18/08/2020 - 19/08/2020  WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET TIGHTENED BOTH SAFETY ROPES ADJUST WHEEL BEARINGS REPLACED LH # 2 BRAKE BOOSTER AIR BRAKE HOSE & CLAMPS REPAIRED RH#1 AXLE LOWER SHOCK ABSORBER MOUNT REPAIRED LH #3 AXLE OUTSIDE TYRE (POSITION 9) RETENTIONED WHEEL NUTS & INFLATED TYRE REPLACED LH INNER STOP/TAIL LIGHT <b>FURTHER ACTION REQUIRED -</b>  LH #3 AXLE OUTSIDE TYRE U/S ADJUST BEARINGS				
50247	11/08/2020	4349	LANDING LEG ISSUE	Invoice
DATE WORK CARRIED OUT: 11/08/2020  WORK CARRIED OUT: TESTED OPERATION OF LANDING LEGS FOUND OPERATION NORMAL RETURNED TO WORKSHOP				