

W/O No	Asset No	Asset Description	Description	Job Type	Finished Date/Time	Downtime	Repair Time	Labour Costs	Material Costs
71	IT201	TEFCO 19m Stag Tipping A/D Service Trailer.	A/D Service was completed	PM	11/07/2016	0	0	0	31.97
278	IT201	TEFCO 19m Stag Tipping Repair / Replace Juice Lock Handle.	Fabricated new Juice lock handle	R & M	10/26/2016	1	1	0	0
547	IT201	TEFCO 19m Stag Tipping Carry out Full Brake Reline, Replace Rotors & Drums	Replaced all 4 x disc rotors on brake pads.	R Correct	12/08/2016	24	22	0	45
563	IT201	TEFCO 19m Stag Tipping A/D Service - Trailer.	A/D Service was completed.	PM	12/08/2016	2	2	0	38.22
1010	IT201	TEFCO 19m Stag Tipping A Service - Trailer		PM	03/06/2017	1.5	1.5	0	38.22
1092	IT201	TEFCO 19m Stag Tipping Rear L/H Brakes & Rotor u/s.	Inspected all brakes, removed guards & tyres. Remove caliper, hub	R & M	03/24/2017	10	9	0	0
1337	IT201	TEFCO 19m Stag Tipping A Service - Trailer		PM	07/19/2017	1.5	1.5	0	41.39
2333	IT201	TEFCO 19m Stag Tipping A Service - Trailer	A Service Completed	PM	05/28/2018	0	0	52.5	56
2662	IT201	TEFCO 19m Stag Tipping A Service - Trailer	A Service completed	PM	08/21/2018	0	0	52.5	56
3110	IT201	TEFCO 19m Stag Tipping Trailer D service	D Service completed	PM	11/26/2018	0	0	52.5	53
3516	IT201	TEFCO 19m Stag Tipping A Service - Trailer	A Service completed	PM	10/15/2018	0	0	97.5	56
3804	IT201	TEFCO 19m Stag Tipping Standard Order	Tarp on Dog need tightening	R & M	12/03/2018	0	0	32.5	0
3808	IT201	TEFCO 19m Stag Tipping Standard Order		R & M	12/03/2018	0	0	17.5	0
4354	IT201	TEFCO 19m Stag Tipping Wash Trailer		R & M	01/11/2019	0	0	273.75	24.23
4373	IT201	TEFCO 19m Stag Tipping C Service - Trailers	C Service Completed	PM	01/14/2019	0	0	727.5	117.71
4918	IT201	TEFCO 19m Stag Tipping Remove and Replace rear axle air bag.	Repair small air leaks around trailer.	R & M	02/16/2019	0	0	195	0
5212	IT201	TEFCO 19m Stag Tipping 2 x new 275/70 fitted to POS 11-12.		R & M	03/04/2019	0	0	35	0
5485	IT201	TEFCO 19m Stag Tipping Check tyre Pressures.		Tyre - S/S	03/21/2019	0	0	17.5	0
5943	IT201	TEFCO 19m Stag Tipping A Service - Trailer	A Service Completed	PM	04/23/2019	0	0	130	49
6657	IT201	TEFCO 19m Stag Tipping Tighten up mudguard poles.	Check for air leaks.	R & M	06/06/2019	0	0	35	0
7083	IT201	TEFCO 19m Stag Tipping Fit new guard on trailer		R & M	07/01/2019	0	0	30	0
7092	IT201	TEFCO 19m Stag Tipping Try to reverse trailer set over pit.	Get ben to guide him over pit. Remove airbag. Drive to Gibbs	R & M	07/01/2019	0	0	160	0
8081	IT201	TEFCO 19m Stag Tipping A Service - Trailer.	A Service Completed. Rear brake calipers on R/H/S missing spring.	PM	09/05/2019	0	0	150	8
8567	IT201	TEFCO 19m Stag Tipping C Service - Trailers	C Service Completed	PM	09/26/2019	0	0	150	61.355
10581	IT201	TEFCO 19m Stag Tipping Replace 2 x rubbed through airlines from relay valve & 2x damaged airlines from middles axle		R & M	12/13/2019	0	0	112.5	75
11527	IT201	TEFCO 19m Stag Tipping Replace king pin, Cu tout shock bolt, Look for bolt, Get Matt to pick one up.		R & M	12/30/2019	0	0	100	0
11547	IT201	TEFCO 19m Stag Tipping Clean up re-pack bearings, pick up new bolts, put capiler back on, phook up trailer set, fix light		R & M	12/31/2019	0	0	292.5	0
11552	IT201	TEFCO 19m Stag Tipping Help Matt finish trailer fix lights and park up.		R & M	12/31/2019	0	0	120	0
11610	IT201	TEFCO 19m Stag Tipping Puncture repair RHF outside check other tyre pressures.		R & M	01/17/2020	0	0	115	0
13832	IT201	TEFCO 19m Stag Tipping 4 x new 11 r Tyres		R & M	04/06/2020	0	0	130	0
13930	IT201	TEFCO 19m Stag Tipping Wash down trailer set with Ricky, Pop rivet front of tarp corner, Cut strands of tarp cable.		R & M	04/11/2020	0	0	160	25
14623	IT201	TEFCO 19m Stag Tipping Trailer D service		PM	05/06/2020	0	0	150	0
15533	IT201	TEFCO 19m Stag Tipping Clean up and grease nipples on back door,		R & M	06/17/2020	0	0	52.740276	25
20074	IT201	TEFCO 19m Stag Tipping Service done adjust wheel bearings remove and replace mudguards remove and replace brake		R & M	02/06/2021	0	0	892.5	0
20082	IT201	TEFCO 19m Stag Tipping Assit tony spooner in service and repairs.		Break	02/06/2021	0	0	425	0
22103	IT201	TEFCO 19m Stag Tipping LOAD UP SERVICE TRUCK FOR SHANE AND STRIP AND FIT 2 TYRES FOR BREAKDOWN		Wear/Tear	04/27/2021	0	0	127.5	0
22111	IT201	TEFCO 19m Stag Tipping Load up service truck ,go to breakdown ,carry out temp repairs to get trailer going replace wlf		Wear/Tear	04/27/2021	0	0	807.5	0
22206	IT201	TEFCO 19m Stag Tipping 2 NEW CONTI WHEELS PRESSURE CHECK		Wear/Tear	05/01/2021	0	0	70	0
25579	IT201	TEFCO 19m Stag Tipping Repair short in wiring right hand side		Wear/Tear	09/14/2021	0	0	170	0
25581	IT201	TEFCO 19m Stag Tipping Remove and replace mudguard remove and replace clearance lights		Scheduled	09/14/2021	0	0	297.5	0
26902	IT201	TEFCO 19m Stag Tipping Fixed 2 pcs snapped tail gate locks		DA	11/03/2021	0	0	42.5	0
28177	IT201	TEFCO 19m Stag Tipping Check valve replacement		Wear/Tear	12/30/2021	0	0	120	0

28387	IT201	TEFCO 19m Stag Tipping Rear RH indicator not working	Wear/Tear	01/12/2022	0	0	127.5	0
29115	IT201	TEFCO 19m Stag Tipping STRIP AND FIT 5 TYRES TO TRAILER	Wear/Tear	02/16/2022	0	0	212.5	0
29140	IT201	TEFCO 19m Stag Tipping Remove and re-fit mud guards so Steve could do tyres	Unsched.	02/16/2022	0	0	85	0
29462	IT201	TEFCO 19m Stag Tipping C Service - Trailers - COMPLETED	PM	02/26/2022	0	0	255	47.71
29463	IT201	TEFCO 19m Stag Tipping D service - Trailer - COMPLETED	PM	02/26/2022	0	0	255	0
29465	IT201	TEFCO 19m Stag Tipping Replace airbag rear axle RHS, Grease hoist pivots, Grease tailgate pins, replace rivets at front o	Wear/Tear	02/26/2022	0	0	297.5	170.01
30267	IT201	TEFCO 19m Stag Tipping WORN BRAKE HOSE ON REAR OF TRAILER	Wear/Tear	03/29/2022	0	0	85	9.72
32264	IT201	TEFCO 19m Stag Tipping A Service - Trailer. 1 - Needs "Do Not Overtake" & other signs replaced. 2 - Side marker lights n	PM	06/18/2022	0	0	340	22.71
36566	IT201	TEFCO 19m Stag Tipping driver complaint about air bag and mud guard to be replace	M/Request	11/10/2022	0	0	510	0
37140	IT201	TEFCO 19m Stag Tipping Trailer - C Service	PM	01/09/2023	0	0	340	0
37374	IT201	TEFCO 19m Stag Tipping Replace the front axle right hand rotor and brakes.	Wear/Tear	12/13/2022	0	0	531.25	0
37764	IT201	TEFCO 19m Stag Tipping Tyre req'd - L/H axle 1 outer	Tyres - UN	01/03/2023	0	0	99.4499915	0
37911	IT201	TEFCO 19m Stag Tipping Service Repair Work - Refer WO# 37140 for service.	Scheduled	01/10/2023	0	0	3952.5	139.32
39682	IT201	TEFCO 19m Stag Tipping tyres worn	Scheduled	03/16/2023	0	0	340	0
40257	IT201	TEFCO 19m Stag Tipping Bring over to welder bay for cracks inspection.	Scheduled	04/12/2023	0	0	170	0
40972	IT201	TEFCO 19m Stag Tipping 1 - Chassis mount - Damage Axle 2 (Hanger bracket) cracked thru. 2 - Axle 2 swing arm & bush	DA	05/26/2023	0	0	7883.75	0
41002	IT201	TEFCO 19m Stag Tipping C - D Service - Trailer	PM	10/25/2023	0	0	212.5	0
41260	IT201	TEFCO 19m Stag Tipping Service Repair Work - - stuck up rear door stopper- side light bracket	DA	07/07/2023	0	0	1126.25	0
41332	IT201	TEFCO 19m Stag Tipping Service Tyre Work - See WO# 41002 for service. Tyres req'd - Axle 2 all tyres.	Tyre - S/S	05/26/2023	0	0	170	0
44406	IT201	TEFCO 19m Stag Tipping damage to side wall	Tyres - UN	09/01/2023	0	0	127.5	0
44853	IT201	TEFCO 19m Stag Tipping Air leak - Axle 2 suspected broken air fitting. [FR 5806 - 7/10/23]	DA	09/20/2023	0	0	85	0
45780	IT201	TEFCO 19m Stag Tipping 2 axle inner-outer tyres worn out	Tyres - UN	10/25/2023	0	0	170	0
45782	IT201	TEFCO 19m Stag Tipping - RHR shock mount and bolt broken- manual drain valve broken cord- LHF mudguard straighten	MFD	10/26/2023	0	0	1020	0
45793	IT201	TEFCO 19m Stag Tipping - broken shock absorber mounting bolt	DA	10/26/2023	0	0	255	0
45810	IT201	TEFCO 19m Stag Tipping indicator light wrong ones	MFD	10/26/2023	0	0	42.5	0
45828	IT201	TEFCO 19m Stag Tipping hub's cover brokens	Unsched.	11/20/2023	0	0	170	0
46126	IT201	TEFCO 19m Stag Tipping Turntable - Remove turntable jaw block from underside of skid plate. [FR 13755 - 10/11/23]	R/Request	12/13/2023	0	0	1232.5	0
46583	IT201	TEFCO 19m Stag Tipping brackets request	R/Request	11/27/2023	0	0	510	0
47091	IT201	TEFCO 19m Stag Tipping Shock absorber - Axle 2 L/H shock absorber stuffed, causing brake lock-up. [FR 13758 - 27/12/2	Wear/Tear	01/02/2024	0	0	63.75	0
47094	IT201	TEFCO 19m Stag Tipping Tarp - Wire holding front of tarp in sail track working out on L/H side. [FR 13759 - 27/12/23]	Wear/Tear	01/04/2024	0	0	255	0
47095	IT201	TEFCO 19m Stag Tipping Lights - Some clearance lights not working. [NO positions supplied] [FR 13759 - 27/12/23]	Wear/Tear	01/03/2024	0	0	42.5	0
47205	IT201	TEFCO 19m Stag Tipping Air bag leak.	MFD	01/04/2024	0	0	340	0
47237	IT201	TEFCO 19m Stag Tipping Wheels from Rear axle L/H are tight	MFD	01/04/2024	0	0	680	0
48421	IT201	TEFCO 19m Stag Tipping A Service - Trailer	PM	01/03/2024	0	0	127.5	0
50347	IT201	TEFCO 19m Stag Tipping C/D Service - Trailer - Brisbane General Fleet	PM	05/25/2024	0	0	722.5	0
51182	IT201	TEFCO 19m Stag Tipping Brake lights - Lights operating intermittently. [FR 16067 - 20/6/24]	Wear/Tear	06/22/2024	0	0	85	0
52305	IT201	TEFCO 19m Stag Tipping Jesus. Tyre check req'd - NO Details supplied. [May be 4-6 tyres][FR 52305 - 31/7/24]	Tyres - UN	10/03/2024	0	0	170	0
52306	IT201	TEFCO 19m Stag Tipping Brake lights - Lights working intermittently. [FR ????? - 31/7/24]	Wear/Tear	08/09/2024	0	0	85	0
52426	IT201	TEFCO 19m Stag Tipping Tyres on L/H axle 1 and 2 are low tread. Outter tyre on L/H axle 2 is showing wires.	Unsched.	08/07/2024	0	0	255	0
53156	IT201	TEFCO 19m Stag Tipping A/D Service - Trailer - Brisbane General Fleet - 19/6/24	PM	10/04/2024	0	0	127.5	0
54383	IT201	TEFCO 19m Stag Tipping Suspension - Swing arm bushes need replacing. [MFD - E.M - 4/10/24] - Scheduled 2/10/24 - N	Wear/Tear	01/14/2025	0	0	1402.5	0
55734	IT201	TEFCO 19m Stag Tipping Oil leak - Hydraulic oil leaking at connection to ram. [FR 17911 - 14/11/24]	Wear/Tear	01/14/2025	0	0	85	0
56294	IT201	TEFCO 19m Stag Tipping A/D Service - Trailer - Brisbane General Fleet - [Updated 19/6/24]	PM	01/14/2025	0	0	170	0

Sum = \$31,610.94 Sum = \$1,190.57