



## Vehicle History

### Vehicle Details

Registration	556RPT	Next Service		Litres	
Make	IVECO	Rego Due		Trans	N/A
Model	STRALIS	Engine #	133360	Air	Yes
Model Series		VIN	6F2SFAT00ADT30101	Cyl	0
Model Code		Build Date	2010	Body	PRIMEMOVER
Colour	White	Odometer	506039	Prod	2010

Invoice No.	Date	Odometer	Description	Type
61127	24/06/2025	506039	DEFECTS	Invoice
REPAIR AIR LEAK ON SEAT AIR SEAT DOESNT OPERATE - NEEDS FURTHER DIAGNOSIS. ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP*** <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>				
61074	12/06/2025	504099	AIR FITTINGS	Invoice
FIT AIR FITTINGS ONTO AIR SUZIS <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				
61046	06/06/2025	500496	REPLACE SUZI COILS	Invoice
BRING TRUCK INTO WORKSHOP REMOVE OLD AIR SUZI COILS REPLACE NEW AIR SUZI COILS TESTED - ALL OKAY <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b> ***RECEIVE A \$25 DISCOUNT FOR ANY POSITIVE GOOGLE REVIEW ON OUR COMPANY GOOGLE WEBPAGE - HEAVY VEHICLE WORKSHOP***				
60582	19/02/2025	500496	DEFECTS	Invoice
JUMP START TRUCK AT SHED 24 BRING VEHICLE TO WORKSOP COMPLETE FULL CHECK OVER  FAULT LIST AS FOLLOWS: REAR U STAY WORN WINDSCREEN CHIPPED FAULT CODES ON DASH				

### Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
			BATTERY DRAINING QYUICKLY TURNTABLE NEARLY OUT OF ADJUSTMENT GEAR SELECTOR LOOSE IN HOUSING ON DASH  ADJUSTED TURNTABLE PUT BATTERIES ON CHARGE ROAD TEST RETURN TO YARD  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE THE STORE FOR PRICING ON - 07 3260 8950</u></b>	
60496	06/02/2025	500461	DEFECTS	Invoice
			COULD NOT CONNECT SCAN TOOL TO VEHICLE REMOVE DOOR CARD INSTALL WINDOW REGULATOR INSTALL DOOR CARD TEST WINDOW - ALL OKAY <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>	
60453	24/01/2025	500461	DEFECTS	Invoice
			REPLACED LEFT AND RIGHT FRONT INDICATOR JUMP START VEHICLE PUT VEHICLE ON CHARGE RETURN VEHICLE TO YARD DROVE TO BUCCINI YARD JUMP STARTED VEHICLE RETURNED TO YARD TO COLLECT KANE DROVE TO BUCCINI YARD, COLLECTED VEHICLE AND DROVE BACK TO WORKSHOP REMOVED BATTERY TERMINAL X4 LOAD TESTED BATTERIES X 4 - ALL FAILED LOCATED NEW BATTERIES DISCONNECTED X4 TERMINALS REMOVED BATTERY CLAMP X2 REMOVED BATTERY X4 FIT NEW BATTERIES X4 FIT BATTERY CLAMPS X2 FIT BATTERY TERMINALS FIT BATTERY COVER  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u></b>	

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
60184	26/11/2024	500458	DEFECTS	Invoice

CHECKED FOR OIL LIGHT ON DASH  
 CHECKED GEARSHIFT FAULT, TEST DRIVE VEHICLE  
 VEHICLE CHANGING GEARS UPWARDS MANUAL BUT NOT DOWNSHIFTING MANUALLY - GEARSHIFT STALK FAULTY  
 CHECKED FOR REAR SIDE LIGHT FAULT - TESTED WIRING AND BULBS  
 CHECKED FOR OIL LEVEL FAULT  
 DRAINED 2L OF ENGINE OIL TO BE BELOW FULL MARK  
 CHECKED FAULTS ON COMPUTER - ERASED FAULT  
 RESET COMPUTER, FAULT STILL ON DASH  
 CHECKED ALL WIRING TO SENSOR  
 OIL LEVEL NOT SHOWING ON DASH  
 JUMP STARTED VEHICLE  
 PARKED VEHCIEL IN WORKSHOP CHECKED FOR RH SEAT AIR LEAK  
 REMOVED STEERING COLUMN COVERS  
 REPLACED COMBI SWITCH/ GEARSTICK STALK  
 REPLACED BOTH FUEL FILTERS  
 CLEANED FUEL SENDER UNIT  
 FIT STEERING COLUMN PANELS  
 REPAIR SEAT AIR LEAK AND RE-ASSEMBLE SEAT  
 PARK OUTSIDE WORKSHOP

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950**

60134	13/11/2024	500362	DEFECTS	Invoice
-------	------------	--------	---------	---------

SUPPLY A/C PARTS AND FIT.  
 REPLACE COMPRESSOR, TX VALVE AND RECEIVER DRIER.  
 REPLACE A/C REFRIGERANT.  
 TEST SYSTEM UPON COMPLETION

60119	11/11/2024	500362	DEFECTS	Invoice
-------	------------	--------	---------	---------

FOUND WIPERS NOT WORKING CARRIED OUT TESTING AND FOUND NO POWER TO WIPER PUMP REMOVED AND TESTED WIPER PUMP WIPER PUMP FUNCTIONS OK, TESTED COMBINATION SWITCH FOR FUNCTION AND FOUND COMBINATION SWITCH NOT FUNCTIONING CORRECTLY REMOVED AND REFITTED NEW COMBI SWITCH, TESTED WATER SPRAYERS - ALL OKAY

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE CHRIS FOR PRICING ON - 07 3260 8950**

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
60064	31/10/2024	500362	DEFECTS	Invoice

TOPPED UP ENGINE OIL - 5L  
**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

60047	29/10/2024	499917	DIAGNOSE FUSE	Invoice
-------	------------	--------	---------------	---------

DIAGNOSE 12V NOT WORKING  
 REPLACE FUSE - AS DRIVER SHORTED  
**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

59858	27/09/2024	498562	A SERVICE & DEFECTS	Invoice
-------	------------	--------	---------------------	---------

PARK VEHICLE IN WORKSHOP  
 CARRY OUT A SERVICE AS PER SERVICE SHEET  
 CARRY OUT WALK AROUND VISUAL INSPECTION  
 SECURE HOIST ON TRUCK  
 CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
 CHECK WIPER AND WASHER OPERATION  
 CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
 LIFT CAB/BONNET TO ACCESS ENGINE BAY  
 CHECK ALL BELTS AND MOUNTS  
 LIFT TRUCK ON HOIST  
 CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
 ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
 CHECK AND ADJUST CLUTCH IF APPLICABLE  
 CHECK GEAR BOX OIL LEVEL AND QUALITY  
 CHECK DIFF OIL LEVEL AND QUALITY  
 CARRY OUT GREASING OF TRUCK  
 LOWER TRUCK  
 CHECK ENGINE OIL  
 TOP UP COOLANT IF REQUIRED  
 LOWER CAB/BONNET AND SECURE IN PLACE  
 FIT SERVICE STICKER  
 COMPLETE PAPERWORK  
 NOTE  
 RE SEALED REAR DIFF PINION SEAL  
 REPLACED LEAKING POWER STEERING SENSOR  
 DRAIN DIFF  
 REMOVE TAIL SHAFT  
 FABRICATE SOCKET TO FIT PINION NUT  
 REMOVE PINION NUT  
 REMOVE YOKE FROM PINION  
 REMOVE PINION SEAL  
 REFIT PINION SEAL + NUT  
 REFIT TAIL SHAFT  
**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND**

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
<b><u>PRICING.</u></b> <b><u>PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
59799	18/09/2024	496430	VCM FAULT	Invoice
CHECKED FOR ENGINE LIGHT FAULT ON DASH TILTED CAB REMOVED AND CLEANED FLYWHEEL SENSOR CHECKED CLUTCH ACTUATOR SCANNED COMPUTER FOR FAULTS VCM FAULT ACTIVE CHECKED BRAKE PEDAL SWITCH AND FOUND CONDENSATION FOUND WATER @ EXHAUST OF TREADLE VALVE DRAINED WATER FROM AIR TANKS REPLACED AIR TANK DRAIN VALVE + FITTED PULL CABLE REMOVED STEERING COLUMN COVERS REMOVED TREADLE VALVE FIT NEW TREADLE VALVE REFITTED STEERING COLUMN COVERS <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b> <b><u>PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
59796	18/09/2024	496430	PARTS NOT ON JOB	Invoice
PARTS NOT CHARGED TO JOB 59191				
59604	23/07/2024	493192	REPLACE DRIVERS DOOR CHECK STRAP	Invoice
COLLECTED VEHICLE FROM BT YARD DOSCONNECTED TRAILER AND PARKED VEHICLE IN WORKSHOP REPLACED RH DOOR ARRESTER BRACKET LUBRICATED HINGES AND LATCHES CHECKED ALL LIGHTS RETURNED VEHICLE TO BUCCINI YARD CONNECTED TO TRAILER  <b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b> <b><u>PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				
59371	11/06/2024	489332	C SERVICE	Invoice
PARK VEHICLE IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET CARRY OUT WALK AROUND VISUAL INSPECTION SECURE HOIST ON TRUCK CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS CHECK WIPER AND WASHER OPERATION CHECK BATTERY LEVELS, TERMINALS AND CLAMPS LIFT CAB/BONNET TO ACCESS ENGINE BAY REPLACE CABIN AND ENGINE AIR FILTERS				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
			CHECK ALL BELTS AND MOUNTS LIFT TRUCK ON HOIST CARRY OUT VISUAL INSPECTION OF UNDERCARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS) DRAIN ENGINE OIL AND CHANGE FILTER ADJUST BRAKES AND CHECK BRAKE THICKNESSES CHECK AND ADJUST CLUTCH IF APPLICABLE CHECK GEARBOX OIL LEVEL AND QUALITY REPLACE IF REQUIRED CHECK DIFF OIL LEVEL AND QUALITY REPLACE IF REQUIRED CARRY OUT GREASING OF TRUCK LOWER TRUCK FIL ENGINE OIL AND CHECK ENGINE OIL TOP-UP COOLANT IF REQUIRED LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK REMOVE HOIST	
			COLLECTED VEHICLE FROM BUCCINI YARD, DISCONNECTED TRAILER AND PARKED VEHICLE IN WORKSHOP CARRIED OUT C SERVICE - AS ABOVE ENGINE OIL AND FILTERS CHANGED TIGHTENED RADIATOR HOSE CLAMPS REPLACED AIR FILTER REPLACED VGT FILTER REPLACED TRANSMISSION OIL REPLACED #1 DIFF OIL REPLACED #2 DIFF OIL AND FOUND METAL ON FRAIN BUNG REPLACED RH SEAT BELT BUCKLE REPLACED P/STEERING FILTER REPLACED AMBER REFLECTORS ON FUEL TANK CLEANED AROUND #1 DIFF HOUSING CHECKED FOR OIL LEAK AND FOUND TOP MOUNTING BOLTS LOOSE, TIGHTENED BOLTS AND CLEANED DIFF REPLACED BRAKE PEDAL RUBBER REPLACED R/H YELLOW SIDE LIGHT REPLACED 3X WEDGE PARK LIGHT GLOBES FOUND L/H INNER FOG LIGHT INOP, PLUGGED IN AND TESTED - ALL OKAY FILLED #2 DIFF WITH OIL FITTED TREAD PLATE TILT CAB REMOVE POWER STEERING RESERVOIR REMOVE FUEL LINES FROM PUMP REMOVE FUEL PUMP REMOVE 2 FUEL LINES FIT NEW FUEL LINES FIT NEW FUEL PUMP FIT LINES TO PUMP FIT RESERVOIR BLEED FUEL SYSTEM AND START TRUCK BRING CAB DOWN CLEAN TOOLS AND AREA FITTED NEW BATTERY COVER REPLACED WIPER BLADES REPLACED FRONT GRILL GAS STRUTS FITTED NEW FAN CONTROL KNOB REPLACED RH SEAT CUSHION REPLACED CABIN AIRFLOW DIRECTIONAL KNOB	

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
			REPLACED STEERING WHEEL FITTED BOLT TO OIL FILTER HOUSING REPLACED ROCKER COVER GASKET SECURED HOSES AT ENGINE DRAINED #2 DIFF OIL, REMOVED AXLES AND AIR LINKS REMOVED DIFF CENTRE CLEANED ALL SURFACES REPLACED TURNTABLE KIT AND TEFLON PADS ADJUSTED TURNTABLE REMOVED LH #2 DIFF MUDGUARD + TAIL LIGHT BRACKET REPLACED LH TAILLIGHT BRACKET REPLACED LH REAR MUDGUARD + PLASTIC HANGING BRACKETS ATTEMPTED TO FIT NEW MUFFLER EXHAUST PIPE REMOVED BROKEN EXHAUST PIPE AND CLAMP REQUIRES SUPPORT BRACE REMOVED #2 DIFF BRAKE BOOSTER AIRLINES AND BRACKETS CLEANED DIFF STUD AND FITTED TO HOUSING FITTED AND SEALED DIFF CENTRE FITTED AXLES, AIR LINES AND ELECTRICAL PLUG SECURED AIRLINES AND WIRING FILLED DIFF WITH OIL RESET AIRBAGS FITTED EXHAUST PIPE AND BRACKET TO MUDFLAP REPAIRED AIR LEAK AT RH AIR TANK TEST DROVE VEHICLE ENGINE OIL LEVEL LIGHT ON DASH DRAINED 2L OF ENGINE OIL AND LIGHT STILL ON DASH	
<b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				

<b>59335</b>	<b>04/06/2024</b>	<b>488224</b>	<b>CHECK AND REPORT ON OIL LIGHT AND</b>	<b>Invoice</b>
			CHECKED FOR ENGINE LIGHT FAULT ON DASH RAISED CAB AND CHECK OIL LEVEL TOPPED UP ENGINE OIL LOWERED CAB CHECKED FOR LIGHT FAULT REPLACED RH REAR REVERSE LIGHT BULB CLEANED AREA COMPLETED PAPERWORK	
<b><u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES &amp; MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u></b>				



## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
59191	09/05/2024	484819	REPAIR DRIVERS SEAT HEIGHT CONTROL	Invoice

DROVE TO BUCCINI YARD  
 CHECKED FOR SEAT FAULT  
 REMOVED SEAT CUSSION  
 FOUND AIRLINE DISCONNECTED  
 REFITTED SEAT  
 UNHOOKED TRAILER  
 RETURNED TO WORKSHOP WITH VEHICLE  
 PARKED IN SHED  
 REMOVED SEAT CUSSION  
 DRIVER REPORTED BATTERY LIGHT WAS ON  
 CHECKED BATTERY - ALL OKAY  
 CHECKED CHARGING SYSTEM FOR ANY OBVIOUS FAULTS - NIL FOUND

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

59059	09/04/2024	482651	BROKEN TAIL LIGHT	Invoice
-------	------------	--------	-------------------	---------

REMOVED BROKEN TAIL LIGHTS  
 RE-FIT LIGHTS WITH NEW LENSES  
 TESTD LIGHTS - RHS REVERSE LIGHT DIDN'T WORK  
 REPLACED BLOWN BULB ON RHS REVERSE - STILL DIDN'T WORK  
 RETURNED VEHICLE TO BUCCINI YARD

**HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950**

58893	13/03/2024	480066	A SERVICE	Invoice
-------	------------	--------	-----------	---------

COLLECT TRUCK FROM BT YARD  
 PARK VEHICLE IN WORKSHOP  
 CARRY OUT A SERVICE AS PER SERVICE SHEET  
 CARRY OUT WALK AROUND VISUAL INSPECTION  
 SECURE HOIST ON TRUCK  
 CHECK ALL LIGHTS INCLUDING ALL REVERSE LAMPS AND BEEPERS  
 CHECK WIPER AND WASHER OPERATION  
 CHECK BATTERY LEVELS, TERMINALS AND CLAMPS  
 LIFT CAB/BONNET TO ACCESS ENGINE BAY  
 CHECK ALL BELTS AND MOUNTS  
 LIFT TRUCK ON HOIST  
 CARRY OUT VISUAL INSPECTION OF UNDER CARRIAGE (DRIVE LINE AND SUSPENSION COMPONENTS)  
 ADJUST BRAKES AND CHECK BRAKE THICKNESSES  
 CHECK AND ADJUST CLUTCH IF APPLICABLE  
 CHECK GEAR BOX OIL LEVEL AND QUALITY  
 CHECK DIFF OIL LEVEL AND QUALITY  
 CARRY OUT GREASING OF TRUCK  
 LOWER TRUCK  
 CHECK ENGINE OIL  
 TOP UP COOLANT IF REQUIRED



## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
<p>LOWER CAB/BONNET AND SECURE IN PLACE FIT SERVICE STICKER COMPLETE PAPERWORK *****</p> <p>FILLED WASHER BOTTLE TO TEST WASHERS - STILL DIDN'T WORK DRIVERS SIDE SEAT BELT HOUSING MISSING TIE ROD ENDS HAVE A LITTLE MOVEMENT - MONITOR EXHAUST TAIL PIPE BROKEN OFF POWER STEERING RESERVOIR LEAKING - MONITOR WINDSCREEN WASHERS NOT WORKING</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58682	13/02/2024	477416	REPLACE SUZI COILS	Invoice
<p>REPLACE SUZI COILS UNTANGLE AND REFIT NEW SUZI COILS TO TRUCK COL RANG AND SAID THEY HAD BEEN RIPPED OUT AGAIN, REFIT ANOTHER SET ALL OK *****REPLACED INTERIOR LIGHT BULB</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58722	13/02/2024	477416	REPLACE INTERIOR LIGHT	Invoice
<p>BROUGHT TRUCK INTO WORKSHOP REPLACED INTERIOR LIGHT BULB</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58723	12/02/2024	477163	TRAVEL TO MEDLOG CONTAINER PARK	Invoice
<p>TRAVELLED TO MEDLOG CONTAINER PARK PORT OF BRISBANE REPLACED BROKEN SUZI COILS TRAVELLED BACK TO THE WORKSHOP</p> <p><b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b></p>				
58642	06/02/2024	472947	STRIP AND FIT 6 X NEW TYRES	Invoice
<p>STRIP AND FIT 6 NEW TYRES TENSION WHEEL NUTS AND REMOVE STANDS</p>				

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58544	23/01/2024	472947	RIDE HEIGHT CONTROL ROD ASSEMBLY	Invoice
DROVE TO BUCCINI YARD REPLACED RIDE HEIGHT ROD ZIP TIED RIGHT HEIGHT VALVE ROD TOGETHER AS THE BALL JOINT WQAS BROKEN <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58468	11/01/2024	472947	NO AIR GETTING TO THE TRAILER.	Invoice
DROVE TO SHED 24 CHECKED VEHICLE FOR NOT RELEASING BRAKES ON TRAILER FOUND AIRLINE SUZI COILS CRIMPED OFF DISCONNECTED TRAILER DROVE TRAILER TO WORKSHOP BROUGHT VEHICLE INTO THE WORKSHOP REPLACED AIRLINE SUZI COILS AND AIR COUPLING SECURED AIRLINE AND ELECTRICAL SUZI COILS TO POGO STCK REPLACED RH TAIL LIGHT LENSE - BROKEN CHECKED FOR TRAILER LOW AIR SUPPLY FAULT LIGHT ON DASH REPLACED AIR FITTING AT TRAILER VALVE REPLACED AIR PRESSURE SWITCH AT TRAILER VALVE CHECKED FOR RH SEAT NOT WORKING SHORTENED AIRLINE UNDER SEAT AS HOSE WAS CRIMPED RE-FITTED TREAD PLATE REPLACED CAB SHOCK - ALL OK TOOK VEHICLE BACK AT SHED 24  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58402	27/12/2023	471962	REPLACED R/H LOW HEADLIGHT GLOBE	Invoice
REPLACED R/H LOW HEADLIGHT GLOBE CHECKED / REPAIRED / TESTED SUZI LEAD - ALL OK  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58346	14/12/2023	470501	DRIVERS SIDE MIRROR HAD FALLEN OFF	Invoice
DRIVERS SIDE BLIND SPOT MIRROR THAT WAS TAPED ON HAD FALLED OFF				

**Vehicle Details**

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
TAPED MIRROR BACK IN PLACE				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58327	12/12/2023	470016	RHS SEAT LEAKING	Invoice
DROVE TO BT YARD CHECKED FOR SEAT AIR LEAK FAULT REMOVED TOP CUSHION FOUND HOLE IN AIRLINE FITTED JOINER TO MAIN AIRLINE TESTED OPERATION RE-FITTED SEAT CUSHION RETURNED TO WORKSHOP				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58265	05/12/2023	469272	TRAILER CONTROL VALVE	Invoice
TRAVEL BT YARD TRAILER NOT RELEASING BRAKES BROUGHT TO WORKSHOP MADE TESTS / CHECKS TO INTERMITTENT PARK BRAKE ERRORS FOUND TRAILER BRAKE AND PARK/RELEASE/DOOR NOT IN SYNCHRONIZATION. RESET / TEST - OK REPLACE RED/YELLOW WIRING HARNESS PLUGS / TERMINALS ETC CARRIED OUT DIAGNOSTICS, FOUND FAULT AS TRAILER PROTECTION VALVE, REMOVED VALVE, SWAPPED FITTINGS AND FIT NEW VALVE TO TRUCK. TIDY UP LOOSE WIRES, FIT COVER ON BACK OF ENGINE AND REFIT WALK PLATE. TRAVELLED TO MULTISPARES DARRA TO COLLECT PARTS				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
58204	27/11/2023	468333	AIR CON ISSUES	Invoice
CHECKED /TRACED REPAIRED BAD LHS STOP LIGHT NOT WORKING / CLEANED UP BAD CONTACT AND RE-TENSIONED SPRING TERMINAL AND TEST WITH NEW GLOBE - ALL OK CHECKED A/C FOR SLOW LEAKS - NONE LOCATED ADDED A/C UV DYE FOR RE-CHECK 1-2 WEEKS ADDED SMALL GAS CHARGE ONLY / TEST - OK REMOVED / DE-GLUED RHS WINDOW TINT AS PER REQUEST AND CLEANED WINDOW RHS				
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
57878	18/10/2023	466639	REPLACED SUZI COILS	Invoice
REPLACED AIR SUZI COILS REFIT WALK PLATE  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57970	18/10/2023	466639	FIT 2ND HAND FRONT BUMPER	Invoice
DRIVE TRUCK INTO WORKSHOP REMOVE FRONT BAR REMOVE ALL LIGHTS FROM BAR PUT LIGHTS INTO 2ND HAND BAR FIT BAR , HAD TO TRIM BAR TO FIT SECURE BAR ZIPTIE HARNESS ORDER PARTS FOR TRUCK PREPARED RH STEP AND WHEEL ARCH FLARE / GUARD FOR PAINTING PLASTC PRIMED GUARDS PRIMED GUARDS PAINTED ALL GUARDS SATIN BLACK STRIP AND FIT NEW STEPS FIT GUARD AND ALIGN ALL BRACKETS CHECK LIGHTS AND FILL UP WASHER FLUID FIT NUMBER PLATE  <b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57380	10/08/2023	465203	CARRY OUT GREASING OF TRUCK	Invoice
<ul style="list-style-type: none"> <li>GREASE AND CARRY OUT INSPECTION OVER TRUCK</li> </ul>				

## Vehicle Details

Registration	556RPT	Next Service	Litres	
Make	IVECO	Rego Due	Trans	N/A
Model	STRALIS	Engine #	Air	Yes
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	PRIMEMOVER
Colour	White	Odometer	Prod	2010

Invoice No.	Date	Odometer	Description	Type
<b><u>HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING &amp; BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.</u></b>				
57247	27/07/2023	465202	TRUCK CAME IN WITH OIL LIGHT ON	Invoice
TRUCK CAME IN WITH OIL LIGHT - FOUND OIL OVER FILLED BUCCINI DIDNT NEED TRUCK FOR REST OF THE NIGHT SO LEFT TRUCK TO COOL DOWN - CAME BACK LATER AND DRAINED SOME OIL OUT TOPPED OIL BACK UP TO CORRECT LEVEL RETURNED TRUCK BACK TO BUCCINI NOTE ALL CURSOR ENGINES GET FILLED SHOWING ON THE DIPSTICK 3 TO 4MM BELOW THE FULL MARK. IF THEY ARE FILLED TO THE FULL MARK THEY SHOW AN OVER FULL LIGHT.				
57241	12/07/2023	465289	INSPECT BRAKE FAULT - REPLACE	Invoice
TRUCK DRIVEN WITH A TRAILER AND BOX ON THE BACK, BRAKES APPLIED VERY LIGHTLY BY THEMSELVES. INSPECT BRAKE FAULT. TRACED BACK TO TRAILER VALVE, FIT NEW TRAILER BRAKE VALVE. TEST DRIVE IN VEHICLE BRAKES ALL OK. DROVE BACK TO YARD.				
57237	11/07/2023	465087	C SERVICE	Invoice
PICKED TRUCK UP FROM BT YARD. CARRIED OUT FULL C SERVICE. REMOVED THE ENGINE BREATHER FILTER HOUSING AND REPAIRED AN OIL LEAK FROM THE ENGINE BREATHER COVER. CONNECTED PRESSURE GAUGE AND CHECKED AIR PRESSURE ALL OK. ADJUSTED THE TURNTABLE AND STRAIGHTEND THE BENT ADJUSTING BOLT. REPLACED 1ST DRIVE DIFF OIL. DROVE BACK TO THE BT YARD.				
57239	05/07/2023	465052	ATTEND TO BRAKES COMING ON	Invoice
ATTEND TO BRAKES COMING ON INTERMITANTLY BY THEMSELVES PARKED VEHICLE IN WORKSHOP DIAGNOSED THAT THE AIR DRIER WAS NOT SUPPLYING THE CORRECT AIR TO THE SYSTEM. REMOVED OLD AIR DRIER ASSEMBLY AND USED COLOURED CABLE TIES TO IDENTIFY WHICH PIPE GOES WHERE WHEN REASSEMBLING. SWAPPED AIR FITTINGS OVER FROM THE OLD DRIER ASSEMBLY AND FITTED ONTO THE NEW ASSEMBLY. FITTED NEW DRIER TO THE TRUCK AND TESTED ALL AIR PRESSURES STEADY AT 10 BAR.OK. TRUCK WAS TEST DRIVEN AND DID NOT FAULT RETURNED TO FLEET FOR TESTING WITH A LOAD.				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
56976	30/06/2023	0	SUPPLY SERVICE FILTERS	Invoice

SUPPLY SERVICE FILTERS

57106	09/06/2023	464659	SENSOR ABS AND BRAKES	Invoice
-------	------------	--------	-----------------------	---------

DIAGNOSE WHY THE ABS WARNING LIGHT IS ON THE DASH.  
DIAGNOSED THAT BOTH OF THE REAR ABS SENSORS WERE IN NEED OF REPLACEMENT.  
TO FIT THE NEW SENSORS REQUIRES THE REMOVAL OF THE WHEELS.  
REMOVED MUDGUARD ASSEMBLIES TO ACCESS THE BRAKE ASSEMBLIES  
REMOVED THE WHEELS OFF THE 2ND DRIVE AXLE AND FOUND THAT THE BRAKE CALIPERS HAVE GOT VERY HOT, IN OUR OPINION THEY WOULD HAVE NEARLY BEEN ON FIRE. THE PAINT HAS BEEN BURNT OFF THE BACKING PLATES.  
WE THEN REMOVE THE WHEELS OFF THE 1ST DRIVE AND FOUND THE BRAKES TO BE IN A SIMILAR OVERHEATED CONDITIONS.  
THE FRONT BRAKE PADS ARE WORN AND IN NEED OF REPLACEMENT BUT DO NOT APPEAR TO HAVE GOT AS HOT.  
REMOVE AND REPLACE REAR ROTORS AND CALIPERS. REMOVE AND REPLACE FRONT BRAKE PADS.  
REMOVE AND REPLACE 2ND AXLE ABS SENSORS.  
REFITTED THE MUDGUARD ASSEMBLIES.  
REMOVED AND REPLACED WORN AIRBAG AXLE VALVE ROD.  
TEST DROVE TRUCK DID NOT FAULT, WARNING LIGHT ON DASH.  
REPLACED 3 BLOWN GLOBES AND WARNING LIGHT WENT OFF.

57101	05/06/2023	464659	DIAGNOSTIC SCAN - NEEDS NEW	Invoice
-------	------------	--------	-----------------------------	---------

HAD TO JUMPSTART TRUCK AS BATTERIES AT 21V - PUT ON CHARGE  
CARRIED OUT TRUCK SCAN AND FOUND MANY / VARIED OLD CODES PRESENT  
CLEARED ALL INACTIVE CODES  
NO TRAILER LIGHTS - CHANGED TRAILER PLUG - FIXED SUZI WIRING TESTED - ALL OK  
TRUCK HAS STARTING FAULT STARTER MOTOR FAULTY.

REMOVED AND REPLACED FAULTY STARTER MOTOR

REPLACED X 3 FAULTY BATTERIES, REMOVED AND REPLACED WITH NEW BATTERIES

STARTED UP AND CHECKED VOLTAGE - ALL OK  
RESCANNED FOR LIGHT ON DASH.

ABS ISSUE, BLOWN FUSE

REPLACED FUSE, CODE WENT AWAY

SIMILAR CODE FOR WHEEL SPEED SENSOR AT REAR

CARRIED OUT A PHYSICAL INSPECTION OF THE SENSORS AND FOUND THE BRAKES HAVE BEEN OVERHEATED CAUSING THE SENSORS TO MELT. ALL THE REAR ROTORS, CALIPERS, ASSOCIATED CALIPER PARTS AND BRAKE PADS ALL ROUND IN NEED OF REPLACING.

56779	30/05/2023	464602	BREAKDOWN AT DINMORE - NOT	Invoice
-------	------------	--------	----------------------------	---------

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
TRAVELLED TO DINMORE TO ATTEND BREAKDOWN INSPECT TRUCK NOT STARTING PLUMB AIR INTO TANKS TO GET TRUCK INTO NEUTRAL ROLLED TRAILER AND TRUCK TO GET GEARBOX TO MOVE JUMP START TRUCK TRIED BRIDGING STARTER TESTED FOR POWER AT STARTER POWER GOING TO SIGNAL WIRE HIT STARTER WITH HAMMER STARTED TRUCK RETURN TO THE WORKSHOP				
57398	11/05/2023	0	REPLACE WINDSCREEN	Invoice
DRIVE TO BT YARD AND LOCATE THE TRUCK, DRIVE BACK TO HVW AND HAVE WINDSCREEN INSTALLED.				
56593	08/05/2023	0	AIR LEAKS	Invoice
PICKED UP TRUCK FROM BUCCINI YARD JACKED UP CAB AND CHECKED OVER FOR AIR LEAKS FOUND SENSOR ON RELASY VALVE AT THE BACK OF TRUCK LEAKING AND AIRLINE FOR FAN HUB RUBBED THOUGH CUT OUT DAMAGED SECTION OF AIRLINE AND FIT JOINER CARRIED OUT REPAIR OF AIR LEAK AT FRONT OF ENGINE BLOCK				
56587	05/05/2023	463434	DASH LIGHTS + AIR LEAK	Invoice
CHECKED VEHICLE TO FIND WHAT IS COMING UP ON THE DASH CHECKED BELTS CHECKED CHARGING RATE TOPPED UP WITH OIL FOUND AIR LEAK THAT MAYBE WHY THERE IS A FAULT COMING UP ON THE DASH				
56457	18/04/2023	461200	REPLACE AND TIDY UP SUZI COILS	Invoice
DRIVER CAME IN REPLACED AND TIDIED UP SUZI COILS				
56257	20/03/2023	0	JUMP START	Invoice
JUMP START TRUCK CHECKED VOLTAGE - ALL OK				
55963	14/02/2023	959102	A SERVICE	Invoice
BROUGHT VEHICLE INTO WORKSHOP JACK UP TRUCK REMOVED AIR VALVES AND MARKER FROM WRECKED TRUCK HERE AT HVW ADJUSTED TURNTABLE MADE TESTS/CHECKS TO LEFT AND RIGHT ELECTRIC WINDOW OPERATION COULD LOCATE NO FAULTS				



**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
			ALL WORKING - OK UNSCREWED FOLDER FROM DOOR SKIN AND RHS AS PER INSTRUCTION INSPECTED RH SIDE FOR ANY POSSIBLE FAULTS CAUSED BY FOLDER SCREWS - NO WIRING / WINDOW RHS - ALL OK DROPPED TRUCK BACK TO BUCCINI YARD NOTE- WINDSCREEN HAS A CRACK DRIVER SEATBELT DOESN'T RETRACT WELL DRIVER SIDE MIRROR HOUSING CRACKED 1ST DIFF HOUSING WEEPING	
55835	25/01/2023	457108	WINDOW REG RHS	Invoice
			BROUGHT TRUCK INTO WORKSHOP MADE TESTS/ CHECKS TO RHS ELECTRIC WINDOW ETC - FOUND MOTOTR/CABLE ASSEMBLY U/S - ORDERED PARTS CHECKED OIL LEVEL ERROR - FOUND VERY LOW - ADD 8LTRS TO JUST BELOW FULL MARK FITTED LHS LOWER STEP ASSEMBLY AND INSTALLED PLASTIC FOOT PLATE GRIPS AS REQUIRED - HAD TO RE-DRILL/ELONGATE 4 X MOUNTINGS TO SUIT/FIT SLIGHTLY BENT STEEL MOUNTING FRAME GOT MOUNT STUDS / BOLTS / NUTS OFF OLD XQ92EM WRECK AS REQUIRED ADDED COOLANT TO CORRECT LEVEL AND CLEARED OLD/INACTIVE FAULT CODES AS REQUIRED / TEST - ALL OK	
55756	16/01/2023	456401	AIR LEAK	Invoice
			DRIVER REPORTED AIR LEAK - CHECKED OVER AND FOUND SPLIT AIR HOSE GOING INTO TOP OF AIR TANK REMOVED AIR HOSES, CUT SPLIT END OFF AND RE-FITTED TO AIR TANK BUILT UP AIR AND CHECKED LEAK - ALL GOOD	
55721	29/12/2022	0	REPLACED TAIL LIGHT GLOBES	Invoice
			REMOVED TAILLIGHT COVERS AND REPLACED 3 X GLOBES	
55863	12/12/2022	452394	TRAVEL TO HEATHWOOD REPLACED	Invoice
			TRAVEL TO HEATHWOOD REMOVE AND REPLACED SUZI COILS RETURNED TO WORKSHOP	
55290	07/11/2022	446732	CARRY OUT B SERVICE	Invoice
			BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT B SERVICE ADJUSTED TURNABLE STRAIGHTENED RH STEP REPLACED LH PARK LIGHT BULB REPLACED RH SIDE LIGHT BULB SECURED RH BUMPER INDICATOR ASSEMBLY SECURED FAN SHROUD	

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
			REPAIRED RH SEAT OPERATION REPAIRED CAB AIRBAG RIDE HEIGHT FAULT REMOVED VALVE, CLEANED OUT BLOCKED AIRLINES AND RE-FITTED VALVE TESTED OPERATION WALKED TO BUCCINI YARD COLLECTED VEHICLE UNHOOKED A DOUBLE TRAILERS ON STREET DROVE TO WORKSHOP REMOVED # 1 DIFF SWAY BAR OXY CUT BOLTS AS THEY WERE RUSTED REMOVED AIR CLEANER HOUSING AND STEP REPLACED LH STEER REAR SPRING EYE BUSH REFITTED AIR CLEANER HOUSING PREPARED STEP FOR PAINTING PLASTIC PRINTED STEP PAINTED STEP	
55284	03/11/2022	446189	TOP UP OIL	Invoice
			TOPPED UP OIL	
55099	10/10/2022	441106	OVER PRESSURE AIR SYSTEM - NEED	Invoice
			BROUGHT TRUCK INTO WORKSHOP MADE TESTS/CHECKS TO A/C SYSTEM - FOUND SLIGHTLY LOW ON GAS CHARGE TO VERY SLOW LEAKS AT COMPRESSOR PIPE FLANGE GASKET/SEALS LEAKING - ORDERED NEW SEALS (O RINGS) AND TOPPED UP GAS / CHECK OK - FOUND SEAT AIR LEAK REPLACED/REPAIRED RHR TAIL LMP DAMAGED, FITTED NEW LENS AND SOME GLOBES - TEST OK CARRIED OUT EASY IVECO SCAN TOOL ASSESS FOUND FRONT / REAR PRESSURE SENSOR, PARK BRAKE FAULT (VCM9) EVIDENT - FOUND AIR DRYER U/S (THAT WILL FIX OVER PRESSURE SENSOR ERRORS) FOUND BRAKE SWITCH ON TREADLE VALVE U/S - ORDERED IN NEW PARTS CHECKED FOR AIR COMPRESSOR OVER PRESSURIZING CHECKED AIRLINES, AIR FITTINGS AND AIR DRYER ASSISTED WITH AIR DRYER CARRIED OUT EASY IVECO SCAN AS REQUIRED TO CHECK VERY INTERMITTENT PARK BRAKE FAULT FOUND VCM FAULT 9 WHICH IS BRAKE SWITCH CORRELTION ERROR -RE-ORDERED PART	
55052	28/09/2022	439268	REPLACED HEADLIGHT BULB	Invoice
			REPLACED HEADLIGHT BULB	
54985	16/09/2022	436402	CHECKED UNDER SEAT FOR AIR LEAK	Invoice
			BROUGHT VEHICLE INTO WORKSHOP CHECKED UNDER SEAT FOR AIR LEAK FITTED NEW 4MM JOINER, OLD ONE WAS LEAKING FOUND ANOTHER LEAK COMING FROM LOOM, HOLDING AIR LINES UNDER THE DRIVERS SEAT CUT LOOM BACK TO CHECK LINES, COULDN'T REACH BACK FAR ENOUGH REMOVED THE DRIVERS SEAT AND LOCATED THE AIR LEAK. CUT AND JOINED THE LEAKING AIR LINE	
54969	13/09/2022	453285	SCAN FOR FAULTS	Invoice

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
BROUGHT VEHICLE INTO WORKSHOP CHECKED / CARRIED OUT EXTENSIVE IVECO / EASY SCAN ON TRUCK TO MAKE CHECKS FOR ANY POSSIBLE ACTIVE FAULTS / ERRORS - NOTHING ACTIVE CHECKED COOLANT LEVEL OK, CHECKED OIL LEVEL - OLD / INTERMITTENT INACTIVE CODE WAS PRESENT - CLEARED OK CHECKED RFC ECU, FOUND OLD REAR PRESSURE SENSOR INACTIVE CODE WAS PRESENT - CLEARED OK NOTE- THIS TRUCK MAY HAVE SOME KIND OF INTERMITTENT FAULT - UNKNOWN AT THIS TIME				
54934	12/09/2022	435093	SUZI COIL & 24V LIGHT PLUG	Invoice
REMOVED DAMAGED SUZI LINES AND FIT NEW ONES REPLACED BROKEN 7 PIN TRAILER PLUG				
54893	05/09/2022	933885	TANGLED /BROKEN SUZI COIL	Invoice
REMOVE TANGLED AND BROKEN SUZI COIL REMOVE FITTINGS FROM OLD SUZI COIL AND FIT NEW SUZI COIL TO TRUCK				
54786	23/08/2022	431898	DIM LIGHTS / RHS INDICATOR BROKEN	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT IVECO SCANTOOL PROCEDURE ETC TO ASSESS VARIOUS FAULTS FOUND / REPAIRED / REPLACED GLOBES FOR RHS PARKLAMP, LOWBEAM HEADLIGHT AND FLASHER AND RE-TEST - ALL OK ALSO LOCATED / REPAIRED AIRLEAK AT AIR COMPRESSOR SMALL "DUMP" SENSE OUTLET FITTING AND RE-TEST - OK REMOVED / REFITTED CHASSIS COVER TO ALLOW ACCESS TO AIR LINES ETC CLEANED UP POWER STEERING RESEVOIR DEGREASED / REGASSED / RECLAIMED / EVACUATED A/C TO ENABLE RADIATOR REPLACEMENT AND LEAK - TEST A/C - ALL OK  REMOVED RADIATOR , A/C FOR CONDENSOR, INTERCOOLER FIT NEW RADIATOR AND SHROUDS AND NEW UPPER AND LOWER HOSES FILLED WITH COOLANT TEST DROVE TRUCK - ALL OK DROVE TO BUCCINI YARD				
54759	17/08/2022	431222	BOLT REPLACED ON MUDFLAP	Invoice
BROUGHT VEHICLE INTO WORKSHOP CHECKED FOR TRAILER LIGHT FAULT CONNECTED ELECTRICAL SUZI SECURED ELECTRICAL AIRLINE SUZI COIL TO POGO STICK REPLACED BOLT IN REAR L/H MUDGUARD POLE				
54695	08/08/2022	429620	REPLACED LHS TAILLIGHT BRAKE	Invoice
REMOVED AND REPLACED LHS TAILLIGHT BRAKE GLOBE				
54649	02/08/2022	429245	CARRY OUT B SERVICE	Invoice
BROUGHT INTO WORKSHOP - TRUCK ARRIVED AT 7PM CARREID OUT B SERVICE DRAINED AND REPLACED OIL/OIL FILTER REPLACED REAR AXLE DIFF OIL AS HAD WATER IN IT. UPON CLOSER INSPECTION FOUND CHUNKS OF				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
CROWN / PINON GEAR IN BOTTOM OF THE DIFF LOWERED TRUCK AND FILLED OIL - STARTED - OK ADJUSTED TURNABLE NOTE- CRANKCASE BREATHER BAD LEAK REAR SWAY BAR BUSHES A BIT PERISHED REPLACED REAR DIFF OIL # 2 DRIVE				
54614	25/07/2022	427593	RHR TAIL LIGHT LENS BROKEN	Invoice
CHECKED / REPLACED BROKEN RHR TAIL LIGHT LENS / CHECK LIGHTS - OK				
54433	20/06/2022	423588	REPLACED SUZI AIR LINES	Invoice
REPLACED SUZI AIR LINES				
54250	31/05/2022	420578	NEW HEADER TANK	Invoice
CHECKED FOR HANDBRAKE LOW AIR LIGHT ON DASH REMOVED AIR SWITCHES UNDER DASH REPLACED AIR SWITCHES AND REFITTED STEERING COLUMN COVERS CHECKED FOR COOLANT FAULT TILTED CAB PRESSURE TESTED SYSTEM CHECKED ALL HOSES AND CLAMPS CHECKED THERMOSTAT TEST DROVE VEHICLE FOUND RADIATOR HEADER TANK LEAKING DRAINED COOLANT REMOVED HEADER TANK FITTED NEW HEADER TANK/EXPANSION FILLED WITH COOLANT REPLACED HOSE CLAMP TEST DROVE VEHICLE CHECK FOR LEAKS				
54390	30/05/2022	420578	DRIVER BROUGHT IN FOR COOLANT	Invoice
DRIVER BROUGHT TRUCK IN TO TOP UP COOLANT LIFTED BONNET AND INSPECTED RESERVOIR, HALF WAY BETWEEN FULL AND EMPTY - TOPPED UP TO FULL INSPECTED COOLING SYSTEM - ALL OK				
54326	20/05/2022	419432	SCAN COOLING SYSTEM	Invoice
CHECKED / PRESSURE TESTED COOLING SYSTEM - NO LEAKS TOPPED UP LOW COOLANT LEVEL. CHECKED REPLACED SUZI LEAD PLUG END AND TESTED. TRACED / LOACTED REPAIRED VARIOUS AIR LEAKS INCLUDING PROTECTION VALVE RLHS. PROVIDE INSULATION TO CHAFFED FUEL LINES NEAR TANK LHS / TEST. ADDED RUBBER TO STOP CHASSIS COVER RATTLE. CHECKED ENGINE LIGHT ON - FOUND TO BE EMISSIONS RELATED / PRESSURES / SETTINGS / TEMPERATURE IN / OUT OK RESET SCR CATALYTIC CONVERTER SETTING AS REQUIRED / ROAD TESTST ALL OK.				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
54116	29/04/2022	416463	WARNING LIGHTS ON DASH	Invoice
CARRIED OUT IVECO SCAN TOOL TO CHECK AND RESET ENGINE FAULT LIGHT WARNING LAMP STAYING ON FOUND TO BE LONG TERM ADBLUE ERROR (UNREMOVABLE - NEEDS AT LEAST 400 CRANK CYCLES TO ERASE CODES FOUND SLIGHT LEAK ON FITTINGS AT ADBLUE TANK - TIGHTENED LOOSE FITTINGS AND RECHECKED - ALL OK RESET ENGINE WARNING LAMP CYCLE COUNTER AT 16 COUNT CODE AS PER CODE RECHECKED START, RUN AND ENGINE - ALL OK				
54065	26/04/2022	415947	BREAKDOWN	Invoice
ATTENDED BREAKDOWN AT CURLEW STREET FOUND TRUCK LEAKING AIR FRONT AIR DRIER BUNG TEMPORARILY FIXED BUNG TO GET VEHICLE BACK TO WORKSHOP ONCE ARRIVED REMOVED AND REPLACED BUNG, USED THE BUNG OFF THE PARTS TRUCK ENGINE LIGHT ON DASH CHECKED COOLANT AND ENGINE OIL LEVEL CONNECTED SCAN TOOL AND FOUND LONG TERM AD BLUE FAULT (LOW ADBLUE) FOUND CATALYST FAULT (BELOW MINIMUM THRESHOLD) CLEARED CODES AND RECHECKED DASH - ALL OK				
54022	13/04/2022	414911	REPLACE SUZI COILS	Invoice
VEHICLE BROUGHT IN WITH NO AIR SUPPLY TO TRUCK REMOVED AND REPLACED SUZI COILS - DAMAGED TESTED OPERATION - ALL OK REMOVED AND REPLACED LHS TAIL LIGHT ASSEMBLY				
53924	25/03/2022	414902	CARRY OUT REPAIRS AND B SERVICE	Invoice
25/3/2022 - BROUGHT TRUCK INTO WORKSHOP DIAGNOSED LEAK AT DIFF - FOUND THAT INPUT SHAFT SEAL ON 3RD AXLE IS LEAKING AND REQUIRES REPLACING ADJUSTED J BRACKET ON LHS REAR MUDGUARD, LOSSENNED GUARD BRACKETS AND SLIDE MUDGUARD OVER SLIGHTLY TO CLEAR THE LHS REAR TYRE CONNECTED SCAN TOOL TO VEHICLE FOUND AND REPLACED MAIN CRANKING BATTERY RESET ALL VOLTAGE RELATED ECU CODES (APPROX 24 CODES/ERRORS PRESENT) RECHECKED ENGINE START/STOP/RUN - ALL OK 29/3/2022 - LIFTED VEHICLE ON HOIST AND REMOVED JACK SHAFT HEAT UP YOKE NUT AND ATTEMPTED TO RATTLE OFF WITH INCH GUN - FAILED 30/3/2022 - CHECKED 2ND DIFF YOLK NUT AND ATTEMPTED TO REMOVE YOLK NUT CARRIED OUT B SERVICE ON VEHICLE REPLACED ALLEN KEY FITTING FOR BREATHER HOUSING - BOLT ROUNDED OFF 6/4/2022 -  FITTED CLUTCH ACTUATOR AND JACKED UP CAB TO CONNECT PLUGS 11/4/2022 - CONNECTED SCAN TOOL AND FOUND TRANSMISSION CODE 7C IS ACTIVE - REMOVED CLUTCH ACTUATOR DIAGNOSED A FAULTY. REMOVED YOKE NUT, SEAL AND CLEANED UP AREA				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
REPLACED BOTH DIFF SEALS AND REFIT JACK SHAFT 12/4/2022 - REPLACED CLUTCH ACTUATOR WITH NEW ASSEMBLY. TEST DROVE VEHICLE AND CHECKED OPERATION - ALL OK PARKED VEHICLE ON STREET FOR COLLECTION				
53849	17/03/2022	413630	CARRY OUT REPAIRS	Invoice
14/3/2022 CARRIED OUT EXTENSIVE LEAK TEST OF A/C SYSTEM AND COMPONENTS FOUND GAS CHANGE ONLY VERY SLIGHTLY LOWER - ADDED A/C GAS TO CORRECT PRESSURE SUCTION SIDE INLET PAD FITTING - TIGHTENED UP FITTING - TEST OK CHECKED UHF ORICOM BRAND FITTED IS U/S ORDERED NEW ONE, REPLACED UHF AND MIC. 15/3/2022 MOVED SCREEN FROM FRONT OF OUTER HEAD CONSOLE T THE OTHER SIDE AS IT WAS INTERFERING WITH VISION OF WINDSCREEN. REPLACED CONSOLE TRIM WITH ONE FROM PARTS TRUCK. CHECKED FOR TRAILER BRAKE FAULT REPLACED TRAILER BRAKE VALVE AND PLASTIC TRIM PARTS ON DASH, TRIM REMOVED FROM PARTS TRUCK.  CHECKED A/C AGAIN - ALL OK CHECKED FOR ENGINE LIGHT - ALL OK 16/3/2022 DROVE TO SHED 24 TO COLLECT TRAILER TO TEST BRAKES RETURNED TO WORKSHOP WITH TRAILER , TESTED BRAKE OPERATION REPLACED TREDLE VALVE WITH TEST VALVE FROM PARTS TRUCK. RE-FITTED ORIGINAL TREDLE VALVE RETURNED TRAILER TO SHED 24 AND RETURNED TO WORKSHOP RE-TESTED OPERATION CHECKED AIR SYSTEM DRAWINGS REMOVED TRAILER BRAKE SERVO CONTROL VALVE FROM WRECK AND FITTED TO 556RPT. TEST FOR LEAKS - ALL OK 17/3/2022 CHECKED/TESTED AIR SWITCH CHANGED CONTROL VALVE - CHECKED OPERATION - TESTED OK CHECKED FOR BRAKE LIGHT FAULT REMOVED BRAKE LIGHT SWITCH UNDER DASH FITTED NEW SWITCH BRAKE LIGHT SWITCH. TEST DROVE WITH TRIALER NO FAULTS AT TIME OF TEST. TRUCK BACK IN SERVICE				
53786	02/03/2022	413608	REPLACED RIGHT REAR TAIL LIGHT	Invoice
REPLACED AND FITTED RIGHT REAR TAIL LIGHT LENSE				
53649	03/02/2022	413476	TRAILER BRAKES	Invoice
3/2/2022 SCANNED AND RESET CALIBRATED  AIR BAG ECAS SUSPENSION AS REQUIRED & TEST OK  RESEALED FAILED LEAKY AIR SWITCH AT REAR TANK & TEST OK AIR VALVE AT LHS REAR CHECKED FOR TRAILER BRAKES LOCKING TEST DROVE VEHICLE FOUND CAB AIR BAG VALVE NOT WORKING				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
FOUND REAR AIRTANK AIR SWITCH LEAKING  FOUND RESTRICTION IN TRAILER RELAY VALVE ASSISTED SET UP OF AIRBAG RIDE HEIGHT FOR VEHICLE REPLACED CAB RIDE HEIGHT VALVE  4/2/2022  REPLACED AIR VALVE AT REAR OF TRUCK  DROVE TRUCK TO BUCCINI YARD				
53501	04/01/2022	412406	TRAILER PLUG REPAIRS	Invoice
ATTENDED PORT OF BRISBANE FOR BREAKDOWN FOUND TRAILER PLUG DAMAGED AND REQUIRED REPLACING REPLACED TRAILER PLUG AND CHECKED OPERATION OF LIGHTS FOUND ALL LIGHTS WORKING EXCEPT RHS INDICATORS ON TRAILER CHECKED FUSES AND TRIED RESETTING BUT INDICATORS STILL NOT WORKING TRAILER BOUGHT INTO WORKSHOP TESTED AND CHECKED ALL TRUCK LIGHTING - NO FAULTS PRESENT TESTED AND CHECKED TRAILER SUZI LEAD POWER SUPPLYS - ALL CIRCUITS ARE OPERATIONAL - POSSIBLE TRAILER FAULT				
53476	21/12/2021	411955	FRONT BUMPER REPAIRS	Invoice
DRILLED AND RESECURED BOTH L AND RHS OF FRONT BUMPER FOR TEMPORARY FIX DILLED HOLES FOR NEW TIE IN POINTS AS REQUIRED CLEANED OFF OLD TAPE/GLUE AND RECHECKED - ALL OK REPLACED D/S MIRROR GLASS WITH FLAT MIRROR				
53406	20/12/2021	411955	REPLACE THERMOSTAT AND MIRROR	Invoice
BROUGHT TRUCK INTO WORKSHOP DIAGNOSE VEHICLE OVERHEATING - TOP RADIATOR HOSE WAS HOT AND BOTTOM HOSE WAS FINE TILT CAB AND DRAINED AND SAVED COOLANT REMOVED OLD THERMOSTAT AND GASKET FIT NEW THERMOSTAT AND GASKET FILL WITH SAVED COOLANT AND TEST DRIVE - ALL OK REMOVED AND REPLACE FRONT LHS HEADLIGHT GLOBE REPLACED CRACKED LHS MIRROR.				
53318	02/12/2021	410078	TAIL LIGHTS	Invoice
REMOVED AND REPLACED BOTH SIDE DAMAGED TAIL LIGHT LENSES CHECKED LIGHT OPERATION - ALL OK				
53280	24/11/2021	408905	REPLACED AIR FILTER	Invoice
RESCANNED IVECO FAULT CODES FOUND ECM 199 CODE- PROGRAM SAYS MAYBE TURBINE SPEED SESNOR OR TURBINE ACTUATOR OR BLOCKED AIR FILTER REPLACED BLOCKED AIR FILTER ELEMENT CLEARED CODES AND REQUESTED TEST DRIVE OF TRUCK REPLACED LEAKING DIESEL AFFECTED ADBLUE O-RING SEAL RECHECKED ALL ADBLUE COMPONENTS INCLUDING CONNECTORS, ENGINE EARTHING, CABLES AND VOLTAGE - ALL OK				



**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
REPLACED LHS BRAKE LIGHT GLOBE 25/11/2021 - CONNECTED IVECO SCAN TOOL - ONE PERVIOUS UNSEEN CODE PRESENT - TURBO ACTUATOR OVERCURRENT OPENED UP WIRING AND FOUND VARIOUS SECTIONS OF CHAFFED WIRING - REINSULATED AND TESTED OPERATION - ALL OK REFIT ENGINE WIRING HARNESS TO LHS AND ASKED FOR VEHICLE TO BE TEST DRIVEN				
53276	23/11/2021	408750	ELECTRICAL REPAIRS	Invoice
CHECK FAULT CODES ON DASH LHS REAR LIGHTING CODE PRESENT/ACTIVE TRACED AND REPAIRED BRAKE IN LHS REAR STOP LIGHT LOCATED FURTHER BACK (ALMOST IN WIRING HARNESS BETWEEN REAR AXLE) RECHECKED LIGHTS AND CODES - ALL OK USING IVECO SCANTOOL TO CHECK FOR ANY INTERMITTENT ADBLUE CODES FOUND LOW ADBLUE LEVEL AND AIR INTAKE TEMPERATURE SENSOR INTERMITTENT CHECKED ADBLUE LEVEL (WAS 50% ALL OK) AND WIRING /PLUGS ALL OK CHECKED AIR TEMP SENSOR - ALL OK CLEARED INTERMITTENT CODES AS REQUIRED REFITTED COVERS/PANELS/DECKING AS REQUIRED REQUESTED HEAVY LOAD ROADTEST REMOVED CHECKER PLATE AND INSPECTED MUFFLER EXHAUST - ALL OK				
53267	23/11/2021	408820	BATTERY ISSUES	Invoice
CONNECTED IVECO SCAN TOOL FOUND FAULT CODE ON DASH RELATING TO EXCESSIVE LOW VOLTAGE REMOVED AND LOAD TESTED ALL BATTERIES - FOUND 1 BATTERY FAILED CLEANED ALL TERMINALS AND POSTS ON BATTERIES GROUND OUT HOLD DOWN FRAMES FOR BATTERIES AND CLEANED FREED UP SEIZIED HOLD DOWN BOLTS AND REPLACED BATTERY TESTED OPERATION AND RECHECK FOR CODES - ALL OK				
53208	19/11/2021	402535	AD BLUE	Invoice
INSPECTED VEHICLE FOR POSSIBLE WIRING FAULTS TO ADBLUE SYSTEM - NO FAULTS FOUND IN WIRING LOCATED AND REPAIRED WIRING TO LIGHTS AND REPLACED FAILED LIGHT GLOBES INSPECTED THE AD BLUE TANK FOR AD BLUE FAULT NOTICED DIESEL RESIDUE ON AROUND THE FILLER NECK OF THE AD BLUE TANK. DRAINED THE TANK AND INSPECTED - FOUND DIESEL FLOATING ON TOP OF THE AD BLUE SAMPLE.  REMOVED SENDER UNIT FROM TANK REMOVED FRONT RHS WHEEL GUARD TO ACCESS AD BLUE TANK  WHILST REMOVING THE AD BLUE TANK THE TANK RETAINING STRAP SNAPPED DRAINED TANK AND FLUSHED SEVERAL TIMES FLUSHED OUT LINES TO FILTER HOUSING REMOVED AD BLUE FILTER - DAMAGED CONNECTED JALTEST AND RUN WARM WATER THROUGH ADBLUE SYSTEM TO REMOVE DIESEL REASSEMBLED TANK AND PARTS AND REFILLED WITH NEW ADBLUE TESTED OPERATION - ALL OK				
53201	18/11/2021	0	BREAKDOWN DERATE	Invoice
ATTENDED BREAKDOWN GATEWAY INSPECTION STATION				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
CHECKED FOR VEHICLE DERATING AND COMPUTER FAULTS FOUND AD BLUE AND CATALYST FAULTS TESTED AD BLUE PUMP AND DOSING PUMP - OK FOLLOWED VEHICLE BACK TO WORKSHOP ONCE VEHICLE GOT BACK TO WORKSHOP CONNECTED JALTEST AND CHECK ADBLUE CODES COULD NOT FAULT CHECKED VEHICLE OPERATION FOUND SOME LIGHT GLOBE BLOWN REPLACED TAIL LIGHT GLOBES, RHS SIDE LIGHT, RHS LOW BEAM HEADLIGHT AND LHS PARK LIGHT GLOBE TESTED OPERATION - ALL OK				
53140	04/11/2021	40584	TOP UP POWER STEERING FLUID	Invoice
TOPPED UP ENGINE OIL AND POWER STEERING FLUID AS RQUESTED				
53126	25/10/2021	404400	RIDE HEIGHT VALVE	Invoice
25/10/2021 - SWAPPED RHS RIDE HEIGHT VALVE WITH XQ91IK - LHS AIR BAGS ARE NOT FILLING WITH AIR 26/10/2021 - INFLATE ALL AIR BAGS AND CHECK FOR LEAKS PLUG INTO UNIT WITH IVECO SCAN TOOL AND GET COMMUNICATIONS FROM SUSPENSION ECU START CALIBRATION PROCESS INFLATE AND DROP DOWN STANDS AT LEVEL NEEDED COMPLETE PROCESS - ALL OK ENGINE OIL LIGHT CAME UP ON DASH TOPPED UP ENGINE OIL LIGHT WOULD NOT CLEAR DISCONNECT BATTERY FOR TEN MINUTES AND RECHECK - LIGHT CLEARED FROM DASH REPLACED MISSING ROUND REFLECTORS ON TRUCK BEFORE VEHICLE LEFT				
53002	18/10/2021	403109	BREAKDOWN	Invoice
18/10/2021 - TRAVELLED TO BREAKDOWN IN ORMEAU AND INSPECTED TRUCK CHARGED UP TANKS IN AN ATTEMPT TO GET VEHICLE OUT OF REVERSE ONCE CHARGED, START VEHICLE BY BRIDGING THE STARTER MOTOR - VEHICLE STARTED DIAGNOSED AN AIR LEAK ON COMPRESSOR OUTPUT PIPE PUT RUBBER HOSE OVER UNIT AND TIE UP WITH HOSE CLAMPS TESTED UNIT - ALL OK FOLLOW TRUCK BACK TO WORKSHOP 19/10/2021 - BROUGHT VEHICLE INTO WORKSHOP AND TILTED CAB REMOVED OLD AIR COMPRESSOR PIPE AND CLAMPS REMOVED AIR COMPRESSOR PIPES AT AIR COMPRESSOR AND REPLACED WITH NEW REFIT HOSE CLAMPS AND TESTED - ALL OK CHECKED VEHICLE BUILT UP AIR AND TEST DROVE - ALL OK				
52843	13/09/2021	396536	CLEAR LIGHT ON DASH	Invoice
CONNECTED JALTEST TO VEHICLE - ENGINE LIGHT ON DASH FOUND TO BE LONG TERM AD-BLUE DOSING WARNING CHECKED ADBLUE SYSTEM - WORKING FINE RESET ADBLUE WARING CODES AND CLEARED WARINGS ALL OK				
52681	17/08/2021	392802	CARRY OUT REPAIRS	Invoice

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
<p>17/8/2021 - CHECKED NUMBER PLATE LIGHT FAULT - BULB BLOWN REMOVED AND REPLACED GLOBE CHECKED FOR PARK LIGHT STAYING ON WHEN BRAKES ARE RELEASED REMOVED STEERING COLUMN COVERS CHECKED HAND PIECE SWITCHES AND WIRING FOUND RUST BLOCKAGE AT T PIECE AND SWITCH CLEANED OUT RUST RESEALED AND REFIT T PIECE AND SWITCH TESTED OPERATION - OK - SWITCH REQUIRED REPLACING VEHICLE WENT BACK TO WORK WHILE WAITING FOR PART</p> <p>9/9/2021 - REMOVED STEERING COLUMN COVERS REMOVED OLD PARK BRAKE SWITCHES AND T PIECE FITTED AIR LINE T AND ONE PRESSURE SWITCH</p> <p>10/9/2021 - REPLACED AIR SWITCH AND L SHAPED AIR FITTING UNDER LHS OF DASH CHECKED FOR AIR LEAKS - ALL OK REFITTED LHS AND STEERING COLUMN COVERS REPAIRED CHAFFED WIRING TO BATTERY POWER DISTRIBUTION MAIN FUSE BOX AND TESTED - ALL OK</p>				
52644	11/08/2021	392276	CARRY OUT REPAIRS	Invoice
<p>REMOVED DAMAGED REAR MUDGUARD AND MOUNTING POLES. FRONT AND REAR MOUNTING POLES BENT AND WILL REQUIRE REPLACING. DRILLED NEW REAR MUDGUARD AND FITTED NEW MOUNTING BRACKETS, FITTED NEW REAR POLES. REPLACED DAMAGED MARKER PLATE. REPLACED DAMAGED TAIL LIGHT ASSEMBLIES. CHECK ALL OK</p> <p>.</p>				
52428	06/07/2021	390473	REPAIRS FROM SERVICE	Invoice
<p>INSPECT STEERING FOR TOO MUCH FREEPLAY. CHECKED STEERING UNI JOINTS, STEERING JOINTS AND FRONT AND REAR SUSPENSION DIAGNOSED THAT THE DRAG LINK IS WORN AND IN NEED OF REPLACEMENT. REMOVED AND REPLACED LHS CAB MOUNT SHOCK ABSORBER AND SWAY BAR BUSHES - BADLY WORN WHEN REMOVED THE SWAY BAR BUSHES FOUND THE NUTS WERE SEIZED ON THE BOTTOM MOUNT CAUSING THE STUD TO SNAP. REMOVED BROKEN STUDS FROM CAB SWAY BAR MOUNTS WELDED NEW BOLTS TO SWAY BAR MOUNTS DRIVERS TOP STEP IS BADLY CRACKED, THIS STEP IS PART OF THE GUARD. THERE IS NO SIGN OF IMPACT OR EXTERNAL DAMAGE. PREPARED RHS MUDGUARD FOR PAINTING PAINTED GUARD WITH PLASTIC PRIMER AND SPRAY PAINTED GREY. FIT NEW STEP GUARD ON RHS. REMOVE AND REPLACE WORN BRAKE PEDAL RUBBER AND WIPER BLADES. DRAIN RADIATOR AND REMOVE TO ACCESS THE WORN FAN HUB. REMOVE FAN HUB AND REPLACE WITH A NEW ONE. REFIT RADIATOR AND REFILL WITH COOLANT. REMOVE CAB PANHARD ROD AS THE BUSHING IS WORN OUT, PRESS OUT OLD BUSHES AND SLEEVE. PRESS IN NEW BUSHING AND SLEEVE REFIT TO TRUCK. LOOSEN OFF FUEL TANK STRAPS AND FIT NEW TANK STRAP RUBBER. DRAIN HYDRAULIC FLUID AND REMOVE LEAKING CAB TILT CYLINDER AND REPLACE WITH A NEW ONE. REFILL WITH HYDRAULIC FLUID. REMOVE DAMAGED REAR AIR BAG AND SUPPLIED AND FITTED A NEW ONE. AIR DRIER IS CONTINUALLY LEAKING AIR AS IT HAS FAILED INTERNALLY, REMOVE OLD AIR DRIER AND REPLACE WITH A NEW ONE.</p>				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
WHEN TEST DRIVING VEHICLE COULD HEAR NOISE COMING FROM REAR OF CAB SIDE SKIRT BRACE WAS BROKEN OF BACK OF WEATHERSHIELD CUT OUT STAINLESS STEEL PLATE AND DRILLED HOLES IN PLATE BY MESURING UP FITTED TO TOP REAR OF CAB WITH RIVETS AND NUTS				
52433	06/07/2021	390466	CARRY OUT C SERVICE	Invoice
CARRY OUT C SERVICE ON VEHICLE ADJUSTED TURN TABLE INSPECTED AND REPAIRED L AND RHS MUDGUARD CLEARANCE SIDE MARKER LAMPS - CORRODED REPLACED LIGHT GLOBES DEFECTS: RHS 2ND DIFF MUDGUARD CRACKED FAN HUB NOT WORKING DRAG LINK WORN LHS CAB AIR BAG WORN SWAY BAR BUSHES WORN RHS 1ST DIFF REAR AIRBAG LEAKING AIR AIR DRIER LEAKING				
52351	24/06/2021	388025	CARRY OUT REPAIRS	Invoice
VEHCILE CAME IN WITH BATTERY LIGHT ON DASH CHECKED CHARGE RATE OF ALTERNATOR - LOW DISCONNECTED BATTERIES AND REMOVED OLD ALTERNATOR REPLACED ALTERNATOR AND CONNECTED BATTERIES TESTED ALL OK				
52138	24/05/2021	384332	LIGHTS ON DASH	Invoice
VEHICLE CAME IN WITH AD BLUE LIGHT ON DASH CONNECTED JELTEST TESTED ADBLUE/SCR SYSTEMS AND FOUND CONSEALED/BRITTLE WIRING AND SENSOR ON AD BLUE TANK REMOVED AND REPLACED ADBLE PICK UP SENDER STARTED ENGINE AND CHECKED OPERATION CLEARNED FAULT CODES, TEST DROVE - ALL OK				
52099	17/05/2021	384070	LIGHTS ON DASH	Invoice
VEHICLE CAME IN WITH ENGINE LIGHT ON DASH CONNETED SCAN TOOL AND FOUND CODES FROM VARIOUS ECM'S LOCATED AND REPAIRED INTERMITTENET FAULT TO BATTERY SUPPLY CABLE TO ALTERNATOR RUBBING ON TO P CLAMP CLEARED ENGINE CODES AND RECHECKED - ALL OK INSPECTED SEAT BELT FAULT - FOUND DRIVER SIDE SEAT HAD BEEN PUSHED BACK TO FAR - HITTING REAR OF SEAT BACK AND JAMMING THE SEATBELT VEHICLE HAD AN AIR LEAK AT BACK OF VEHICLE - FOUND THE BRAKE VALVE LEAKING AT THE REAR CROSS MEMBER REMOVED EBS VALVE, ALL AIR LINES AND PLUG. CLEANED THREADS AND INSPECT FOR DAMAGED - ALL OK INSTALLED FITTINGS TO NEW VALVE AND SECURED VALVE TO CHASSIS CROSSMEMBER REFIT AIR LINES AND ELECTRICAL PLUG TESTED VEHICLE LETTING IT BUILD UP AIR PRESSURE AND CHECKED FOR LEAKS - ALL OK				
52080	13/05/2021	383905	LIGHTS ON DASH	Invoice

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
VEHICLE CAME IN WITH LIGHTS ON DASH CONNECTED SCAN TOOL AND FOUND SCR CODES CLEARED CODES AND TEST DROVE. VEHICLE TESTED OK				
52031	10/05/2021	383589	LIGHT ISSUES	Invoice
VEHICLE CAME IN WITH SIDE LIGHTS NOT WORKING INSPECTED WIRING AND CONNECTIONS AND FOUND SUZI COIL DAMAGED - WIRING RIPPED OUT REPAIRED WIRING FAULTS IN SUZI COIL AND REPLACE TRAILER PLUG RECHECKED ALL TRUCK LIGHTS - ALL OK				
51984	30/04/2021	383501	SUZI COIL REPAIRS	Invoice
VEHICLE CAME IN AS TRAILER PLUG HAD BEEN RIPPED OUT REPAIRED TRAILER PLUG AND FIT NEW SUZI COILS DUE TO DAMAGED SUPPLY LINE USED PIPE SEALANT ON THE NEW FEMALE AND MALE AIR FITTINGS AND TESTED FOR AIR LEAKS - ALL OK				
51916	16/04/2021	382771	TRAILER LIGHTS NOT WORKING.	Invoice
PRE-START FOUND TRAILER PLUG DAMAGED VEHICLE CAME IN AND DAMAGED TRAILER PLUG WAS REMOVED AND REPLACED. LIGHT LEAD KEPT GETTING CAUGHT AND TRAILER PLUG WAS DAMAGED A SECOND TIME - REMOVED AND REPLACED AGAIN. VEHICLE CAME BACK IN FOR TRAILER LIGHTS NOT WORKING CHECKED CONNECTION @ SUZIE COIL TO TRAILER CONNECTORS - FOUND PIN HAD BEEN BENT - STRAIGHTENED UNIT. CHECKED AT END OF CAB AND ADJUSTED ALL PINS OUTWARDS CLEAN UNIT AND LIGHTS ALL WORKED				
51899	15/04/2021	382462	REPLACE SUZI COIL	Invoice
BLUE SUZI-COIL DAMAGED (CRUSHED). REMOVED AND REPLACED SUZI COILS - TESTED OK				
51891	15/04/2021	382332	REPLACE BATTERIES	Invoice
CONNECTED SCAN TOOL FOR BODY COMPUTER LOW VOLTAGE FAULT CHECKED ALTERNATOR - OK CHARGE RATE AT 28.2VOLT LOAD TESTED BATTERIES - FAILED REMOVED AND REPLACED 4 X BATTERIES, CONNECTED TERMINALS AND CHECKED CHARGE RATE OK. CLEARED CODES				
51887	15/04/2021	382332	REPLACE TAIL LAMPS	Invoice
REMOVE BROKEN TAIL LAMP ASSEMBLIES AND SUPPLY AND FIT NEW ONES.				
51825	01/04/2021	381756	HEADLIGHT GLOBE	Invoice
VEHICLE BROUGHT IN WITH LHS LOW BEAM HEADLIGHT GLOBE BLOWN REMOVED AND REPLACED HEADLIGHT GLOBE.				
51766	25/03/2021	381268	VEHICLE WONT START	Invoice
CALL OUT TO FUMO-PAD YARD/SHED 24 AREA TO JUMP START TRUCK - BATTERY FLAT REPAIR AND REFIT SCALES PLUG AND WIRING - DAMAGED				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
TESTED ALL OK				
51686	16/03/2021	380897	BREAKDOWN	Invoice
TRAVEL TO 24 INDUSTRY PLACE - (MAMMOTH EQUIPMENT) REMOVE BROKEN AIR LINE, AIR LINE AND FITTING HAD BEEN BLOWN OUT. REPLACED 8MM AIR LINE AND JOINER. TESTED OK				
51644	11/03/2021	379919	REPAIRS	Invoice
REMOVE BROKEN SCREWS FOR TAILLIGHT HOUSING FIT FOUR PENNY WASHERS TO GET VEHICLE LEGALLY MOVING AGAIN NEW TAIL LIGHT LENS NEEDS TO BE ORDERED				
51472	11/02/2021	377422	PUT AIR JOINER ONTO SEAT	Invoice
DATE WORK CARRIED OUT: 11/02/2021 WORK CARRIED OUT: FITTED AIR JOINER ONTO SEAT TO REPAIR CRACK IN LINE				
51453	05/02/2021	387837	CARRY OUT B SERVICE	Invoice
DATE WORK CARRIED OUT: 05/02/2021 WORK CARRIED OUT: CARRIED OUT B SERVICE  DEFECTS NOTED: <ul style="list-style-type: none"><li>- LHF LOWER BUMPER COVER MISSING</li><li>- LEAK FROM BELL HOUSING OR SUMP</li><li>- LHR LIGHT LENS BROKEN</li><li>- LHR CAB AIRBAG RUBBING THROUGH</li><li>- CAB REAR SWAY BAR BUSH WORN</li></ul>				
51450	05/02/2021	376837	A/C REPAIRS	Invoice
DATE WORK CARRIED OUT: 05/02/2021 WORK CARRIED OUT: CHECKED A/C FOUND GAS CHARGE LOW – ADDED GAS & UV DYE TO SYSTEM RECHECKED FOR LEAKS – NO LEAKS FOUND AT THE TIME CLEANED OUT BLOCKED POLLEN A/C FILTER CHECKED/LOCATED FAULTS TO LIGHTING WARNING COMING UP ON THE DASH FOUND/FIXED/CLEANED UP POOR GLOBE HOLDER CONNECTIONS AT L & R REAR LIGHTS REMOVED WATER FROM LHS SIDE MARKER LAMP HOLDER REPLACED U/S GLOBE & TESTED – ALL OK TOPPED UP ENGINE OIL AS FAULT LIGHT WAS ON				
51344	25/01/2021	375568	DAMAGED SUZI COIL	Invoice
DATE WORK CARRIED OUT: 25/01/2021 WORK CARRIED OUT:				

## Vehicle Details

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
REPLACED DAMAGED SUZI COIL				
RR:15321				
51342	21/01/2021	374889	SMASHED LIGHT ASSEMBLY	Invoice
<b>DATE WORK CARRIED OUT:</b> 21/01/2021 <b>WORK CARRIED OUT:</b> TRUCK CAME IN WITH SMASHED REAR LEFT LIGHT ASSEMBLY REPLACED REAR LEFT LIGHT ASSEMBLY WITH SECOND HAND ONE REPLACED INDICATOR & PARK LIGHT BULB				
51267	14/01/2021	373976	SUZI COIL & R/H WING BRACKET	Invoice
<b>DATE WORK CARRIED OUT:</b> 14/01/2021 <b>WORK CARRIED OUT:</b> REPAIRED RH CAB SIDE SKIRT BRACKET REPLACED AIRLINE SUZI COILS RR:15314 / 15316				
51216	06/01/2021	373542	JUMP START	Invoice
<b>DATE WORK CARRIED OUT:</b> 06/01/2020 <b>WORK CARRIED OUT:</b> DROVE TO BUCCINI YARD JUMP STARTED VEHICLE RETURNED TO WORKSHOP				
51217	06/01/2021	373542	DASH LIGHT FAULTS	Invoice
<b>DATE WORK CARRIED OUT:</b> 06/01/2020 <b>WORK CARRIED OUT:</b> DROVE TO BUCCINI YARD CHECKED FOR DASH LIGHT FAULTS AIRBAG RIDE HEIGHT FAULT – RESET AIRBAGS TRAILER BRAKES NOT RELEASING FAULT – RELEASED TRAILER BRAKE SWITCH ENGINE LIGHT ON – FUEL LEVEL LOW (NEEDS REFUELING) CHECKED ALTERNATOR BELTS – OK RETURNED TO WORKSHOP				
51233	04/01/2021	373342	JUMP START	Invoice
<b>DATE WORK CARRIED OUT:</b> 04/01/2021 <b>WORK CARRIED OUT:</b> TRAVELLED TO BT YARD JUMPSTARTED TRUCK RETURNED TO WORKSHOP				



**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
51064	09/12/2020	371695	AIRCON REPAIRS	Invoice
<b>DATE WORK CARRIED OUT:</b> 09/12/2020 <b>WORK CARRIED OUT:</b> INSPECTED A/C NOT WORKING FOUND GAS & POWER TO A/C COMPRESSOR ALL OK FOUND A/C BELT MISSING REPLACED A/C BELT PUT BATTERIES ON CHARGE AS TRUCK DIDN'T START				
51009	02/12/2020	371695	FAN BELTS & SUZI COILS	Invoice
<b>DATE WORK CARRIED OUT:</b> 02/12/2020 <b>WORK CARRIED OUT:</b> REPLACED DAMAGED SUZI COILS (AIR) REPLACED WORN BELTS  <b>RR:</b> 15309   15310				
50903	17/11/2020	370895	A/C ISSUE	Invoice
<b>DATE WORK CARRIED OUT:</b> 17/11/2020  <b>WORK CARRIED OUT:</b> INSPECTED AND TEST TO A/C SYSTEM FOUND SUCTION HOSE/PIPE ASSEMBLY LEAKING RECLAIMED GAS (380GMS) REMOVED AND REPLACED PIPE / HOSE ASSY AS REQUIRED EVACUATED / REGASED SYSTEM - TEST ALL OK				
50826	04/11/2020	369500	TURNTABLE REBUILD	Invoice
<b>DATE WORK CARRIED OUT:</b> 04/11/2020  <b>WORK CARRIED OUT:</b> INSPECTED AND TRIED TO ADJUST TURNTABLE FOUND IT IS RIGHT AT THE END OF THE ADJUSTMENT AND STILL HAS A LOT OF PLAY NEEDS A REKIT REMOVED TURNTABLE OFF TRUCK CLEANED ALL OVER AND INSIDE THE TURNTABLE TO REMOVE ALL OLD GREASE STRIPPED INTERNALS FITTED NEW KIT TO TURNTABLE REFITTED TO TRUCK TORQUED BOLTS TO JOST SPECS ADJUSTED TURNTABLE				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
50810	02/11/2020	369316	A SERVICE & REPAIRS	Invoice
DATE WORK CARRIED OUT: 02/11/2020				
WORK CARRIED OUT: COLLECTED VEHICLE FROM YARD				
CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET REPLACED CRANK CASE BREATHER FILTER REPLACED BENT GUARD POLE LH 3RD AXLE REPLACED MISSING MUDFLAP & MARKER PLATE LH 3RD REPLACED MISSING MUDFLAP & LH 2ND AXLE				
Requirements for next service are -				
VEHICLE STILL NEED TO HAVE THE BELTS REPLACED DUE IN TO WORKSHOP TODAY 3/11.				
50786	23/10/2020	368470	INTERIOR LIGHTS ISSUE	Invoice
DATE WORK CARRIED OUT: 23/10/2020				
WORK CARRIED OUT: INSPECTED INTERIOR LIGHTS FOUND SWITCH ON DASH FALLEN APART REPLACED WITH 2ND HAND SWITCH FROM ROLLER OVER TRUCK TESTED OK				
50611	06/10/2020	364724	REPLACE LIGHT BULBS	Invoice
DATE WORK CARRIED OUT: 06/10/2020				
WORK CARRIED OUT: COLLECT FROM YARD				
REPLACE RR TAIL LIGHT BULB REPLACE FR MUDGUARD MARKER LIGHT BULB RETURNED TO YARD				
50600	01/10/2020	364360	BREAKDOWN	Invoice
DATE WORK CARRIED OUT: 01/10/2020				
WORK CARRIED OUT: ATTEND BREAKDOWN & HUTCHISON PORT				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
TRAVELLED TO SITE AND REPLACED SUZI COILS				
50566	29/09/2020	363943	TOP UP ENGINE OIL	Invoice
DATE WORK CARRIED OUT: 29/09/2020  WORK CARRIED OUT: TOPPED UP ENGINE OIL				
50535	24/09/2020	363637	PAINT STEP & INSTALL	Invoice
DATE WORK CARRIED OUT: 22/09/2020 - 24/09/2020  WORK CARRIED OUT: PREPARED PLASTIC FOR UNDER COAT SANDED , PRIMED , PAINTED STEP REMOVED AND REPLACED DAMAGED DRIVER STEP DELIVERED TO YARD				
50389	01/09/2020	0	TAILSHAFT	Invoice
DATE WORK CARRIED OUT: 01/09/2020 WORK CARRIED OUT: DROPPED REAR UNI ON TAILSHAFT AND DISCONNECTED SHAFT FROM FRONT UNI JOINT, ALIGNED TAILSHAFT WITH FRONT UNI JOINT, REFITTED AND TIGHTENED ALL BOLTS (ALL LOOSE) REPLACED DAMAGED SUZI COILS. REPAIRED WIRING TO SCALE PLUG. REPLACED DAMAGED ABS PLUG HOUSING (INTERNALS OK).  **TRUCK REQUIRES A LONGER CAT WALK TO PREVENT SUZI'S AND CABLES BEING LEFT TO DROP DOWN AND HANG IN THE TAILSHAFT**				
50327	24/08/2020	359160	CARRY OUT B SERVICE	Invoice
DATE WORK CARRIED OUT: 24/08/2020  WORK CARRIED OUT: CARRIED OUT B SERVICE AS PER HVW SERVICE SHEET REPLACED WIPER BLADES REPLACED BLOWN R/H BRAKE LIGHT BULB REPLACED SCALE PLUG (CUSTOMER SUPPLIED)  PICKED UP AND COLLECTED VEHICLE FROM BT YARD				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>		<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>		<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	133360	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	6F2SFAT00ADT30101	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	2010	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	506039	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
<b>FURTHER ACTION REQUIRED-</b>				
STEER TYRES LOW TOP STEP DRIVER SIDE BROKEN CLIP OFF AIR BOX COVER MISSING ENGINE BREATHER COVER LEAKING OIL - REPLACE FILTER PLUG FOR SCALES NEEDS CHANGING				
50270	12/08/2020	357503	COOLANT LEAK	Invoice
DATE WORK CARRIED OUT: 12/08/2020  WORK CARRIED OUT: INSPECT COOLANT LEAK FOUND TOP RADIATOR HOSE CLAMP (ENG SIDE) LOOSE REPLACED HOSE CLAMP TOPPED UP COOLANT				
50254	12/08/2020	356249	REPLACE SCALE SOCKET	Invoice
DATE WORK CARRIED OUT: 12/08/2020  WORK CARRIED OUT: DROVE TO YARD  REPLACE TORN OUT SCALE SOCKET ZIP TIED UP PLUG LEAD				
50271	11/08/2020		INSPECT DAMAGE	Invoice
DATE WORK CARRIED OUT: 11/08/2020  WORK CARRIED OUT: INSPECT DAMAGE ON TRUCK AND INSPECT SHAKE ON STEERING WHEEL. FOUND TO BE OUT OF ALIGNMENT AND TYRES NEED TO BE RE BALANCED INSPECTED DAMAGE ON TRAILERS AND DOLLY REAR MUDGUARD BRACKET WILL NEED TO BE RE WELDED BACK INTO PLACE AND MUDGUARD TO BE REPLACED INSPECTED DAMAGE TO DOLLY DRAW BAR HAS SLIGHT BEND IN LEFT DRAW BAR				
50234	04/08/2020	356652	REPLACE MIRROR	Invoice
DATE WORK CARRIED OUT: 04/08/2020				

**Vehicle Details**

<b>Registration</b>	556RPT	<b>Next Service</b>	<b>Litres</b>	
<b>Make</b>	IVECO	<b>Rego Due</b>	<b>Trans</b>	N/A
<b>Model</b>	STRALIS	<b>Engine #</b>	<b>Air</b>	Yes
<b>Model Series</b>		<b>VIN</b>	<b>Cyl</b>	0
<b>Model Code</b>		<b>Build Date</b>	<b>Body</b>	PRIMEMOVER
<b>Colour</b>	White	<b>Odometer</b>	<b>Prod</b>	2010

Invoice No.	Date	Odometer	Description	Type
WORK CARRIED OUT: REMOVE AND REPLACE U/S LHS MIRROR DELIVERED TRUCK TO YARD				

<b>50048</b>	<b>09/07/2020</b>	<b>0</b>	<b>SERVICE &amp; REPAIRS</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 09/07/2020 - 10/07/2020				
WORK CARRIED OUT: CARRIED OUT C SERVICE REPLACED AIR DRYER FILTER FITTED NEW WIPER BLADES TIGHTENED UP REAR HOUSING ON BACK OF TIMING COVER REPAIRED WEIGH SCALE WIRING & REFITTED ELECTRICAL PLUG REPAIRED ABS PLUG CLIP				
<b>DEFECTS NOTED ON SERVICE</b>				
L/H TAIL LIGHT LENS CRACKED V STAY BUSHES WORN (MONITOR) - FRONT DRIVE DIFF (REPLACE) TRACK ROD BUSHES WORN SUMP GASKET LEAKING REAR TIMING COVER LEAKING BACK OF MOTOR TIE ROD END BALL JOINTS WORN DRAG LINK WORN TURN TABLE FEET BUSHES HAVE MOVEMENT KING PIN MINOR MOVEMENT (MONITOR) CAB MOUNT SHOCKIES WORN AND RUBBING (REPLACE)				

<b>50097</b>	<b>02/07/2020</b>	<b>0</b>	<b>DOLLY FOOT LOCK PIN</b>	<b>Invoice</b>
DATE WORK CARRIED OUT: 2/07/2020				
WORK CARRIED OUT: INSPECT ISSUE WITH DOLLY FOOT LOCK PIN FOUND PIN TO BE BENT AGAIN - STRAIGHTENED PIN BACK OUT, RE HUNG FOOT AND LOCKS IN FINE				