



Vehicle History

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
61367	07/08/2025	58353	DEFECTS	Invoice
COLLECTED VEHICLE FROM SHED 24 TYRES AND MORE COMPLETED WORK RETURN VEHICLE TO SHED 24				
60573	18/02/2025	42542	BRAKE ADJUSTMENT	Invoice
ADJUST BRAKES <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u>				
60490	05/02/2025	42542	BRAKE BOOSTER	Invoice
REMOVE HARDWARE FROM BOOSTER REMOVED BRAKE BOOSTER COLLECT PART FROM SUPPLIER LOOSENE CLAMP ROTATED BOOSTER TIGHTENED CLAMP FIT AIR FITTINGS FIT AIR LINES TO BOOSTER FIT BOOSTER TO TRAILER PUT AIR IN TRAILER FIT FORK PACKED TOOLS CLEANED AREA DISPOSED OF OLD PART <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE COREY FOR PRICING ON - 07 3260 8950</u>				
60188	26/11/2024	35355	LABOUR - BUCCINI	Invoice
PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER				

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
			CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY REMOVED RH SAFETY ROP, SIDE MARKER LIGHTS, WIRING AND LIGHT BRACKETS REMOVED TWISTLOCK HOUSING GROUND ALL WELD ON TWISTLOCK BEAM CARRY OUT INSTALL OF NEW TWIST LOCK BOX AND WELD INTO PLACE, PRIME AND PAINT WELDED SURFACES APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP	

60060	30/10/2024	29933	DAY LABOUR	Invoice
			CARRY OUT REPLACEMENT OF DAMAGED TWIST LOCK TWIST LOCK FROM 237QXK NEW TWIST LOCK ORDERED <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	

59855	18/09/2024	29933	ASSESS DAMAGE	Invoice
			REPAIR DAMAGE CAUSED BY INCIDENT ASSESS DAMAGE QUOTE DAMAGE CUT, CLEAN AND REWELD NEW TWIST LOCK (FRONT RIGHT) PUT 2 NEW LIGHT BRACKETS CLEAN, GRIND AND PAINT REPLACE 2 MARKER LIGHTS <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND</u>	

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
<u>MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				

59831	18/09/2024	29933	LABOUR - BUCCINI	Invoice
-------	------------	-------	------------------	---------

PARKED TRAILER IN WORKSHOP CHECKED FOR AIRBAG RIDE HEIGHT FAULT REPOSITIONED ROD MOUNT FOUND LH #1 AXLE AIRBAG BLOWN REMOVED AIRBAG FITTED NEW AIRBAG FITTED NEW MUDGUARD AND MUDFLAP ADJUSTED AIRBAG RIDE HEIGHT VALVE FOUND RH #1 AXLE BROKEN SHOCK ABSORBER MOUNTING BOLT MOVED SHOCK ABSORBER DRILLED OUT BOLT AND USED EASY OUT TO REMOVE BROKEN BOLT BOLT STILL SEIZED REMOVED BRAKE BOOSTER FITTED NEW SHOCK ABSORBER MOUNTING BOLT KIT REFITTED BRAKE BOOSTER CLEAN AREA AND PACK AWAY TOOLS COMPLETE PAPERWORK <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>				
---	--	--	--	--

59325	03/06/2024	23245	A SERVICE	Invoice
-------	------------	-------	-----------	---------

PARK TRAILER IN WORKSHOP CARRY OUT A SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK WHEEL BEARINGS FOR MOVEMENT CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL TENSION CHECK WHEEL BEARING GREASE FOR CONTAMINANTS CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA MOVE TRAILER OUT OF WORKSHOP NOTE RHF SIDE LIGHT REPLACED				
---	--	--	--	--

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
			RHM SIDE LIGHT REPLACED LHR BRAKE LIGHT LESS THAN 70% TYRES RUST IN REAR BAR DOCK RUBBERS DAMAGED REMOVE TAIL LIGHT REMOVE AND REPLACE REFLECTORS REMOVE AND REPLACE 2 SIDE MARKER LIGHTS <u>HEAVY VEHICLE WORKSHOP WELCOMES HEMMANT TYRES & MORE ABOARD - STOCKING A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING. PHONE JEFF FOR PRICING ON - 07 3260 8950</u>	

58102	02/11/2023	10848	C SERVICE	Invoice
			TRAVEL TO SHED 24 AND COLLECT THE TRAILER PARK TRAILER IN WORKSHOP CARRY OUT C SERVICE AS PER SERVICE SHEET APPLY AIR TO TRAILER TEST LIGHTING FUNCTION LIFT TRAILER WITH HOIST CHECK SUSPENSION COMPONENTS CHECK KING PIN BOLT TENSION CHECK SKID PLATE CHECK THE UNDERCARRIAGE OF THE TRAILER CARRY OUT GREASING OF AXLES CARRY OUT DE-ADJUSTMENT OF BRAKES REMOVE HUB CAPS AND REMOVE BEARING ADJUSTMENT NUTS REMOVE BEARINGS FROM HUBS CLEAN STUB AXLES AND APPLY NEW FILM OF GREASE TO STUB AXLES CLEAN BEARINGS IN TURBO WASH CLEAN HUBS OF GREASE AND REPACK HUBS AS REQUIRED REMOVED BEARINGS FROM PARTS WASHER BLOW OUT WITH AIR AND REPACK BEARINGS INSTALL BEARINGS TO HUBS INSTALL INNER HUB SEALS INSTALL HUBS TO THE TRAILER AND TENSION-BEARING ADJUSTMENT NUTS SECURE BEARING ADJUSTMENT NUTS WITH RETAINERS REINSTALL HUB CAPS TO AXLES AND TENSION HUB CAPS CARRY OUT ADJUSTMENT OF BRAKES LOWER TRAILER CHECK WHEEL NUT TENSION CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVRONS, AND OVERTAKE SIGNAGE CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY APPLY SERVICE STICKER COMPLETE PAPERWORK CLEAN WORK AREA ***** WELDED BRACKETS OF LEGS ON TRAILER PAINTED WELDED AREAS MOVED TRAILER BACK TO SHED 24	

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
-------------	------	----------	-------------	------

HEAVY VEHICLE WORKSHOP NOW STOCKS A WIDE RANGE OF TYRES FOR TRUCKS, TRAILERS, BUSES, LIGHT VEHICLES, AND MACHINERY AS WELL AS FITTING & BALANCING PLEASE ENQUIRE TODAY FOR SIZING AND PRICING.

57170	08/06/2023	16039	A SERVICE AND REPAIRS	Invoice
-------	------------	-------	-----------------------	---------

PARKED VEHICLE IN WORKSHOP
CARRY OUT A SERVICE AS PER SERVICE SHEET

- APPLY AIR TO TRAILER
- TEST LIGHTING FUCTION
- LIFT TRAILER WITH HOIST
- CHECK WHEEL BEARINGS FOR MOVEMENT
- CHECK SUSPENSION COMPONENTS
- CHECK KING PIN BOLT TENSION
- CHECK SKID PLATE
- CHECK UNDERCARAGE OF TRAILER
- CARRY OUT GREASING OF AXLES
- CARRY OUT ADJUSTMENT OF BRAKES
- LOWER TRAILER
- CHECK WHEEL TENSION
- CHECK WHEEL BEARING GREASE FOR CONTAMINENTS
- CHECK ALL LIVERY INCLUDING MUDFLAPS AND DECAL
- INSPECT MARKER PLATES INCLUDING CON SIGN, CHEVERONS AND OVER TAKE SIGNAGE
- CHECK TOP DECK OF TRAILER FOR ALL FUNCTIONALITY
- APPLY SERVICE STICKER
- COMPLETE PAPER WORK
- CLEAN WORK AREA

REMOVE BROKEN GUARD

STRAIGHTEN UP BRACKET

TRAILER PLUG REMOVED, CHECKED WIRING AT THE BACK OF PINS - ALL OK

CUT OFF REAR MUDGUARD BRACKET

STRAIGHTENED IT WITH THE OXY

CLEANED ALL WELDS AND PAINTED

STRAIGHTENED MIDDLE MUDGUARD BRACKET

MEASURED HOLES AND DRILL NEW HOLES IN NEW BLUE MUDGARD FITTED AND ATTACHED A BUCCINI MUDFLAP TO THE GUARD

REMOVE AND REPLACE RHF AIRBAG

REMOVE AND REPLACE RIDE HEIGHT RUBBER

REMOVE T PIECE FROM RHF AIRBAG AND REPLACED WITH NEW T PIECE

REMOVE AND REPLACE RED/AMBER MARKER LIGHT

56438	13/04/2023	0	RHS STOP/TAIL LIGHT MISSING	Invoice
-------	------------	---	-----------------------------	---------

TRAILER CAME IN WITH RHS STOP/TAIL LED MISSING

FOUND A SIMILIAR ONE IN CUPBOARD AND HOOKED IT UP BUT IT HAD A WHITE REVERSE LIGHT INSTEAD OF A AMBER INDICATOR

REMOVED AND ZIPTIED WIRING OUT OF THE WAY

TRAILER NEEDS TO COME BACK AND HAVE CORRECT LIGHT ORDERED AND FITTED

55860	30/01/2023	0	REPLACEMENT OF LHF + LHR TWIST	Invoice
-------	------------	---	--------------------------------	---------

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
CARRY OUT REPLACEMENT OF LHF + LHR TWIST LOCK ASSEMBLIES				
55485	02/12/2022	0	TWIST LOCK ASSMBLY	Invoice
SUPPLY TWIST LOCK AND FIT TWIST LOCK.				
55398	22/11/2022		CARRY OUT REPAIRS	Invoice
BROUGHT TRUCK INTO THE WORKSHOP REPLACED LH #3 AXLE AIRBAG REPLACED LH REAR MUDFLAP PARKED TRAILER AT SHED 24				
55199	24/10/2022		C SERVICE - DAMAGED GUARD	Invoice
BROUGHT VEHICLE INTO WORKSHOP CARRIED OUT C SERVICE SECURED AIRLINE AND ELECTRICAL CABLES REPAIRED RH SAFETY ROPE STRAIGHTENED LH #3 AXLE MUDGUARD BRACKETS REPLACED REAR MUDFLAPS REPLACED RH FRONT TWISTLOCK PARKED AT SHED 24				
54206	20/06/2022	123308	LR BOOSTER LEAKING ON SUPPLY SIDE -	Invoice
LR BOOSTER LEAKING ON SUPPLY SIDE - NEEDS REPLACING REMOVE LEAKING BOOSTER SCAN & CAGED NEW BOOSTER. SWAPPED FITTINGS FIT NEW BOOSTER FOR CR AND CHECKED FOR ANY LEAKS - ALL OKAY				
53754	24/02/2022	119815	A SERVICE AND REPAIRS	Invoice
24/2/2022 CARRIED OUT A SERVICE REPLACED AND FIT NEW MARKER LIGHT REPLACED AND FIT NEW RHS REAR MUDGUARD REPLACED AND FIT NEW 1ST AXLE RHS BOOSTER REPLACED AND FIT NEW MUDFLAP				
53461	30/12/2021	115062	AIR LEAK	Invoice
DRIVER BROUGHT IN TRAILER LEAKING AIR FROM MALE COUPLING REMOVED AND REPLACE AIR COUPLING AND TESTED OPERATION - ALL OK				
53132	09/11/2021	111306	REPLACE BLOWN AIR BAG	Invoice
DIAGNOSED AIR BAG FAILURE TRAVELLED TO SUPPLIER TO PICK UP REPLACEMENT AIRBAG WHEN BACK IN WORKSHOP REMOVED OLD AIR BAG EXISTING TOP MOUNTING NUTS WERE SEIZED AND THREAD WAS DAMAGED LIFTED REAR OF TRAILER AND FIT NEW AIRBAG FIT NEW NUTS, PIPE SEALANT ON FITTING AND TIGHTENED TESTED OPERATION - ALL OK MOVED TRAILER ON TO STREET FOR COLLECTION				
53043	25/10/2021	110240	CARRY OUT C SERVICE	Invoice

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
<p>CARRY OUT C SERVICE ON VEHICLE DIAGNOSED FAILED RIDE HEIGHT VALVE - DISCONNECTED ALL AIR LINES AND DRAINED AIR TANK CONNECTED NEW VALVE AND SECURE INTO PLACE ADJUSTED - ALL OK INSPECTED SHOCK ASBORBERS FOUND FRONT LHS AXLE SHOCK FAILED - BROKEN IN HALF LHS REAR AND MIDDLE RHS SHOCK ABSORBERS FAILED REMOVED AND REPLACED SHOCKS ABSORBERS AND FIT SHOCK STRAPS TIGHTENED LHS REAR LOWER RETAINING NUT AND FIT BACK BOOSTER DEFECTS: AIR BAGS CRACKING AT BASE RHS REAR MUDFLAP TORN REAR RUBBER BUMP STOPS DAMAGED</p>				
51465	03/02/2021	91759	A SERVICE	Invoice
<p>DATE WORK CARRIED OUT: 03/02/2021 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED: - LHF SHOCK ABSORBER BROKEN</p>				
51343	25/01/2021	90088	PIN FAULT	Invoice
<p>DATE WORK CARRIED OUT: 25/01/2021 WORK CARRIED OUT: INSPECTED FAULT WITH THE PINS THAT HOLD THE CONTAINER ON WAS SITTING 10MM HIGH OPERATED PIN AND TRIED TO FAULT OPERATION OF PIN – COULDN'T FAULT TRIED PRYING PIN DOWN – NO FAULT LOOKED AT LOCKING TABS ON TRAILER SPRAYED SOME LUBE IN MECHANISM AND OPERATED PINS – COULDN'T FAULT COULDN'T FAULT TRAILER PIN CONTAINER MAY HAVE BEEN DEFECTIVE AND THAT'S WAY IT WAS SITTING HIGHER THEN USUAL</p>				
50875	11/11/2020	0	A SERVICE	Invoice
<p>DATE WORK CARRIED OUT: 10/11/2020 – 11/11/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE DEFECTS NOTED - AIR BAGS HAVE AGE CRACKS</p>				
50723	22/10/2020	83323	C SERVICE & REPAIRS	Invoice
<p>DATE WORK CARRIED OUT: 20/10/2020</p>				

Vehicle Details

Registration	236QXK	Next Service	Litres	
Make	KRUEGER	Rego Due	Trans	N/A
Model	40' TRI AXLE SKEL	Engine #	Air	No
Model Series		VIN	Cyl	0
Model Code		Build Date	Body	SKEL
Colour		Odometer	Prod	2014

Invoice No.	Date	Odometer	Description	Type
WORK CARRIED OUT: CARRIED OUT C SERVICE AS PER HVW SERVICE SHEET STRAIGHTENED RH FRONT SIDE MARKER LIGHT AND BRACKET REPLACED RH FRONT SIDE MARKER LIGHT HOUSING REPLACED LH SAFETY ROPE SPRING REPLACED NUMBER PLATE LIGHT REPLACED KING PIN & BOLTS REPLACED SERVICE BRAKE COUPLING				
50359	28/08/2020	79853	CARRY OUT A SERVICE	Invoice
DATE WORK CARRIED OUT: 28/08/2020 WORK CARRIED OUT: CARRIED OUT A SERVICE AS PER HVW SERVICE SHEET TIGHTENED AIR TANK BOLTS FURTHER ACTION REQUIRED - RHC SHOCKIE WEEPING				
50056	14/07/2020	77250	INSPECT DAMAGE TWIST LOCK BEAM	Invoice
DATE WORK CARRIED OUT: 25/06/2020 - 14/07/2020 WORK CARRIED OUT: INSPECT & MEASURE DAMAGED TWIST LOCK BEAM REMOVED #5 TWIST LOCK BEAM HOUSINGS REMOVED ALL MUD-GUARDS, AIRLINES, & WIRING CUT OUT BEAM & CLEANED SURFACE FITTED WELDED NEW BEAM, TWIST LOCK HOUSING UNDERCOATED & PAINTED TWIST LOCK BEAM FITTED ALL MUDGUARDS AIRLINES, RE SOLDERED ALL WIRING REPLACED RH SAFETY ROPE REPLACED RH FRONT MARKER LIGHT HOUSING REPLACED RH #4 SIDE MARKER LIGHT				