



Vehicle History Summary

Fleet #	
Registration	
Make	Kenworth
Model	T610
VIN / Chassis #	6F5000000HA459932
Build Date	21/12/2024

Date	Reading / Units	Type / Repairer Notes	Repairer
03/09/2026	997,048 kms	A - 10k S-2141 A Service, replace L/H front drive tyres 2x replace leaking pinion seal and worn yoke	
11/08/2026		Breakdown, shock absorber R-4256 Had cummins attend + diagnose ordered shock rubbers + ambient air temp sensor + drain locks	Internal Workshop
10/08/2026		Coolant Top Up, GREASE, Radiator R-4254 Bled + topped up coolant tightened coolant filter grease + brake adjustment tightened leaking lower radiator hose tightened leaking filler neck hose clamp	Internal Workshop
14/07/2026	977,913 kms	air leak, clearance lights, tailgate, tow eye bush R-4243 Removed + replaced tow eye bush removed + replaced faulty tailgate ram fixed air leak on dolly repaired break on clearance light P/S truck	Internal Workshop
02/07/2026	974,492 kms	trailer plug, wiring R-4226 removed = replaced faulty trailer wiring harness inspected plug for damages / corrosion	Internal Workshop
29/06/2026	973,031 kms	airbag, tow eye bush R-4225 removed + replaced bent airbag saddle 1st axle dolly D/S removed + replaced tow eye bush	Internal Workshop
24/06/2026	957,006 kms	B - 50k S-2055 B SERVICE	Internal Workshop
23/06/2026	970,642 kms	airbag, air leak, brake, reverse switch R-4220 Diagnosed faulty reverse switch inspected air leak on dolly - found bent airbag saddle Adjusted brakes per driver complaint	Internal Workshop
15/06/2026	965,812 kms	exhaust, Starting and Charging system, tail lights, Turbo R-4216 inspect dim taillight operations - faulty earth remove + replace exhaust stock rubbers remove + replace turbo dump rubbers	Internal Workshop
13/06/2026	965,812 kms	interior light, Tarp, trailer lights R-4214 Removed + replaced P/S headlamp unit removed + replaced taillights on dog trailer secured tarp removed + replaced x2 taillight assemblies on dog	Internal Workshop
09/06/2026	964,304 kms	tyres R-4210 Removed + replaced P/S 3rd axle trailer outer with runout Removed + replaced P/S 4th axle inner + outer tyres	Internal Workshop
25/05/2026		wiring R-4259 repaired broken wiring in P/S step lights	Internal Workshop
07/05/2026	953,667 kms	Hydraulics, mudflap R-4190 Removed and replaced failed hydraulic coupling Changed 4 Mudflaps on dog trailer for shorter mudflaps	Internal Workshop
19/03/2026	937,023 kms	A - 10k S-2056	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		A SERVICE	
28/02/2026	927,995 kms	A - 10k S-1850 Completed "A" service.	Internal Workshop
24/02/2026	926,340 kms	Drive T-519 Replaced four drive tyres Replaced outer and inner trailer tyres opposite sides of axle and paired other two up	Internal Workshop
13/02/2026	918,000 kms	A - 10k S-1849 Completed "A" service.	Internal Workshop
28/01/2026	908,075 kms	A - 10k S-1848 Completed "A" service.	Internal Workshop
19/12/2025	899,013 kms	A - 10k S-1847 Completed "A" service.	Internal Workshop
27/11/2025	895,674 kms	BRAKES R-3051 Fitted new drive shoes n drums to 1st drive Fitted missing bolt to leaking fuel pump B serviced coolabah engine	Internal Workshop
20/11/2025	894,097 kms	Hydraulics R-3493 Removed and replaced hydraulic coupling, tested all components for serviceability - all in working condition.	Internal Workshop
05/11/2025	893,969 kms	Brakes, fuel leak. R-3516 fitted new brake shoes, fixed leaking fuel pump	Internal Workshop
31/10/2025		Torque rod Bushes R-3557 installed new plate, replaced torque rod brushes	Internal Workshop
31/10/2025	890,000 kms	B - 50k S-1696 Completed B service	Internal Workshop
31/10/2025	889,860 kms	body R-3023 Removed cracked plate and gusset, installed new plate. Removed and replaced torque rod bushes. Torqued all bolts to spec, tested components - all in working condition.	Internal Workshop
28/10/2025		nhvr sticker, number plate, Tarp R-3545 fit new NHVS stickers, bent number plate holder out, bent tarp hook back into position	Internal Workshop
22/10/2025		wheel nut indicators R-3538 installed wheel nut indicators	Internal Workshop
09/10/2025	885,724 kms	light, shock absorber, slack adjusters, Torque rod Bushes, TYRE, windscreen washers R-3522 replaced washer motor, replaced drive lights, replaced 2 torque rod bushes, replaced steer shock, replaced 3 shocks on truck, replaced door hinge, put new slack adjuster,	Internal Workshop
08/08/2025	889,200 kms	A - 10k S-1844 Completed "A" service.	Internal Workshop
05/04/2025	879,209 kms	A - 10k S-1843 Completed "A" service.	Internal Workshop
05/01/2025	869,900 kms	A - 10k S-1300 Completed "A" service.	
10/12/2024	703,832 kms	air leak R-1288 at time of test no fault found	
09/10/2024	853,677 kms	Ad Blue, Brakes, hubseal R-871 new hub seal new brake shoe on drum 1 brake shoe 1 brake drum 1 adblue injector	Internal Workshop
01/10/2024	859,916 kms	A - 10k S-643	Internal Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		A Service Carried out A Service Checked all Levels. All ok	
09/09/2024	844,610 kms	Transmission, TYRE R-728 4 drive Tyres 2 steer Tyres 17L Gearbox oil 1 PTO	Internal Workshop
28/07/2024	850,002 kms	A - 10k S-1846 Completed "A" service.	Internal Workshop
19/07/2024	840,445 kms	C - 100k S-648 Service Carried out Service Changed Oil Filter Oil Coolant All Ok	Internal Workshop
12/07/2024	837,759 kms	Axle Seals, belt R-746 Replaced noisy A/C belt and tensioner had new seat fitted	Internal Workshop
08/07/2024	835,338 kms	belt R-745	Internal Workshop
06/06/2024	832,200 kms	A - 10k S-1845 Completed "A" service.	Internal Workshop

Signed: _____

Name: _____

Date: _____