

2018 Kenworth T659 SN 463032 TKP00755

Work Order	Plant Description	Type	Work Description	Finish Date	Actual Cost	
011169	KENWORTH T659 PR MOVER	P2	REPLACE FRONT DIFF INPUT SEAL NUT	27/11/2019	0.00	7000hrs
010730	KENWORTH T659 PR MOVER	P2	N134609-INPUT SHAFT FRONT DIFF	20/12/2019	1,136.68	7000hrs
029045	KENWORTH T659 PR MOVER	P2	REPLACED REAR ENGINE MOUNTS	29/06/2020	0.00	11640hrs
033138	KENWORTH T659 PR MOVER	P2	REPLACED ENGINE FAN	16/10/2020	0.00	
037806	KENWORTH T659 PR MOVER	P2	FIT NEW DIFF TO FIRST DRIVE AXLE	30/12/2020	0.00	14548hrs
037273	KENWORTH T659 PR MOVER	P2	REPLACED DRIVE SHAFT FROM CENTRE BEARING FRONT DIFF	31/12/2020	0.00	14548hrs
035868	KENWORTH T659 PR MOVER	P2	NPR127681, ENZED TO SUPPLY FITTING DIFF 5017023	3/02/2021	0.00	1600hrs
036524	KENWORTH T659 PR MOVER	P2	N117039-NEW DIFF QUOTE	10/02/2021	0.00	1600hrs
036966	KENWORTH T659 PR MOVER	P2	DIFF REMOVAL	14/02/2021	0.00	1600hrs
038656	KENWORTH T659 PR MOVER	P2	SUPPLY NEW DIFF CENTRE	6/03/2021	6,484.50	1600hrs
045000	KENWORTH T659 PR MOVER	P2	Remove old engine and replace with new one and turbo Cummins	22/04/2021	0.00	
043442	KENWORTH T659 PR MOVER	P2	NPR155540 Cummins to replace engine @ 16755 hrs	19/05/2021	6,436.00	16755hrs
048062	KENWORTH T659 PR MOVER	P2	Replaced rear diff. Removed and install rear diff	23/06/2021	0.00	17000hrs
048240	KENWORTH T659 PR MOVER	P2	Cleaned around front diff, removed axles and bolts around	29/06/2021	0.00	
050579	KENWORTH T659 PR MOVER	P2	Remove and replace uni at gearbox. Remove and replace RH day	28/07/2021	0.00	18356hrs
059034	KENWORTH T659 PR MOVER	P2	Remove/replace front diff. Rear diff yoke. Through shaft	28/11/2021	0.00	20000hrs
061621	KENWORTH T659 PR MOVER	P2	B&H 30.12.2021: ESTDIFREB Strip, inspect, quote and rebuild	3/02/2022	10,435.20	21262hrs
063951	KENWORTH T659 PR MOVER	P2	Replace front Diff.	12/02/2022	0.00	21903hrs
072170	KENWORTH T659 PR MOVER	P2	B&H supply gearbox, clutch & access as per quote @ 24347hrs	21/06/2022	0.00	24346hrs
072972	KENWORTH T659 PR MOVER	P2	GEAR BOX AND CLTUCH	21/06/2022	0.00	24346hrs
073037	KENWORTH T659 PR MOVER	P2	G/BOX U/S	21/06/2022	0.00	24346hrs
077989	KENWORTH T659 PR MOVER	P2	REAR DIFF PINION, REPLACE AXLE AND YOKE	7/07/2022	0.00	
073154	KENWORTH T659 PR MOVER	P2	Wrights to do repairs to rear diff housing	8/07/2022	226.00	
085484	KENWORTH T659 PR MOVER	P2	Replaced SCR harness across gearbox	7/12/2022	0.00	
086525	KENWORTH T659 PR MOVER	PM	Strip and assess front diff 222471	22/12/2022	0.00	
090824	KENWORTH T659 PR MOVER	P2	Repairs to diff 222471	9/02/2023	7,384.04	28296hrs
092161	KENWORTH T659 PR MOVER	P2	Replace Harness engine	20/02/2023	2,023.99	28300hrs
112398	KENWORTH T659 PR MOVER	P2	Quote to repair dfff 203563	21/11/2023	10,128.51	33332hrs
114496	KENWORTH T659 PR MOVER	P2	Install front diff	21/11/2023	0.00	33332hrs
117667	KENWORTH T659 PR MOVER	P2	Quote to repair diff 203598	5/02/2024	8,858.91	34754hrs
121682	KENWORTH T659 PR MOVER	P2	Replace diff lock out kit	21/03/2024	0.00	
123757	KENWORTH T659 PR MOVER	P2	Replace Engine	23/04/2024	85,613.50	35652hrs
123787	KENWORTH T659 PR MOVER	P2	Replace engine harness	24/04/2024	1,873.99	35652hrs
124650	KENWORTH T659 PR MOVER	P2	Changed front right hand diff hub seal	27/04/2024	0.00	
126534	KENWORTH T659 PR MOVER	P2	Replace rear diff	27/05/2024	0.00	35970hrs
126754	KENWORTH T659 PR MOVER	P2	Quote to repair diff 222471	28/05/2024	6,537.59	35970hrs
136726	KENWORTH T659 PR MOVER	P2	Replace engine mounts and center bearing	4/10/2024	1,167.98	
138515	KENWORTH T659 PR MOVER	P2	Front engine mounts, replaced	25/10/2024	957.00	
147040	KENWORTH T659 PR MOVER	P2	Fixed wiring loom rubbers, fixed bully bar, fixed grease	5/03/2025	0.00	
149193	KENWORTH T659 PR MOVER	P2	SUPPLY PARTS FOR ENGINE MIDLIFE		8,880.31	
150303	KENWORTH T659 PR MOVER	P2	Replaced front diff = LH /RH axles, Replaced through bearing	24/04/2025	0.00	41446hrs

151630	KENWORTH T659 PR MOVER	P2	Replace engine oil filter & cabin filter, Replace Fuel	16/05/2025	0.00	42614hrs
150511	KENWORTH T659 PR MOVER	P2	TKP755 FRONT DANA DIFF QUOTE	30/06/2025	4,166.62	
160314	KENWORTH T659 PR MOVER	P3	REPLACE DRIVELINE GEARBOX TO FRONT DIFF - BREAKDOWN CALL	22/09/2025	0.00	
163446	KENWORTH T659 PR MOVER	P2	REPLACED LEAKING DIFF PINION SEAL	1/11/2025	0.00	