

2020 Kenworth T659 SN 467287 TKP00767

Work Order	Description	Start Date	Status
017532	N133947-CUMMINS TO ADJUST SPEED LIMIT	04/18/2020	F
018122	C-(A) 250HR SERVICE @ 226 (250) HR TKP KENWORTH T659	05/01/2020	F
018341	N133834-VHF UPDATE	05/03/2020	F
019769	DRAIN HYDR OIL , REMOVE PTO PUMP, CLEAN UP SURFACE I=OF	05/06/2020	F
018618	N134449-HEADLIGHT HARNESS RUINED BY FITTER	05/08/2020	F
019987	FIT ESOC FITTINGS	05/08/2020	F
020012	RETENTION SUSPENSION	05/08/2020	F
018941	C-(B) 500HR SERVICE @ 524 (500) HR SERVICE TKP KENWORTH	05/17/2020	F
021647	REPLACED DASH LAMP BULB	05/30/2020	F
022286	2 X SP382 385/65R 22.5 STEER TYRE	06/04/2020	F
019674	C-(A) 250HR SERVICE @ 795 (750) HR TKP KENWORTH T659	06/05/2020	F
020150	N133680-GOODYEAR DRIVE TYRES	06/10/2020	F
022926	REPLACED DRIVE TYRES AS REQUIRED, TORQUED WHEEL NUTS	06/12/2020	F
020720	N133246-SAIL TARP	06/18/2020	F
024099	REPAIR BROKEN GREASE LINE TO RH SIDE 1ST AXLE SCAM TUBE	06/29/2020	F
024108	REMOVE CLUTCH ROD ASSEM, RENEW WORN ROSE JOINTS AND BELL	06/29/2020	F
021496	N133308-PTO CHANGE OUTS	07/01/2020	F
023954	FIT NEW P CLAMP TO SECURE BOTTOM RADIATOR HOSE	07/01/2020	F
021811	C-(A) 250HR SERVICE @ 1,324 (1,250) HR TKP KENWORTH T659	07/03/2020	F
022059	C-(B) 500HR SERVICE @ 1,551 (1,500) HR TKP KENWORTH C509	07/05/2020	F
022862	C-(A) 250HR SERVICE @ 1,853 (1,750) HR TKP KENWORTH T659	07/17/2020	F
025962	REPLACED A/C BELT	07/21/2020	F
025963	REPLACED ALTERNATOR PULLEY AND BEARING	07/21/2020	F
025964	FIT NEW DRIVE TYRES	07/21/2020	F
024300	C-(D) 2000HR SERVICE @ 2,145 (2,000) HR TKP KENWORTH T659	08/02/2020	F
025079	C-(A) 250HR SERVICE @ 2,375 (2,250) HR TKP KENWORTH C509	08/12/2020	F
025649	N117240-DRIVE TYRES	08/21/2020	F
025716	C-(B) 500HR SERVICE @ 2,545 (2,500) HR TKP KENWORTH T659	08/22/2020	F
028276	REPLACED DRIVE TYRES	08/27/2020	F
029361	FITTED NEW STEER TYRES	09/04/2020	F
029347	4 X NEW TYRES 3RD AXLE ON 1ST DOLLY	09/06/2020	F
029348	REPLACED TOW EYE	09/06/2020	F
029366	FOUND GOVERNOR VALVE LEAKING THROUGH EXHAUST CONSISTENTLY,	09/06/2020	F

026800	C-(A) 250HR SERVICE @ 2,750 (2,774) HR TKP KENWORTH T659	09/09/2020	F
029250	C-(B) 500HR SERVICE @ 3,511 (3,500) HR TKP KENWORTH T659	09/12/2020	F
027217	C-(C) 1000HR SERVICE @ 3,053 (3,000) HR TKP KENWORTH T659	09/16/2020	F
030176	DC-4 VALVE ON RHS AIR TANK SNAPPED AT FITTING, REPLACED VALV	09/21/2020	F
030243	FITTED NEW SPRING PACK TO RH DRIVE	09/23/2020	F
030244	FITTED 4 X NEW N70 BATTERIES	09/23/2020	F
030284	DC 4 VALVE REPLACED ON RHS AIR TANK,SNAPPED AT FITTING	09/23/2020	F
028236	C-(A) 250HR SERVICE @ 3,265 (3,250) HR TKP KENWORTH T659	09/26/2020	F
030824	C-(A) 250HR SERVICE @ 3,797 (3,750) HR TKP KENWORTH T659	10/05/2020	F
031051	FIT 3 X NEW ROSE JOINTS, PLUS BELL CRANK BEARING TO CLUTCH	10/06/2020	F
031052	FIT NEW RH BRAKE HOSE TO REAR DRIVE AXLE AND AXLE BREATHER	10/06/2020	F
031088	C-(D) 2000HR SERVICE @ 3,999 (4,000) HR TKP KENWORTH T659	10/09/2020	F
030215	NPR 100706: Supply 4 x N7022 Batteries	10/23/2020	F
030221	N100706-BATTERIES	10/23/2020	F
032376	C-(A) 250HR SERVICE @ 4,270 (4,250) HR TKP KENWORTH T659	11/01/2020	F
034475	REPLACED RH AND LH ROOF BEACONS	11/06/2020	F
033669	C-(B) 500HR SERVICE @ 4,528 (4,500) HR TKP KENWORTH T659	11/21/2020	F
032354	C-CLIP WASTEGATE ELELET RETAINER DAMAGED	11/28/2020	F
034760	C-(A) 250HR SERVICE @ 4,762 (4,750) HR TKP KENWORTH T659	12/07/2020	F
033018	NPR115633, DIFF FAILURE, PARTS FROM CJD DARWIN	12/10/2020	F
033165	NPR133722, DIFF AXLE NUTS WASHER AND LOCK TAB MURPHY'S	12/11/2020	F
035883	C-(A) 250HR SERVICE @ 5,353 (5,250) HR TKP KENWORTH T659	01/07/2021	F
042827	Replaced brake LHS 2nd trailer middle	01/31/2021	F
035890	DONE Replaced A/C idler bearing	02/03/2021	F
038932	C-(A) 250HR SERVICE @ 5,500 (5,500) HR TKP KENWORTH T659	02/12/2021	F
038146	N117150-REPLACEMENT HEADLIGHTS	02/28/2021	F
038221	N115738-AIR CONDITIONER U/S	03/03/2021	F
042875	Replaced 1st uni on drive line	03/12/2021	F
042876	Replaced steer & drive tyres, tensioned nuts @ 5832 hrs	03/12/2021	F
042503	C-(A) 250HR SERVICE @ 5,832 (5,750) HR TKP KENWORTH T659	04/10/2021	F
044982	C-(C) 1000HR SERVICE @ 6,000 (6,000) HR TKP KENWORTH T659	05/21/2021	F
045231	C-(A) 250HR SERVICE @ 6,247 (6,250) HR TKP KENWORTH T659	05/23/2021	F
044424	Turbo westgate , valve set	06/09/2021	F
044763	NPR116620 Cummins repaired fault in motor @ 6750 hrs	06/16/2021	F
048117	Replace the 4x N7022 batteries.	06/27/2021	F

049621	Supply 4 x truck cab shocks	07/26/2021	F
049682	C-(A) 250HR SERVICE @ 7,750 (7,797) HR TKP KENWORTH T659	07/29/2021	F
049765	C-(C) 1000HR SERVICE @ 6,983 (7,000) HR TKP KENWORTH T659	07/30/2021	F
049773	C-(A) 250HR SERVICE @ 7,516 (7,500) HR TKP KENWORTH T659	07/30/2021	F
050698	5273337NX DOSER PUMP RECON 12V 1250	08/10/2021	F
051854	Supply front diff	08/30/2021	F
052807	C-(C) 1000HR SERVICE @ 8,099 (8,000) HR TKP KENWORTH T659	09/11/2021	F
053079	CJD Remove & reseal diff, wheel alignment,install mine radio	09/13/2021	F
054141	Supply A/C compressor @ 8591 hours	09/29/2021	F
055173	C-(A) 250HR SERVICE @ 8,272 (8,250) HR TKP KENWORTH T659	10/21/2021	F
055451	C-(A) 250HR SERVICE @ 8,540 (8,500) HR TKP KENWORTH T659	10/23/2021	F
057683	Replace trailer plug socket, and RH low beam light.	11/09/2021	F
057600	Bears Mech supply Roadworthy certificate	11/23/2021	F
063224	Replace 7 pin plug/socket. Repair wiring, re-align tarp.	12/04/2021	F
058111	C-(C) 1000HR SERVICE @ 9,014 (9,000) HR TKP KENWORTH T659	12/05/2021	F
059676	Replace fuel line RHS fuel tasks.	12/08/2021	F
058967	Beaurepairs supply 8 x drive tyres @ 499131 klms	12/14/2021	F
059342	Bears mech to do RW for Mine pass outs	12/17/2021	F
059385	Beaurepairs supply 8 x drive tyres @ 502612 klms	12/17/2021	F
059644	Cummins preset speed as requested @ 9735 hrs	12/22/2021	F
060523	Replaced wiper blades, both sides. Repairs LH taillight and	12/28/2021	F
062248	Remove/replace cab airbags and shocks.	01/06/2022	F
059907	Cummins change speed parameters	01/10/2022	F
062396	Remove/replace turbo intake pipe.	01/10/2022	F
062406	Front diff centre loose.	01/10/2022	F
062407	LH windscreen cracked.	01/10/2022	F
062408	Fan cracked - remove/replace fan.	01/10/2022	F
062409	Exhaust down pipe bushes fault.	01/10/2022	F
062410	Turbo outlet gasket fault.	01/10/2022	F
062401	Replace turntable, repair fan shroud, replace mudguard.	01/11/2022	F
060068	SOS elect replace evaporator & regas	01/12/2022	F
060199	(A) 250HR SERVICE @ (9,500) HR TKP KENWORTH T659	01/16/2022	F
060636	(A) 250HR SERVICE @ (9,750) HR TKP KENWORTH T659	01/21/2022	F
060924	Cummins supply manifold gaskets & turbo gasket @ 10361 hrs	01/24/2022	F
061769	Steer uni fault.	01/24/2022	F

061770	Coolant pipe leaking.	01/24/2022	F
062149	Ad-blue fault.	01/30/2022	F
061232	Beaurepairs supply 8 x drive tyres @ 540968 klms	01/31/2022	F
061664	(C) 1000HR SERVICE @ 10,113 (10,000) HR TKP KENWORTH T659	02/06/2022	F
063318	Start wheel not working. Remove and replace clock spring.	02/06/2022	F
061965	(A) 250HR SERVICE @ 10,361 (10,250) HR TKP KENWORTH T659	02/10/2022	F
062463	(A) 250HR SERVICE @ 10,571 (10,500) HR TKP KENWORTH T659	02/14/2022	F
064542	Removed and replaced LHS high beam.	02/25/2022	F
064444	(A) 250HR SERVICE @ 10,810 (10,750) HR TKP KENWORTH T659	03/19/2022	F
064532	(C) 1000HR SERVICE @ 10,955 (11,000) HR TKP KENWORTH T659	03/19/2022	F
066522	Change fuel/oil filters. Change Engine oil.	03/27/2022	F
065508	Beaurepairs supply 8 x drive tyres @ 598342 klms	03/28/2022	F
068000	New steer tyres.	04/11/2022	F
068001	New air governor fitted.	04/11/2022	F
068010	Replace Bonnet indicator - RHS.	04/11/2022	F
069448	Remove and replace 2 uni's on tail shaft.	04/23/2022	F
069259	Replaced LHR booster - booster leaking air on maxi side.	04/24/2022	F
067368	Q Crush recovery of PM off wet haul road	04/26/2022	F
067391	Cummins supply water pump @ 12166hrs	04/26/2022	F
067435	Cummins supply fuel pump assem @ 12166hrs	04/26/2022	F
066149	(A) 250HR SERVICE @ 11,380 (11,250) HR TKP KENWORTH T659	04/28/2022	F
068047	(A) 250HR SERVICE @ 11,885 (11,750) HR TKP KENWORTH T659	05/03/2022	F
066592	(A) 250HR SERVICE @ 11,583 (11,500) HR TKP KENWORTH T659	05/04/2022	F
071696	REPLACED STAUFF CLAMP ON A FRAME, FIXED GREASE LEAK.	05/08/2022	F
071719	CRACKED WINDSCREEN	05/08/2022	F
071720	YOKE	05/08/2022	F
071721	AIR REG	05/08/2022	F
070100	BRAKE	05/21/2022	F
070099	SERVICE AND REPAIRS	05/22/2022	F
070267	REAR DIFF NEEDS REPLACING	05/22/2022	F
070549	(C) 1000HR SERVICE @ 12,166 (12,000) HR TKP KENWORTH T659	06/02/2022	F
071975	BLOWN HYD HOSE	06/02/2022	F
071925	service and repairs	06/04/2022	F
071999	SERVICE AND REPAIRS	06/04/2022	F
070711	Enzed supply air fittings @ 12921hrs	06/06/2022	F

070714	B&H supply shockies, bolts & bushes @ 12921hrs	06/06/2022	F
072436	STARTER	06/06/2022	F
070994	(A) 250HR SERVICE @ 12,373 (12,250) HR TKP KENWORTH T659	06/09/2022	F
072467	COMBINATION SWITCH	06/10/2022	F
071472	(A) 250HR SERVICE @ 12,663 (12,500) HR TKP KENWORTH T659	06/14/2022	F
073597	F/DIFF	06/18/2022	F
073996	front diff	06/19/2022	F
074149	R/R STEER TYRES	06/24/2022	F
074150	SERVICE REPAIRS	06/24/2022	F
072475	STEER TYRES AND BALANCE BAGS	06/27/2022	F
072486	STEER TYRES AND BALANCE BAGS	06/27/2022	F
074203	VALVE COVER LEAK, BOOSTER HOSE	07/01/2022	F
074239	DERATE AN D H/LIGHTS NOT WORKING	07/02/2022	F
072784	B&H supply sets of wiper blades	07/04/2022	F
077562	remove and reseal front yoke. Tighten center bearing nut	07/05/2022	F
077987	OIL LEAK @ FRONT DIFF	07/05/2022	F
073067	(A) 250HR SERVICE @ 12,922 (12,750) HR TKP KENWORTH T659	07/07/2022	F
073075	(C) 1000HR SERVICE @ 12,922 (13,000) HR TKP KENWORTH T659	07/07/2022	F
077619	Service Repairs	07/10/2022	F
073311	B&H supply drive scam, brake, brake drum	07/11/2022	F
073323	B&H supply drive scam, brake, drum @ 13625hrs	07/11/2022	F
073400	B&H supply clutch & bell housing and access @ 13639hrs	07/11/2022	F
073476	(A) 250HR SERVICE @ 13,318 (13,250) HR TKP KENWORTH T659	07/12/2022	F
073778	Supply starter motor @ 13699hrs	07/15/2022	F
073783	Cummins R&R rear main seal @ 13669hrs	07/15/2022	F
073784	Eng EXcell skim flywheel @ 13669hrs	07/15/2022	F
075111	Replace Anderson head for supply.	07/16/2022	F
074347	1ST TRAILER TARP BOX FAULTY	07/20/2022	F
077673	FLUSH AD BLUE CLOSER UNIT. FLUSH LINES. REPLACE INJECTOR AND	07/22/2022	F
077690	replace leaking ryco's and hydraulic hose.	07/26/2022	F
077948	REMOVE+REPLACE HORTON, A/C BELT TENSIONER, FAN + A/C BELTS	08/01/2022	F
078291	FRONT DIFF REPLACE	08/13/2022	F
075745	NPR047451 B&H supply dana/spicer pinion seals @ 14208hrs	08/15/2022	F
075957	(A) 250HR SERVICE @ 13,626 (13,500) HR TKP KENWORTH T659	08/16/2022	F
078301	REPLACE FEMALE TRAILER PLUG ON BACK OF 1ST TRAILER. REPAIR	08/16/2022	F

076227	(A) 250HR SERVICE @ 13,964 (13,750) HR TKP KENWORTH T659	08/18/2022	F
076235	(C) 1000HR SERVICE @ 13,964 (14,000) HR TKP KENWORTH T659	08/18/2022	F
078329	REPLACE FAN BELT & CRANK PULLEY	08/19/2022	F
078330	8X NEW DRIVE TYRES FITTED	08/19/2022	F
082445	(A) 250HR SERVICE @ 14,358 (14,250) HR TKP KENWORTH T659	08/19/2022	F
082928	(A) 250HR SERVICE @ 14,358 (14,250) HR TKP KENWORTH T659	08/19/2022	F
076347	NPR157108 B&H supply alternator, starter motor, pulley @	08/22/2022	F
076356	NPR157114 Beaurepiars supply 8 x drive tyres @ 738984 kms	08/22/2022	F
078601	SERVICE REPAIRS	08/29/2022	F
078602	500HR + REPAIRS	08/29/2022	F
080385	(A) 250HR SERVICE @ 14,538 (14,500) HR TKP KENWORTH T659	08/29/2022	F
078156	Replace nox sensor active fault	09/01/2022	F
077140	Cummins supply NOX sensor @ 14746hrs	09/09/2022	F
077185	NPR047534 Enzed replace blown hoses on birdsnest @ 14792 hrs	09/12/2022	F
081485	(A) 250HR SERVICE @ 14,830 (14,750) HR TKP KENWORTH T659	09/12/2022	F
077381	NPR047573 Cummins supply Mid Life parts as quoted @ 14835hrs	09/15/2022	F
077384	NPR047564 Beaurepairs flip 2 x steer tyres& bags @	09/15/2022	F
077442	NPR047591 Cummins repair after treatment faults @ 14677hrs	09/19/2022	F
078953	STEER	09/26/2022	F
079507	REPAIRS / 1000 HOUR SERVICE	09/30/2022	F
079518	1000 HR SERVICE	09/30/2022	F
081800	(C) 1000HR SERVICE @ 15,186 (15,000) HR TKP KENWORTH T659	09/30/2022	F
079155	Replace Anderson plugs to trailers	10/03/2022	F
078845	NPR157292 B&H supply steering uni's and khitch spring eye	10/04/2022	F
082643	(A) 250HR SERVICE @ 15,242 (15,250) HR TKP KENWORTH T659	10/04/2022	F
079772	REWired TARP SWITCH	10/07/2022	F
079774	GEARBOX BOOT UNSERVICABLE, REMOVED & REPLACED.	10/08/2022	F
080572	Pos 6 Drive Tyre had a puncture, had repaired & refitted to	10/20/2022	F
080629	Top up hyd oil after blown hose, 70 L	10/21/2022	F
080628	Replace RH drivers front windscreen	10/22/2022	F
080567	Replace speed sensor harness	10/24/2022	F
081087	Repair speed sensor wiring	10/24/2022	F
082891	(A) 250HR SERVICE @ 15,680 (15,500) HR TKP KENWORTH T659	10/26/2022	F
083085	(A) 250HR SERVICE @ 15,680 (15,500) HR TKP KENWORTH T659	10/26/2022	F
080875	Flip steer tyres on rims	10/27/2022	F

080950	Replace gearbox harness	10/28/2022	F
081169	Replace steer tyres	11/01/2022	F
081356	Replace steer tyres	11/03/2022	F
081717	Replace alternator and checked charged 14V	11/03/2022	F
082225	CLASSIC PLUS ENGINE REBUILD	11/14/2022	F
083090	Replace battery isolator assy	11/22/2022	F
083820	2 X SMALL P CLAMPS	11/25/2022	F
086430	(C) 1000HR SERVICE @ 16,073 (16,000) HR TKP KENWORTH T659	11/25/2022	F
083511	Air dryers not working properly	11/27/2022	F
085430	Replaced starter motor	12/04/2022	F
083978	Replace hyd hose dkt 20312	12/04/2022	F
084048	Replace starter motor	12/06/2022	F
084975	Replaced upper & lower gearstick boots on prime mover	12/09/2022	F
085332	Repair Doser pump fault	12/13/2022	F
085361	Repair exhaust leak	12/13/2022	F
085562	FLUSH ADBLUE SYSTEM AND CLEAR CODES	12/13/2022	F
085513	Replaced LH mudguard with new	12/14/2022	F
085824	2 X GASKET #2866337	12/16/2022	F
086630	Wiper Blades	12/20/2022	F
086523	Strip and assess front diff 206780	12/22/2022	F
086764	Replaced leaking rocker cover gasket	12/24/2022	F
087191	(A) 250HR SERVICE @ 16,366 (16,250) HR TKP KENWORTH T659	12/26/2022	F
086942	Replaced power steering pump	12/30/2022	F
087001	G/Box cooler line leaking	12/30/2022	F
090678	R&R top boost hose on hot side. dump pipe ubolt clamp, LHS	01/02/2023	F
086938	Headlight flickering - Replaced LH headlight harness	01/03/2023	F
086850	Replace head light buckets	01/04/2023	F
087192	(A) 250HR SERVICE @ 16,739 (16,500) HR TKP KENWORTH T659	01/06/2023	F
087193	(A) 250HR SERVICE @ 16,739 (16,750) HR TKP KENWORTH T659	01/06/2023	F
087597	Dump pipe bushes - cut welded studs onto exhaust bracket (no	01/08/2023	F
087478	Replace gearbox assy	01/10/2023	F
089229	Gearbox and Clutch replaced @ 16950hrs replaced all rose	01/11/2023	F
088310	Replace Pto unit	01/17/2023	F
089053	Replace x 2 front steer tyres	01/22/2023	F
089945	Replace hyd hoses dkt 19084	01/30/2023	F

089977	Replace ac hose as per sample	01/31/2023	F
091293	A/c not working	01/31/2023	F
087194	(C) 1000HR SERVICE @ 17,159 (17,000) HR TKP KENWORTH T659	02/02/2023	F
091769	(A) 250HR SERVICE @ 17,159 (17,250) HR TKP KENWORTH T659	02/02/2023	F
090737	Fit grease lines to steering link ball joints + Align wheels	02/05/2023	F
090515	Replace tie rod assy	02/06/2023	F
092125	Replaced Drive Tyres	02/13/2023	F
094405	Prime mover wouldn't start	02/16/2023	F
092071	Replace fuel pro cover	02/17/2023	F
092250	Repair Ac faults	02/22/2023	F
092477	Hub Seal	02/23/2023	F
092484	Replace steer tyres	02/23/2023	F
093479	Remove & replace Hi/Low head light harness	02/28/2023	F
095004	(A) 250HR SERVICE @ 17,500 (17,500) HR TKP KENWORTH T659	03/10/2023	F
095005	(A) 250HR SERVICE @ 17,680 (17,750) HR TKP KENWORTH T659	03/14/2023	F
094079	Replace headlight harness	03/15/2023	F
094354	Replaced auto greaser	03/16/2023	F
096544	Changed brake shoes on front axle RHS	03/16/2023	F
094390	Replace cab shockies	03/17/2023	F
094974	Repair Ac fault	03/22/2023	F
095006	(C) 1000HR SERVICE @ 18,020 (18,000) HR TKP KENWORTH T659	04/02/2023	F
095957	Exhaust repairs	04/03/2023	F
095993	Replace steering uni joints	04/03/2023	F
095007	(A) 250HR SERVICE @ 18,453 (18,250) HR TKP KENWORTH T659	04/23/2023	F
095008	(A) 250HR SERVICE @ 18,453 (18,500) HR TKP KENWORTH T659	04/23/2023	F
097643	Repaired R/H Bonnet Indicator	04/24/2023	F
097644	Replaced rear engine mounts, complete with new bolts washer	04/24/2023	F
098124	Replace starter motor	05/09/2023	F
099251	Replaced all 8 drive tyres with new drive tyres due to being	05/11/2023	F
095009	(A) 250HR SERVICE @ 18,857 (18,750) HR TKP KENWORTH T659	05/15/2023	F
099259	Changed exhaust flex pipe, 3 pipe clamps and 1 gasket	05/15/2023	F
099151	Replace Gearbox and clutch	05/22/2023	F
099310	Replace pto assy	05/24/2023	F
099731	Fixed tap on small tank of prime mover for fuel tank	05/26/2023	F
101359	No Clutch	05/26/2023	F

099647	Replace cab ride height valve	05/29/2023	F
101366	Had Problem Starting	05/29/2023	F
099800	Replace batteries n70zz	05/30/2023	F
099850	Replace alternator assy	05/31/2023	F
095010	(C) 1000HR SERVICE @ 19,183 (19,000) HR TKP KENWORTH T659	06/05/2023	F
095011	(A) 250HR SERVICE @ 19,183 (19,250) HR TKP KENWORTH T659	06/05/2023	F
100115	Repairs to horton and engine mounts	06/05/2023	F
100533	NPR 035418 REPLACE TYRES	06/11/2023	F
101084	Replace steering shaft strut and cable	06/19/2023	F
095012	(A) 250HR SERVICE @ 19,528 (19,500) HR TKP KENWORTH T659	06/23/2023	F
102259	Repairs to diff 206780	06/30/2023	F
095013	(A) 250HR SERVICE @ 19,751 (19,750) HR TKP KENWORTH T659	07/06/2023	F
102759	Replace hyd hoses Callout dkt 21312	07/10/2023	F
103278	L/H Front Drive Hubs	07/16/2023	F
103152	Replace lhf hub assy	07/17/2023	F
103349	Replace Belt + Tensioner	07/18/2023	F
103620	Adblue Fault	07/19/2023	F
103636	Hydraulic oil	07/23/2023	F
095014	(C) 1000HR SERVICE @ 20,115 (20,000) HR TKP KENWORTH T659	07/25/2023	F
103795	Replace torque rods	07/26/2023	F
103836	Replace torque rod bushes	07/27/2023	F
104952	Replaced oil hose from gear box to oil filter housing	07/27/2023	F
104954	Replace broken drive spring leaf	07/27/2023	F
102603	Bears Mech conduct Certificate of Inspection/NHVAS	07/28/2023	F
105155	Remove & replace all torque rod bushes (x12)	07/28/2023	F
105156	Fit all new drive tyres	07/28/2023	F
104263	Replace hyd hoses dkt 21212	08/07/2023	F
104288	Replace front springs	08/07/2023	F
104933	Changed fuel lines @ pump	08/07/2023	F
104324	Replace oem harness	08/08/2023	F
105092	Replace steer tyres	08/11/2023	F
105335	Aftertreat light	08/11/2023	F
095015	(A) 250HR SERVICE @ 20,535 (20,250) HR TKP KENWORTH T659	08/17/2023	F
095016	(A) 250HR SERVICE @ 20,535 (20,500) HR TKP KENWORTH T659	08/17/2023	F
105891	Fan shroud cracked	08/18/2023	F

105906	Broken wiring engine harness	08/18/2023	F
095017	(A) 250HR SERVICE @ 20,798 (20,750) HR TKP KENWORTH T659	09/01/2023	F
107921	Repair grease line/fitting @clutch throw out bearing	09/02/2023	F
106933	Removed and refit new windscreen	09/04/2023	F
108211	Repair L.H.F.D brake booster rod to slack adj as req	09/15/2023	F
095018	(C) 1000HR SERVICE @ 21,054 (21,000) HR TKP KENWORTH T659	09/16/2023	F
107952	Changed steer tyres	09/16/2023	F
107942	Replace starter motor and seat belt	09/19/2023	F
108208	Replace x2 cab air bags, as leaking air	09/19/2023	F
108209	Straightened steering wheel	09/19/2023	F
108911	Turntable jammed	09/30/2023	F
108780	Replace drive tyres	10/02/2023	F
108781	Rekit turntable	10/02/2023	F
108807	Repairs to return spring plate	10/03/2023	F
108920	FITTINGS & ADAPTORS FOR VALVE CHANGE OUTS TKP00767	10/04/2023	F
109581	Removed & replaced both steer tyres with x2 new steer tyres	10/07/2023	F
095019	(A) 250HR SERVICE @ 21,497 (21,250) HR TKP KENWORTH T659	10/09/2023	F
095020	(A) 250HR SERVICE @ 21,497 (21,500) HR TKP KENWORTH T659	10/09/2023	F
110444	Find leaking air valve QR for trailer, replace	10/10/2023	F
109815	Pinion seal leak	10/16/2023	F
110157	Front pinion seal oil leak	10/21/2023	F
110339	Repair leak in hyd tank	10/25/2023	F
110758	Aftertreat light on dash	10/26/2023	F
095021	(A) 250HR SERVICE @ 21,835 (21,750) HR TKP KENWORTH T659	10/27/2023	F
111404	Closed drain tape on bottom of fuel pro, filled & primed	10/31/2023	F
110955	Replace nox sensor	11/01/2023	F
111405	Engine Derate	11/01/2023	F
111406	Tarps not working	11/04/2023	F
111403	Removed & replaced UHF hand held radio, check all ok	11/06/2023	F
111985	Replace clutch assy	11/13/2023	F
112104	Diff Leaking	11/13/2023	F
112025	Quote to Replace Engine	11/14/2023	F
112030	Replace uni straps	11/14/2023	F
112102	Clutch adjusted incorrectly	11/14/2023	F
112326	Changed oil seal on steering gear box	11/17/2023	F

112278	Replace Steering box	11/18/2023	F
115904	Steering box failure	11/19/2023	F
112354	Replace add blue injector	11/21/2023	F
115905	Aftertreat light on dash	11/21/2023	F
112456	Replace diff assy	11/22/2023	F
112582	Quote to repair diff 242015	11/24/2023	F
112788	Rectify & repair defect notice	11/24/2023	F
095022	(C) 1000HR SERVICE @ 22,340 (22,000) HR TKP KENWORTH T659	12/01/2023	F
095023	(A) 250HR SERVICE @ 22,340 (22,250) HR TKP KENWORTH T659	12/01/2023	F
114387	LH 3rd bottom spring broken	12/01/2023	F
112983	Replace drive springs	12/04/2023	F
116546	Truck had no power going to trailer wiring light plug,repair	12/06/2023	F
114412	Breakdown	12/11/2023	F
115078	A/C fan cutting in and out	12/27/2023	F
114825	8 x new drive tyres	12/30/2023	F
095024	(A) 250HR SERVICE @ 22,824 (22,500) HR TKP KENWORTH T659	01/01/2024	F
115858	(A) 250HR SERVICE @ 22,824 (22,750) HR TKP KENWORTH T659	01/01/2024	F
116078	LH steer hub seal + brake reline + snapped wheel stud	01/01/2024	F
116082	LHFD slack adjuster pin missing, fit	01/01/2024	F
114718	Replace drive spring pack and exhaust flex	01/02/2024	F
115860	(C) 1000HR SERVICE @ 23,158 (23,000) HR TKP KENWORTH T659	01/18/2024	F
118427	(A) 250HR SERVICE @ 23,158 (23,250) HR TKP KENWORTH T659	01/18/2024	F
116626	ELECTRICAL FAULTS TKP767	01/24/2024	F
117003	Block off booster to get truck back to yard on lead trailer	01/25/2024	F
117002	Windscreen cracked	01/26/2024	F
116898	Wipers not working	01/27/2024	F
116899	Booster leaking	01/27/2024	F
120197	(A) 250HR SERVICE @ 23,663 (23,500) HR TKP KENWORTH T659	02/15/2024	F
120198	(A) 250HR SERVICE @ 23,663 (23,750) HR TKP KENWORTH T659	02/15/2024	F
118802	Replaced LHS broken bonnet strap x 1	02/16/2024	F
119362	LHS 1st drive slack adjuster seized	02/17/2024	F
119367	2 x torque rod bushes, replaced	02/17/2024	F
119369	Replace RH spotlight	02/17/2024	F
119370	Exhaust leak at flex hose	02/17/2024	F
119829	1 x 11R22.5 runout tyre RHS rear drive	03/01/2024	F

120120	Replace KW 512894 D190 OUTPUT SHAFT KIT	03/06/2024	F
120122	Replace drive springs	03/06/2024	F
120964	Remove and replace exhaust flex pipe, replace gasket & clamp	03/15/2024	F
121574	(C) 1000HR SERVICE @ 24,316 (24,000) HR TKP KENWORTH T659	03/22/2024	F
121575	(A) 250HR SERVICE @ 24,316 (24,250) HR TKP KENWORTH T659	03/22/2024	F
121749	8 x new drive tyres	03/22/2024	F
121915	No RH head light, broken & corroded wiring	03/26/2024	F
122181	Fan belt damaged	03/29/2024	F
122176	Drivers door won't open	03/30/2024	F
122262	Welded up fan shroud	03/31/2024	F
121576	(A) 250HR SERVICE @ 24,748 (24,500) HR TKP KENWORTH T659	04/17/2024	F
121577	(A) 250HR SERVICE @ 24,748 (24,750) HR TKP KENWORTH T659	04/17/2024	F
123305	Replace steering column	04/17/2024	F
123474	Replace alternator	04/22/2024	F
125174	Removed adblue filter cleaned out all lines from tank to	04/25/2024	F
130061	Repaired clutch quadrant bearing, installed shim	04/28/2024	F
123948	Replace alternator	04/29/2024	F
121578	(C) 1000HR SERVICE @ 25,107 (25,000) HR TKP KENWORTH T659	05/06/2024	F
124552	(A) 250HR SERVICE @ 25,107 (25,250) HR TKP KENWORTH T659	05/06/2024	F
125954	Adjust brakes	05/16/2024	F
125881	Replace recon doser pump	05/20/2024	F
125918	Replace CU 5307918 6 HOLE INJECTOR DOSER	05/20/2024	F
126332	Adblue faults & not dosing	05/22/2024	F
126586	(A) 250HR SERVICE @ 25,437 (25,500) HR TKP KENWORTH T659	05/25/2024	F
126531	Replace hyd hoses dkt 22465	05/27/2024	F
127698	Wheel stud broken	05/27/2024	F
127487	Broken 5 inch exhaust flex	06/01/2024	F
128005	Exhaust flex pipe broken	06/02/2024	F
127969	Aftertreat light on dash	06/04/2024	F
126674	Replace hyd hoses dkt 22465	06/10/2024	F
128535	Starter solenoid broken	06/12/2024	F
128574	Beacon light switch broken, replaced beacon switch	06/14/2024	F
117219	2023-2024 ** NHVAS INSPECTION - Passed 23.06.2024	06/23/2024	F
126588	(A) 250HR SERVICE @ 25,929.5 (25,750) HR TKP KENWORTH T659	06/23/2024	F
129258	Replace Alternator and belt	06/23/2024	F

129625	(C) 1000HR SERVICE @ 25,929.5 (26,000) HR TKP KENWORTH T659	06/23/2024	F
129719	LH steer hub seal + bearing adjust	06/25/2024	F
129515	Replace drive spring pack	06/26/2024	F
129712	Rekitted turntable due to wear and replaced foot pins	06/26/2024	F
129721	LH drive spring cracked	06/26/2024	F
129641	Delco Remy Starter Motor 39MT	06/27/2024	F
129682	Oil leak LH steer	06/27/2024	F
130971	Straighten steering wheel	07/04/2024	F
130970	Replace 10 x steer wheel studs, driver's side	07/07/2024	F
130983	Replace blower motor for A/C fan	07/08/2024	F
130989	8 x 11r22.5 new roadway drive tyres	07/08/2024	F
130483	Replace drive spring pack	07/11/2024	F
130746	Found air leaking from RHFD brake booster hose as rub on	07/13/2024	F
125092	(A) 250HR SERVICE @ 26,363 (26,250) HR TKP KENWORTH T659	07/18/2024	F
125093	(A) 250HR SERVICE @ 26,363 (26,500) HR TKP KENWORTH T659	07/18/2024	F
131382	Replaced king pin RHS, replaced RHS steer booster hose	07/18/2024	F
131256	Replace king pins on steer and shockies	07/19/2024	F
131384	2 x roadway steer tyres	07/19/2024	F
132523	4 x 11r22.5 roadway trailer tyres, rear axle	08/03/2024	F
132624	Driver reported no A/C	08/03/2024	F
125094	(A) 250HR SERVICE @ 26,748 (26,750) HR TKP KENWORTH T659	08/08/2024	F
132787	Changed windscreen RHS	08/09/2024	F
133534	Outer through shaft seal bearing failure	08/09/2024	F
132781	Changed air governor valve	08/10/2024	F
132835	LHS front drive brake low, replaced brakes	08/10/2024	F
133159	POST WORK CHECK Replace Power steering hoses dkt 23282	08/18/2024	F
133164	Replace add blue injector	08/18/2024	F
133714	Removed & replaced the outside tyre on LH rear with a runout	08/19/2024	F
133515	Replace front spring pack steer	08/21/2024	F
125095	(C) 1000HR SERVICE @ 27,103 (27,000) HR TKP KENWORTH T659	08/31/2024	F
125096	(A) 250HR SERVICE @ 27,103 (27,250) HR TKP KENWORTH T659	08/31/2024	F
134954	8 x drive roadway tyres	09/02/2024	F
135084	Repairs to Ac fault	09/12/2024	F
135535	Replace alternator	09/19/2024	F
135579	Repair VSS sensor air gap not correct	09/20/2024	F

125097	(A) 250HR SERVICE @ 27,432 (27,500) HR TKP KENWORTH T659	09/22/2024	F
135594	Replace batteries	09/22/2024	F
136343	4 x 11R Roadway drives	09/23/2024	F
136746	Replaced ABS brake valve	09/23/2024	F
136922	Removed & replaced LH wheel stud on steer	10/02/2024	F
136727	Replace Starter motor	10/04/2024	F
137505	Airbags leaking	10/14/2024	F
125098	(A) 250HR SERVICE @ 27,844 (27,750) HR TKP KENWORTH T659	10/18/2024	F
137781	Critical Works Re-Kit Turntable 19.10.2024	10/19/2024	F
137784	Critical Works Tow Eye 19.10.2024	10/19/2024	F
137790	Critical Works Replace King Pin 20.10.2024	10/20/2024	F
138504	Drive spring broken	10/21/2024	F
139040	8 x new roadway drive tyres	11/03/2024	F
125099	(C) 1000HR SERVICE @ 28,225 (28,000) HR TKP KENWORTH T659	11/10/2024	F
125100	(A) 250HR SERVICE @ 28,225 (28,250) HR TKP KENWORTH T659	11/10/2024	F
139559	Front jackshaft uni failed	11/11/2024	F
139563	Repaired wiring for rear tail light + side lights + LH front	11/11/2024	F
139662	S-cam brackets missing	11/11/2024	F
139664	Front & rear grease leak	11/11/2024	F
140044	Replace clutch assy	11/24/2024	F
140925	Breakdown	11/25/2024	F
140838	Aftertreat light on	11/26/2024	F
125101	(A) 250HR SERVICE @ 28,627.4 (28,500) HR TKP KENWORTH T659	12/05/2024	F
125102	(A) 250HR SERVICE @ 28,627.4 (28,750) HR TKP KENWORTH T659	12/05/2024	F
141038	Replace drive spring pack	12/06/2024	F
141169	POST WORK CHECK - Engine brakes faulty	12/07/2024	F
141629	2 x roadway steer tyres	12/09/2024	F
141726	Drove out to McNamara turn off 767, lost its splitter	12/10/2024	F
141438	Replace Pto hoses dkt 19959	12/13/2024	F
141534	No clutch	12/14/2024	F
142250	REPLACED FLAT TYRE WITH RUNOUT	12/25/2024	F
125103	(C) 1000HR SERVICE @ 29,019 (29,000) HR TKP KENWORTH T659	12/30/2024	F
142838	CUMMINS REPAIR TO DIAGNOSED BRAKE WIRING BREAKAGE ISSUE 2ND	12/30/2024	F
142837	REPLACED BROKEN SUNVISOR LATCH RHS	12/31/2024	F
142839	LHS INDICATOR LIGHT OUT, REPLACED BULB	12/31/2024	F

142840	REPLACED LH SPOTLIGHT ALL LED'S BLOWN, SECURED WIRING	12/31/2024	F
140207	TMA Higher Mass Fees for all *2025	01/01/2025	I
140541	MT data - Monthly Service & Licence Fees for all *2025	01/01/2025	S
141937	CUMMINGS TO REPAIR JAKE BRAKE FAULT	01/01/2025	F
141940	Welding repairs to Bullbar	01/02/2025	F
144400	REPLACED 8 X 11R ROADWAY DRIVE TYRES	01/05/2025	F
114190	MT data - Monthly Service & Licence Fees for all *2024	01/09/2025	F
118257	TMA Higher Mass Fees for all *2024	01/09/2025	F
144018	TKP767 ENZED PARTS AS PER DD23318 - FUEL ISSUES, BURNT HOSES	01/28/2025	F
144019	TKP767 EXHAUST DAMAGE	01/28/2025	F
145410	replaced wiper blades-replaced bearing in clutch pivot	02/09/2025	F
125104	(A) 250HR SERVICE @ 29,539 (29,250) HR TKP KENWORTH T659	02/09/2025	F
125105	(A) 250HR SERVICE @ 29,539 (29,500) HR TKP KENWORTH T659	02/09/2025	F
145471	Replaced stripped cleaned select P+O and refit	02/10/2025	F
145468	radiator pouring coolant, due to a coolant leak, release	02/11/2025	F
145971	Replaced AC belt-Idler belt 6PKI590- Idler 3689465 needs AC	02/17/2025	F
145973	Voltage Issue	02/18/2025	F
146372	Adjust clutch free travel	02/26/2025	F
146370	Diagnosed issue rubbed wiring at RH tail light -Tested	02/27/2025	F
146371	Replaced 1 x by 11r/22.5 runout tyre rear LHS, replace flat	02/28/2025	F
146460	Replaced POS 4 booster air line & secured	03/02/2025	F
125106	(A) 250HR SERVICE @ 29,968 (29,750) HR TKP KENWORTH T659	03/03/2025	F
125107	(C) 1000HR SERVICE @ 29,968 (30,000) HR TKP KENWORTH T659	03/03/2025	F
147080	Replace with 2x by 385/65/22.5 roadways steers	03/04/2025	F
146613	Repairs to Ac fault	03/07/2025	F
147264	evaporator clogged removed & replaced A/C compressor	03/10/2025	F
147155	fuel tank over fueled ,drain fuel 20l 40l worth in 20l drums	03/11/2025	F
147577	Replace 8 x by 11r/22.5 roadway drive tyres	03/16/2025	F
147501	Replace steering box	03/19/2025	F
147989	Replaced o'rings on fitting to steering box .Topped up oil	03/21/2025	F
148325	jumped under to check starter +wire was loose tightened +	03/21/2025	F
147990	Replaced starter motor	03/22/2025	F
148322	Replaced Bolt at AGM	03/26/2025	F
151694	Replace bell cradle bearing including arm and all hose joint	03/30/2025	F
125108	(A) 250HR SERVICE @ 30,388 (30,250) HR TKP KENWORTH T659	04/05/2025	F

125109	(A) 250HR SERVICE @ 30,388 (30,500) HR TKP KENWORTH T659	04/05/2025	F
136443	2024-2025 ** NHVAS INSPECTION - Passed 06.04.2025	04/06/2025	F
148895	Critical Works Ring Feeder 07.04.2025	04/07/2025	F
150263	Replaced booster and booster hoses on 1st axle RH side	04/20/2025	F
125110	(A) 250HR SERVICE @ 30,765 (30,750) HR TKP KENWORTH T659	04/30/2025	F
151751	Replaced 2 x 385/65/22.5 roadways steers tyres	05/15/2025	F
151754	LH rear air lines had rubbed threw , cut & put joiner in ,	05/15/2025	F
151748	Replaced LH quarter guard bracket , adjusted wheel	05/17/2025	F
151764	Checked new tie rod, Installed auto grease lines, installed	05/17/2025	F
125111	(C) 1000HR SERVICE @ 31,114 (31,000) HR TKP KENWORTH T659	05/19/2025	F
152163	Replaced exhaust flex + 2x gasket & clamps , repaired some	05/20/2025	F
137761	SUPPLY PARTS FOR ENGINE MIDLIFE	05/21/2025	F
151396	Replace tie rod beam	05/21/2025	F
151649	Replace fan blade and shroud	05/23/2025	F
153681	Removed flat from 2 RH outer , had no run outs on hand m	06/13/2025	F
125112	(A) 250HR SERVICE @ 31,429 (31,250) HR TKP KENWORTH T659	06/17/2025	F
125113	(A) 250HR SERVICE @ 31,429 (31,500) HR TKP KENWORTH T659	06/17/2025	F
153815	QUOTE TO REFURBISH SEAT ASSY	06/27/2025	I
154805	Replaced harness and truck started straight away and all	07/11/2025	F
155119	Replaced steer springs (LH & RH), shockys (LH & RH), cab	07/13/2025	F
154621	REPLACE STEER SPRING PACKS	07/14/2025	F
154622	REPLACE ENGINE HARNESS	07/14/2025	F
125114	(A) 250HR SERVICE @ 31,836 (31,750) HR TKP KENWORTH T659	07/22/2025	F
155355	REPLACE STARTER MOTOR ASSY	07/23/2025	F
156398	Attend to vehicle breakdown at Stargully. Found gearstick	07/30/2025	F
156431	Replaced gear stick tower as it failed and got stuck in gear	07/30/2025	F
155449	REPLACE OEM HARNESS FAILED	07/31/2025	F
157304	Replaced RH windscreen (cracked) and 1x gearbox air fitting	08/02/2025	F
157305	Replaced RH front hub seal & axle gasket (leaking), rear	08/03/2025	F
157324	Replaced broken RHS drive spring and leaking RHF drive hub	08/03/2025	F
159431	REPAIRED ADBLUE SYSTEM LEAK & FLUSHED SYSTEM	08/06/2025	F
159385	REAR LH DRIVE BOOSTER NEARLY DUE FOR RELINES X4	08/07/2025	F
159432	REPLACED STEER HUB SEAL, REPLACED FRONT ENG MOUNTS	08/10/2025	F
125115	(C) 1000HR SERVICE @ 32,132 (32,000) HR TKP KENWORTH T659	08/17/2025	F
125116	(A) 250HR SERVICE @ 32,132 (32,250) HR TKP KENWORTH T659	08/17/2025	F

157072	REPLACE FAN SHROUD	08/18/2025	F
157177	REPLACE GEARBOX TOWER	08/18/2025	F
157599	REPLACE ALTERNATOR AND PULLEY	08/21/2025	I
160839	Replaced alternator & fan belt	08/21/2025	F
159519	REPLACED FAN/ALT BELT TENSIONER & CRANK DOLLY	08/23/2025	F
160838	BELT SQUEALING	08/24/2025	F
159597	REPLACE REAR RH & LH ENGINE MOUNTS, TIDY UP WIRING & HOSES	09/02/2025	F
125117	(A) 250HR SERVICE @ 32,500 (32,500) HR TKP KENWORTH T659	09/05/2025	F
157272	WELDING REPAIRS TO RADIATOR SHROUD	09/08/2025	F
157930	CUMMINS TO DO ECM REFLASH	09/08/2025	F
159252	QUOTE TO REPAIR DIFF 230769	09/13/2025	I
158392	REPLACE CENTRE BEARING SHAFT	09/14/2025	F
158784	2025-2026 ** NHVAS INSPECTION	09/15/2025	S
160542	REPLACE TRAILER PROTECTION VALVE (TPV) DUE TO LEAKING	09/19/2025	F
125118	(A) 250HR SERVICE @ 32,743 (32,750) HR TKP KENWORTH T659	09/23/2025	F
160880	FITTED FRIDGE (ROUGHLY WIRED IN CASE IT DOESN'T WORK)	09/23/2025	F
160881	ADJUSTED PASSENGER DOOR AND DOOR FRAME	09/23/2025	F
160882	FITTED NEW SEALS INTO RYCO FITTINGS	09/23/2025	F
159492	REPLACE CROSS LOCK AIR HOSES	09/26/2025	F
160863	WATER IN FUEL ISSUES	10/01/2025	F
160861	REPAIRS - HVAC SYSTEM	10/03/2025	F
160862	2 X NEW 385.66.22.5 ROADWAY STEERS	10/03/2025	F
162282	INTERCOOLER	10/06/2025	F
162285	REPLACE INTERCOOLER, HOSE & HOSE CLAMPS DUE TO LEAKING	10/06/2025	F
125119	(C) 1000HR SERVICE @ 33,002 (33,000) HR TKP KENWORTH T659	10/08/2025	F
162284	PTO AIR FITTING	10/08/2025	F
162280	REPLACED INTERCOOLER	10/09/2025	F
160943	REPLACE CHARGE AIR COOLER ASSY	10/10/2025	F
161831	TARP NOT WORKING	10/13/2025	F
160795	REPLACE TURBO WASTE GATE ASSY	10/14/2025	F
161794	1 X 11R 22.5 R/O DRIVE	10/18/2025	F
125120	(A) 250HR SERVICE @ 33,280 (33,250) HR TKP KENWORTH T659	10/22/2025	F
162528	REPLACED P/S PUMP GASKET	10/23/2025	F
162526	8 X LOW TREAD DRIVES REPLACED WITH 8 X NEW 11R 22.5 DRIVES	10/25/2025	F
162527	REPLACED LH TRUNNION. REPLACED LH DRIVE SPRING	10/25/2025	F

162531	Replaced leaking wheel seal on RHF drive	10/25/2025	F
163592	REPLACED WORN BEARINGS & AXLE STUDS & GASKET ON RHF DRIVE	10/25/2025	F
125123	(C) 1000HR SERVICE @ (34,000) HR TKP KENWORTH T659	11/01/2025	Q
125121	(A) 250HR SERVICE @ 33,523 (33,500) HR TKP KENWORTH T659	11/05/2025	F
163736	CRITICAL WORKS WHEEL END MAINTENANCE 06.11.2025	11/06/2025	F
163737	CRITICAL WORKS WHEEL END MAINTENANCE 06.11.2025	11/06/2025	F
164246	DRIVE BRAKE SHOES	11/13/2025	I
125124	(A) 250HR SERVICE @ (34,250) HR TKP KENWORTH T659	11/15/2025	Q
164529	REPLACE FUEL PUMP ACTUATOR	11/16/2025	I
164612	FUEL PUMP LACKING FUEL - REPLACED FUEL PUMP PRESSURE SWITCH	11/16/2025	F
164532	REPLACE RADIATOR ASSY	11/17/2025	I
164840	GUARDIAN MONITORING MONTHLY FEES FOR ALL *2025	11/19/2025	I
125122	(A) 250HR SERVICE @ 33,769 (33,750) HR TKP KENWORTH T659	11/20/2025	F
165249	ADJUSTED STEERING SHAFT	11/20/2025	F
165250	TIGHT STEERING	11/21/2025	F
165371	2 X NEW 385.65 22.5 ROADWAY STEERS	11/23/2025	F
165525	QUOTE TO REPAIR DIFF 251673	11/26/2025	I
165561	REPLACE DIFFERENTIAL	11/26/2025	F
165562	FILL UP FRONT DIFF OIL	11/26/2025	F
165563	INSTALL TAIL & JACK SHAFT	11/26/2025	F
165564	MANUALLY GREASE TRUCK & FILL UP GREASE POD	11/26/2025	F
165627	REPAIRS TO SPLITTER VALVE	11/28/2025	I
165628	REPLACE ALTERNATOR ASSY AND BELT	11/28/2025	I
165634	REPLACE GEARBOX ASSY	11/28/2025	I
125125	(A) 250HR SERVICE @ (34,500) HR TKP KENWORTH T659	11/29/2025	Q
166053	HEADLIGHT NOT WORKING	12/03/2025	F
166353	REPLACED LEAKING CAB AIRBAGS LH & RH	12/07/2025	F
125126	(A) 250HR SERVICE @ (34,750) HR TKP KENWORTH T659	12/13/2025	Q
125127	(C) 1000HR SERVICE @ (35,000) HR TKP KENWORTH T659	12/27/2025	Q
125128	(A) 250HR SERVICE @ (35,250) HR TKP KENWORTH T659	01/01/2026	Q
125129	(A) 250HR SERVICE @ (35,500) HR TKP KENWORTH T659	01/24/2026	Q