

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
28-Oct-2014 16	111	0	178079	21-519-003	Fabricate Hitch Assembly	08-Jan-2015 15:37:25	BWELD	C	DON	13,987.31
28-Oct-2014 16	111	0	178079	01-065-017	Adjust Reservoir/Tank	03-Feb-2015 14:42:04	BTRUCK	C	DON	335.59
28-Oct-2014 16	111	0	178079	14-078-012	Install Tie-Down - Tarpaulin	15-Jan-2015 12:22:42	BSETUP	C	DON	25.67
28-Oct-2014 16	111	0	178079	14-506-001	Install Fuel Tank	15-Jan-2015 11:26:24	BSETUP	C	DON	103.14
28-Oct-2014 16	111	0	178079	14-506-002	Install Hydraulic Tank	03-Feb-2015 14:42:13	BSETUP	C	DON	35.77
28-Oct-2014 16	111	0	178079	14-071-003	Install Side Wall Assembly	13-Jan-2015 09:29:48	BSETUP	C	DON	131.42
28-Oct-2014 16	111	0	178079	14-078-009	Install Mud Flaps and Hanger Brackets	12-Jan-2015 14:33:03	BSETUP	C	DON	100.43
28-Oct-2014 16	111	0	178079	14-002-003	Install Running Boards / Step Tubes	12-Jan-2015 08:40:21	BSETUP	C	DON	25.01
28-Oct-2014 16	111	0	178079	14-034-006	Install Warning Lamps - Special Application	02-Feb-2015 12:16:30	BSETUP	C	DON	882.52
28-Oct-2014 16	111	0	178079	14-053-004	Install Safety Equipment	15-Jan-2015 13:09:06	BSETUP	C	DON	13.39
28-Oct-2014 16	111	0	178079	14-523-003	Install Tool Rack	13-Jan-2015 14:59:19	BSETUP	C	DON	199.93
28-Oct-2014 16	111	0	178079	12-519-003	Refinish Hitch Assembly	07-Jan-2015 17:03:21	BBODY	C	DON	596.34
28-Oct-2014 16	111	0	178079	15-519-003	Paint Prep Hitch Assembly	08-Jan-2015 09:14:24	BSAND	C	DON	607.20
28-Oct-2014 16	111	0	178079	14-268-002	Install Cables and Pulleys (Sheaves)	17-Jan-2015 08:54:19	BTRUCK	C	DON	550.62
28-Oct-2014 16	111	0	178079	14-052-014	Install Cellular Telephone Accessories	02-Feb-2015 15:39:12	BSETUP	C	DON	0.10
28-Oct-2014 16	111	0	178079	14-063-003	Install Transceiver - GPS Tracker	02-Feb-2015 15:40:03	BSETUP	C	DON	14.14
28-Oct-2014 16	111	0	178079	14-053-005	Install Markings - Vehicle - Decals	02-Feb-2015 15:39:22	BSETUP	C	DON	0.09
28-Oct-2014 16	111	0	178079	14-053-014	Install Floor Mats	02-Feb-2015 15:39:31	BSETUP	C	DON	15.61
28-Oct-2014 16	111	0	178079	14-052-015	Install Power Inverter/Converter	27-Jan-2015 14:29:28	BSETUP	C	DON	976.05
28-Oct-2014 16	111	0	178079	24-034-004	Repair Clearance & Marker Lamps	03-Feb-2015 10:58:29	BTRUCK	I	DON	29.04
28-Oct-2014 16	111	0	178079	14-002-063	Install Computer Stand / Dock	02-Feb-2015 15:39:01	BSETUP	C	DON	0.13
28-Oct-2014 16	111	0	178079	01-042-002	Adjust Radiator	03-Feb-2015 12:00:41	BTRUCK	I	DON	55.93
28-Oct-2014 16	111	0	178079	14-052-003	Install Radio Equipment	30-Jan-2015 17:02:02	BSETUP	C	DON	181.63
28-Oct-2014 16	111	0	178079	14-052-011	Install Auxiliary Power	02-Feb-2015 15:38:46	BSETUP	C	DON	90.75
28-Oct-2014 16	111	0	178079	14-034-002	Install Stop, Tail, Turn & License	03-Feb-2015 14:42:22	BTRUCK	C	DON	172.31
28-Oct-2014 16	111	0	178079	06-100-DOT	Inspect DOT Federal Inspection	03-Feb-2015 10:08:46	BTRUCK	P	DON	46.79
28-Oct-2014 16	111	0	178079	14-058-001	Install Winch Assembly		BTRUCK	C	CAN	0.00
13-Feb-2015 0	125	0	191365	14-014-002	Install Bumpers & Attaching Parts	20-Feb-2015 14:06:03	TUMSHP	Q	DON	360.17
13-Feb-2015 0	125	0	191365	14-051	Install General Accessories	23-Feb-2015 14:05:59	TUMSHP	Q	DON	1,305.63

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
09-Mar-2015 1	4,715	0	194233	03-044	Replace Fuel System	11-Mar-2015 08:23:46	TUMFLD	I	DON	34.22
09-Mar-2015 1	4,715	0	194233	24-506-001	Repair Fuel Tank	29-Apr-2015 08:46:14	TUMFLD	E	DON	103.55
09-Mar-2015 1	4,715	0	194233	35-056-003	Diagnose Powershift PTO	29-Apr-2015 13:20:48	TUMFLD	F	DON	119.92
09-Mar-2015 1	4,715	0	194233	03-044-020	Replace Vapor Cannister	18-Apr-2015 17:07:57	TUMFLD	F	DON	285.45
04-May-2015 (	6,169	0	200001	06-100-009	Inspect Safety Check	05-May-2015 22:28:09	TUMFLD	P	DON	34.22
04-May-2015 (	6,169	0	200001	06-100-PMA	Inspect A PMI	05-May-2015 22:29:35	TUMFLD	P	DON	51.66
19-Oct-2015 1'	6,500	0	218842	14-078-009	Install Mud Flaps and Hanger Brackets	19-Oct-2015 17:27:50	TUMSHP	Q	DON	10.13
19-Oct-2015 1'	6,500	0	218842	14-052-015	Install Power Inverter/Converter	18-Nov-2015 09:20:41	TUMSHP	I	DON	557.09
19-Oct-2015 1'	6,500	0	218842	14-002-068	Install Service Body / Utility Box	16-Nov-2015 19:06:08	TUMSHP	O	DON	688.83
19-Oct-2015 1'	6,500	0	218842	03-032-001	Replace Battery	24-Nov-2015 11:39:46	TUMSHP	I	DON	121.47
19-Oct-2015 1'	6,500	0	218842	24-052-003	Repair Radio Equipment	17-Nov-2015 14:02:56	TUMSHP	I	DON	174.15
19-Oct-2015 1'	6,500	0	218842	03-056	Replace Power Take Off	19-Nov-2015 02:30:57	TUMSHP	O	DON	440.17
23-Nov-2015 2	8,414	0	223593	03-034-022	Replace Harness - Main	24-Nov-2015 00:00:00	ME0899	O	DON	465.14
12-Dec-2015 0	6,500	0	225584	03-017-001	Replace Tire - Pneumatic	19-Jan-2016 12:05:02	TUMSHP	N	DON	3,263.78
30-Dec-2015 0	13,163	0	230408	06-100-PMA	Inspect A PMI	22-Jan-2016 16:32:34	TUMSHP	P	DON	105.38
06-Jan-2016 08	13,163	0	227762	03-034-006	Replace Warning Lamps - Special Application	11-Jan-2016 09:00:00	ME1209	O	DON	190.20
06-Jan-2016 08	13,163	0	227762	24-034-004	Repair Clearance & Marker Lamps	07-Jan-2016 10:00:00	ME1209	O	DON	69.03
06-Jan-2016 08	13,163	0	227762	03-002-035	Replace Windshield Wiper & Washer	06-Jan-2016 08:30:00	ME1209	O	DON	17.26
29-Feb-2016 1'	16,148	0	235420	03-034-025	Replace Spot Light - Go Light	03-Mar-2016 12:00:00	ME1209	O	DON	47.65
29-Feb-2016 1'	16,148	0	235420	14-045	Install Power Plant	04-Mar-2016 18:40:17	TUMSHP	I	DON	122.09
29-Feb-2016 1'	16,148	0	235420	06-100-009	Inspect Safety Check	29-Feb-2016 18:55:21	TUMSHP	P	DON	36.52
29-Feb-2016 1'	16,148	0	235420	06-100-DOT	Inspect DOT Federal Inspection	01-Mar-2016 16:40:34	TUMSHP	P	DON	6.69
29-Feb-2016 1'	16,148	0	235420	38-040	Service Engine / Motor Systems Group		TUMSHP	P	CAN	0.00
29-Feb-2016 1'	16,148	0	235420	06-100-PMA	Inspect A PMI	04-Mar-2016 18:30:09	TUMSHP	P	DON	27.84
03-May-2016 (	24,920	0	243389	03-032-001	Replace Battery	01-Jun-2016 12:30:00	ME1078	I	DON	171.63
03-May-2016 (	24,920	0	243389	06-100-PMA	Inspect A PMI	13-May-2016 11:30:00	TUMSHP	P	DON	112.16
03-May-2016 (	24,920	0	243389	03-044-013	Replace Cap - Fuel Tank	03-May-2016 09:00:00	ME1209	O	DON	173.49
11-Jun-2016 16	24,920	0	249269	09-017-001	Align Tire - Pneumatic	22-Jun-2016 14:20:42	TUMSHP	O	DON	68.54
29-Jun-2016 0'	24,920	0	250042	03-013-002	Replace Rear Brakes & Drums	29-Jun-2016 07:08:10	BVLOFC	I	DON	389.89

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
29-Jun-2016 0'	24,920	0	250042	03-041-007	Replace Filter - Outer	29-Jun-2016 07:11:39	BVLOFC	P	DON	89.80
29-Jun-2016 0'	24,920	0	250042	06-100-009	Inspect Safety Check	29-Jun-2016 07:07:11	BVLOFC	I	DON	363.06
29-Jun-2016 0'	24,920	0	250042	24-016-006	Repair Shock Absorber - Rear	29-Jun-2016 07:09:54	BVLOFC	I	DON	265.31
22-Jul-2016 16	24,920	0	252970	06-100-PMA	Inspect A PMI	25-Jul-2016 10:14:05	TUMSHP	P	DON	0.00
22-Jul-2016 16	24,920	0	252970	14-MSC	Install Miscellaneous	26-Jul-2016 13:24:55	TUMSHP	I	DON	112.47
22-Jul-2016 16	24,920	0	252970	07-058-001	Lubricate Winch Assembly	27-Jul-2016 13:12:50	TUMSHP	I	DON	135.80
22-Jul-2016 16	24,920	0	252970	09-017-001	Align Tire - Pneumatic	28-Jul-2016 14:28:02	TUMSHP	I	DON	68.54
22-Jul-2016 16	24,920	0	252970	06-100-009	Inspect Safety Check	25-Jul-2016 12:55:47	TUMSHP	I	DON	93.17
01-Sep-2016 0	24,920	0	257941	24-044-001	Repair Tank - Fuel, Liquid	22-Nov-2016 11:39:38	MA0722	O	DON	241.31
01-Sep-2016 0	24,920	0	257941	06-100-PMA	Inspect A PMI	10-Sep-2016 02:00:00	MA0722	N	DON	20.82
01-Sep-2016 0	24,920	0	257941	06-040	Inspect Engine / Motor Systems Group	22-Nov-2016 11:20:38	MA0722	O	DON	162.52
01-Sep-2016 0	24,920	0	257941	03-044-002	Replace Filters	22-Nov-2016 11:19:28	MA0722	I	DON	17.18
01-Sep-2016 0	24,920	0	257941	03-017-001	Replace Tire - Pneumatic	19-Oct-2016 16:01:38	BTIRE	F	DON	613.64
06-Nov-2016 1	32,293	0	265669	03-002-024	Replace Glass / Windshield	22-Nov-2016 11:44:24	ME1078	I	DON	32.15
06-Nov-2016 1	32,293	0	265669	11-044-016	Rebuild Tank - Fuel Auxiliary	22-Nov-2016 11:40:04	ME1078	D	DON	1,322.14
06-Nov-2016 1	32,293	0	265669	03-017-001	Replace Tire - Pneumatic	15-Nov-2016 17:27:40	TUMSHP	N	DON	2,360.90
06-Nov-2016 1	32,293	0	265669	06-100-PMA	Inspect A PMI	15-Nov-2016 14:32:41	TUMSHP	P	DON	102.63
06-Nov-2016 1	32,293	0	265669	24-034-006	Repair Warning Lamps - Special Application	09-Jan-2017 09:32:06	ME1078	O	DON	51.59
27-Jan-2017 12	39,432	0	275166	02-002-030	Clean Interior Moldings	21-Feb-2017 15:58:44	TUMSHP	I	DON	70.54
27-Jan-2017 12	39,432	0	275166	03-013-001	Replace Front Brakes & Drums	20-Feb-2017 11:09:49	TUMSHP	I	DON	115.55
27-Jan-2017 12	39,432	0	275166	03-044-018	Replace Fuel Hose / Line	27-Jan-2017 16:51:55	TUMSHP	I	DON	190.34
27-Jan-2017 12	39,432	0	275166	03-053-004	Replace Safety Equipment	17-Feb-2017 13:45:46	TUMSHP	I	DON	100.75
27-Jan-2017 12	39,432	0	275166	03-052-013	Replace Antenna and Mounting	27-Jan-2017 18:18:20	TUMSHP	I	DON	113.71
27-Jan-2017 12	39,432	0	275166	03-054-002	Replace Alarm - Reverse Signal	20-Feb-2017 14:01:32	TUMSHP	I	DON	110.24
27-Jan-2017 12	39,432	0	275166	06-100-DOT	Inspect DOT Federal Inspection	20-Feb-2017 12:01:45	TUMSHP	I	DON	29.77
27-Jan-2017 12	39,432	0	275166	06-100-009	Inspect Safety Check	21-Feb-2017 13:26:08	TUMSHP	I	DON	30.98
27-Jan-2017 12	39,432	0	275166	02-071-001	Clean Floor / Decking / Flatbed	21-Feb-2017 17:59:47	TUMSHP	I	DON	69.38
27-Jan-2017 12	39,432	0	275166	03-065-034	Replace Switch - Pressure	27-Jan-2017 16:07:58	TUMSHP	I	DON	42.63
27-Jan-2017 12	39,432	0	275166	03-052-009	Replace Speakers	20-Feb-2017 09:27:57	TUMSHP	I	DON	34.78

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
27-Jan-2017 12	39,432	0	275166	06-100-PMA	Inspect A PMI	20-Feb-2017 18:05:03	TUMSHP	P	DON	64.27
27-Jan-2017 12	39,432	0	275166	14-053-001	Install Tire Chains	16-Feb-2017 12:35:42	TUMSHP	I	DON	141.63
27-Jan-2017 12	39,432	0	275166	14-053-005	Install Markings - Vehicle - Decals	27-Jan-2017 16:16:05	TUMSHP	I	DON	4.65
19-May-2017 0	39,434	0	289621	21-059-003	Fabricate Tow Hooks	19-May-2017 11:56:52	TUMSHP	P	DON	91.59
19-Jul-2017 09	45,901	0	300262	03-032-001	Replace Battery	09-Aug-2017 12:30:20	TUMSHP	O	DON	179.82
19-Aug-2017 0	46,102	0	301739	03-056-001	Replace Power Take Off	19-Aug-2017 10:00:00	ME1244	I	DON	53.50
01-Feb-2018 0	50,998	0	322041	24-056-001	Repair Power Take Off	04-Feb-2018 17:57:50	ME1078	I	DON	15.80
01-Feb-2018 0	50,998	0	322041	06-100-DOT	Inspect DOT Federal Inspection	01-Feb-2018 15:19:54	ME1078	P	DON	31.60
01-Feb-2018 0	50,998	0	322041	06-100-PMA	Inspect A PMI	01-Feb-2018 15:16:52	ME1078	P	DON	85.02
01-Feb-2018 0	50,998	0	322041	03-042-016	Replace Fan Clutch	04-Feb-2018 17:57:10	ME1078	I	DON	183.13
26-Feb-2018 1	50,998	0	325165	31-017-001	Rotate Tire - Pneumatic	28-Feb-2018 17:08:49	TUMSHP	I	DON	42.21
26-Feb-2018 1	50,998	0	325165	35-013-011	Diagnose Anti-Lock Sensor Assembly	01-Mar-2018 09:18:33	TUMSHP	I	DON	31.95
26-Feb-2018 1	50,998	0	325165	06-100-PMB	Inspect B PMI	28-Feb-2018 15:12:17	TUMSHP	I	DON	62.06
26-Feb-2018 1	50,998	0	325165	03-053-005	Replace Markings - Vehicle - Decals	28-Feb-2018 17:40:18	TUMSHP	I	DON	16.58
26-Feb-2018 1	50,998	0	325165	06-100-009	Inspect Safety Check	28-Feb-2018 11:37:29	TUMSHP	P	DON	68.24
26-Feb-2018 1	50,998	0	325165	03-025	Replace Transfer Case		TUMSHP	I	CAN	0.00
26-Feb-2018 1	50,998	0	325165	03-051-006	Replace Safety Devices	28-Feb-2018 15:24:34	TUMSHP	I	DON	127.30
30-Apr-2018 0	53,386	3,162	333706	24-034-002	Repair Stop, Tail, Turn & License	01-May-2018 09:00:36	ME1209	O	DON	104.80
25-Jul-2018 08	57,738	3,162	345401	06-100-PMA	Inspect A PMI	03-Aug-2018 15:17:33	ME1078	P	DON	80.77
25-Jul-2018 08	57,738	3,162	345401	24-510-002	Repair Tool Box	30-Aug-2018 14:20:12	ME1078	O	DON	90.84
23-Aug-2018 1	58,270	3,162	349471	03-044-003	Replace Fuel Pump	23-Aug-2018 11:47:28	BVLOFC	O	DON	904.42
09-Oct-2018 0	60,237	3,162	355676	03-043-002	Replace Exhaust Manifold	29-Nov-2018 14:57:11	BVLOFC	O	DON	3,249.13
28-Jan-2019 15	66,998	3,162	370322	03-078-009	Replace Mud Flaps and Hanger Brackets	28-Jan-2019 16:53:09	TUMSHP	I	DON	13.82
28-Jan-2019 15	66,998	3,162	370322	06-100-DOT	Inspect DOT Federal Inspection	31-Jan-2019 13:41:02	TUMSHP	P	DON	54.52
28-Jan-2019 15	66,998	3,162	370322	24-034-004	Repair Clearance & Marker Lamps	28-Jan-2019 16:44:48	TUMSHP	I	DON	8.65
28-Jan-2019 15	66,998	3,162	370322	03-053-017	Replace First Aid Kit	28-Jan-2019 17:28:56	TUMSHP	I	DON	72.59
28-Jan-2019 15	66,998	3,162	370322	03-013-002	Replace Rear Brakes & Drums	08-Feb-2019 11:14:57	TUMSHP	I	DON	850.31
28-Jan-2019 15	66,998	3,162	370322	02-044-007	Clean Throttle Controls	31-Jan-2019 11:41:19	TUMSHP	I	DON	64.38
28-Jan-2019 15	66,998	3,162	370322	24-052-003	Repair Radio Equipment	31-Jan-2019 13:26:44	TUMSHP	Q	DON	87.63

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
28-Jan-2019 15	66,998	3,162	370322	03-017-001	Replace Tire - Pneumatic	08-Feb-2019 11:21:54	TUMSHP	I	DON	3,432.70
28-Jan-2019 15	66,998	3,162	370322	06-100-PMA	Inspect A PMI	14-Feb-2019 10:52:57	TUMSHP	P	DON	185.10
11-Apr-2019 1	70,275	3,162	380801	06-100-PMA	Inspect A PMI	11-Apr-2019 12:43:07	TUMSHP	P	DON	57.63
15-May-2019 1	74,055	3,162	385972	06-100-PMA	Inspect A PMI	15-May-2019 14:27:27	BVLOFC	P	DON	128.12
11-Jun-2019 08	87,648	4,020	412465	38-100-PMA	Service A PMI	11-Jun-2019 10:21:00	TUMSHP	P	DON	70.84
20-Jun-2019 11	74,055	3,924	391080	06-100-PMA	Inspect A PMI	20-Jun-2019 13:44:59	BVLOFC	P	DON	0.00
20-Jun-2019 11	74,055	3,924	391080	38-100-PMA	Service A PMI	20-Jun-2019 13:44:59	BVLOFC	P	DON	68.15
06-Aug-2019 0	87,648	4,020	412466	38-100-PMA	Service A PMI	06-Aug-2019 08:05:00	TUMSHP	P	DON	187.12
19-Aug-2019 0	82,236	3,924	399158	06-100-PMA	Inspect A PMI	19-Aug-2019 07:13:26	BVLOFC	P	DON	0.00
19-Aug-2019 0	82,236	3,924	399158	38-100-PMB	Service B PMI	19-Aug-2019 07:13:26	BVLOFC	P	DON	180.01
03-Sep-2019 1	84,265	3,926	401317	14-034-010	Install Socket - Trailer Light Cord	18-Sep-2019 16:27:20	TUMSHP	I	DON	30.66
03-Sep-2019 1	84,265	3,926	401317	03-044	Replace Fuel System	23-Oct-2019 10:37:21	BVLOFC	O	DON	911.02
03-Sep-2019 1	84,265	3,926	401317	03-032-002	Replace Starter	18-Sep-2019 16:27:17	TUMSHP	I	DON	198.47
03-Sep-2019 1	84,265	3,926	401317	03-058-005	Replace Winch Control / Wiring	18-Sep-2019 16:27:23	TUMSHP	I	DON	78.06
03-Sep-2019 1	84,265	3,926	401317	03-034-019	Replace Switch (Other)	29-Oct-2019 15:53:55	TUMSHP	I	DON	56.02
03-Sep-2019 1	84,265	3,926	401317	03-032-001	Replace Battery	18-Sep-2019 16:27:03	TUMSHP	O	DON	178.48
03-Sep-2019 1	84,265	3,926	401317	03-043-002	Replace Exhaust Manifold	18-Sep-2019 16:27:25	TUMSHP	I	DON	37.77
03-Sep-2019 1	84,265	3,926	401317	02-044-016	Clean Tank - Fuel Auxiliary	18-Sep-2019 16:27:15	TUMSHP	I	DON	16.44
03-Sep-2019 1	84,265	3,926	401317	03-013-001	Replace Front Brakes & Drums	23-Oct-2019 10:37:54	BVLOFC	I	DON	397.70
21-Oct-2019 0	86,236	3,989	408420	06-100-PMA	Inspect A PMI	21-Oct-2019 06:46:28	TUMSHP	P	DON	0.00
21-Oct-2019 0	86,236	3,989	408420	38-100-PMA	Service A PMI	21-Oct-2019 06:46:28	BVLOFC	P	DON	118.99
12-Nov-2019 0	87,648	4,020	412184	06-016	Inspect Suspension	12-Nov-2019 05:56:12	BVLOFC	O	DON	75.42
12-Nov-2019 0	87,648	4,020	412184	03-042-016	Replace Fan Clutch	12-Nov-2019 05:56:12	BVLOFC	O	DON	836.65
12-Nov-2019 0	87,648	4,020	412184	03-042-002	Replace Radiator	12-Nov-2019 05:56:12	BVLOFC	I	DON	951.56
12-Nov-2019 0	87,648	4,020	412184	24-013-012	Repair Electric Brakes	12-Nov-2019 05:56:12	BVLOFC	O	DON	266.58
12-Nov-2019 0	87,648	4,020	412184	38-042	Service Cooling System	12-Nov-2019 05:56:12	BVLOFC	O	DON	234.95
13-Nov-2019 1	74,579	4,023	412559	38-100-PMA	Service A PMI	13-Nov-2019 15:28:58	TUMSHP	P	DON	123.69
13-Nov-2019 1	74,579	4,023	412559	06-100-PMA	Inspect A PMI	13-Nov-2019 15:29:04	TUMSHP	P	DON	0.00
09-Dec-2019 0	89,359	4,105	415860	06-100-PMA	Inspect A PMI	09-Dec-2019 06:35:33	BVLOFC	P	DON	0.00

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
09-Dec-2019 0	89,359	4,105	415860	38-100-PMA	Service A PMI	09-Dec-2019 06:35:33	BVLOFC	P	DON	110.70
09-Dec-2019 0	89,359	4,105	415860	03-041-007	Replace Filter - Outer	09-Dec-2019 06:35:33	BVLOFC	P	DON	25.69
09-Dec-2019 0	89,359	4,105	415860	03-002-035	Replace Windshield Wiper & Washer	09-Dec-2019 06:35:33	BVLOFC	P	DON	67.02
13-Dec-2019 0	90,485	4,122	416756	24-030	Repair Electrical Group	13-Dec-2019 06:09:05	BVLOFC	O	DON	560.94
19-Dec-2019 0	90,667	4,128	417588	03-031-001	Replace Generator/Alternator	19-Dec-2019 05:51:05	BVLOFC	B	DON	1,072.45
10-Jan-2020 09	78,542	4,155	420575	06-100-DOT	Inspect DOT Federal Inspection	10-Jan-2020 16:00:00	TRK040	P	DON	54.51
30-Jan-2020 15	79,230	4,177	423935	03-053-004	Replace Safety Equipment	31-Jan-2020 12:11:43	TUMSHP	I	DON	62.75
30-Jan-2020 15	79,230	4,177	423935	03-002-035	Replace Windshield Wiper & Washer	31-Jan-2020 11:31:51	TUMSHP	I	DON	30.51
30-Jan-2020 15	79,230	4,177	423935	03-013-002	Replace Rear Brakes & Drums	31-Jan-2020 15:15:04	TUMSHP	I	DON	330.24
30-Jan-2020 15	79,230	4,177	423935	06-100-009	Inspect Safety Check	30-Jan-2020 16:52:34	TUMSHP	P	DON	76.31
30-Jan-2020 15	79,230	4,177	423935	03-034-004	Replace Clearance & Marker Lamps	03-Feb-2020 11:09:19	TUMSHP	I	DON	11.66
30-Jan-2020 15	79,230	4,177	423935	12-018-003	Refinish Wheels	03-Feb-2020 10:35:39	TUMSHP	I	DON	68.69
30-Jan-2020 15	79,230	4,177	423935	03-053-017	Replace First Aid Kit	03-Feb-2020 11:23:38	TUMSHP	I	DON	23.55
30-Jan-2020 15	79,230	4,177	423935	24-058-001	Repair Winch Assembly	10-Mar-2020 17:13:13	TUMSHP	I	DON	701.12
30-Jan-2020 15	79,230	4,177	423935	24-510-002	Repair Tool Box	31-Jan-2020 11:27:23	TUMSHP	I	DON	323.62
30-Jan-2020 15	79,230	4,177	423935	03-034-025	Replace Spot Light - Go Light	31-Jan-2020 12:35:09	TUMSHP	I	DON	448.82
30-Jan-2020 15	79,230	4,177	423935	03-016-003	Replace Shock Absorber - Front	24-Feb-2020 15:30:35	TUMSHP	I	DON	255.67
30-Jan-2020 15	79,230	4,177	423935	38-100-PMA	Service A PMI	24-Feb-2020 11:33:02	TUMSHP	P	DON	59.85
30-Jan-2020 15	79,230	4,177	423935	38-100-PMB	Service B PMI	24-Feb-2020 10:55:36	TUMSHP	P	DON	302.03
30-Jan-2020 15	79,230	4,177	423935	03-016-006	Replace Shock Absorber - Rear	24-Feb-2020 15:03:09	TUMSHP	I	DON	295.27
30-Jan-2020 15	79,230	4,177	423935	06-100-PMA	Inspect A PMI	10-Mar-2020 11:50:29	TUMSHP	P	DON	0.00
30-Jan-2020 15	79,230	4,177	423935	03-064-001	Replace Portable Generator Assembly	10-Mar-2020 14:58:03	TUMSHP	I	DON	21.02
30-Jan-2020 15	79,230	4,177	423935	03-052-015	Replace Power Inverter/Converter	12-Mar-2020 16:50:51	TUMSHP	I	DON	585.76
30-Jan-2020 15	79,230	4,177	423935	03-051-009	Replace Fire Extinguisher	31-Jan-2020 11:38:59	TUMSHP	I	DON	85.60
25-Feb-2020 0	91,938	4,185	430963	03-027	Replace Transmission - Main, Automatic	13-Mar-2020 00:00:00	BVLOFC	N	DON	2,326.00
25-Feb-2020 0	91,938	4,185	430963	06-027-037	Inspect Transmission Assembly - Automatic	13-Mar-2020 00:00:00	BVLOFC	O	DON	138.88
02-Apr-2020 0	80,122	4,303	434193	14-052-009	Install Speakers	02-Apr-2020 13:14:45	TUMSHP	O	DON	49.45
02-Apr-2020 0	80,122	4,303	434193	03-044-002	Replace Filters	02-Apr-2020 13:14:42	TUMSHP	P	DON	23.60
15-Apr-2020 1	92,779	4,363	436106	03-033-003	Replace Spark Plugs	15-Apr-2020 13:24:37	BVLOFC	I	DON	502.34

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
15-Apr-2020 1	92,779	4,363	436106	03-044	Replace Fuel System	15-Apr-2020 13:24:37	BVLOFC	O	DON	1,312.49
11-May-2020 C	93,464	4,373	440027	03-024-002	Replace Drive Shaft, Behind Main Transmission	11-May-2020 06:12:17	BVLOFC	I	DON	1,534.20
11-May-2020 C	93,464	4,373	440027	24-027-001	Repair Case Assembly - Automatic Transmission	11-May-2020 06:12:17	BVLOFC	W	DON	0.00
07-Jul-2020 08	83,895	4,743	449886	03-034-010	Replace Socket - Trailer Light Cord	10-Jul-2020 12:34:48	TUMSHP	O	DON	32.03
07-Jul-2020 08	83,895	4,743	449886	03-097	Replace Pump - Product Transfer	23-Jul-2020 10:56:58	TUMSHP	O	DON	1,797.20
30-Jul-2020 08	84,766	4,943	453521	03-017-001	Replace Tire - Pneumatic	05-Aug-2020 09:20:06	TRK040	I	DON	3,210.50
05-Aug-2020 C	85,144	5,039	454932	38-100-PMA	Service A PMI	18-Aug-2020 11:59:49	TUMSHP	I	DON	94.80
05-Aug-2020 C	85,144	5,039	454932	06-100-PMA	Inspect A PMI	07-Aug-2020 15:46:51	TUMSHP	P	DON	0.00
05-Aug-2020 C	85,144	5,039	454932	24-053-015	Repair Tool Box	07-Aug-2020 14:54:13	TUMSHP	P	DON	65.75
16-Oct-2020 0:	87,111	5,384	467199	06-052-015	Inspect Power Inverter/Converter		ME1209	P	CAN	0.00
16-Oct-2020 0:	87,111	5,384	467199	24-002-071	Repair Side Window		ME1209	P	CAN	0.00
02-Nov-2020 C	87,112	5,385	469886	24-056	Repair Power Take Off	04-Nov-2020 16:13:07	TUMSHP	I	DON	1,501.67
02-Nov-2020 C	87,112	5,385	469886	06-100-009	Inspect Safety Check	02-Nov-2020 12:19:02	TUMSHP	P	DON	71.19
02-Nov-2020 C	87,112	5,385	469886	03-053-025	Replace Wheel Chock	02-Nov-2020 15:42:49	TUMSHP	E	DON	42.25
02-Nov-2020 C	87,112	5,385	469886	03-078-009	Replace Mud Flaps and Hanger Brackets	02-Nov-2020 13:48:59	TUMSHP	I	DON	36.08
02-Nov-2020 C	87,112	5,385	469886	03-002-035	Replace Windshield Wiper & Washer	03-Nov-2020 09:21:32	TUMSHP	I	DON	23.98
02-Nov-2020 C	87,112	5,385	469886	03-034-025	Replace Spot Light - Go Light	02-Nov-2020 15:34:21	TUMSHP	E	DON	392.23
02-Nov-2020 C	87,112	5,385	469886	03-051-009	Replace Fire Extinguisher	02-Nov-2020 13:52:09	TUMSHP	Q	DON	39.80
02-Nov-2020 C	87,112	5,385	469886	24-034-014	Repair Auxiliary Work / Flood Light	02-Nov-2020 13:21:54	TUMSHP	I	DON	126.02
02-Nov-2020 C	87,112	5,385	469886	24-510-002	Repair Tool Box	03-Nov-2020 10:40:41	TUMSHP	I	DON	229.12
29-Dec-2020 0	87,114	5,386	479166	06-100-007	Inspect In-Service Inspection		TUMSHP	P	CAN	0.00
07-Jan-2021 1C	87,114	5,386	480640	02-002-048	Clean Upholstery Trim - Cab	08-Jan-2021 12:18:40	TUMSHP	I	DON	185.40
07-Jan-2021 1C	87,114	5,386	480640	24-510-002	Repair Tool Box	08-Jan-2021 14:00:34	TUMSHP	I	DON	22.84
07-Jan-2021 1C	87,114	5,386	480640	03-032-001	Replace Battery	07-Jan-2021 12:29:13	TUMSHP	I	DON	167.31
07-Jan-2021 1C	87,114	5,386	480640	06-100-DOT	Inspect DOT Federal Inspection	07-Jan-2021 13:22:09	TUMSHP	P	DON	17.17
07-Jan-2021 1C	87,114	5,386	480640	24-052-015	Repair Power Inverter/Converter	08-Jan-2021 13:29:00	TUMSHP	I	DON	96.00
07-Jan-2021 1C	87,114	5,386	480640	06-100-007	Inspect In-Service Inspection	07-Jan-2021 12:58:25	TUMSHP	P	DON	53.14
13-Jan-2021 08	102,395	5,386	481968	03-001-008	Replace Motor - Blower	02-Feb-2021 09:50:26	TUMSHP	O	DON	314.60
13-Jan-2021 08	102,395	5,386	481968	24-052-003	Repair Radio Equipment	13-Jan-2021 18:59:06	TUMSHP	O	DON	86.82

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
22-Jan-2021 08	102,395	5,386	495268	06-100-PMA	Inspect A PMI	19-Mar-2021 09:43:40	SCHED	P	DON	0.00
22-Jan-2021 08	102,395	5,386	495268	38-100-PMA	Service A PMI	19-Mar-2021 09:43:44	TUMSHP	I	DON	94.23
09-Feb-2021 0	102,395	5,386	487389	24-056	Repair Power Take Off	12-Feb-2021 16:10:38	TUMSHP	O	DON	86.82
26-Feb-2021 1	102,395	5,386	490544	06-100-007	Inspect In-Service Inspection		TUMSHP	P	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	03-042-017	Replace Fan Shroud		BVLOFC	I	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	34-044-007	Reseal Throttle Controls		BVLOFC	I	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	03-044-007	Replace Throttle Controls		BVLOFC	I	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	06-049	Inspect Electronic Management System		BVLOFC	I	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	24-015	Repair Steering		BVLOFC	I	CAN	0.00
01-Mar-2021 0	102,395	5,386	494624	03-042-002	Replace Radiator		BVLOFC	I	CAN	0.00
03-Mar-2021 0	102,395	5,386	491454	06-100-007	Inspect In-Service Inspection	03-Mar-2021 11:05:51	TUMSHP	P	DON	56.62
20-Apr-2021 0	102,395	5,386	501689	06-032-001	Inspect Battery	21-Apr-2021 09:32:37	TRK040	O	DON	153.09
04-May-2021 1	102,395	5,386	504486	03-015-004	Replace Steering Linkage	06-May-2021 14:00:45	TUMSHP	I	DON	481.52
04-May-2021 1	102,395	5,386	504486	03-016-004	Replace Stabilizer (Sway) Bar - Front	06-May-2021 12:57:05	TUMSHP	I	DON	149.94
04-May-2021 1	102,395	5,386	504486	03-016-020	Replace Ball Joint - Upper Control Arm	05-May-2021 14:00:32	TUMSHP	I	DON	426.78
04-May-2021 1	102,395	5,386	504486	03-016-021	Replace Ball Joint - Lower Control Arm	06-May-2021 11:02:07	TUMSHP	I	DON	529.21
04-May-2021 1	102,395	5,386	504486	03-034-004	Replace Clearance & Marker Lamps	04-May-2021 15:15:05	TUMSHP	I	DON	10.28
04-May-2021 1	102,395	5,386	504486	24-027	Repair Transmission - Main, Automatic	04-May-2021 15:36:20	TUMSHP	I	DON	96.84
04-May-2021 1	102,395	5,386	504486	06-100-009	Inspect Safety Check	04-May-2021 13:26:04	TUMSHP	P	DON	140.07
04-May-2021 1	102,395	5,386	504486	03-052-013	Replace Antenna and Mounting	04-May-2021 13:44:26	TUMSHP	I	DON	31.99
04-May-2021 1	102,395	5,386	504486	24-510-002	Repair Tool Box	04-May-2021 15:05:52	TUMSHP	I	DON	34.29
04-May-2021 1	102,395	5,386	504486	03-002-035	Replace Windshield Wiper & Washer	04-May-2021 13:39:32	TUMSHP	I	DON	24.65
04-May-2021 1	102,395	5,386	504486	09-015	Align Steering	11-May-2021 10:44:30	TUMSHP	I	DON	113.47
04-May-2021 1	102,395	5,386	504486	24-034	Repair Lighting System	06-May-2021 15:13:27	TUMSHP	I	DON	44.89
04-May-2021 1	102,395	5,386	504486	24-054-002	Repair Alarm - Reverse Signal	04-May-2021 15:20:17	TUMSHP	I	DON	3.76
04-May-2021 1	102,395	5,386	504486	03-013-037	Replace Caliper - Front	06-May-2021 11:32:47	TUMSHP	I	DON	214.36
04-May-2021 1	102,395	5,386	504486	24-518-001	Repair Steps	13-May-2021 15:37:26	TUMSHP	I	DON	13.70
09-Sep-2021 10	102,395	5,386	530092	24-027	Repair Transmission - Main, Automatic	09-Sep-2021 10:35:17	TUMSHP	O	DON	853.52
01-Dec-2021 1	104,829	6,222	550295	24-053-015	Repair Tool Box	03-Dec-2021 09:26:42	TUMSHP	I	DON	190.86

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
01-Dec-2021 1	104,829	6,222	550295	03-053-004	Replace Safety Equipment	01-Dec-2021 17:07:16	TUMSHP	I	DON	70.44
01-Dec-2021 1	104,829	6,222	550295	03-052-009	Replace Speakers	02-Dec-2021 13:11:31	TUMSHP	I	DON	38.74
01-Dec-2021 1	104,829	6,222	550295	31-017-001	Rotate Tire - Pneumatic	02-Dec-2021 12:17:58	TUMSHP	I	DON	129.32
01-Dec-2021 1	104,829	6,222	550295	06-100-DOT	Inspect DOT Federal Inspection	01-Dec-2021 17:30:23	TUMSHP	P	DON	101.00
01-Dec-2021 1	104,829	6,222	550295	24-043-007	Repair Exhaust Pipe/Elbow	01-Dec-2021 16:57:06	TUMSHP	I	DON	21.78
17-Dec-2021 1	104,829	6,222	554546	03-063-003	Replace Transceiver - GPS Tracker	18-Dec-2021 09:43:14	TRK040	Q	DON	406.93
17-Dec-2021 1	104,829	6,222	554546	06-100-DOT	Inspect DOT Federal Inspection	18-Dec-2021 09:12:24	TRK040	P	DON	306.17
17-Dec-2021 1	104,829	6,222	554546	14-044-002	Install Filters	17-Dec-2021 17:06:54	TUMSHP	O	DON	757.71
08-Feb-2022 1	104,829	6,222	565008	14-052-003	Install Radio Equipment	08-Feb-2022 12:29:09	TUMSHP	E	DON	245.32
22-Mar-2022 1	104,829	6,222	576551	06-100-PMA	Inspect A PMI	22-Mar-2022 17:45:38	TUMSHP	P	DON	0.00
22-Mar-2022 1	104,829	6,222	576551	38-100-PMA	Service A PMI	22-Mar-2022 17:56:23	TUMSHP	P	DON	167.42
21-Apr-2022 1	104,829	6,222	583381	14-052-014	Install Cellular Telephone Accessories		TUMSHP	E	CAN	0.00
01-Jun-2022 0	114,026	6,222	592576	03-015-004	Replace Steering Linkage	03-Jun-2022 11:04:12	TUMSHP	I	DON	386.35
01-Jun-2022 0	114,026	6,222	592576	03-014-010	Replace Toolbox Mounting	02-Jun-2022 15:40:21	TUMSHP	I	DON	111.99
01-Jun-2022 0	114,026	6,222	592576	01-017-001	Adjust Tire - Pneumatic	02-Jun-2022 14:00:09	TUMSHP	I	DON	106.77
01-Jun-2022 0	114,026	6,222	592576	03-034-004	Replace Clearance & Marker Lamps	02-Jun-2022 11:32:34	TUMSHP	I	DON	32.21
01-Jun-2022 0	114,026	6,222	592576	38-100-PMA	Service A PMI		SCHED	P	CAN	0.00
01-Jun-2022 0	114,026	6,222	592576	06-100-007	Inspect In-Service Inspection	06-Jun-2022 11:21:29	TUMSHP	P	DON	156.81
01-Jun-2022 0	114,026	6,222	592576	06-100-PMA	Inspect A PMI		SCHED	P	CAN	0.00
01-Jun-2022 0	114,026	6,222	592576	06-100-PMB	Inspect B PMI	02-Jun-2022 15:39:58	TUMSHP	P	DON	0.00
01-Jun-2022 0	114,026	6,222	592576	03-018-011	Replace Seal - Wheel	06-Jun-2022 11:20:47	TUMSHP	I	DON	218.90
01-Jun-2022 0	114,026	6,222	592576	38-100-PMB	Service B PMI	03-Jun-2022 12:27:53	TUMSHP	P	DON	513.94
01-Jun-2022 0	114,026	6,222	592576	35-056-003	Diagnose Powershift PTO	01-Jun-2022 17:00:53	TUMSHP	I	DON	66.72
16-Jun-2022 0	114,026	6,222	596478	06-013-032	Inspect ABS - ECU	18-Aug-2022 08:45:35	TRK040	I	DON	178.60
01-Aug-2022 0	114,902	7,031	606244	21-268-037	Fabricate Arbor Bar	01-Aug-2022 17:30:16	TUMSHP	I	DON	152.06
01-Aug-2022 0	114,902	7,031	606244	06-045	Inspect Power Plant	09-Aug-2022 12:44:48	BVLOFC	O	DON	335.21
01-Aug-2022 0	114,902	7,031	606244	06-100-007	Inspect In-Service Inspection	01-Aug-2022 12:32:13	TUMSHP	P	DON	145.66
16-Aug-2022 0	114,965	7,035	609710	24-013-011	Repair Anti-Lock Sensor Assembly	16-Aug-2022 13:28:21	BVLOFC	O	DON	557.92
26-Sep-2022 1	115,153	7,071	619264	24-017-001	Repair Tire - Pneumatic	26-Sep-2022 12:35:08	TUMSHP	O	DON	23.34

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
07-Nov-2022 1	115,500	7,193	630422	03-034-010	Replace Socket - Trailer Light Cord	16-Nov-2022 16:05:31	TUMSHP	I	DON	128.05
07-Nov-2022 1	115,500	7,193	630422	03-065-017	Replace Reservoir/Tank	05-Dec-2022 09:09:31	TUMSHP	I	DON	72.62
07-Nov-2022 1	115,500	7,193	630422	03-071-005	Replace Side Door Assembly - Hinged	18-Nov-2022 10:51:41	TUMSHP	I	DON	123.36
07-Nov-2022 1	115,500	7,193	630422	06-040	Inspect Engine / Motor Systems Group		TUMSHP	P	CAN	0.00
07-Nov-2022 1	115,500	7,193	630422	06-100-007	Inspect In-Service Inspection	05-Dec-2022 09:34:44	TUMSHP	P	DON	130.00
07-Nov-2022 1	115,500	7,193	630422	21-370-004	Fabricate Mandrel Assembly	18-Nov-2022 10:51:59	TUMSHP	I	DON	114.06
07-Nov-2022 1	115,500	7,193	630422	03-053-004	Replace Safety Equipment	21-Nov-2022 17:28:21	TUMSHP	Q	DON	43.03
07-Nov-2022 1	115,500	7,193	630422	06-100-DOT	Inspect DOT Federal Inspection	18-Nov-2022 14:24:08	TUMSHP	P	DON	18.63
17-Jan-2023 02	116,221	7,247	645859	03-034-001	Replace Headlamps / Fog Lamps	24-Jan-2023 20:06:15	TRK040	O	DON	55.94
17-Jan-2023 02	116,221	7,247	645859	06-064-001	Inspect Portable Generator Assembly	17-Jan-2023 19:11:12	TRK040	O	DON	65.60
17-Jan-2023 02	116,221	7,247	645859	06-017-001	Inspect Tire - Pneumatic	18-Jan-2023 19:47:34	TRK040	O	DON	43.73
03-Feb-2023 12	116,403	7,265	650341	03-072-011	Replace Door Seal	07-Feb-2023 16:17:11	TUMSHP	I	DON	36.45
03-Feb-2023 12	116,403	7,265	650341	03-193-010	Replace Wipers	07-Feb-2023 16:08:46	TUMSHP	I	DON	16.91
03-Feb-2023 12	116,403	7,265	650341	06-100-009	Inspect Safety Check	08-Feb-2023 13:07:21	TUMSHP	P	DON	355.07
03-Feb-2023 12	116,403	7,265	650341	09-043-007	Align Exhaust Pipe/Elbow	07-Feb-2023 13:07:30	TUMSHP	I	DON	14.98
03-Feb-2023 12	116,403	7,265	650341	03-044-016	Replace Tank - Fuel Auxiliary	08-Feb-2023 09:29:48	TUMSHP	I	DON	62.17
03-Feb-2023 12	116,403	7,265	650341	03-072-006	Replace Door Latch Mechanism	07-Feb-2023 14:00:04	TUMSHP	I	DON	50.29
25-Apr-2023 1	117,043	7,467	670023	03-013-037	Replace Caliper - Front	02-May-2023 10:56:25	TUMSHP	I	DON	135.73
25-Apr-2023 1	117,043	7,467	670023	03-013-038	Replace Caliper - Rear	04-May-2023 12:16:35	TUMSHP	I	DON	320.93
25-Apr-2023 1	117,043	7,467	670023	03-032-001	Replace Battery	25-May-2023 13:13:09	TUMSHP	I	DON	182.92
25-Apr-2023 1	117,043	7,467	670023	03-044-016	Replace Tank - Fuel Auxiliary	03-May-2023 16:50:43	TUMSHP	I	DON	107.00
25-Apr-2023 1	117,043	7,467	670023	03-051-006	Replace Safety Devices	27-Apr-2023 12:43:37	TUMSHP	Q	DON	73.36
25-Apr-2023 1	117,043	7,467	670023	03-065-031	Replace Seal / Gasket - Pump	15-May-2023 16:20:23	TUMSHP	I	DON	270.85
25-Apr-2023 1	117,043	7,467	670023	03-078-009	Replace Mud Flaps and Hanger Brackets	15-May-2023 12:11:10	TUMSHP	I	DON	25.84
25-Apr-2023 1	117,043	7,467	670023	03-715-001	Replace Clamp	15-May-2023 13:39:45	TUMSHP	I	DON	44.38
25-Apr-2023 1	117,043	7,467	670023	06-100-009	Inspect Safety Check	15-May-2023 16:20:36	TUMSHP	P	DON	1,001.75
25-Apr-2023 1	117,043	7,467	670023	06-100-PMA	Inspect A PMI	25-May-2023 13:13:18	TUMSHP	P	DON	0.10
25-Apr-2023 1	117,043	7,467	670023	14-034-025	Install Spot Light - Go Light	17-May-2023 12:36:07	TUMSHP	I	DON	418.48
25-Apr-2023 1	117,043	7,467	670023	14-064-001	Install Portable Generator Assembly	18-May-2023 13:40:26	TUMSHP	I	DON	105.96

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
25-Apr-2023 1	117,043	7,467	670023	21-519-001	Fabricate Front Bumper	28-Apr-2023 16:43:30	TUMSHP	I	DON	20.43
25-Apr-2023 1	117,043	7,467	670023	24-043-007	Repair Exhaust Pipe/Elbow	25-May-2023 10:02:02	TUMSHP	I	DON	29.56
25-Apr-2023 1	117,043	7,467	670023	24-096-002	Repair Power Shaft Assembly - PTO	02-May-2023 17:30:55	TUMSHP	I	DON	129.39
25-Apr-2023 1	117,043	7,467	670023	38-100-PMA	Service A PMI	25-May-2023 13:13:29	TUMSHP	P	DON	357.59
07-Jun-2023 1	117,209	7,478	679635	03-017-001	Replace Tire - Pneumatic	07-Jun-2023 16:01:32	BVLOFC	B	DON	624.35
17-Jul-2023 01	118,107	7,531	688913	03-034-001	Replace Headlamps / Fog Lamps	20-Jul-2023 16:26:57	TRK040	I	DON	131.19
17-Jul-2023 01	118,107	7,531	688913	03-002-035	Replace Windshield Wiper & Washer	27-Jul-2023 18:17:51	TRK040	O	DON	67.55
17-Jul-2023 01	118,107	7,531	688913	03-013-001	Replace Front Brakes & Drums	14-Aug-2023 14:23:36	TRK040	B	DON	819.75
17-Jul-2023 08	118,660	7,581	693592	35-052-015	Diagnose Power Inverter/Converter	17-Jul-2023 19:51:00	BVLOFC	E	DON	396.00
21-Sep-2023 0	120,606	7,751	709089	24-043-003	Repair Muffler	22-Sep-2023 19:32:00	BVLOFC	B	DON	444.00
21-Sep-2023 1	120,541	7,744	707031	03-017-001	Replace Tire - Pneumatic	21-Sep-2023 17:56:26	BVLOFC	N	DON	2,067.42
26-Oct-2023 0	120,607	7,751	716077	06-100-007	Inspect In-Service Inspection	30-Oct-2023 10:11:58	TRK040	P	DON	131.19
26-Oct-2023 0	120,607	7,751	716077	03-017-001	Replace Tire - Pneumatic	30-Oct-2023 10:12:38	TRK040	I	DON	43.73
26-Oct-2023 0	120,607	7,751	716077	24-510-002	Repair Tool Box	27-Oct-2023 17:26:45	TRK040	I	DON	349.84
26-Oct-2023 0	120,607	7,751	716077	03-034-004	Replace Clearance & Marker Lamps	30-Oct-2023 10:13:08	TRK040	I	DON	43.73
26-Oct-2023 0	120,607	7,751	716077	06-100-DOT	Inspect DOT Federal Inspection	30-Oct-2023 10:15:40	TRK040	P	DON	131.19
26-Oct-2023 0	120,607	7,751	716077	03-705	Replace Vise	27-Oct-2023 15:02:08	TRK040	I	DON	131.19
26-Oct-2023 0	120,607	7,751	716077	03-053-017	Replace First Aid Kit	30-Oct-2023 10:53:16	TRK040	Q	DON	61.48
09-Jan-2024 1	120,629	7,753	731133	03-032-001	Replace Battery	11-Jan-2024 10:09:48	TUMSHP	N	DON	199.17
09-Jan-2024 1	120,629	7,753	731133	03-051-009	Replace Fire Extinguisher	12-Jan-2024 09:29:56	TUMSHP	N	DON	53.14
09-Jan-2024 1	120,629	7,753	731133	03-064-001	Replace Portable Generator Assembly	12-Jan-2024 09:24:57	TUMSHP	N	DON	51.33
09-Jan-2024 1	120,629	7,753	731133	06-100-PMA	Inspect A PMI	11-Jan-2024 15:40:41	TUMSHP	P	DON	11.05
09-Jan-2024 1	120,629	7,753	731133	38-100-PMA	Service A PMI	11-Jan-2024 15:22:52	TUMSHP	P	DON	107.74
09-Jan-2024 1	120,629	7,753	731133	06-100-007	Inspect In-Service Inspection	11-Jan-2024 14:34:34	TUMSHP	P	DON	52.63
16-Apr-2024 1	120,629	7,755	753119	06-100-007	Inspect In-Service Inspection	16-Apr-2024 14:53:25	TUMSHP	P	DON	126.68
16-Apr-2024 1	120,629	7,755	753119	03-098-001	Replace Ball Valve Assembly (Blowdown Valve		TUMSHP	N	CAN	0.00
16-Apr-2024 1	120,629	7,755	753119	03-053-999	Replace Vehicle Fluids, Lubricants, Gases, & Pa	16-Apr-2024 14:53:00	TUMSHP	N	DON	367.19
06-May-2024 (	121,069	7,805	761646	95-015-001	Travel Steering Wheel	10-May-2024 19:45:00	BVLOFC	N	DON	80.00
06-May-2024 (	121,069	7,805	761646	35-015-001	Diagnose Steering Wheel	10-May-2024 19:43:00	BVLOFC	N	DON	452.28

Unit Job History

Michels Corporation

Report Printed: 26-Sep-2025 12:37:09 By User: VRIES

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: F0924 - 2015 F550 CREWCAB										
31-May-2024 1	121,208	7,835	763256	03-094	Replace Lines, Tubes, Hoses & Fittings - Bulk P	01-Jun-2024 16:08:13	TRK040	N	DON	157.50
15-Jul-2024 14	121,756	7,877	772462	06-100-PMB	Inspect B PMI	18-Jul-2024 09:05:18	TUMSHP	P	DON	323.35
15-Jul-2024 14	121,756	7,877	772462	25-015-001	Remove Steering Wheel	16-Jul-2024 16:53:18	TUMSHP	N	DON	97.46
15-Jul-2024 14	121,756	7,877	772462	03-078-009	Replace Mud Flaps and Hanger Brackets	16-Jul-2024 10:26:45	TUMSHP	N	DON	40.86
15-Jul-2024 14	121,756	7,877	772462	24-053-015	Repair Tool Box	16-Jul-2024 15:01:53	TUMSHP	N	DON	148.21
15-Jul-2024 14	121,756	7,877	772462	03-041-007	Replace Filter - Outer	16-Jul-2024 10:32:34	TUMSHP	N	DON	19.87
15-Jul-2024 14	121,756	7,877	772462	03-015-004	Replace Steering Linkage	17-Jul-2024 18:02:31	TUMSHP	N	DON	443.84
15-Jul-2024 14	121,756	7,877	772462	03-051-006	Replace Safety Devices	17-Jul-2024 12:39:53	TUMSHP	N	DON	132.65
15-Jul-2024 14	121,756	7,877	772462	03-065-034	Replace Switch - Pressure	18-Jul-2024 09:30:31	TUMSHP	N	DON	38.45
17-Jul-2024 09	123,569	8,103	817764	03-015-004	Replace Steering Linkage	17-Jul-2024 09:22:24	TUMSHP	N	DON	120.65
29-Aug-2024 C	122,931	8,032	783049	95-MSC-004	Travel Travel Time - To/From Job Site	30-Aug-2024 08:13:11	TRK040	N	DON	52.50
29-Aug-2024 C	122,931	8,032	783049	03-090	Replace Bulk Product Transfer Systems Group	30-Aug-2024 07:53:14	TRK040	N	DON	688.95
12-Aug-2025 1	123,569	8,105	856692	06-100-DOT	Inspect DOT Federal Inspection	26-Aug-2025 17:11:56	TUMSHP	P	DON	73.66
12-Aug-2025 1	123,569	8,105	856692	03-053-004	Replace Safety Equipment	12-Aug-2025 16:20:34	TUMSHP	N	DON	75.80
12-Aug-2025 1	123,569	8,105	856692	27-002	De-Identify Cab & Sheet Metal	21-Aug-2025 15:08:26	TUMSHP	Z	DON	331.01
12-Aug-2025 1	123,569	8,105	856692	25-063-003	Remove Transceiver - GPS Tracker	21-Aug-2025 15:59:40	TUMSHP	Z	DON	31.76
12-Aug-2025 1	123,569	8,105	856692	35-040	Diagnose Engine / Motor Systems Group	15-Aug-2025 15:34:59	TUMSHP	N	DON	32.83

Unit No: F0924

Count: 336

94,652.98